MODELS OF THE TRAPPED

RADIATION ENVIRONMENT


Volume II: Inner and

Outer Zone Electrons

VETTE, LUCERO, AND WRIGHT



N66 35685
(ACCESSION NUMBER)
(PAGES)





MODELS OF THE TRAPPE

RADIATION ENVIRONMENT

A Volume i Resimination

Outer Zone Electrons

JAMES I. VETTE, ANTONIO B. LUCERO, AND JON A. WRIGHT Aerospace Corporation

A study sponsored by the National Aeronautics and Space Administration and the United States Air Force and prepared under Air Force contract by Aerospace Corporation, El Segundo, California.



PREFACE

Space systems planners—space engineers as well as physicists—require for their work accurate values of the fluxes and energy spectra of protons and electrons trapped in the geomagnetic field. Numerous measurements have been made of the Van Allen belt radiations on many satellites, with different instruments and at different times. Most of the experimenters organize their data in terms of McIlwain's B, L coordinates, but intercomparison of the results from different experiments is still complicated by temporal variations of the fluxes and differences in energy response of the various instruments used to obtain the data. A need existed, therefore, for collating the individual measurements and for constructing a model environment.

A program, sponsored jointly by the National Aeronautics and Space Administration (Defense Purchase Request W-11, 683) and the United States Air Force (Contract AF 04(695)-469) is in progress under the direction of Dr. Vette for the express purpose of constructing such a model environment. In the NASA report SP-3024, Volume I, a description was published of the inner radiation belt. The purpose of this report (Volume II) is to update the electron environment in the inner belt and to extend it out to L = 6. In addition, codes have been developed for integrating the flux along satellite orbits. Persons on NASA sponsored projects may request such integrations from Wilmot N. Hess, Goddard Space Flight Center, and those on Air Force projects should request it from James I. Vette, Aerospace Corporation.

As this effort continues, major emphasis will be placed on describing time dependence of the flux in the outer radiation belt, updating the model of the inner belt, and developing the capability to predict changes that are likely to occur in the particle populations. Hopefully, such changes can be correlated with geophysical indicators or other events.

This effort would not be possible without the assistance given to this project by the experimenters who made the measurements originally. All users of this environment will greatly appreciate these efforts. It is to be hoped that this enthusiasm will continue and permit us to maintain an up-to-date model environment.

A. W. Schardt
Physics & Astronomy Programs
NASA Headquarters

CONTENTS

Preface	iii
INTRODUCTION	1
AE2 ELECTRON ENERGY SPECTRUM	3
AE2 DISTRIBUTION FUNCTION	5
ORBITAL INTEGRATIONS	7
PUNCHED CARD FORMAT	8
DISCUSSION	
References	g

INTRODUCTION

This is the second in a series of updated model environments intended to be of general use to space researchers having need for a detailed description of the trapped radiation. The first environment (Reference 1) gave a description of electron and protons in the inner zone for the summer of 1963. A preliminary report on AE1 and a general description of the program have been given in Reference 2. The present report describes the electron environment AE2, which covers both inner and outer zone out to L=6.0 for the time period around August 1964. The data that have been used in constructing this model are listed in Table 1. The code symbols given in Table 1 are used to refer to the various data in this report.

The methods employed in the production of the model environments are described in detail in Reference 1. A comparison of the model with the existing data is presented here, along with a detailed listing of both the flux distribution and energy spectrum. The orbital integration results for circular orbits up to 18,000 n. miles are given for 29 energies and energy bands. Similar results are also presented for an electron environment projected to the end of 1968. It is hoped that this will provide some guidance in determining radiation damage estimates for future space missions.

Table 1

Data Used in Making AE2 Environment.

		Data Timo	Contractive	Nominal	F		
Experim ental Group	Satellite	Period	Type of Measurement	Energy Range	for Data	source of Data	Reference
State University of Iowa Frank - Van Allen	Explorer XIV 1962 BΓ1	Oct, 1962 - Aug. 1963	Omnidirectional - 213 Geiger Averaged Over Spin	>40 keV	E1	Reference	Frank, Reference 3 Frank, et al. Reference 4
			Omnidirectional - 213 Geiger Averaged Over Spin	>230 keV	E2	Reference	Frank, et al. Reference 4
			Omnidirectional - 302 Geiger	>1.6 MeV	E3	Reference	Frank, Reference 3,5 Frank, et al. Reference 4
State University of Iowa Armstrong - Van Allen	Injun III 1962 BT2	Dec. 1962 - Sept. 1963	Unidirectional, Perp. 213 Geiger	>40 keV	E4	Reference	Armstrong Reference 6
			Unidirectional, Perp. 213 Geiger	>230 keV	ES	Reference	Armstrong Reference 6
			Omnidirectional - 302 Geiger	>1.6 MeV	93	Reference	Armstrong Reference 6
Lawrence Radiat ion Laboratory West	Starad 1962 BK	Oct Dec. 1962	Unidirectional, Beta Ray Spectrometer	0,325 - 3,25 in 5 Channels	E 7	Reference	West, et al. Reference 7
Lockheed Missile and Space Company Imhof - Smith	1963 - 42	Oct Nov. 1963	Omnidirectional- Scintillator PHA Spectrometer	0,3 - 13 MeV in 32 Channels	E8	Reference	Imhof and Smith Reference 8
Applied Physics Laboratory Bostrom - Williams	1963 - 38C	Sept. 1963 - June. 1965	Unidirectional, Perp. Solid State	>1.2 MeV	E9	Graphs obtained from Bostrom - Williams and Reference	Bostrom and Williams Reference 9 Williams and Smith Reference 10
		Oct Nov. 1963	Unidirectional, Perp. Solid State	>280 keV	E10	Reference	Williams and Smith Reference 10
Aerospace - TRW Vette - Denney	TRS-II 1964 - 40C	July - Sept. 1964	Omnidirectional Solid State	>0,71 MeV	E11	Data points from Vette	Vette and Denney Reference 11
Aerospace Freden - Paulik as	P-11 1964 - 45A	Aug. 1964	Omnidirectional Solid State	>0.9 MeV	E12	Data points from Paulikas	Blake, Freden, Paulikas Private Communication
			Omnidirectional Solid State	>1,6 MeV	E13	Data points from Paulikas	Blake, Freden, Paulikas Private Communication
Aerospace Mihalov - White	F-11 1964 - 45A	Aug. 1964	Unidirectional, PHA Spectrometer	0.17 - 4.5 MeV in 10 Channels	E14	Graphs obtained from Mihalov	Mihalov and White Reference 12
University of Minnesota Pfitzer	OGO 1 1964 - 54A	Sept Oct. 1964	Unidirectional, Beta Ray Spectrometer	0.05 - 4 MeV in 5 Channels	E15	Graphs obtained from Pfitzer	Pfitzer Reference 13

AE2 ELECTRON ENERGY SPECTRUM

The data fall into two categories; (a) detailed spectral measurements at specific B,L points with spectrometers and (b) threshold detector measurements that provide good mapping of B,L space. The spectral measurements have been used to obtain a first order model spectrum which has been adjusted slightly in some cases to produce a better fit of all the data. Since the available spectrometer data are presented only at specific points, the L space is broken into the various sectors given in Table 2. The spectrum is assumed uniform within a given sector. No B variations in the various spectra are readily discernible, except from data taken at extremely low altitude.

The comparison of the various spectrometer measurements with the model spectrum are given in Figures 1 through 12. An arbitrary normalization of each set of data has been made; only the spectral shapes are studied. The E8 data were taken at low altitudes and cover the minimum mirror altitude range 200 km < h_{min} < 350 km. All the E14 data presented were taken where h_{min} > 400 km during the magnetically quiet period of August 15, 1964. The E8 data at L = 1.17 show a transient peak around 13 MeV which decayed over the period of observation (Reference 14) and is certainly not a permanent feature; with this exception the data around L = 1.2 agree. In the region L = 1.25 - 1.5 there is a distinct difference in the lower energy portion between the data taken above and below h_{min} \approx 350 km. The E15 data were taken close to the equator. A study of all the E14 data and comparison with the E15 data show no appreciable B dependence in the

Table 2

L Space Sectoring for AE2 Spectrum.

Assigned L value	Lower L limit (greater than or equal to)	Upper L limit (less than)	Assigned L value	Lower L limit (greater than or equal to)	Upper L limit (less than)
1.2	0	1.22	2.80	2.75	2.85
1.25	1.22	1.27	2.90	2.85	2.95
1.30	1.27	1.32	3.00	2.95	3.10
1.35	1.32	1.37	3.20	3.10	3.30
1.40	1.37	1.45	3.40	3.30	3.50
1.50	1.45	1.55	3.60	3.50	3.70
1.60	1.55	1.65	3.80	3.70	3.90
1.70	1.65	1.75	4.00	3.90	4.10
1.80	1.75	1.85	4.20	4.10	4.30
1.90	1.85	1.95	4.40	4.30	4.50
2.00	1.95	2.05	4.60	4.50	4.70
2.10	2.05	2.15	4.80	4.70	4.90
2.20	2.15	2.25	5.00	4.90	5.10
2.30	2.25	2.35	5.20	5.10	5.30
2.40	2.35	2.45	5.40	5.30	5.50
2.50	2.45	2.55	5.60	5.50	5.70
2.60	2.55	2.65	5.80	5.70	5.90
2.70	2.65	2.75	6.00	5.90	9.99

spectrum. The E7 data taken in late 1962 also showed little B dependence. Because the fluxes are quite low for $h_{min} \le 350$ km, no attempt has been made to build into the model a spectral change with B that begins abruptly in this low altitude regime. This region of space is characterized by fluxes and spectra which also depend on longitude (Reference 15) so a detailed representation would be quite complicated.

At L = 1.6 the data taken at all altitudes agree; however, in the region L = 1.7 - 2.8, the E14 data show a high energy tail which is not present in the E8 or E15 data. This high energy tail was even more evident in the E7 data about two years earlier, where it showed up as a peak in the 1.5 - 3 MeV range and extended out past L = 3.6. Some E7 data is given in Figures 7 through 10 for comparison, with the model spectrum chosen to be consistent with the E14 data in this region. This tail may be caused by high energy electrons injected during the nuclear detonations in 1962. If this is true, they are still evident two years later.

For L values greater than about 2.0, the electron fluxes show time variations which will be illustrated later. Spectral changes with time have been shown by Frank (Reference 3), Frank, Van Allen and Hills (Reference 4), Imhof and Smith (Reference 8) and Pfitzer (Reference 13). Representative spectra have been used for L > 2.0. The fact that selected data taken in 1962, 1963 and 1964 show reasonable agreement support the notion that these are typical. Until more data are available over extended periods of time, real time averaged spectra cannot be obtained. This, of course, would be the most useful quantity.

The model spectrum is given in Table 3 (pages 22 through 39) where the differential energy spectrum is denoted by N(E, 0.5) and the integral energy spectrum by N(*E, 0.5). These functions are normalized such that

$$\int_{0.5}^{\infty} N(E, 0.5) dE = 1.$$

The negative reciprocals of the logarithmic slopes, namely

$$EO(D) = -\frac{1}{\frac{d}{dE} \ln N(E, 0.5)} = -\frac{N(E, 0.5)}{\frac{dN}{dE} (E, 0.5)},$$

$$EO(I) = -\frac{1}{\frac{d}{dE} \ln N(*E, 0.5)} = -\frac{N(*E, 0.5)}{\frac{dN}{dE} (*E, 0.5)},$$

are given in the fourth and sixth columns, respectively. Thus, if EO(D) and EO(I) are independent of energy, an exponential spectrum is assumed. An exponential spectrum above 2.5 MeV has been assumed and has been extrapolated to 7 MeV. The extrapolations to zero energy have been done in

* similar manner and should not be interpreted as accurate values for the thermal plasma in the magnetosphere. Punched cards giving N(E, 0.5) and N(*E, 0.5) as a function of energy for the various L values are available. The card format is illustrated in Figure 13.

AE2 DISTRIBUTION FUNCTION

Since the electron spectrum is relatively independent of B, it is possible to compare directly spectral measurements taken with both directional and omnidirectional instruments. However, to compare actual flux measurements the energy and angular characteristics of the detectors must be known. The same means of comparison has been used for AE2 that were used for AE1; the details are given in Reference 1. All the directional measurements were converted to omnidirectional fluxes. The efficiency curves for the detectors which produced the E9, E11, E12, and E13 data were available. By use of the model spectrum it was possible to calculate the flux of electrons above 0.5 MeV from the true omnidirectional counting rate of each of these detectors. This is done by the formula

$$J(>0.5, B, L) = \frac{C(B, L)}{\int_0^\infty \epsilon(E) N(E, 0.5) dE} = \frac{C(B, L)}{\overline{\epsilon}}.$$

The values of $\overline{\epsilon}$ obtained for these detectors are given in Table 4. For the other measurements the nominal energy threshold has been taken as being exact and a flux above energy E was converted to the flux above 0.5 MeV by means of the formula

$$J(>0.5, B, L) = \frac{J_m(>E, B, L)}{N(*E, 0.5)}$$
.

The comparisons of the model environment with the various data are given in Figures 14 through 26. The E9 data for $L \le 1.8$ that was available was for the October 1963 and March 1964 time periods. These were decayed to August 1964 using the curves presented by Bostrom, Williams and Beall (Reference 16). These curves, which were given for B = 0.19, are shown plotted in a different way in Figure 27. They are normalized to 1 at August 1964. All of the data shown in Figures 14 through 17, except E11, are taken from smooth curves through the scatter of data points. There were only a few E11 points at each L value; these are shown without smoothing.

Because of the large time variations which are observed above L=2.0 and because of the lack of availability of high altitude data in the August 1964 time period, data have been processed from as far back as October 1962. In Figures 18 through 26 the time period of each set of data is shown and an attempt has been made to show the typical time variations. The E4, E5 and E6 data of Armstrong that are shown are his median values; the upper and lower limits represent the maximum and minimum fluxes reached during the time interval of observation. These limits are

Table 4

Detector Efficiencies for 0.5 MeV Threshold.

L		$\overline{\epsilon}$ (cm ²) fo	r Detector	
	E 9	E11	E12	E4
1.2	4.26 x 10 ⁻⁴	2.88 x 10 ⁻³	6.80 x 10 ⁻³	1.07 x 10 ⁻³
1.3	4.14	2.55	5.45	1.14
1.4	3 . 75	2.46	5.20	1.02
1.5	3.7 8	2.51	5.35	1.02
1.6	3.09	2.31	4.76	8.25×10^{-4}
1.7	1.86	1.80	3.30	4.85
1.8	1.36	1.45	2.31	3.71
1.9	1.58	1.32	2.23	4.41
2.0	1.48	1.24	1.96	4.17
2.2	1,66	1.28	2.27	4.62
2.5	1.57	1.83	3.29	3.62
2.8	1.62	2.00	3.73	3.62
3.5	2.31	2.21	4.39	5.70
4.0	2.48	2.30	4.65	6.12
4.5	1.53	2.06	3.79	3.26
5.0	1.05	1.91	3.24	1.96
6.0	4.28 x 10 ⁻⁵	1.52 x 10 ⁻⁴	2.15	5.44×10^{-5}

not shown at each B value but are used to indicate the amplitude of variation. The E1, E2, E3 and E10 data have been shown in a similar manner. However the median values were not available for this data and an estimated time average of the logarithm of the flux was used to provide the central point. The upper and lower limits represent the approximate limits the fluxes reached during the interval of observation. All of the data for $L \ge 2.0$ except E10 and E11 were converted to omnidirectional flux above 0.5 MeV using the model spectrum. These have been converted to 0.5 MeV but still represent flux perpendicular to the field line. On the basis of conversion of E5 median data to omnidirectional flux in this same region, a multiplying factor of 5 is appropriate. The horizontal lines shown on E1, E2 and E3 data give the B region over which the flux was measured.

In the region $2.0 \le L \le 3.5$ the E10 and E11 data are high compared to the others. The agreement is better as the L value increases; however, if one uses a factor of 5 to convert the data to omnidirectional fluxes, they remain high throughout the region. The model follows the E11, E12 and E13 data more closely in the $2.0 \le L \le 3.5$ range than the earlier data but at the higher L values there seem to be little differences between the 1962, 1963 or 1964 data considering the large fluctuations. To demonstrate the typical time scale of these variations at both high and low altitudes the curves taken from Frank, et al. (Reference 4) and Williams and Smith (Reference 10) are shown in Figures 28 through 31. Thus AE2 attempts to represent a typical value, median value or crude average of the logarithm of the flux in the outer zone where the values vary by \pm a factor 5 - 10 from these values in periods of several months. Many of these variations are correlated with magnetic (and therefore solar) activity (References 3 and 10).

The resulting flux map obtained by this procedure is shown in Figure 32 as the plot of log B(L, F), where F is the fixed flux value for each contour. Figure 33 shows the L region below 3.5 in the conventional B-L flux map form. The R-\(\lambda\) map is given in Figure 34 to illustrate the more intuitive presentation. Because of the crossing of many lines it is not feasible to show the F(B, L) plot. This form is presented in Table 5 (pages 40 through 56) where the flux is given at a series of B values holding L constant. An examination of this table will reveal the listing of the flux at non real (B, L) values which lie below the equator shown in Figures 32 and 33. These are just extrapolations of the map to assign values at useful points. Since this environment was read into a digital computer in the form of a grid or matrix, it is necessary to have points below the equator in order to interpolate the value of the function at or near the equator. The normal four point interpolation using the logarithm of the flux employed in various calculations is given in Reference 1. The listing shown in Table 5 (pages 40 through 56) is the actual grid fed into the computer. This grid is available on punched cards in the format shown in Figure 35.

The AE2 environment is specified by the distribution function and the spectral function. The omnidirectional flux above energy E is given by

$$J(>E, B, L) = F(B, L) N(*E, 0.5)$$
.

Plots of the AE2 flux above various energies at the equator are given in Figure 36. The spectra were not smoothed completely in the model; the points represent the actual values whereas the curves are smooth fits. All the curves for energies greater than 4 MeV are pure extrapolations and no physical significance should be attached to features of these curves such as the small peak at L = 2.0.

ORBITAL INTEGRATIONS

The flux accumulated in given satellite orbits are calculated on the computer. This was done for 29 energy bands and a large number of circular orbits. The results are presented in Table 6 (pages 57 through 72) with the flux values in units of electrons/cm²-day. The time interval between successive orbit points and the total running time are shown; however, the total accumulated fluxes are divided by the running time to obtain the average per day. The lower (E1) and upper (E2) energies for the given band are listed in the first two columns. The average accumulated fluxes above energy E1 are given in the third, fifth, seventh and ninth columns for 0°, 30°, 60° and 90° inclination orbits, respectively. The average accumulated fluxes between energies E1 and E2 are given in the remaining columns for the four inclinations.

One of the primary uses of these model environments is to estimate the radiation dose or damage a future satellite system will experience. Because of the changing character of the radiation belts with the solar cycle as well as the continuing decay of the Starfish injected electrons, it it not always easy to project a model environment into the future. However, to provide guidance in this direction the inner zone electrons have been decayed using the energy dependent decay

curves shown in Figure 27. The fluxes have been increased in the outer zone to represent the solar maximum conditions. This estimated environment is for the time period December 1968. Our present understanding is that the outer zone fluxes decrease during times of magnetic quiet. Because magnetic activity increases during solar maximum, the average fluxes are expected to be larger. However, the peak fluxes may be the same as those measured in 1962-64. This would be the case if instabilities in the outer zone due to field line loading impose limitations on the amount of trapped radiation. The orbital integrations for this case have been computed and the results presented in Table 7 (pages 73 through 88). Plots showing the comparison of the orbital fluxes above 0.5 MeV for the two time periods are given in Figures 37 through 40.

PUNCHED CARD FORMAT

Some minor modifications in the punched card format described in Reference 1 were found necessary. The header card format now uses columns 77 through 80 to give the L value as X.XX instead of using columns 76, 77 and 78 to give it as X.X, otherwise the format is identical to the previous description.

The data card format for the flux distribution function is the same as before for the first sixty columns. These columns contain all the data and in Fortran notation the format is written as 4(F6.5, 1x, E7.3, 1x). The last twenty columns of these cards are only used for bookkeeping purposes; in fact all this information can be obtained from the header cards. Starting with the AE2 environment columns 68 and 69 are used for indexing the data cards and columns 77 through 80 are used for giving the L value as X.XX. Columns 71 through 75 give the same information about the data as previously described.

The electron spectrum data card shown in Figure 13 contains data in the first seventy-two columns. In Fortran notation the format is written as 3(F5.2, 1x, E8.2, 1x, E8.2, 1x). Columns 73, 74 and 75 are used to give a three digit identification number and columns 77 through 80 to give the L value.

DISCUSSION

The AE2 environment has been carried out to L = 6.0 using the B, L coordinate system calculated from surface magnetic measurements. Starting around 5 to 6 earth radii, the data does not order well in this coordinate system. It is clear that the distorted magnetosphere must be taken into account at higher altitudes. Frank (Reference 5) has reported a diurnal variation in the > 1.6 MeV electron fluxes of a factor of 50 at the synchronous altitude. Therefore extrapolations of AE2 to higher L values should be interpreted with caution and only used for order of magnitude estimates. It is planned to make a separate map for the synchronous region in the near future using a more appropriate coordinate system.

A more detailed representation of the time variability of outer zone fluxes will be done when there is enough data available. As indicated earlier, a time averaged flux and energy spectrum

would be useful for radiation damage calculations. It is quite likely the next updated environment will contain this information.

Since no single number can describe the accuracy of the model, it is hoped that the extensive comparisons with the existing data presented in this report will serve that purpose.

REFERENCES

- 1. Vette, J. I., "Models of the Trapped Radiation Environment Volume 1 Inner Zone Electrons and Protons," NASA SP-3024, 1965.
- 2. Vette, J. I., "The Updating and Dissemination of the Knowledge of Trapped Radiation Model Environments:" Proceedings of Second Symposium on Protection Against Radiation in Space, NASA SP-71, 45-55, 1965.
- 3. Frank, L. A., "A Survey of Electrons E > 40 kev Beyond 5 Earth Radii with Explorer 14," J. Geophys. Res. 70:1593-1626, 1965.
- 4. Frank, L. A., Van Allen, J. A., and Hills, H. K., "A Study of Charged Particles in the Earth's Outer Radiation Zone with Explorer 14," J. Geophys. Res. 70:2171-2191, 1965.
- 5. Frank, L. A., "On the Local-Time Dependence of Outer Radiation Zone Electron (E > 1.6 MeV) Intensities Near the Magnetic Equator," J. Geophys. Res. 70:4131-4138, 1965.
- 6. Armstrong, T., "Morphology of the Outer Zone Electron Distribution at Low Altitudes from January through July and September 1963 from Injun 3," J. Geophys. Res. 70:2077-2110, 1965.
- West, Jr., H. I., Mann, L. G., and Bloom, S. D., "Some Electron Spectra in the Radiation Belts in the Fall of 1962," in: Space Research V: Proc. 5th Internat. Space Sci. Sympos., Florence, May 12-16, 1964, ed. by D. G. King-Hele, P. Muller, G. Righini, Amsterdam: North-Holland Pub. Co., 1965, pp. 423-445.
- 8. Imhof, W. L., and Smith, R. V., "Energy Spectrum of Electrons at Low Altitudes," J. Geophys. Res. 70:2129-2134, 1965.
- 9. Bostrom, C. O. and Williams, D. J., "Time Decay of the Artificial Radiation Belt," J. Geophys. Res. 70:240-242, 1965.
- 10. Williams, D. J., and Smith, A. M., "Daytime Trapped Electron Intensities at High Latitudes at 1100 Kilometers," J. Geophys. Res. 70:541-556, 1965.
- 11. Vette, J. I., and Denney, J. M., in Terminal Flight Report Tetrahedral Research Satellite Mark II Flight Unit No. 2, SSD-TDR-65-16, 1965.
- 12. Mihalov, J. D., and White, R. S., "Some Quiet Time Energetic Electron Spectra in the Radiation Belts," to be published in J. Geophys. Res.

- 13. Pfitzer, K. A., and Winckler, J. R., "Energy Spectra of Electrons in the Radiation Belts from 50 kev to 4 MeV," Trans. Am. Geophys. Union: 46, 124, 1965.
- 14. Imhof, W. L., and Smith, R. V., "Longitudinal Variations at Low Altitudes of High Energy Electrons in the Outer Belt," *Trans. Am. Geophys. Union:* 46, 138, 1965.
- 15. Imhof, W. L., and Smith, R. V., "Longitudinal Variations of High Energy Electrons at Low Altitudes," J. Geophys. Res. 70:569-578, 1965.
- 16. Bostrom, C. O., Williams, D. J., and Beall, D. S., "Time Decay of the Artificial Radiation Belt," *Trans. Am. Geophys. Union:* 46, 137, 1965.




Figure 1—A comparison of the AE2 spectrum at L=1.2 with satellite data. The code for the various data points is given in Table 1.




Figure 3—A comparison of the AE2 spectrum at L = 1.4 with satellite data.




Figure 2—A comparison of the AE2 spectrum at L=1.3 with satellite data.




Figure 4—A comparison of the AE2 spectrum at L=1.5 with satellite data.




Figure 5—A comparison of the AE2 spectrum at L=1.6 with satellite data.




Figure 7—A comparison of the AE2 spectrum at L=2.0 with satellite data.




Figure 6—A comparison of the AE2 spectrum at L = 1.7 with satellite data.




Figure 8—A comparison of the AE2 spectrum at L = 2.5 with satellite data.




Figure 9—A comparison of the AE2 spectrum at L=3.5 with satellite data.




Figure 11—A comparison of the AE2 spectrum at L = 5.0 with satellite data.




Figure 10—A comparison of the AE2 spectrum at L = 4.0 with satellite data.




Figure 12—A comparison of the AE2 spectrum at L = 6.0 with satellite data.

4.33E 00 2.25E 0.25 1.83E 1.39E 0.50 1.15E 1.00E E N(E.0.5)N(*E.0.5)Ε N(E, 0.5)N(E, 0.5)N(*E,0.5)Code No. L N(*E, 0.5)Ε 0 0000000000 0000000 0000000000 0000000 0.0 0000000 000 0 0 000000 0.0 333333 333333333 3333 3 333333

Figure 13—The card format for the AE2 spectrum. The values for the energy E, differential spectrum, N(E, 0.5), and the integral spectrum, N(*E, 0.5) are listed. The 805 is the AE2 code number. The L value is given in the last four columns.




Figure 14—A comparison of the AE2 flux map at L=1.2 with satellite data. The data has been converted to flux above 0.5 MeV by use of the AE2 spectrum. The code for the various points is given in Table 1.

Figure 15—A comparison of the AE2 flux map at L = 1.4 with satellite data.





Figure 16—A comparison of the AE2 flux map at L = 1.6 with satellite data.






Figure 17—A comparison of the AE2 flux map at L = 1.8 with satellite data.

Figure 18—A comparison of the AE2 flux map at L=2.0 with satellite data. The points with arrows mark the upper and lower limits of the measurements within the time period of data collection.




Figure 19—A comparison of the AE2 flux map at L=2.5 with satellite data.




Figure 21—A comparison of the AE2 flux map at L = 3.5 with satellite data.




Figure 20—A comparison of the AE2 flux map at L = 3.0 with satellite data.




Figure 22—A comparison of the AE2 flux map at L = 4.0 with satellite data.




Figure 23—A comparison of the AE2 flux map at L = 4.5 with satellite data.




Figure 25—A comparison of the AE2 flux map at L = 5.5 with satellite data.




Figure 24—A comparison of the AE2 flux map at L = 5.0 with satellite data.




Figure 26—A comparison of the AE2 flux map at L = 6.0 with satellite data.




Figure 27—The time decay of Starfish electron fluxes. The ratio of the fluxes at time t to those measured in August 1964 are shown at various L values. These curves are based on the measurements of Bostrom et. al. (Reference 16) at B=0.19 gauss.




Figure 28—Temporal variations of electron fluxes at L=2.8 near the geomagnetic equatorial plane (after Frank et. al. Reference 4).





Figure 29—Temporal variations of electron fluxes at L = 2.5 at 1100 kilometers (after Williams and Smith Reference 10).






Figure 32—The log B-L flux map of the AE2 environment. The contours are the omnidirectional flux above 0.5 MeV. The dotted contour for 1 electron/cm²-sec. represents the limit of the map at low altitudes.

Figure 30—Temporal variations of electron fluxes at L=4.8 near the geomagnetic equator (after Frank et. al. Reference 4).




Figure 31—Temporal variations of electron fluxes at L = 5.0 at 1100 kilometers (after Williams and Smith Reference 10).




Figure 33—The B-L flux map of the AE2 environment.




Figure 34—The R- λ flux map of the AE2 environment.




Figure 36—AE2 fluxes at the geomagnetic equator.

.110	.145E10	.120	.100E10	.130	. 523E 09	.140	.189E09	1	77805	1.25
В	F(B,L)	В	F(B,L)	В	F(B,L)	В	F(B,L)	Index	Code No.	L
1234567		15 16 17 18 19 20 21 2	17 23 24 25 26 77 <mark>28 29</mark> 38	9 31 32 33 34 35 3E 3	7 38 38 40 41 42 43 44 -	45 46 47 48 49 50 51 S	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	65 66 67 68 69 70	0 71 72 73 74 75 76	
	2222222						11 1111111111 222222222222222			
							3 3 3 3 3 3 3 3 3 3 3 3			
		4444444	14444444	444444	1444444	444 444	44444444444	4 4 4 4 4 4	44444	4 4 4 4
5 5 5 5 5 5 5	555 55	5555555	55555 555	5555555	55 55 55	55555555	55555 5555555	5 5 5 5 5 5	5555 5	5 5 5
6 6 6 6 6 6	6666666	6666666	6 6 6 6 6 6 6 6	6666666	6666666	6 6 6 6 6 6 6	6666666666666	6 6 6 6 6	666666	6 6 6 6
1111111	1111111	1111111	,,,,,,,,,	'7777777	1111111	,,,,,,,,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	771777	, 7777	1111
8 8 8 8 8 8	888888	8 8 8 8 8 8	8 8 8 8 8 8 8	88888	8 8 8 8 8 8	8 8 8 8 8 8	8 3 888888888	888888	888888	8 8 8
9 9 9 9 9 9 9 1 2 3 4 5 6 7 mc-sqg	9999999	9 9 9 9 9 9 9 9 9 9 15 16 17 18 19 20 21 2	9 9 9 9 9 9 9 9 9 9 2 23 24 25 26 27 20 29 30	9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	9 9 9 9 9 9 9 9 9 17 326 39 10 41 42 43 44 4	9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	9 9 9 9 9 9 65 66 67 68 69 7	9999999 371 12 13 14 15 76	9 9 9 9 9 77 75 79 80

Figure 35—The card format for the AE2 distribution function. The value of B and F(B, L) are listed for four different points. The L value is given in the last four columns.




Figure 37—Comparison of orbital integrations at 0° inclination.




Figure 38—Comparison of orbital integrations at 30° inclination.




Figure 39—Comparison of orbital integrations at 60° inclination.




Figure 40—Comparison of orbital integrations at 90° inclination.

TABLE 3
AE2 SPECTRUM

			** L=1.20 **		
NO	E	N(E,.50)	EC(D)	N(*E,.50)	E0(I)
1	0.	0.696E CO	Ç.	C.135E C1	0.181E 01
2 3	0.25 0.50	0.696E 00 0.696E 00	0. 0.	0.117E C1 C.100E C1	0.156E 01 0.131E 01
4	C.75	0.696E CC	0.	0.826E 00	0.191E 91
5	1.00	C.696E 00	c.	C.652E 00	0.806E 00
6	1.25	0.696E 00	0.322F 01	0.478E 00	0.604E 00
7	1.50	0.583E 00	0.727E 00	C.316E 00	0.513E 00
8 9	1.75 2.00	0.391E 00	0.488E 00	C.194E 00	0.498E 00
10	2.25	0.235E 00 0.143E 00	0.500E 00 0.500E 00	0.118E 00 0.712E-01	0.499E 00 0.498E 00
11	2.50	0.867E-01	0.497E 00	C.431E-01	0.497E JC
12	2.75	0.524E-01	C-497E 00	0.261E-01	0.497E 00
13	3.00	0.317E-01	0.497E 00	0.158E-01	0.497E 00
14 15	3.25 3.50	0.192F-01 0.116E-01	C.4976 00 G.497E 00	0.954E-02 0.577E-02	0.497E 00 0.497E 00
16	3.75	0.702E-02	0.497E 00	0.349E-02	0.497E 00
17	4.00	0.425E-02	0.497E 00	0.211E-02	0.497E 00
18	4.25	0.257E-02	0.497E 00	0.128E-02	0.497E 00
19	4.50	0.155E-02	0.497E 00	C.773E-03	0.497E 00
20 21	4.75 5.00	0.940E-03 0.569E-03	0.497E 00 0.497E 00	0.468E-03 0.283E-03	0.497E 00 0.497E 00
22	5.25	0.344E-03	0.497E 00	0.171E-03	0.497E 00
23	5.50	0.208E-03	0.497E 00	0.104E-03	0.497E 00
24	5.75	0.126E-03	0.497E 00	0.626E-04	0.497E 00
25 24	6.00	0.762F-04	0.497E 00	C-379E-04	0.497E 00
26 27	6 • 25 6 • 50	0.461E-04 0.279E-04	0.497E 00 -0.497E 00	0.229E-04 0.139E-04	0.497E 00 0.497E 00
28	6.75	0.169E-04	0.497E 00	0.839E-05	0.497E 00
29	7.00	0.102E-04	0.497E 00	0.507E-05	0.497E 00
NO	Ε	N(E50)	** L=1.25 ** EO(D)	N(*E50)	E0(I)
NO	E	N(E,•50)	EO(D)	N(*E,.50)	E0(I)
1	0.	0.433E 01	EO(D) 0.519E 00	0.225E 01	0.519E 00
1 2	0. 0.25	0.433E 01 0.183E 01	E0(D) 0.519E 00 0.759E 00	0.225E 01 0.139E 01	0.519E 00 0.759E 00
1	0.	0.433E 01	EO(D) 0.519E 00	0.225E 01	0.519E 00
1 2 3 4 5	0. 0.25 0.50 0.75 1.00	0.433£ 01 0.183£ 01 0.115£ 01 0.823£ 00 0.669£ 00	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00
1 2 3 4 5	0. 0.25 0.50 0.75 1.00 1.25	0.433£ 01 0.183£ 01 0.115£ 01 0.823£ 00 0.669£ 00 0.542£ 00	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00
1 2 3 4 5 6 7	0. 0.25 0.50 0.75 1.00 1.25 1.50	0.433E 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00
1 2 3 4 5	0. 0.25 0.50 0.75 1.00 1.25	0.433£ 01 0.183£ 01 0.115£ 01 0.823£ 00 0.669£ 00 0.542£ 00	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00
1 2 3 4 5 6 7 8 9	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.219E 00 0.150E 00	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00
1 2 3 4 5 6 7 8 9 10	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.219E 00 0.150E 00 0.105E 00	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.219E 00 0.150E 00 0.105E 00 0.650E-01 0.497E-01	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.219E 00 0.150E 00 0.105E 00 0.650E-01 0.497E-01 0.380E-01	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60 3.25 3.50	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.219E 00 0.150E 00 0.105E 00 0.650E-01 0.497E-01	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60 3.75	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01 0.312E-01 0.238E-01 0.182E-01	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.19E 00 0.150E 00 0.105E 00 0.105E 00 0.497E-01 0.380E-01 0.290E-01 0.222E-01 0.170E-01	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60 3.75 4.00	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01 0.312E-01 0.238E-01 0.182E-01 0.139E-01	EO(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.19E 00 0.150E 00 0.105E 00 0.650E-01 0.497E-01 0.380E-01 0.222E-01 0.170E-01 0.130E-01	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60 3.75 4.00 4.25	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01 0.312E-01 0.238E-01 0.182E-01 0.139E-01 0.107E-01	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.150E 00 0.150E 00 0.105E 00 0.650E-01 0.497E-01 0.380E-01 0.290E-01 0.222E-01 0.170E-01 0.130E-01 0.992E-02	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60 3.75 4.00	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01 0.312E-01 0.238E-01 0.182E-01 0.139E-01	EO(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.19E 00 0.150E 00 0.105E 00 0.650E-01 0.497E-01 0.380E-01 0.222E-01 0.170E-01 0.130E-01	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60 3.75 4.00 4.25 4.50 4.75 5.00	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01 0.312E-01 0.238E-01 0.182E-01 0.182E-01 0.139E-01 0.107E-01 0.815E-02 0.623E-02 0.476E-02	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.219E 00 0.150E 00 0.150E 00 0.105E 00 0.650E-01 0.497E-01 0.380E-01 0.222E-01 0.170E-01 0.130E-01 0.130E-01 0.992E-02 0.758E-02 0.580E-02 0.443E-02	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60 3.75 4.00 4.25 4.50 4.75 5.00 5.25	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01 0.312E-01 0.238E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.150E 00 0.150E 00 0.105E 00 0.650E-01 0.497E-01 0.380E-01 0.290E-01 0.170E-01 0.130E-01 0.1992E-02 0.758E-02 0.580E-02 0.443E-02 0.339E-02	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01 0.312E-01 0.312E-01 0.139E-01 0.139E-01 0.139E-01 0.139E-01 0.107E-01 0.815E-02 0.623E-02 0.476E-02 0.364E-02 0.278E-02	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.150E 00 0.150E 00 0.105E 00 0.650E-01 0.497E-01 0.380E-01 0.290E-01 0.170E-01 0.130E-01 0.1992E-02 0.758E-02 0.580E-02 0.443E-02 0.339E-02 0.259E-02	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60 3.75 4.00 4.25 4.50 4.75 5.00 5.25	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01 0.312E-01 0.238E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01 0.182E-01	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.150E 00 0.150E 00 0.105E 00 0.650E-01 0.497E-01 0.380E-01 0.290E-01 0.170E-01 0.130E-01 0.1992E-02 0.758E-02 0.580E-02 0.443E-02 0.339E-02	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.75 3.00 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00 6.25	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01 0.408E-01 0.312E-01 0.139E-01 0.139E-01 0.139E-01 0.107E-01 0.815E-02 0.623E-02 0.476E-02 0.364E-02 0.213E-02 0.213E-02 0.163E-02 0.124E-02	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.150E 00 0.150E 00 0.150E 00 0.650E-01 0.497E-01 0.380E-01 0.222E-01 0.170E-01 0.130E-01 0.92E-02 0.758E-02 0.580E-02 0.443E-02 0.39E-02 0.443E-02 0.259E-02 0.198E-02	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	0. 0.25 0.50 0.75 1.00 1.25 1.75 2.00 2.25 2.50 2.75 3.60 3.75 3.50 3.75 4.50 4.75 5.00 5.25 5.50 5.75 6.00 6.25 6.50	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01 0.312E-01 0.312E-01 0.139E-01 0.139E-01 0.107E-01 0.815E-02 0.476E-02 0.476E-02 0.278E-02 0.213E-02 0.163E-02 0.124E-02 0.950E-03	EO(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.150E 00 0.150E 00 0.650E-01 0.497E-01 0.380E-01 0.222E-01 0.170E-01 0.130E-01 0.992E-02 0.758E-02 0.580E-02 0.443E-02 0.399E-02 0.151E-02 0.16E-02 0.884E-03	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.75 3.00 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00 6.25	0.433£ 01 0.183E 01 0.115E 01 0.823E 00 0.669E 00 0.542E 00 0.426E 00 0.332E 00 0.214E 00 0.201E 00 0.698E-01 0.534E-01 0.408E-01 0.408E-01 0.312E-01 0.139E-01 0.139E-01 0.139E-01 0.107E-01 0.815E-02 0.623E-02 0.476E-02 0.364E-02 0.213E-02 0.213E-02 0.163E-02 0.124E-02	E0(D) 0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00	0.225E 01 0.139E 01 0.100E 01 0.750E 00 0.570E 00 0.425E 00 0.309E 00 0.150E 00 0.150E 00 0.150E 00 0.650E-01 0.497E-01 0.380E-01 0.222E-01 0.170E-01 0.130E-01 0.992E-02 0.758E-02 0.580E-02 0.443E-02 0.339E-02 0.151E-02 0.151E-02 0.116E-02	0.519E 00 0.759E 00 0.869E 00 0.911E 00 0.852E 00 0.784E 00 0.726E 00 0.661E 00 0.701E 00 0.521E 00 0.931E 00

NO E N(E, 3C) EC(D) N(*E, \$50) EO(1)				** L=1.30 **		
2 C.25	NO	E 	N(E,.50)	EŬ(D)	N(*E50)	E0(1)
3 0.50 0.144E 01 C.528E 0C C.100E 01 C.735F 0C 5 1.00 0.612E 0C C.574F 90 0.712E 90 0.817E 00 5 1.00 0.612E 0C C.747F 0C 0.524F C0 0.876E 00 6 1.25 0.438E 0C C.785F 0C 0.306E C0 0.919F 0C 7 1.50 0.319F 0O C.857E 0C 0.306E C0 0.919F 0C 8 1.75 0.319F 0O C.857E 0C 0.306E C0 0.955E 0D 8 1.75 0.319F 0O C.897E 0C C.231E CO 0.981F 0D 10 2.25 0.139E 0O 0.999F 0C C.139E 0O 0.999E 0C 11 2.25 0.139E 0O 0.999F 0C 0.139E 0O 0.999E 0C 12 2.75 0.865E-01 0.999E 0C 0.139E 0O 0.999E 0C 12 2.75 0.865E-01 0.999E 0C 0.108E 0O 0.999E 0C 13 3.0C 0.658E-C1 0.999E 0C 0.657E-C1 0.999E 0C 14 3.25 0.512E-01 0.999E 0C 0.657E-C1 0.999E 0C 15 3.50 0.399E-01 0.999E 0C 0.512E-01 0.999E 0C 16 3.75 0.311E-C1 0.999E 0C 0.512E-01 0.999E 0C 16 3.75 0.311E-C1 0.999E 0C 0.512E-01 0.999E 0C 16 3.75 0.311E-C1 0.999E 0C 0.52E-01 0.999E 0C 16 3.75 0.311E-C1 0.999E 0C 0.52E-01 0.999E 0C 17 4.00 0.242E-01 0.999E 0C 0.146E-01 0.999E 0C 18 4.25 0.147E-01 0.999E 0C 0.146E-01 0.999E 0C 20 4.75 0.147E-01 0.999E 0C 0.146E-01 0.999E 0C 21 5.00 0.147E-01 0.999E 0C 0.146E-01 0.999E 0C 22 5.25 0.602E-02 0.999E 0C 0.146E-01 0.999E 0C 23 5.50 0.539E-02 0.999E 0C 0.53E-02 0.999E 0C 24 5.75 0.419E-02 0.999E 0C 0.53E-02 0.999E 0C 25 6.0C 0.366E-02 0.999E 0C 0.53E-02 0.999E 0C 27 6.50 0.198E-02 0.999E 0C 0.53E-02 0.999E 0C 28 6.75 0.154E-02 0.999E 0C 0.154E-02 0.999E 0C 29 7.00 0.120E-02 0.999E 0C 0.154E-02 0.999E 0C 29 7.00 0.120E-02 0.999E 0C 0.154E-02 0.999E 0C 29 7.00 0.120E-02 0.999E 0C 0.154E-02 0.999E 0C 20 0.587E-02 0.999E 0C 0.154E-02 0.999E 0C 21 0.550C 0.156E-02 0.999E 0C 0.156E-02 0.999E 0C 22 0.255 0.254E-02 0.999E 0C 0.154E-02 0.999E 0C 23 0.500 0.167E-01 0.966E 0O 0.158E 0O 0.475E 0O 24 0.75 0.156E-02 0.999E 0C 0.156E-02 0.999E 0C 25 0.000 0.157E-02 0.999E 0C 0.156E-02 0.999E 0C 26 0.255 0.256E-02 0.999E 0C 0.156E-02 0.999E 0C 27 0.500 0.167E-01 0.966E 0O 0.158E 0O 0.0753E 0O 28 0.755 0.000 0.000 0.00000 0.0000 0						
4 C.75 O.913E CC O.574H 90 C.712E GC O.817E 00 5 1.00 C.612E 0C C.747F 0C O.524F CC O.876F 00 6 1.25 C.438E GC C.785F 0C C.394E CO C.919F 0C 7 1.50 C.319E CC C.857F 0C C.304E CO C.919F 0C 8 1.75 C.238H 0C C.897E 0C C.301E CO C.995E 00 9 2.00 C.18CE 0C C.973F 0C C.179E CC C.999E 0C 11 2.50 C.139E CO C.999F 0C C.179E CO C.999E 0C 12 2.75 C.845E-01 C.999F 0C C.139E 0O C.999E 0C 13 3.CC C.658E-C1 C.999F 0C C.10ME 0C C.999E 0C 14 3.25 C.512E-01 C.999F 0C C.512E-01 C.999E 0C 15 3.50 C.399E-01 C.999F 0C C.512E-01 C.999E 0C 16 3.75 C.319E-01 C.999F 0C C.512E-01 C.999F 0C 17 4.00 C.242E-01 C.999F 0C C.398E-C1 C.999F 0C 18 4.25 C.188E-01 C.999F 0C C.241E-01 C.999F 0C 18 4.25 C.188E-01 C.999F 0C C.241E-01 C.999F 0C 18 4.25 C.188E-01 C.999F 0C C.241E-01 C.999F 0C 19 4.50 C.176E-01 C.999F 0C C.241E-01 C.999F 0C 20 4.75 C.114E-01 C.999F 0C C.241E-01 C.999F 0C 21 5.CO C.888E-02 C.999F 0C C.146E-C1 C.999F 0C 22 5.25 C.692E-02 C.999F 0C C.88TE-02 C.999F 0C 23 5.50 C.539F-02 C.999F 0C C.88TE-02 C.999F 0C 24 5.75 C.492E-02 C.999F 0C C.891E-02 C.999F 0C 25 6.CC C.326E-02 C.999F 0C C.326E-02 C.999F 0C 27 6.50 C.158E-02 C.999F 0C C.36EE-02 C.999F 0C 28 6.75 C.154E-02 C.999F 0C C.38EE-02 C.999F 0C 29 7.00 C.126E-02 C.996F 0C C.98EE-02 C.996F 0C 29 2.00 C.98EE-01 C.966F 0C C.98EE-0						
5 1.00 C.612E OC C.747F OC 2.524F C2 0.8766 OC 7 1.50 C.438E CC C.785E OC 0.394E C2 0.0.919F OC 7 1.50 C.319F OC C.857E OC 0.304E C2 0.0.919F OC 7 1.50 C.319F OC C.857E OC 0.306E C2 0.0.955E OD 8 1.75 C.238F OC C.899F OC C.231E C2 0.0.981F O2 9 2.00 C.186E OC C.973F OC C.231E C2 0.0.981F O2 11 2.25 C.139E OC 0.799F OC C.139E OC 0.799F OC 11 2.25 C.139E OC 0.799F OC C.139E OC 0.799F OC 0.199F OC 0.799F OC 0.757F-C1 0.799F-C1 0.799F-C		_				
6 1.25						
8 1.75						
9 2.00	7	1.50	0.319E 00	0.857E 00	0.300E CO	0.955E 00
10 2.25						
11 2.50 0.1(9F 0C					_	
12						
13 3.CC						
14 3.25						
16 3.75 0.311E-C1 0.999E 00 C.310E-O1 0.999E 00 17 4.00 0.242E-G1 C.999E 00 C.241E-O1 0.999E 00 18 4.25 0.188E-O1 C.999E 00 0.188E-C1 0.999E 00 19 4.50 0.147E-O1 0.999E 00 C.146E-C1 C.999E 00 20 4.75 0.114E-O1 0.999E 00 C.146E-C1 0.999E 00 21 5.00 C.888E-O2 0.999E 00 C.887E-O2 0.999E 00 22 5.25 0.692E-O2 0.999E 00 C.887E-O2 0.999E 00 23 5.50 0.539E-O2 0.999E 00 C.691E-O2 0.999E 00 24 5.75 0.419E-O2 0.999E 00 C.538E-O2 0.999E 00 25 6.00 0.326E-O2 0.999E 00 C.326E-O2 0.999E 00 26 6.25 0.254E-O2 0.999E 00 C.326E-O2 0.999E 00 27 6.50 0.198E-C2 0.999E 00 0.254E-O2 0.999E 00 28 6.75 0.154E-O2 0.999E 00 0.254E-O2 0.999E 00 28 6.75 0.154E-O2 0.999E 00 0.154E-C2 0.999E 00 28 6.75 0.154E-O2 0.999E 00 0.154E-C2 0.999E 00 29 7.00 0.120E-O2 0.999E 00 0.154E-O2 0.999E 00 29 7.00 0.120E-O2 0.999E 00 0.154E-O2 0.999E 00 29 7.00 0.339E 00 0.330E 01 0.339E 00 20 0.999E 00 0.999E 00 0.120E-O2 0.999E 00 210 0.999E 00 0.999E 00 0.120E-O2 0.999E 00 22 0.999E 00 0.999E 00 0.120E-O2 0.999E 00 23 0.50 0.48E 01 0.547E 00 0.158E 01 0.547E 00 24 0.75 0.917E 00 0.753E 00 0.499E 01 0.573E 00 25 0.376E 00 0.978E 00 0.368E 00 0.978E 00 26 1.25 0.376E 00 0.978E 00 0.368E 00 0.978E 00 27 1.50 0.306E 00 0.978E 00 0.285E 00 0.933E 00 2 0.167E 00 0.753E 00 0.285E 00 0.933E 00 2 0.167E 00 0.755E 00 0.100E 01 0.577E 00 3 0.50 0.14E 01 0.757E 00 0.753E 00 0.368E 00 0.978E 00 4 0.75 0.917E 00 0.753E 00 0.368E 00 0.978E 00 5 1.00 0.306E 00 0.978E 00 0.358E 00 0.988E 00 0.988E 00 5 1.20 0.366E 00 0.978E 00 0.355E-01 0.966E 00 10 2.25 0.152E 00 0.877E 00 0.101E 01 0.100E 01 0.966E 00 11 2.50 0.167E 00 0.966E 00 0.772E-01 0.966E 00 12 2.75 0.799E-01 0.966E 00 0.772E-01 0.966E 00 13 3.00 0.368E-01 0.966E 00 0.772E-01 0.966E 00 14 3.25 0.167E-01 0.966E 00 0.772E-01 0.966E 00 15 3.50 0.368E-01 0.966E 00 0.775E-01 0.966E 00 22 5.25 0.600E-02 0.966E 00 0.206E-02 0.966E 00 23 5.50 0.468E-02 0.966E 00 0.206E-02 0.966E 00 24 5.75 0.388E-02 0.966E 00 0.206E-02 0.966E 00 25 6.00 0.276E-02 0.966E 00 0.206E-02 0.966E 00 26 6.25 0.213E-02 0.966E 00 0.206E-02 0.966E 00						
17	15	3.50	0.399E-01			
18				·		
19 4.50 0.147E-01 0.999E 0C C.146E-C1 0.999E 0C 20 4.75 0.114E-01 0.999F 0C C.114E-C1 0.999E 0C 21 5.00 C.888E-02 0.999E 0C C.887E-02 0.999E 0C 22 5.25 0.692E-02 0.999E 0C C.691E-02 0.999E 0C 23 5.50 0.539F-02 0.999E 0C C.691E-02 0.999E 0C 24 5.75 0.419E-02 0.999E 0C C.419E-02 0.999E 0C 25 6.00 0.326E-02 0.999E 0C C.419E-02 0.999E 0C 26 6.25 0.254E-02 0.999E 0C C.419E-02 0.999E 0C 27 6.50 0.198E-02 0.999E 0C 0.326E-02 0.999E 0C 28 6.75 0.154E-02 0.999E 0C 0.154E-02 0.999E 0C 28 6.75 0.154E-02 0.999E 0C 0.154E-02 0.999E 0C 29 7.00 0.120E-02 0.999E 0C 0.154E-02 0.999E 0C 29 7.00 0.120E-02 0.999E 0C 0.154E-02 0.999E 0C 29 7.00 0.120E-02 0.999E 0C 0.154E-02 0.999E 0C 20 0.972E 01 0.339E 00 0.330E 01 0.339E 00 20 0.972E 01 0.339E 00 0.330E 01 0.547E 00 3 0.50 0.148E 01 0.547E 00 0.150E 01 0.547E 00 4 0.75 0.917E 00 0.753E 00 0.495E 00 0.753E 00 5 1.00 0.587E 00 0.843E 00 0.495E 00 0.843E 00 6 1.25 0.376E 00 0.978E 00 0.368E 00 0.978E 00 7 1.50 0.306C 0C 0.993E 0C 0.386E 00 0.978E 00 7 1.50 0.306C 0C 0.933E 0C 0.333E 0C 0.933E 0C 8 1.75 0.217E 00 0.101E 01 0.218E 00 0.978E 01 10 2.25 0.152E 00 0.843E 00 0.495E 00 0.978E 00 12 2.00 0.167E 00 0.161E 01 0.218E 00 0.101E 01 10 2.25 0.152E 00 0.877E 00 0.133E 00 0.877E 00 11 2.50 0.104E 00 0.966E 00 0.772E-01 0.966E 00 13 3.00 0.017E-01 0.966E 00 0.772E-01 0.966E 00 14 3.25 0.476E-01 0.966E 00 0.772E-01 0.966E 00 15 3.50 0.368E-01 0.966E 00 0.274E-01 0.966E 00 16 3.75 0.284E-01 0.966E 00 0.259E-01 0.966E 00 17 4.00 0.219E-01 0.966E 00 0.216E-01 0.966E 00 20 4.75 0.101E-01 0.966E 00 0.773E-02 0.966E 00 21 5.00 0.078E-02 0.966E 00 0.775E-02 0.966E 00 22 5.25 0.600E-02 0.966E 00 0.751E-02 0.966E 00 23 5.50 0.463E-02 0.966E 00 0.751E-02 0.966E 00 24 5.75 0.127E-02 0.966E 00 0.751E-02 0.966E 00 25 6.00 0.276E-02 0.966E 00 0.266E-02 0.966E 00 26 6.25 0.213E-02 0.966E 00 0.266E-02 0.966E 00 27 6.50 0.164E-02 0.966E 00 0.266E-02 0.966E 00 28 6.75 0.127E-02 0.966E 00 0.266E-02 0.966E 00 29 6.50 0.164E-02 0.966E 00 0.266E-02 0.966E 00						
20						
21 5.00						
22 5.25						
24 5.75				0.999E 00	C.691E-02	0.999E 00
25 6.CC					-	
26 6.25						
27 6.50						
28 6.75						
NO E N(E,.50) E0(D) N(*E,.50) E0(T)						
NO E N(E,.50) EO(D) N(*E,.50) EO(I)						
1						
2						
3	NO	E		** L=1.35 **		
4 C.75 0.917E CO 0.753E OO C.690E OO 0.753E CO 5 1.CO G.587E OO 0.843E OO 0.495E OO 0.843E OO 6 1.25 C.376E CO 0.978E OO C.368E OO 0.978E OO 7 1.50 0.306E CO 0.933E OO C.285E OO 0.933E OO 8 1.75 0.217E OO 0.101E O1 0.218E OO 0.101E O1 9 2.CO 0.167E OO C.102E O1 C.170E OO 0.102E O1 10 2.25 0.152E OO C.877E OO C.133E OO 0.877E OO 11 2.50 C.104E CO 0.966E OO C.100E OO 0.966E OO 12 2.75 0.799E-C1 0.966E OO C.772E-O1 0.966E OO 12 2.75 0.799E-C1 0.966E OO C.596E-O1 0.966E OO 13 3.0C C.617E-O1 0.966E OO C.596E-O1 0.966E OO 14 3.25 0.476E-O1 0.966E OO C.355E-O1 0.966E OO 1			N(E,.50)	** L=1.35 ** E0(D) U.339E 00	N(*E,.50)	E0(I) 0.339E 00
5 1.CO	1 2	0. C.25	N(E,.50) 0.972E 01 0.289E 01	** L=1.35 ** E0(D) 0.339E 00 0.547E 00	N(*E50) 0.330E 01 0.158E 01	E0(I) 0.339E 00 0.547E 00
6 1.25	1 2 3	0. C.25 0.50	N(E,.50) 0.972E 01 0.289E 01 0.148E 01	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01	E0(I) 0.339E 00 0.547E 00 0.674E 00
7 1.50 0.306E CO 0.933E 00 0.285E 00 0.933F 00 8 1.75 0.217E 00 0.101E 01 0.218E 00 0.101E 01 9 2.00 0.167E 00 0.102E 01 0.170E 00 0.102E 01 10 2.25 0.152E 00 0.877E 00 0.133E 00 0.877E 00 11 2.50 0.104E 00 0.966E 00 0.100E 00 0.966E 00 12 2.75 0.799E-01 0.966E 00 0.772E-01 0.966E 00 13 3.00 0.617E-01 0.966E 00 0.596E-01 0.966E 00 14 3.25 0.476E-01 0.966E 00 0.460E-01 0.966E 00 15 3.50 0.368E-01 0.966E 00 0.274E-01 0.966E 00 16 3.75 0.284E-01 0.966E 00 0.274E-01 0.966E 00 17 4.00 0.219E-01 0.966E 00 0.212E-01 0.966E 00 18 4.25 0.169E-01 0.966E 00 0.163E-01 0.966E 00 20 4.75 0.101E-01 0.966E 00 0.775IE-02 0.966E 00 <	1 2 3 4	0. C.25 O.50 C.75	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00	EO(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00
9 2.00 C.167E 00 C.102E 01 C.170E 00 O.102E 01 10 2.25 O.152E 00 O.877E 00 C.133E 00 O.877E 00 11 2.50 C.104E 00 O.966E 00 G.100E 00 O.966E 00 12 2.75 O.799E-G1 O.966E 00 O.772E-O1 O.966E 00 13 3.00 C.617E-O1 O.966E 00 C.596E-O1 O.966E 00 14 3.25 C.476E-O1 O.966E 00 C.460E-O1 O.966E 00 15 3.50 O.368E-O1 O.966E 00 C.355E-O1 O.966E 00 16 3.75 O.284E-O1 C.966E 00 O.274E-O1 O.966E 00 17 4.00 O.219E-O1 C.966E 00 O.274E-O1 O.966E 00 18 4.25 O.169E-O1 C.966E 00 O.163E-O1 O.966E 00 19 4.50 O.131E-O1 O.966E 00 O.163E-O1 O.966E 00 20 4.75 O.101E-O1 O.966E 00 O.126E-C1 O.966E 00 21 5.00 O.778E-O2 O.966E 00 O.751E-O2 O.966E 00 22 5.25 O.600E-O2 C.966E 00 O.751E-O2 O.966E 00 23 5.50 O.463E-O2 O.966E 00 O.447E-O2 O.966E 00 24 5.75 C.358E-C2 O.966E 00 O.447E-O2 O.966E 00 25 6.00 O.276E-O2 C.966E 00 O.267E-O2 O.966E 00 26 6.25 C.213E-C2 O.966E 00 O.267E-O2 O.966E 00 27 6.50 O.164E-O2 C.966E 00 O.267E-O2 O.966E 00 28 6.75 C.127E-C2 O.966E 00 O.159E-O2 O.966E 00	1 2 3 4 5	0. C.25 0.50 C.75	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00	EO(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00
10 2.25 0.152E 00 C.877E 00 0.133E 00 0.877E 00 11 2.50 C.1C4E CO 0.966E 00 0.1C0E 00 0.966E 00 12 2.75 0.799E-C1 0.966E 00 0.772E-01 0.966E 00 13 3.00 C.617E-01 0.966E 00 0.596E-01 0.966E 00 14 3.25 0.476E-01 0.966E 00 0.460E-01 0.966E 00 15 3.50 0.368E-01 0.966E 00 0.355E-01 0.966E 00 16 3.75 0.284E-01 0.966E 00 0.274E-01 0.966E 00 17 4.00 0.219E-01 0.966E 00 0.212E-01 0.966E 00 18 4.25 0.169E-01 0.966E 00 0.163E-01 0.966E 00 19 4.50 0.131E-01 0.966E 00 0.163E-01 0.966E 00 20 4.75 0.101E-01 0.966E 00 0.773E-02 0.966E 00 21 5.00 0.778E-02 0.966E 00 0.751E-02 0.966E 00 22 5.25 0.600E-02 0.966E 00 0.580E-02 0.966E 00 23 5.50 0.463E-02 0.966E 00 0.447E-02 0.966E 00 24 5.75 0.358E-02 0.966E 00 0.267E-02 0.966E 00 25 6.00 0.276E-02 0.966E 00 0.267E-02 0.966E 00 26 6.25 C.213E-02 0.966E 00 0.206E-02 0.966E 00 27 6.50 0.164E-02 0.966E 00 0.159E-02 0.966E 00 28 6.75 0.127E-02 0.966E 00 0.123E-02 0.966E 00	1 2 3 4 5	C. C.25 0.50 C.75 1.CO	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00
11 2.50 C.1C4E CO 0.966E 00 0.1C0E 00 0.966E 00 12 2.75 0.799E-C1 0.966E 00 0.772E-01 0.966E 00 13 3.00 C.617E-01 0.966E 00 0.596E-01 0.966E 00 14 3.25 0.476E-01 0.966E 00 C.460E-01 0.966E 00 15 3.50 0.368E-01 0.966E 00 C.355E-01 0.966E 00 16 3.75 0.284E-01 C.966E 00 0.274E-01 0.966E 00 17 4.00 0.219E-01 C.966E 00 0.212E-01 0.966E 00 18 4.25 0.169E-01 C.966E 00 0.163E-01 0.966E 00 19 4.50 0.131E-01 0.966E 00 0.126E-C1 0.966E 00 20 4.75 0.101E-C1 0.966E 00 0.773E-02 0.966E 00 21 5.C0 0.778E-02 0.966E 00 0.751E-02 0.966E 00 22 5.25 0.600E-02 C.966E 00 0.580E-02 0.966E 00 23 5.50 0.463E-02 C.966E 00 0.447E-02 0.966E 00 24 5.75 C.358E-C2 0.966E 00 0.267E-02 0.966E 00 25 6.00 0.276E-02 C.966E 00 0.267E-02 0.966E 00 26 6.25 C.213E-C2 0.966E 00 0.267E-02 0.966E 00 27 6.5C 0.164E-02 C.966E 00 0.206E-02 0.966E 00 28 6.75 0.127E-C2 0.966E 00 0.123E-02 0.966E 00	1 2 3 4 5 6 7	C. C.25 0.50 C.75 1.C0 1.25 1.50	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.306E 00	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.285E 00 0.218E 00	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01
12 2.75 0.799E-C1 0.966E 00 0.772E-01 0.966E 00 13 3.00 C.617E-01 0.966E 00 0.596E-01 0.966E 00 14 3.25 0.476E-01 0.966E 00 C.460E-01 0.966E 00 15 3.50 0.368E-01 0.966E 00 C.355E-01 0.966E 00 16 3.75 0.284E-01 0.966E 00 0.274E-01 0.966E 00 17 4.00 0.219E-01 0.966E 00 0.212E-01 0.966E 00 18 4.25 0.169E-01 0.966E 00 0.163E-01 0.966E 00 19 4.50 0.131E-01 0.966E 00 0.126E-C1 0.966E 00 0.131E-01 0.966E 00 0.778E-02 0.966E 00 0.778E-02 0.966E 00 0.778E-02 0.966E 00 0.751E-02 0.966E 00 0.778E-02 0.966E 00 0.751E-02 0.966E 00 0.973E-02 0.966E 00 0.966E 00 0.973E-02 0.966E 00 0.	1 2 3 4 5 6 7 8	C. C.25 0.50 C.75 1.C0 1.25 1.50 1.75 2.00	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.306E C0 0.217E 00 0.167E 00	** L=1.35 **	N(*E,.50) 0.330E 01 6.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.285E 00 0.218E 00 0.170E 00	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 06 0.933E 00 0.101E 01 0.102E 01
13 3.00 C.617E-01 0.966E 00 0.596E-01 0.966E 00 14 3.25 0.476E-01 0.966E 00 C.460E-01 0.966E 00 15 3.50 0.368E-01 0.966E 00 C.355E-01 0.966E 00 16 3.75 0.284E-01 C.966E 00 0.274E-01 0.966E 00 17 4.00 0.219E-01 C.966E 00 0.212E-01 0.966E 00 18 4.25 0.169E-01 C.966E 00 0.163E-01 0.966E 00 19 4.50 0.131E-01 0.966E 00 C.126E-C1 0.966E 00 20 4.75 0.101E-01 0.966E 00 0.973E-02 0.966E 00 21 5.00 0.778E-02 0.966E 00 0.751E-02 0.966E 00 22 5.25 0.600E-02 0.966E 00 0.580E-02 0.966E 00 23 5.50 0.463E-02 0.966E 00 0.447E-02 0.966E 00 24 5.75 0.358E-02 0.966E 00 0.267E-02 0.966E 00 25 6.00 0.276E-02 0.966E 00 0.267E-02 0.966E 00	1 2 3 4 5 6 7 8 9	0. C.25 0.50 C.75 1.00 1.25 1.50 1.75 2.00 2.25	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.376E 00 0.217E 00 0.167E 00 0.152E 00	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00	N(*E,.50) 0.330E 01 6.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.285E 00 0.218E 00 0.170E 00 0.133E 60	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 06 0.933E 00 0.101E 01 0.102E 01 0.877E 00
14 3.25 0.476E-01 0.966E 00 0.460E-01 0.966E 00 15 3.50 0.368E-01 0.966E 00 0.355E-01 0.966E 00 16 3.75 0.284E-01 0.966E 00 0.274E-01 0.966E 00 17 4.00 0.219E-01 0.966E 00 0.212E-01 0.966E 00 18 4.25 0.169E-01 0.966E 00 0.163E-01 0.966E 00 19 4.50 0.131E-01 0.966E 00 0.126E-01 0.966E 00 20 4.75 0.101E-01 0.966E 00 0.973E-02 0.966E 00 21 5.00 0.778E-02 0.966E 00 0.751E-02 0.966E 00 22 5.25 0.600E-02 0.966E 00 0.447E-02 0.966E 00 23 5.50 0.463E-02 0.966E 00 0.447E-02 0.966E 00 24 5.75 0.358E-02 0.966E 00 0.267E-02 0.966E	1 2 3 4 5 6 7 8 9	0. C.25 0.50 C.75 1.C0 1.25 1.50 1.75 2.00 2.25 2.50	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.376E 00 0.217E 00 0.167E 00 0.152E 00 0.104E 00	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.285E 00 0.218E 00 0.170E 00 0.133E 00 0.100E 00	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 06 0.978E 06 0.101E 01 0.102E 01 0.877E 00 0.966E 00
15	1 2 3 4 5 6 7 8 9 10 11	0. C.25 0.50 C.75 1.00 1.25 1.75 2.00 2.25 2.50 2.75	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.376E 00 0.217E 00 0.167E 00 0.152E 00 0.799E-01	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00 0.966E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.285E 00 0.218E 00 0.170E 00 0.133E 00 0.100E 00 0.772E-01	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E C0 0.843E 00 0.978E 00 0.933F 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00
17 4.00 0.219E-01 0.966E 00 0.212E-01 0.966E 00 18 4.25 0.169E-01 0.966E 00 0.163E-01 0.966E 00 19 4.50 0.131E-01 0.966E 00 0.126E-01 0.966E 00 20 4.75 0.101E-01 0.966E 00 0.973E-02 0.966E 00 21 5.00 0.778E-02 0.966E 00 0.751E-02 0.966E 00 22 5.25 0.600E-02 0.966E 00 0.580E-02 0.966E 00 23 5.50 0.463E-02 0.966E 00 0.447E-02 0.966E 00 24 5.75 0.358E-02 0.966E 00 0.447E-02 0.966E 00 25 6.00 0.276E-02 0.966E 00 0.267E-02 0.966E 00 26 6.25 0.213E-02 0.966E 00 0.266E-02 0.966E 00 27 6.50 0.164E-02 0.966E 00 0.123E-02 0.966E	1 2 3 4 5 6 7 8 9 10 11 12	0. C.25 0.50 C.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.306E 00 0.217E 00 0.167E 00 0.152E 00 0.104E 00 0.799E-01 0.617E-01	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00 0.966E 00 0.966E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.285E 00 0.218E 00 0.170E 00 0.133E 00 0.100E 00 0.772E-01 0.596E-01	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 06 0.933F 06 0.101E 01 0.102E 01 0.877E 00 0.966E 00 0.966E 00
18 4.25 0.169E-01 C.966E 00 0.163E-01 0.966E 00 19 4.50 0.131E-01 0.966E 00 0.126E-01 0.966E 00 20 4.75 0.101E-01 0.966E 00 0.973E-02 0.966E 00 21 5.00 0.778E-02 0.966E 00 0.751E-02 0.966E 00 22 5.25 0.600E-02 0.966E 00 0.580E-02 0.966E 00 23 5.50 0.463E-02 0.966E 00 0.447E-02 0.966E 00 24 5.75 0.358E-02 0.966E 00 0.345E-02 0.966E 00 25 6.00 0.276E-02 0.966E 00 0.267E-02 0.966E 00 26 6.25 0.213E-02 0.966E 00 0.266E-02 0.966E 00 27 6.50 0.164E-02 0.966E 00 0.159E-02 0.966E 00 28 6.75 0.127E-02 0.966E 00 0.123E-02 0.966E 00	1 2 3 4 5 6 7 8 9 10 11 12 13	0. C.25 0.50 C.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.306E 00 0.217E 00 0.167E 00 0.152E 00 0.152E 00 0.104E 00 0.799E-01 0.617E-01	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00 0.966E 00 0.966E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.285E 00 0.218E 00 0.170E 00 0.133E 00 0.120E 00 0.772E-01 0.596E-01 0.460E-01	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00 0.966E 00 0.966E 00
19 4.50 0.131E-01 0.966E 00 0.126E-C1 0.966E 00 20 4.75 0.101E-C1 0.966E 00 0.973E-02 0.966E 00 21 5.00 0.778E-02 0.966E 00 0.751E-02 0.966E 00 22 5.25 0.600E-02 0.966E 00 0.580E-02 0.966E 00 23 5.50 0.463E-02 0.966E 00 0.447E-02 0.966E 00 24 5.75 0.358E-02 0.966E 00 0.345E-02 0.966E 00 25 6.00 0.276E-02 0.966E 00 0.267E-02 0.966E 00 26 6.25 0.213E-02 0.966E 00 0.206E-02 0.966E 00 27 6.50 0.164E-02 0.966E 00 0.159E-02 0.966E 00 28 6.75 0.127E-02 0.966E 00 0.123E-02 0.966E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14	0. C.25 0.50 C.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.306E 00 0.217E 00 0.167E 00 0.152E 00 0.152E 00 0.199E-01 0.617E-01 0.476E-01 0.368E-01	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00 0.966E 00 0.966E 00 0.966E 00 0.966E 00	N(*E50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.285E 00 0.218E 00 0.170E 00 0.133E 00 0.100E 00 0.772E-01 0.596E-01 0.460E-01 0.355E-01 0.274E-01	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00 0.966E 00 0.966E 00 0.966E 00
20 4.75 0.101E-C1 0.966E 00 0.973E-O2 0.966E 00 21 5.00 0.778E-O2 0.966E 00 0.751E-O2 0.966E 00 22 5.25 0.600E-O2 0.966E 00 0.580E-O2 0.966E 00 23 5.50 0.463E-O2 0.966E 00 0.447E-O2 0.966E 00 24 5.75 0.358E-C2 0.966E 00 0.345E-O2 0.966E 00 25 6.00 0.276E-O2 0.966E 00 0.267E-O2 0.966E 00 26 6.25 0.213E-C2 0.966E 00 0.206E-O2 0.966E 00 27 6.50 0.164E-O2 0.966E 00 0.159E-G2 0.966E 00 28 6.75 0.127E-C2 0.966E 00 0.123E-O2 0.966E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16	0. C.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	N(E,.50) 0.972F 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.306E 00 0.17E 00 0.152E 00 0.152E 00 0.152E 00 0.152E 00 0.152E 01 0.476E-01 0.476E-01 0.368E-01 0.284E-01 0.219E-01	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.285E 00 0.218E 00 0.170E 00 0.133E 00 0.100E 00 0.772E-01 0.596E-01 0.460E-01 0.355E-01 0.274E-01 0.212E-01	EO(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933F 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00 0.966E 00 0.966E 00 0.966E 00 0.966E 00
21 5.C0 0.778E-02 0.966E 00 0.751E-02 0.966E 00 22 5.25 0.6C0E-02 C.966E 00 0.580E-02 0.966E 00 23 5.50 0.463E-02 0.966E 00 0.447E-02 0.966E 00 24 5.75 0.358E-02 0.966E 00 0.345E-02 0.966E 00 25 6.00 0.276E-02 0.966E 00 0.267E-02 0.966E 00 26 6.25 0.213E-02 0.966E 00 0.206E-02 0.966E 00 27 6.50 0.164E-02 0.966E 00 0.159E-02 0.966E 00 28 6.75 0.127E-02 0.966E 00 0.123E-02 0.966E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. C.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.306E 00 0.217E 00 0.167E 00 0.152E 00 0.164E 00 0.799E-01 0.476E-01 0.368E-01 0.284E-01 0.219E-01	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00	N(*E,.50) 0.330E 01 6.158E 01 0.100E 01 0.690E 00 0.495E 00 0.285E 00 0.218E 00 0.170E 00 0.133E 00 6.100E 00 0.772E-01 0.596E-01 0.460E-01 0.274E-01 0.212E-01 0.163E-01	EO(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00 0.966E 00 0.966E 00 0.966E 00 0.966E 00 0.966E 00
22 5.25 0.6C0E-02 C.966E CO C.580E-02 0.966E CO 23 5.50 0.463E-02 C.966E CO 0.447E-02 0.966E CO 24 5.75 C.358E-C2 0.966E CO C.345E-02 0.966E CO 25 6.00 0.276E-02 C.966E CO 0.267E-02 0.966E CO 26 6.25 C.213E-C2 0.966E CO 0.206E-02 0.966E CO 27 6.5C 0.164E-02 C.966E CO 0.159E-C2 0.966E CO 28 6.75 C.127E-C2 0.966E CO 0.123E-02 0.966E CO	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. C.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.376E 00 0.167E 00 0.152E 00 0.152E 00 0.152E 00 0.167E-01 0.476E-01 0.368E-01 0.219E-01 0.169E-01 0.131E-01	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.285E 00 0.218E 00 0.170E 00 0.133E 00 0.100E 00 0.772E-01 0.596E-01 0.460E-01 0.355E-01 0.274E-01 0.212E-01 0.163E-01 0.166E-01	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933F 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00
23 5.50 0.463E-02 0.966E 00 0.447E-02 0.966E 00 24 5.75 0.358E-02 0.966E 00 0.345E-02 0.966E 00 25 6.00 0.276E-02 0.966E 00 0.267E-02 0.966E 00 26 6.25 0.213E-02 0.966E 00 0.206E-02 0.966E 00 27 6.50 0.164E-02 0.966E 00 0.159E-02 0.966E 00 28 6.75 0.127E-02 0.966E 00 0.123E-02 0.966E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	0. C.25 0.50 C.75 1.00 1.25 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.376E 00 0.167E 00 0.152E 00 0.152E 00 0.164E 00 0.799E-01 0.476E-01 0.368E-01 0.284E-01 0.219E-01 0.169E-01 0.131E-01 0.101E-01	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.978E 00 0.978E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.285E 00 0.218E 00 0.170E 00 0.133E 00 0.100E 00 0.772E-01 0.596E-01 0.460E-01 0.355E-01 0.274E-01 0.212E-01 0.163E-01 0.166E-01	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.978E 06 0.978E 06 0.933F 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00
25 6.00 0.276E-02 C.966E 0C 0.267E-02 0.966E 00 26 6.25 C.213E-C2 0.966E 0C 0.206E-02 0.966E 0C 27 6.5C 0.164E-02 C.966E 0C 0.159E-G2 0.966E 0C 28 6.75 C.127E-C2 0.966E 0C 0.123E-02 0.966E CO	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	0. C.25 0.50 C.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.50 4.50 4.75 5.00	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.376E 00 0.17E 00 0.152E 00 0.152E 00 0.152E 00 0.152E 01 0.476E-01 0.476E-01 0.284E-01 0.284E-01 0.219E-01 0.131E-01 0.101E-01 0.778E-02	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.218E 00 0.170E 00 0.133E 00 0.172E-01 0.596E-01 0.460E-01 0.355E-01 0.274E-01 0.274E-01 0.212E-01 0.163E-01 0.163E-01 0.163E-01 0.165E-01 0.973E-02	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 06 0.933F 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00
26 6.25 C.213E-C2 C.966E 00 0.206E-02 0.966E 00 27 6.5C 0.164E-02 C.966E 00 0.159E-G2 0.966E 00 28 6.75 C.127E-C2 0.966E 0C 0.123E-02 0.966E CO	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. C.25 0.50 C.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.75 4.00 4.25 4.50 4.75 5.00 5.25	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.376E 00 0.17E 00 0.152E 00 0.152E 00 0.152E 00 0.164E 00 0.799E-01 0.617E-01 0.476E-01 0.284E-01 0.219E-01 0.169E-01 0.169E-01 0.101E-01 0.778E-02 0.600E-02 0.463E-02	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.285E 00 0.218E 00 0.170E 00 0.133E 00 0.100E 00 0.772E-01 0.596E-01 0.460E-01 0.274E-01 0.274E-01 0.212E-01 0.163E-01 0.126E-01 0.163E-01 0.126E-01 0.164E-01 0.126E-01 0.164E-01 0.126E-01 0.164E-01 0.164E-01 0.164E-01 0.164E-01	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00
27 6.5C 0.164E-C2 C.966E 00 0.159E-C2 0.966E 00 28 6.75 C.127E-C2 0.966E 0C 0.123E-O2 0.966E CO	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	0. C.25 0.50 C.75 1.00 1.25 1.50 1.75 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.00 5.75	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.376E 00 0.17E 00 0.167E 00 0.152E 00 0.152E 00 0.164E 00 0.799E-01 0.617E-01 0.476E-01 0.284E-01 0.284E-01 0.219E-01 0.169E-01 0.169E-01 0.131E-01 0.178E-02 0.600E-02 0.463E-02 0.463E-02	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00	N(*E,.50) 0.330E 01 0.158E 01 0.100E 01 0.690E 00 0.495E 00 0.368E 00 0.285E 00 0.218E 00 0.170E 00 0.172E-01 0.596E-01 0.460E-01 0.274E-01 0.212E-01 0.163E-01 0.126E-01 0.163E-01 0.163E-01 0.164E-01 0.165E-01	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 06 0.933F 06 0.101E 01 0.102E 01 0.877E 00 0.966E 00
28 6.75 C.127E-C2 0.966E 0C C.123E-O2 0.966E CO	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25	0. C.25 0.50 C.75 1.00 1.25 1.50 1.75 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.50 5.50 5.75 6.00	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.306E C0 0.217E 00 0.152E 00 0.152E 00 0.152E 00 0.164E 00 0.799E-01 0.617E-01 0.476E-01 0.284E-01 0.219E-01 0.169E-01 0.169E-01 0.169E-01 0.178E-02 0.600E-02 0.463E-02 0.276E-02	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00	N(*E,.50)	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E C0 0.843E 00 0.978E 0C 0.933F 0C 0.101E 01 0.102E 01 0.877E 00 0.966E 00
	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. C.25 0.50 C.75 1.00 1.25 1.50 1.75 2.00 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.75 5.00 5.75 6.00 6.25	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.376E 00 0.306E 00 0.217E 00 0.152E 00 0.152E 00 0.152E 00 0.164E 00 0.799E-01 0.617E-01 0.476E-01 0.368E+01 0.284E-01 0.219E-01 0.169E-01 0.131E-01 0.101E-01 0.778E-02 0.600E-02 0.463E-02 0.463E-02 0.276E-02 0.213E-02	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00	N(*E*.50)	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E C0 0.843E 00 0.978E 00 0.933F 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00
29 7.00 0.980E-03 0.966E 00 0.946E-03 0.966E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	0. C.25 0.50 C.75 1.00 1.25 1.50 2.50 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.75 6.00 6.25 6.50	N(E,.50) 0.972E 01 0.289E 01 0.148E 01 0.917E 00 0.587E 00 0.306E 00 0.217E 00 0.167E 00 0.152E 00 0.164E 00 0.799E-01 0.617E-01 0.476E-01 0.284E-01 0.219E-01 0.169E-01 0.131E-01 0.101E-01 0.778E-02 0.600E-02 0.463E-02 0.276E-02 0.213E-02 0.164E-02	** L=1.35 ** E0(D) 0.339E 00 0.547E 00 0.674E 00 0.753E 00 0.843E 00 0.978E 00 0.933E 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00	N(*E,.50)	E0(I) 0.339E 00 0.547E 00 0.674E 00 0.753E C0 0.843E 00 0.978E 00 0.933F 00 0.101E 01 0.102E 01 0.877E 00 0.966E 00

NO	E	N(E,.50)	** L=1.40 ** E0(D)	N(#E,.50)	E0(I)
1 2	3. 0.25	0.133E 62 0.381E 01	0.191E 00 0.250E 00	0.349E 01 0.163E 01	0.329E 00 0.512E 00
3	0.50	0.167E 01	0.417E 00	0.100E 01	0.656E 00
4 5	0.75 1.00	0.959E 00 0.616E 00	0.532E 00	0.683E 00	0.756E 00
6	1.25	9.422E 00	0.659E 00 0.785E 00	0.491E 00 0.363E 00	0.826E 00 0.874E 00
7	1.50	0.307E 00	0.802E 00	0.2728 00	0.904E 00
8 9	1.75 2.00	0.224E 00 0.171E 00	0.921E 00 0.911E 00	0.207E 00	0.921E 00 0.922E 00
ıć	2.25	0.130E 00	0.930E 00	0.157E 00 0.120E 00	0.923E 00
11	2.50	0.994E-01	0.922E 00	0.916E-01	0.9228 00
12 13	2.75 3.00	0.758E-01 0.578E-01	0.922E 00 0.922E 00	0.698E-01 0.532E-01	0.922E 00 0.922E 00
14	3.25	0.440E-01	0.922F 00	0.406E-01	0.922E 00
15	3.50	0.336E-01	0.922+ 00	0.309E-01	0.922E 00
16 17	3.75 4.00	0.256E-01 0.195E-01	0.922E 00 0.922E 00	0.236E-01 0.180E-01	0.922E 00 0.922E 00
18	4.25	0.149E-01	0.9228 00	0.137E-01	0.922E 00
19	4.50 4.75	0.1136-01	0.922E 00	0.105E-01	0.922E 00
20 21	5.00	0.865E-02 0.659E-02	0.922F 00 0.922E 00	0.797E-02 0.608E-02	0.922E 00 0.922E 00
22	5.25	0.503E-02	0.922E 00	0.463E-02	0.922E 00
23 24	5.50 5.75	0.383F-02	0.922E 00	0.353E-02	0.922E 00
25	6.00	0.292E-02 0.223E-02	0.922E 00 0.922E 00	0.269E-02 0.205E-02	0.922E 00 0.922E 00
26	6.25	0.170E-02	0.922E 00	0.157E-02	0.922E 00
2 7 28	6.50 6.75	0.129E-02 0.987E-03	0.922E 00 0.922E 00	0.119E-02	0.922E 00
29	7.00	0.753E-03	0.922E 00	0.910E-03 0.694E-03	0.922E 00 0.922E 00

***			** L=1.50 **		
NO	E	N(E,.50)		N(#E,.50)	E0(I)
1	0.	N(E,.50)	** L=1.50 ** E0(D) 0.193E 00	N(*E,.50)	E0(1)
1 2	0 • 0 • 25	N(E,.50) 0.141E 02 0.401E 01	** L=1.50 ** E0(D) 0.193E 00 0.226E 00	N(*E,.50) 0.362E C1 0.164E C1	E0(1) 0.315E 00 0.507E 00
1 2 3 4	0. 0.25 0.50 0.75	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00	** L=1.50 ** E0(D) 0.193E 00	N(*E,.50)	E0(1)
1 2 3 4 5	0. 0.25 0.50 0.75 1.00	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00	N(*E,.50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00	E0(1) 0.315E 00 0.507E 00 0.694E 00 0.798E 00 0.822E 00
1 2 3 4	0. 0.25 0.50 0.75 1.00 1.25	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.808E 00	N(*E,.50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 C.376E 00	E0(1) 0.315E 00 0.507E 00 0.694E 00 0.798E 00 0.822E 00 0.822F 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00	N(*E,.50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00	E0(1) 0.315E 00 0.507E 00 0.694E 00 0.798E 00 0.822E 00 0.822E 00 0.824E 00 0.825E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.183E 00	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.808E 00 0.830E 00 0.810E 00 0.827E 00	N(*E50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 0.376E 00 0.277E 00 C.205E C0 0.151E 00	E0(1) 0.315E 00 0.507E 00 0.694E 00 0.798E 00 0.822E 00 0.822E 00 0.824E 00 0.825E 00 0.827E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.808E 00 0.830E 00 0.810E 00	N(*E,.50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 0.376E 00 0.277E 00 C.205E C0	E0(1) 0.315E 00 0.507E 00 0.694E 00 0.798E 00 0.822E 00 0.822E 00 0.824E 00 0.825E 00
1 2 3 4 5 6 7 8 9 10	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.183E 00 0.135E 00	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.808E 00 0.808E 00 0.810E 00 0.827E 00 0.827F 00	N(*E50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 C.376E 00 0.277E 00 C.205E C0 0.151E 00 0.112E 00	E0(1) 0.315E 00 0.507E 00 0.694E 00 0.798E 00 0.822E 00 0.822E 00 0.824E 00 0.825E 00 0.827E 00
1 2 3 4 5 6 7 8 9 10 11 12	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.183E 00 0.185E 00 0.999E-01 0.739E-01 0.546E-01	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.808E 00 0.830E 00 0.810E 00 0.827E 00 0.827E 00 0.827E 00 0.827E 00 0.827E 00	N(*E,.50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 0.277E 00 C.205E 00 0.151E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01	E0(1) 0.315E 00 0.507E 00 0.694E 00 0.798E 00 0.822E 00 0.822E 00 0.825E 00 0.827E 00 0.827E 00 0.827E 00 0.827E 00 0.827E 00
1 2 3 4 5 6 7 8 9 10	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 60 0.183E 00 0.135E 00 0.999E-01 0.739E-01	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.808E 00 0.810E 00 0.827E 00 0.827E 00 0.827E 00 0.827E 00 0.827E 00 0.827E 00	N(*E,.50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 0.277E 00 C.205E C0 0.151E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01 C.334E-01	E0(1) 0.315E 00 0.507E 00 0.694E 00 0.798E 00 0.822E 00 0.822E 00 0.825E 00 0.827E 00 0.827E 00 0.827E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.183E 00 0.135E 00 0.999E-01 0.739E-01 0.546E-01 0.404E-01 0.298E-01	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.820E 00 0.810E 00 0.827E 00	N(*E,.5C) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 C.376E 00 0.277E 00 C.205E C0 0.151E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01 0.334E-01 0.247E-01 0.182E-01	E0(1)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.183E 00 0.135E 00 0.999E-01 0.739E-01 0.546E-01 0.4C4E-01 0.298E-01 0.220E-01 0.163E-01	** L=1.50 ** E0(D) 0.193E 0C 0.226E 00 0.398E 00 0.531E 0C 0.832E 00 0.808E 00 0.810E 00 0.827E 00	N(*E5C) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 C.376E 00 0.277E 00 C.205E C0 0.151E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01 0.334E-01 0.247E-01 0.182E-01 0.135E-01	E0(1)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.183E 00 0.135E 00 0.999E-01 0.739E-01 0.546E-01 0.404E-01 0.298E-01	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.820E 00 0.810E 00 0.827E 00	N(*E,.5C) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 C.376E 00 0.277E 00 C.205E C0 0.151E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01 0.334E-01 0.247E-01 0.182E-01	E0(1)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.50 2.75 2.00 2.25 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.459E 00 0.459E 00 0.336E 00 0.249E 60 0.183E 00 0.135E 00 0.999E-01 0.739E-01 0.739E-01 0.249E-01 0.220E-01 0.163E-01 0.120E-01 0.891E-02 0.658E-02	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.826E 00 0.827E 00	N(*E50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 0.277E 00 C.205E C0 0.151E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01 0.334E-01 0.247E-01 0.135E-01 0.135E-01 0.997E-02 0.737E-02 0.545E-02	E0(1) 0.315E 00 0.507E 00 0.694E 00 0.798E 00 0.822E 00 0.824E 00 0.825E 00 0.827E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.135E 00 0.999E-01 0.739E-01 0.546E-01 0.404E-01 0.298E-01 0.20E-01 0.120E-01 0.891E-02 0.658E-02 0.487E-02	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.820E 00 0.827E 00	N(*E,.50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 0.277E 00 C.205E C0 0.151E 00 0.112E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01 0.334E-01 0.247E-01 0.135E-01 0.135E-01 0.997E-02 0.737E-02 0.545E-02 0.403E-02	E0(1) 0.315E 00 0.507E 00 0.694E 00 0.798E 00 0.822E 00 0.822E 00 0.825E 00 0.827E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.135E 00 0.999E-01 0.739E-01 0.546E-01 0.404E-01 0.298E-01 0.120E-01 0.163E-01 0.120E-01 0.891E-02 0.487E-02 0.360E-02	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.826E 00 0.827E 00	N(*E50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 0.277E 00 C.205E C0 0.151E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01 0.334E-01 0.247E-01 0.135E-01 0.135E-01 0.997E-02 0.737E-02 0.545E-02	E0(1) 0.315E 00 0.507E 00 0.694E 00 0.798E 00 0.822E 00 0.822E 00 0.825E 00 0.827E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.025 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.75 5.00 5.25 5.75	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.135E 00 0.135E 00 0.999E-01 0.739E-01 0.546E-01 0.4C4E-01 0.298E-01 0.20E-01 0.163E-01 0.120E-01 0.163E-02 0.487E-02 0.360E-02 0.266E-02 0.197E-02	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.826E 00 0.827E 00	N(*E,.50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 0.277E 00 C.205E G0 0.151E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01 0.334E-01 0.247E-01 0.135E-01 0.135E-01 0.997E-02 0.737E-02 0.737E-02 0.545E-02 0.403E-02 0.298E-02 0.20E-02 0.163E-02	E0(1)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.135E 00 0.999E-01 0.739E-01 0.546E-01 0.404E-01 0.298E-01 0.120E-01 0.163E-01 0.120E-01 0.891E-02 0.487E-02 0.360E-02	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.830E 00 0.810E 00 0.827E 00	N(*E,.50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 0.277E 00 C.205E C0 0.151E 00 0.112E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01 0.334E-01 0.247E-01 0.135E-01 0.135E-01 0.997E-02 0.737E-02 0.545E-02 0.403E-02 0.20E-02 0.163E-02 0.120E-02	E0(1)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.025 2.75 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 6.00 6.25 6.50	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.135E 00 0.135E 00 0.739E-01 0.739E-01 0.546E-01 0.4C4E-01 0.298E-01 0.220E-01 0.163E-01 0.120E-01 0.891E-02 0.658E-02 0.487E-02 0.197E-02 0.145E-02 0.197E-02 0.145E-02 0.794E-03	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.830E 00 0.810E 00 0.827E 00	N(*E,.50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 0.277E 00 C.205E G0 0.151E 00 0.112E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01 0.34E-01 0.247E-01 0.185E-01 0.135E-01 0.997E-02 0.737E-02 0.545E-02 0.403E-02 0.298E-02 C.20E-02 0.889E-03 0.657E-03	E0(1)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.025 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.00 6.25	N(E,.50) 0.141E 02 0.401E 01 0.161E 01 0.916E 00 0.619E 00 0.459E 00 0.336E 00 0.249E 00 0.135E 00 0.135E 00 0.739E-01 0.739E-01 0.546E-01 0.4C4E-01 0.298E-01 0.120E-01 0.120E-01 0.891E-02 0.658E-02 0.487E-02 0.145E-02 0.145E-02 0.145E-02 0.145E-02	** L=1.50 ** E0(D) 0.193E 00 0.226E 00 0.398E 00 0.531E 00 0.832E 00 0.832E 00 0.810E 00 0.827E 00	N(*E,.50) 0.362E C1 0.164E C1 0.100E 01 C.697E 00 0.510E 00 0.277E 00 C.205E G0 0.151E 00 0.112E 00 0.112E 00 0.827E-01 0.611E-01 0.452E-01 0.34E-01 0.247E-01 0.135E-01 0.997E-02 0.737E-02 0.545E-02 0.403E-02 0.298E-02 0.120E-02 0.889E-03	E0(1)

			** L=1.60 **		
NO	E	N(E,.50)	E3(D)	N(+E,.50)	EC(I)
1	0.	0.254E 02	0.183E-00	0.542E 01	0.246E 00
2	C.25	C.647E 01	C.21CE 00	0.196E C1	0.372E 00
3	0.50	0.216E 01	0.275E 00	0.100E 01	0.543E 00
4 5	0.75 1.00	0.100E 01 0.600E 00	0.437E 00 0.657E 00	0.631E 00 0.438E 00	0.683E CO 0.744E OO
6	1.25	0.412E 00	0.743E 00	0.313E 00	0.762E 00
7	1.50	0.294E 00	0.768E 00	0.225E 00	0.765E 90
8	1.75	0.213E 00	0.768E 00	0.163E 00	0.764E 00
9	2.00	0.154E 00	0.764E 00	0.117E 00	0.764E 00
10	2.25	0.111E 0C	0.764E 00	0.845E-01	0.764E 00
11	2.50	0.798E-01	0.764E 00	0.609E-01	0.764E 00
12 13	2.75 3.00	0.575E-01 0.414E-01	0.764E 00 0.764E 00	0.439E-01 0.316E-01	0.764E 00 0.764E 00
14	3.25	0.299E-01	0.764E 00	0.228E-01	0.764E 00
15	3.50	0.215E-01	0.764E 00	0.164E-01	0.764E 00
16	3.75	0.155E-01	0.764E 00	C.119E-01	0.764E 30
17	4.00	G.112E-01	0.764E 00	0.854E-02	0.764E 00
18	4.25	0.806E-02	0.764E 00	0.616E-02	0.764E 00
19	4.50	0.581E-02	0.764E 00	0.444E-02	0.764E 00
20 21	4.75 5.00	0.419E-02 0.302E-02	0.764E 00 0.764E 00	0.320E-02 0.231E-02	0.764E 00 0.764E 00
22	5.25	G.218E-02	0.764E 00	6.166E-32	0.764E 00
23	5.50	J.157E-J2	0.764E 00	0.120E-02	0.764E 00
24	5.75	0.113E-02	0.764E 00	C.863E-03	0.764E 00
25	6.00	0.815E-03	0.764E 00	0.622E-03	0.764E 00
26	6.25	0.588E-03	0.764E 00	0.449E-03	0.764E 00
27 28	6.50 6.75	0.423E-03 0.305E-03	0.764E 00 0.764E 00	0.323E-03 0.233E-03	0.764E 00 0.764E 00
29	7.90	0.220E-03	0.764E 00	0.1685-03	0.764E 00
NO	E	N(E,.50)	** L=1.70 ** E0(D)	N(*E,.5G)	E0(I)
			** L=1.70 **		
NO1 2	e 0. 0.25	N(E,.50)	** L=1.70 ** E0(D) 0.222E 00 0.262E 00	N(*E50) 0.800E 01 0.260E 01	E0(I) 0.222E 00 0.262E 00
NO1 2 3	6. C.25 C.50	N(E50) 0.36CE 02 0.994E 01 0.304E 01	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01	E0(I) 0.222E 00 0.262E 00 0.329E 00
NO 1 2 3 4	0. 0.25 0.50 0.75	N(E,.50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00
NO	0. C.25 C.50 C.75 1.00	N(E,.50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0
NO	0. 0.25 0.50 0.75 1.00 1.25	N(E,.50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.263E 00	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E 00 0.717E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00 0.188E 00	0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C
NO	0. C.25 C.50 C.75 1.00	N(E,.50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.263E 00 0.177E 00	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E 00 0.717E 00 0.752E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0
NO	C. C.25 C.50 C.75 1.CO 1.25 1.50	N(E,.50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.263E 00	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E 00 0.717E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00
NO	C. C.25 C.50 C.75 1.C0 1.25 1.50 1.75 2.00 2.25	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.263E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E 00 0.717E 00 0.752E 00 0.760E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.687E-01 0.495E-01	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.760E 00 0.764E 00 0.764E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.263E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-01	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E 00 0.717E 00 0.752E 00 0.760E 00 0.764E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.687E-01 0.495E-01 0.357E-01	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E 00 0.7152E 00 0.752E 00 0.760E 00 0.764E 00 0.764E 00 0.764E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.263E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E 00 0.717E 00 0.752E 00 0.760E 00 0.764E 00 0.764E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.687E-01 0.495E-01 0.257E-01	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.760E 00 0.764E 00 0.764E 00 0.764E 00 0.764E 00
NO	C. C.25 C.50 C.75 1.C0 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.717E 00 0.752E 00 0.760E 00 0.764E 00 0.764E 00 0.764E 00 0.764E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E G1 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.687E-01 0.495E-01 0.257E-01 0.185E-01	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.760E 00 0.764E 00 0.764E 00 0.764E 00 0.764E 00 0.764E 00
NO	C. C.25 C.50 C.75 1.CO 1.25 1.50 1.75 2.90 2.25 2.50 2.75 3.00 3.25	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01 0.175E-01	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.717E 00 0.752E 00 0.760E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.687E-01 0.495E-01 0.257E-01 0.185E-01 0.134E-01	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.760E 00 0.764E 00 0.764E 00 0.764E 00 0.764E 00 0.764E 00
NO	C. C.25 C.50 C.75 1.C0 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.717E 00 0.752E 00 0.760E 00 0.764E 00 0.764E 00 0.764E 00 0.764E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E G1 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.687E-01 0.495E-01 0.257E-01 0.185E-01	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.760E 00 0.764E 00 0.764E 00 0.764E 00 0.764E 00 0.764E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01 0.175E-01 0.126E-01	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.717E 00 0.752E 00 0.766E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.495E-01 0.357E-01 0.257E-01 0.134E-01 0.964E-02	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.764E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01 0.175E-01 0.126E-01	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.717E 00 0.752E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.495E-01 0.357E-01 0.257E-01 0.134E-01 0.134E-01 0.964E-02 0.695E-02 0.501E-02 0.361E-02	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.764E 00
NO	C. C.25 C.50 C.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-01 0.243E-01 0.243E-01 0.175E-01 0.126E-01 0.910E-02 0.656E-02 0.473E-02	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.494E 00 0.622E 00 0.717E 00 0.762E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.495E-01 0.357E-01 0.257E-01 0.134E-01 0.134E-01 0.964E-02 0.695E-02 0.501E-02 0.361E-02 0.260E-02	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.764E 00
NO	C. C.25 C.50 C.75 1.C0 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.125E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01 0.175E-01 0.126E-01 0.910E-02 0.656E-02 0.473E-02 0.341E-02 0.246E-02	** L=1.70 ** E0(D) C.222E 00 C.262E 00 C.329E 00 C.494E 00 C.622E 00 C.717E 00 C.752E 00 C.764E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.495E-01 0.357E-01 0.257E-01 0.134E-01 0.134E-01 0.964E-02 0.695E-02 0.501E-02 0.361E-02 0.260E-02 0.188E-02	EO(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.764E 00
NO	C. C.25 C.50 C.75 1.C0 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.125E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01 0.175E-01 0.126E-01 0.910E-02 0.656E-02 0.473E-02 0.341E-02 0.246E-02 0.177E-02	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E 00 0.717E 00 0.752E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E G1 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.495E-01 0.357E-01 0.257E-01 0.134E-01 0.964E-02 0.695E-02 0.501E-02 0.361E-02 0.260E-02 0.135E-02	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.764E 00
NO	C. C.25 C.50 C.75 1.C0 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01 0.175E-01 0.126E-01 0.910E-02 0.656E-02 0.473E-02 0.341E-02 0.246E-02 0.177E-02 0.128E-02	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E 00 0.717E 00 0.752E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E 01 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.495E-01 0.357E-01 0.257E-01 0.134E-01 0.134E-01 0.964E-02 0.695E-02 0.501E-02 0.361E-02 0.260E-02 0.188E-02	EO(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.764E 00
NO	C. C.25 C.50 C.75 1.C0 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.125E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01 0.175E-01 0.126E-01 0.910E-02 0.656E-02 0.473E-02 0.341E-02 0.246E-02 0.177E-02	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E 00 0.717E 00 0.752E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E G1 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.495E-01 0.357E-01 0.257E-01 0.134E-01 0.964E-02 0.695E-02 0.501E-02 0.361E-02 0.135E-02 0.135E-02 0.135E-02 0.975E-03	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.764E 00
NO	C. 25 C.50 C.75 1.CO 1.25 1.50 1.75 2.90 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.60	N(E50) 0.36CE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01 0.175E-01 0.126E-01 0.910E-02 0.656E-02 0.473E-02 0.473E-02 0.246E-02 0.177E-02 0.128E-02 0.920E-03	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.717E 00 0.752E 00 0.764E 00	N(*E,.5G) 0.800E 01 0.260E G1 0.100E 01 0.467E 00 0.282E 00 0.188E 00 0.133E 00 0.954E-01 0.495E-01 0.357E-01 0.257E-01 0.134E-01 0.964E-02 0.695E-02 0.501E-02 0.361E-02 0.135E-02 0.135E-02 0.135E-02 0.135E-03 0.703E-03 0.507E-03 0.365E-03	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.764E 00
NO	C. 25 C.50 C.75 1.CO 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50 6.00 6.25	N(E50) 0.36GE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01 0.175E-01 0.126E-01 0.910E-02 0.656E-02 0.473E-02 0.341E-02 0.246E-02 0.177E-02 0.128E-02 0.128E-03 0.663E-03 0.478E-03 0.6345E-03	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.717E 00 0.752E 00 0.764E 00	N(*E,.5G)	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.764E 00
NO	C. 25 C.50 C.75 1.C0 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50 6.25 6.50	N(E50) 0.36GE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01 0.175E-01 0.126E-01 0.910E-02 0.656E-02 0.473E-02 0.341E-02 0.246E-02 0.177E-02 0.128E-02 0.177E-02 0.128E-03 0.663E-03 0.478E-03 0.478E-03 0.248E-03	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.494E 00 0.622E 00 0.717E 00 0.762E 00 0.764E 00	N(*E,.5G)	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.764E 00
NO	C. 25 C.50 C.75 1.CO 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50 6.00 6.25	N(E50) 0.36GE 02 0.994E 01 0.304E 01 0.945E 00 0.453E 00 0.177E 00 0.125E 00 0.899E-01 0.648E-01 0.467E-C1 0.337E-01 0.243E-01 0.175E-01 0.126E-01 0.910E-02 0.656E-02 0.473E-02 0.341E-02 0.246E-02 0.177E-02 0.128E-02 0.128E-03 0.663E-03 0.478E-03 0.6345E-03	** L=1.70 ** E0(D) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.717E 00 0.752E 00 0.764E 00	N(*E,.5G)	E0(I) 0.222E 00 0.262E 00 0.329E 00 0.494E 00 0.622E C0 0.717E 0C 0.752E 00 0.764E 00

NO	E	N(E,.50)	** L=1.80 ** E0(D)	N(#E,.50)	E0(1)
1	Ç.,	0.812E C2	0.1788 00	0.146E 02	0.1816 00
2	0.25	0.199E 02	0.178E 00	0.367E 01	0.192E 00
3 4	0.50 0.75	0.489E 01 0.119E 01	0.177E 00 0.181E 00	0.100E 01 0.346E 00	0.236E 00 0.400E 00
5	1.00	C.302E CO	0.1816 00 0.279E 00	0.185E 00	0.450E 90
6	1.25	0.156F 00	0.678E CO	0.133E 00	G.870F 00
7	1.50	C.114E CC	0.888E 00	0.999E-01	0.874E GO
8	1.75	0.860E-01	C.872E OC	0.750E-01	0.872E 00
9 10	2.00 2.25	0.646E-01 0.485F-01	0.872E 00 0.872E 00	0.563E-01 0.423E-01	0.872E 00 0.872E 00
11	2.50	C.364E-01	0.8720 00	0.317E-01	0.872E 00
12	2.75	0.2736-01	0.872E 00	0.238E-01	0.872E 00
13	3.00	0.205E-C1	0.872E 00	0.179E-01	0.872E 00
14 15	3.25 3.50	0.1546-01 0.1166-01	0.872E 00 0.872E 00	0.134E-01 0.101E-01	0.872E 00 0.872E 00
16	3.75	0.868E-02	0.872E 00	0.757E-02	0.872E 00
17	4.00	0.652E-02	0.872E 00	0.568E-02	0.872E 00
18	4.25	0.489E-02	0.872E 00	0.427E-C2	0.872E 00
19 20	4.50 4.75	0.367E-02 0.276E-02	0.872E 00 0.872E 00	0.320E-02	0.8728 00
21	5.00	0.207E-02	0.872E 00	0.241E-02 C.181E-02	0.872E 00 0.872E 00
22	5.25	0.155E-02	0.872E 00	C.136E-02	0.872E 00
23	5.50	0.117E-02	0.872E 00	0.102E-02	C.872E 00
24 25	5.75 6.00	0.876E-03	C.872E 00	0.764E-03	0.872E 00
26	6.25	0.658F-03 0.494E-03	0.872E 00 C.872E 00	0.574E-03 0.431E-03	0.872E 00 0.872E 00
27	6.50	0.371E-03	0.872E 00	0.323E-C3	0.872E 00
28	6.75	0.278E-03	0.872E 00	0.243E-03	0.872E 00
29	7.00	C.269E-03	€.872⊨ 00	0.182E-03	0.872E OC
NΠ	F	N(E 50)	** L=1.90 **		E0(I)
NO	E	N(E,.5C)	** L=1.90 ** E0(D)	N(*E,.50)	E0(I)
1	0.	0.278E 03	EO(D) 0.131E 00	N(*E,.50) 0.367E 02	0.133E 00
1 2	0. 0.25	0.278E 03 0.414E 02	EO(D) 0.131E 00 0.131E 00	N(*E,.50) 	0.133E 00 0.145E 00
1 2 3	0. 0.25 0.50	0.278E 03 0.414E 02 C.617E 01	E0(D) 0.131E 00 0.131E 00 0.131E 00	N(*E,.50) 	0.133E 00 0.145E 00 0.214E 00
1 2 3 4 5	0. 0.25	0.278E 03 0.414E 02 C.617E 01 0.918F 00 0.217F 00	EO(D) 0.131E 00 0.131E 00	N(*E,.50) 	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00
1 2 3 4 5 6	0. 0.25 0.50 0.75 1.00 1.25	0.278E 03 0.414E 02 C.617E 01 0.918F 00 0.217F 00 0.154E 00	0.131E 00 0.131E 00 0.131E 00 0.131E 00 0.142E 00 0.730E 00 0.102E 01	N(*E,.50) 	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.976E 00
1 2 3 4 5 6 7	0. 0.25 0.50 0.75 1.00 1.25 1.50	0.278E 03 0.414E 02 C.617E 01 0.918F 00 0.217F 00 0.154E 00 C.121E 00	0.131E 00 0.131E 00 0.131E 00 0.131E 00 0.142E 00 0.730E 00 0.102E 01 0.971E 00	N(*E,.50) 	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.976E 00 0.971E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217E 00 0.154E 00 C.121E 00 0.932E-01	0.131E 00 0.131E 00 0.131E 00 0.131E 00 0.142E 00 0.730E 00 0.102E 01 0.971E 00 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.976E 00 0.971E 00
1 2 3 4 5 6 7	0. 0.25 0.50 0.75 1.00 1.25 1.50	0.278E 03 0.414E 02 C.617E 01 0.918F 00 0.217F 00 0.154E 00 C.121E 00	0.131E 00 0.131E 00 0.131E 00 0.131E 00 0.142E 00 0.730E 00 0.102E 01 0.971E 00	N(*E,.50) 	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.976E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10	0.25 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.60 2.25 2.50	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217F 00 0.154E 00 C.121E 00 0.932E-01 0.720E-01 0.557E-01 0.430E-01	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142E 00 0.730E 00 0.102E G1 0.971E 00 0.971E 00 0.971E 00 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.60 2.25 2.50 2.75	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217F 00 0.154E 00 C.121E 00 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142F 00 0.730E 00 0.102E 01 0.971E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.60 2.25 2.50 2.75 3.00	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217F 00 0.154E 00 C.121E 00 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01 0.257E-01	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142F 00 0.730E 00 0.102E 01 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.60 2.25 2.50 2.75	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217F 00 0.154E 00 C.121E 00 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142F 00 0.730E 00 0.102E 01 0.971E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217E 0C 0.154E 0C C.121E 00 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01 0.257E-01 0.199E-01 C.154E-01 C.119E-01	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142F 00 0.730E 00 0.102E 01 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217E 00 0.154E 00 C.121E 00 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01 0.257E-01 0.199E-01 0.154E-01 0.19E-01 0.119E-01 0.917E-02	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142F 00 0.730E 00 0.102E 01 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217E 00 0.154E 00 C.121E 00 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01 0.257E-01 0.199E-01 C.154E-01 C.199E-01 C.199E-01 C.199E-02	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142E 00 0.730E 00 0.102E 01 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217E 00 0.154E 00 C.121E 00 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01 0.257E-01 0.199E-01 0.154E-01 0.19E-01 0.119E-01 0.917E-02	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142F 00 0.730E 00 0.102E 01 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	0.25 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.50 4.75 5.60	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217F 00 0.154E 00 C.121E 00 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01 0.257E-01 0.199E-01 0.154E-01 0.119E-01 0.917E-02 0.709E-02 0.548E-02	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142E 00 0.730E 00 0.102E 01 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0.25 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.25 4.50 4.75 5.60 5.25	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217F 00 0.154E 00 0.121E 00 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01 0.257E-01 0.199E-01 0.119E-01 0.119E-01 0.917E-02 0.709E-02 0.548E-02 0.424E-02 0.327E-02 0.253E-02	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142E 00 0.730E 00 0.102E G1 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217F 00 0.154E 00 0.154E 00 0.932E-01 0.720E-01 0.430E-01 0.333E-01 0.257E-01 0.199E-01 0.119E-01 0.119E-01 0.917E-02 0.709E-02 0.424E-02 0.327E-02 0.253E-02 0.253E-02 0.253E-02	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142F 00 0.730E 00 0.102E G1 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0.25 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.25 4.50 4.75 5.60 5.25	0.278E 03 0.414E 02 C.617E 01 0.918E 00 0.217F 00 0.154E 00 0.121E 00 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01 0.257E-01 0.199E-01 0.119E-01 0.119E-01 0.917E-02 0.709E-02 0.548E-02 0.424E-02 0.327E-02 0.253E-02	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142F 00 0.730E 00 0.102E 01 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0.25 0.25 0.50 0.75 1.00 1.75 1.50 2.60 2.75 3.00 3.25 3.75 4.00 4.75 5.00 5.75 6.00 6.25	0.278E 03 0.414E 02 C.617E C1 0.918E 0C 0.217E 0C 0.154E 0C C.121E 0C 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01 0.257E-01 C.199E-01 C.194E-01 C.119E-01 0.917E-02 0.709E-02 0.548E-02 0.424E-02 0.327E-02 0.253E-02 0.151E-02 0.151E-02 0.117E-02 0.903E-03	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142F 00 0.730E 00 0.102E G1 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	0.25 0.25 0.50 1.00 1.25 1.50 1.75 2.05 2.250 2.75 3.00 3.25 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.25 6.00 6.25 6.50	0.278E 03 0.414E 02 C.617E C1 0.918E 0C 0.217F 0C 0.154E 0C C.121E 0C 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.430E-01 0.199E-01 C.199E-01 C.199E-01 C.196E-02 0.709E-02 0.548E-02 0.424E-02 0.327E-02 0.253E-02 0.151E-02 0.117E-02 0.903E-03 0.698E-03	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142E 00 0.730E 00 0.102E 01 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0.25 0.25 0.50 0.75 1.00 1.75 1.50 2.60 2.75 3.00 3.25 3.75 4.00 4.75 5.00 5.75 6.00 6.25	0.278E 03 0.414E 02 C.617E C1 0.918E 0C 0.217E 0C 0.154E 0C C.121E 0C 0.932E-01 0.720E-01 0.557E-01 0.430E-01 0.333E-01 0.257E-01 C.199E-01 C.194E-01 C.119E-01 0.917E-02 0.709E-02 0.548E-02 0.424E-02 0.327E-02 0.253E-02 0.151E-02 0.151E-02 0.117E-02 0.903E-03	E0(D) 0.131E 00 0.131E 00 0.131E 00 0.142F 00 0.730E 00 0.102E 01 0.971E 00	N(*E,.50)	0.133E 00 0.145E 00 0.214E 00 0.548E 00 0.941E 00 0.971E 00

			** L=2.00 **		
NO	E	N(E5G)	EC(D)	N(*E,.5C)	EC(1)
1	C.	0.267F 03	C.134E 00	0.358E C2	0.135E 00
2	G • 25	0.411E 62	0.1346 00	0.565E 01	0.144E 00
3 4	0.50 C.75	0.634E 01 0.970E 00	0.133E 00 0.133E 00	0.100E 01 0.285E 00	0.199E 00
5	1.00	0.976E 00	0.342E 00	0.170E 00	0.486E 00 0.103E 01
6	1.25	0.116E 00	0.654E 00	0.134E 00	0.118E G1
7	1.50	0.909E-01	0.119F 01	0.108E CO	0.119E 01
8	1.75	0.737E-01	0.119E 01	0.877E-01	0.119E 01
9 13	2.00 2.25	0.597E-01 C.484E-01	0.119E 01 0.119E 01	0.711E-C1 0.576E-01	0.119E 01 0.119E 01
11	2.50	0.392E-01	0.119E 01	0.467E-01	0.119E 01
12	2.75	0.318E-01	0.119E 01	0.378E-01	0.119E 01
13	3.00	0.258E-C1	0.119E 01	0.307E-01	0.119E 01
14	3.25	0.209E-01	0.119E C1	0.249E-01	0.119E C1
15 16	3.50 3.75	0.169E-01 0.137E-01	0.119E 01 0.119E 01	0.202E-01 0.163E-01	0.119E 01 0.119E 01
17	4.00	0.111E-01	0.119E 01	0.132E-01	0.1196 01
18	4.25	0.902E-02	0.119E C1	0.107E-01	0.119E 01
19	4.50	0.731E-02	0.119E 01	0.870E-02	0.119E 01
20	4.75	0.592E-02	0.119E 01	0.705E-02	0.1198 01
21 22	5.00 5.25	0.480E-02 0.389E-02	0.119E 01 0.119E 01	0.572E-02 0.463E-02	0.119E 01 0.119E 01
23	5.50	0.316E-02	0.119E 01	0.405E-02	0.119E 01
24	5.75	0.256E-02	C.119E 01	0.304E-02	0.119F 01
25	6.00	0.207E-02	0.119E 01	0.247E-02	0.119E 01
26	6.25	0.168E-02	0.119E 01	0.200E-02	0.119E 01
27 28	6.50 6.75	0.136F-02 0.110E-02	0.119E 01 0.119E 01	0.162E-02	0.119E 01 0.119E 01
29	7.00	0.895E-03	0.119E 01	0.131E-02 0.107E-02	0.119E 01
			** L=2.20 **		
NO	£	N(E+.50)	EC(D)	N(*E,.50)	E0(I)
NO 1	E 	N(E,.50) 0.652E 03		N(*E,.50) 0.729E 02	E0(I) 0.112E 00
1 2	0. C.25	0.652E 03 0.695E 02	0.112E 00 0.109E 00	0.729E 02 0.782E 61	0.112E 00 0.122+ 00
1 2 3	0. 0.25 0.50	0.652E 03 0.695E 02 0.704E 01	0.112E 00 0.109E 00 0.109E 00	0.729E 02 0.762E 01 0.160E 01	0.112E 00 0.122± 00 0.213E 00
1 2 3 4	0. 0.25 0.50 0.75	0.652E 03 0.695E 02 0.704E 01 0.752E 00	0.112E 00 0.109E 00 0.109E 00 0.109E 00 0.124E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00	0.112E 00 0.122± 00 0.213E 00 0.635E 00
1 2 3 4 5	0. 0.25 0.50 0.75 1.00	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00	0.112E 00 0.109E 00 0.109E 00 0.109E 00 0.124E 00 0.505E 00	0.729E 02 0.782E 01 0.100E 01 0.308E 00 0.208E 00	0.112E 00 0.122± 00 0.213E 00
1 2 3 4	0. 0.25 0.50 0.75	0.652E 03 0.695E 02 0.704E 01 0.752E 00	0.112E 00 0.109E 00 0.109E 00 0.109E 00 0.124E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 6.123E 00 0.965E-01	C(D) 0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E 00 0.837E 00 0.103F 01 0.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.708E 00 0.158E 00 0.122E 00 0.949E-01	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.989E 00 0.984E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.60	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 0.123E 00 0.965E-01 0.748E-01	C(D) 0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E 00 0.837E 00 0.103F 01 0.984E 00 0.984E 00	0.729E 02 C.782E 01 O.10CE 01 C.308E 00 C.708E 00 O.158E 00 O.122E 00 O.949E-01 O.736E-01	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.989E 00 0.984E 00 0.984E 00
1 2 3 4 5 6 7 8 9	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.90 2.25	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 6.123E 30 0.965E-01 0.748E-01 0.580E-01	EC(D) 0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E C0 0.837E 00 0.103F 01 0.984E 00 0.984E 00 0.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.158E 00 0.158E 00 0.122E 00 0.949E-01 0.736E-01 0.571E-01	0.112E 00 0.122F 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.989E 00 0.984E 00 0.984F 00
1 2 3 4 5 6 7 8 9 10	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.60 2.25 2.50	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 0.123E 30 0.965E-01 0.748E-01 0.580E-01	C(D) 0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E 00 0.837E 00 0.103F 01 0.984E 00 0.984E 00 0.984E 00	0.729E 02 C.782E 01 O.10CE 01 C.308E 00 C.708E 00 O.158E 00 O.122E 00 O.949E-01 O.736E-01	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.989E 00 0.984E 00 0.984E 00
1 2 3 4 5 6 7 8 9	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.90 2.25	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 6.123E 30 0.965E-01 0.748E-01 0.580E-01	EC(D) 0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E C0 0.837E 00 0.103F 01 0.984E 00 0.984E 00 0.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.208E 00 0.158E 00 0.122E 00 0.949E-01 0.736E-01 0.571E-01 0.443E-01	0.112E 00 0.122E 06 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.989E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 0.123E 30 0.965E-01 0.748E+01 0.580E-01 0.450E-01 0.349E-01 0.271E-01 0.210E-01	0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E 00 0.837E 00 0.103F 01 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984F 00 0.984E 00 0.984E 00	0.729E 02 0.762E G1 0.10GE 01 0.308E G0 0.708E 00 0.158E 00 0.122E 00 0.949E-01 0.736E-01 0.571E-01 0.443E-01 0.344E-01 0.267E-01 0.207E-01	0.112E 00 0.122E 06 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.989E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50	0.652E C3 0.695E 02 0.704E 01 0.752E C0 C.247E G0 C.166E 00 G.123E 30 0.965E-C1 0.748E-01 C.58CE-C1 G.450E-C1 0.349E-C1 C.271E-C1 0.21CE-O1 0.163E-O1	C(D) 0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E 00 0.837E 00 0.103F 01 0.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.708E 00 0.158E 00 0.122E 00 0.949E-01 0.736E-01 0.571E-01 0.443E-01 0.344E-01 0.267E-01 0.207E-01 0.160E-01	0.112E 00 0.122E 06 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.989E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 0.123E 30 0.965E-01 0.748E-01 0.580E-01 0.450E-01 0.349E-01 0.271E-01 0.210E-01 0.163E-01 0.126E-01	EC(D) 0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E 00 0.837E 00 0.103F 01 0.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.158E 00 0.122E 00 0.949E-01 0.736E-01 0.571E-01 0.443E-01 0.344E-01 0.267E-01 0.207E-01 0.160E-01 0.124E-01	0.112E 00 0.122E 06 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17	0. C.25 C.50 0.75 1.00 1.25 1.50 1.75 2.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 0.123E 30 0.965E-01 0.748E-01 0.580E-01 0.450E-01 0.349E-01 0.271E-01 0.210E-01 0.163E-01 0.126E-01 0.981E-02	0.112E 00 0.109E 00 0.109E 00 0.109E 00 0.505E 00 0.837E 00 0.103F 01 0.984E 00 0.984E 00	0.729E 02 C.782E G1 0.10GE 01 C.308E G0 C.708E C0 0.158E 00 0.122E 00 0.949E-C1 0.736E-01 0.571E-01 0.443E-C1 0.344E-01 0.267E-01 0.207E-01 0.160E-01 0.124E-01 0.965E-02	0.112E 00 0.122E 06 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.989E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 0.123E 30 0.965E-01 0.748E-01 0.580E-01 0.450E-01 0.349E-01 0.271E-01 0.210E-01 0.163E-01 0.126E-01	EC(D) 0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E 00 0.837E 00 0.103F 01 0.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.158E 00 0.122E 00 0.949E-01 0.736E-01 0.571E-01 0.443E-01 0.344E-01 0.267E-01 0.207E-01 0.160E-01 0.124E-01	0.112E 00 0.122E 06 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.989E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.166E 00 0.123E 30 0.965E-01 0.748E-01 0.580E-01 0.450E-01 0.349E-01 0.210E-01 0.163E-01 0.163E-01 0.126E-01 0.981E-02 0.761E-02 0.590E-02 0.458E-02	EC(D) 0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E C0 0.837E 00 0.103F 01 0.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.158E 00 0.158E 00 0.122E 00 0.949E-01 0.736E-01 0.571E-01 0.443E-01 0.344E-01 0.267E-01 0.160E-01 0.124E-01 0.124E-01 0.965E-02 0.749E-02 0.581E-02 0.450E-02	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.60 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.75 5.00	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.166E 00 0.123E 30 0.965E-01 0.748E-01 0.580E-01 0.450E-01 0.349E-01 0.210E-01 0.163E-01 0.163E-01 0.126E-01 0.981E-02 0.761E-02 0.590E-02 0.458E-02 0.458E-02	EC(D) 0.112E 00 C.109E 0C U.109E 0C U.109E 0C C.505E CC C.837E 0C G.103F 01 C.984E 0C	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.158E 00 0.158E 00 0.122E 00 0.949E-01 0.736E-01 0.571E-01 0.443E-01 0.344E-01 0.267E-01 0.160E-01 0.124E-01 0.124E-01 0.965E-02 0.749E-02 0.581E-02 0.450E-02 0.349E-02	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.60 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.75 5.00 5.25	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 0.123E 30 0.965E-01 0.748E+01 0.580E-01 0.450E-01 0.349E+01 0.271E-01 0.163E-01 0.163E-01 0.126E-01 0.126E-01 0.981E-02 0.761E-02 0.761E-02 0.590E-02 0.458E-02 0.458E-02 0.275E-02	0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E 00 0.837E 00 0.103F 01 0.984E 00 0.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.158E 00 0.158E 00 0.122E 00 0.949E-01 0.571E-01 0.443E-01 0.344E-01 0.267E-01 0.267E-01 0.160E-01 0.124E-01 0.965E-02 0.749E-02 0.581E-02 0.450E-02 0.349E-02 0.271E-02	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.60 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 0.123E 30 0.965E-01 0.748E-01 0.580E-01 0.450E-01 0.349E-01 0.271E-01 0.210E-01 0.163E-01 0.126E-01 0.981E-02 0.761E-02 0.761E-02 0.590E-02 0.458E-02 0.458E-02 0.275E-02 0.275E-02 0.214E-02	0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E 00 0.837E 00 0.103F 01 0.984E 00 0.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.158E 00 0.158E 00 0.122E 00 0.949E-01 0.736E-01 0.571E-01 0.443E-01 0.344E-01 0.267E-01 0.160E-01 0.124E-01 0.124E-01 0.965E-02 0.749E-02 0.581E-02 0.450E-02 0.349E-02	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.60 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.75 5.00 5.25	0.652E 03 0.695E 02 0.704E 01 0.752E 00 0.247E 00 0.166E 00 0.123E 30 0.965E-01 0.748E+01 0.580E-01 0.450E-01 0.349E+01 0.271E-01 0.163E-01 0.163E-01 0.126E-01 0.126E-01 0.981E-02 0.761E-02 0.761E-02 0.590E-02 0.458E-02 0.458E-02 0.275E-02	0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E 00 0.837E 00 0.103F 01 0.984E 00 0.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.158E 00 0.158E 00 0.122E 00 0.949E-01 0.736E-01 0.571E-01 0.443E-01 0.344E-01 0.267E-01 0.160E-01 0.124E-01 0.965E-02 0.749E-02 0.581E-02 0.450E-02 0.349E-02 0.271E-02 0.210E-02	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	0. C.25 C.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50 6.25	0.652E C3 0.695E 02 0.704E 01 0.752E C0 C.247E G0 C.166E 00 G.123E 30 0.965E-C1 0.748E+01 C.58CE-C1 0.450E-C1 0.349E-01 0.21CE-01 0.126E-01 0.126E-01 0.126E-01 0.126E-02 0.590E-02 0.458E-C2 0.355E-02 0.275E-02 0.214E-C2 0.129E-02 0.129E-02	EC(D) 0.112E CO C.109E OC C.109E OC C.109E OO C.124E OO C.505E CO C.837E OO G.103F 01 O.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.158E 00 0.158E 00 0.122E 00 0.949E-01 0.571E-01 0.443E-01 0.57E-01 0.267E-01 0.267E-01 0.124E-01 0.124E-01 0.124E-01 0.965E-02 0.749E-02 0.581E-02 0.450E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	0. C.25 C.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50 6.25 6.50	0.652E C3 0.695E 02 0.704E 01 0.752E C0 C.247E C0 C.166E 00 G.123E 30 0.965E-C1 0.748E+01 C.58CE-C1 G.450E-C1 0.349E-01 C.271E-01 0.21CE-01 0.163E-01 0.126E-C1 0.981E-02 0.761E-02 0.590E-02 0.458E-C2 0.355E-02 0.275E-C2 0.214E-C2 0.129E-C3 0.129E-C3 0.773E-C3	0.112E 00 0.109E 00 0.109E 00 0.124E 00 0.505E C0 0.837E 00 0.103F 01 0.984E 00 0.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.158E 00 0.158E 00 0.122E 00 0.949E-01 0.736E-01 0.571E-01 0.443E-01 0.267E-01 0.160E-01 0.160E-01 0.124E-01 0.965E-02 0.749E-02 0.581E-02 0.450E-02 0.349E-02 0.271E-02 0.271E-02 0.271E-02 0.210E-02 0.166E-02 0.126E-02 0.126E-02 0.126E-02 0.981E-03 0.761E-03	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.984E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. C.25 C.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50 6.25	0.652E C3 0.695E 02 0.704E 01 0.752E C0 C.247E G0 C.166E 00 G.123E 30 0.965E-C1 0.748E+01 C.58CE-C1 0.450E-C1 0.349E-01 0.21CE-01 0.126E-01 0.126E-01 0.126E-01 0.126E-02 0.590E-02 0.458E-C2 0.355E-02 0.275E-02 0.214E-C2 0.129E-02 0.129E-02	EC(D) 0.112E CO C.109E OC C.109E OC C.109E OO C.124E OO C.505E CO C.837E OO G.103F 01 O.984E 00	0.729E 02 0.762E 01 0.100E 01 0.308E 00 0.158E 00 0.158E 00 0.122E 00 0.949E-01 0.571E-01 0.443E-01 0.57E-01 0.267E-01 0.267E-01 0.124E-01 0.124E-01 0.124E-01 0.965E-02 0.749E-02 0.581E-02 0.450E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02 0.271E-02	0.112E 00 0.122E 00 0.213E 00 0.635E 00 0.911E 00 0.972E 00 0.984E 00

NO	E	N(E,.50)	** L=2.10 ** E0(D)	N(*E,.5ú)	(1) C3
1	0.	0.402E 03	0.124E 00	0.500E 02	0.124E 00
2	0.25	0.510E 02	0.131E 00	G.670E 01	0.1316 00
3	0.50	0.497E 01	0.201E 00	0.100E 01	0.201E 00
4 5	0.75 1.00	0.535E 00 0.165E 00	0.541E 00 0.110E 01	0.289E 00 0.182E 00	0.541E 00 0.110E 01
6	1.25	0.134E 00	0.108E 01	0.145E 00	0.108E 01
7	1.50	0.104E 00	C.111E 01	9.115E 00	0.111E C1
8	1.75	0.8926-01	0.103E 01	0.918E-01	0.103E 01
9 10	2.00 2.25	0.658E-01 0.440E-01	C.109E 01 C.130E 01	0.720E-01 0.573E-01	0.109E 01 0.130E 01
11	2.50	0.429E-01	0.110E C1	0.473E-01	0.110E 01
12	2.75	0.342E-01	0.110E 01	0.377E-01	0.110E 01
13	3.00	0.273E-01	C.110E 01	0.301E-01	0.110E 01
14 15	3.25 3.50	0.217E-01 0.173E-01	0.110E 01 0.110E 01	0.240E-01 0.191E-01	0.110E 01 0.110E 01
16	3.75	0.138E-01	0.110E 01	0.152E-01	0.110E 01
1.7	4.00	0.11CE-61	0.110E 01	0.121E-01	0.110E 01
18	4.25	0.877E-02	0.110E 01	0.968E-02	0.110E 01
19 20	4.50 4.75	0.699E-02 0.558E-02	0.110E 01 0.110E 01	0.771E-02 0.615E-02	0.110E 01 0.110E 01
21	5.00	0.444E-02	0.110E 01	0.490E-02	0.110E C1
22	5.25	0.354E-02	0.110E 01	0.391E-02	0.110E 01
23	5.50	0.282E-02	0.110E 01	0.311E-02	0.110E 01
24 25	5.75 6.00	0.2258-02	0.110E 01	0.248E-02	0.110E 01
26	6.25	0.179E-02 0.143E-02	C.110E 01 C.110E 01	0.198E-02 C.158E-02	0.110E 01 0.110E 01
27	6.50	0.114E-02	0.110E 01	C.126E-02	0.110E 01
28	6.75	0.909E-03	0.110E 01	0.100E-02	0.110E 01
29	7.CO	0.725E-03	C.110E 01	0.799E-03	0.110E 01
NO	E	N(E,.50)	** L=2.3C ** E0(D)	N(*E,.50)	EG(1)
			EO(D)		
1 2	C.25	N(E,.50) 0.134E c4 0.464E c2	0.861E-01 0.136E 00	0.115E C3 C.630E O1	0.861E-01 G.136E 00
1 2 3	0. 0.25 0.50	0.134E 04 0.464E 02 0.422E 01	0.861E-01 0.136E 00 0.237E 00	0.115E 03 0.630E 01 0.100E 01	0.861E-01 0.136E 00 0.237E 00
1 2 3 4	0. 0.25 0.50 0.75	0.134E 04 0.464E 02 0.422E 01 0.576E 00	0.861E-01 0.136E 00 0.237E 00 0.604E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00	0.861E-01 0.136E 00 0.237E 00 0.604E 00
1 2 3	0. 0.25 0.50	0.134E 04 0.464E 02 0.422E 01	0.861E-01 0.136E 00 0.237E 00	0.115E 03 0.630E 01 0.100E 01	0.861E-01 0.136E 00 0.237E 00
1 2 3 4 5 6	0. 0.25 0.50 0.75 1.00 1.25 1.50	0.134E C4 C.464E C2 0.422E O1 0.576E OO C.328E OO 0.206E CO C.144E CO	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00	0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.144E 00 0.113E 00	0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01	0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.144E 00 0.113E 00 0.822E-01	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.620E-01	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.144E 00 0.113E 00	0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01	0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00
1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.144E 00 0.113E 00 0.822E-01 0.655E-01 0.384E-01 0.281E-01	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.620E-01 0.445E-01 0.308E-01 0.225E-01	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.144E 00 0.113E 00 0.822E-01 0.655E-01 0.384E-01 0.281E-01 0.206E-01	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.620E-01 0.445E-01 0.308E-01 0.225E-01 0.165E-01	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25	0.134E C4 C.464E C2 0.422E 01 C.576E 00 C.328E 00 0.206E C0 C.144E C0 0.113E 00 0.822E-01 C.655E-01 C.384E-01 U.281E-01 C.206E-01 O.151E-01	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.609E 00 0.801E 00 0.801E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.620E-01 0.445E-01 0.308E-01 0.225E-01 0.165E-01 0.121E-01	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00 0.801E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00	0.134E C4 C.464E C2 0.422E 01 C.576E 00 C.328E 00 0.206E C0 0.144E C0 0.113E 00 0.822E-01 0.655E-01 0.384E-01 0.281E-01 0.206E-01 0.151E-01 0.110E-01	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00 0.754E 00 0.754E 00 0.679E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.620E-01 0.445E-01 0.308E-01 0.225E-01 0.165E-01	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	0.134E C4 C.464E C2 0.422E 01 C.576E 00 C.328E 00 0.206E C0 0.144E C0 0.113E 00 0.822E-01 0.655E-01 0.384E-01 0.281E-01 0.206E-01 0.151E-01 0.110E-01 0.808E-02 0.591E-02	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.620E-01 0.445E-01 0.308E-01 0.225E-01 0.165E-01 0.165E-01 0.121E-01 0.884E-02 0.647E-02	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.754E 00 0.679E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.144E 00 0.113E 00 0.822E-01 0.655E-01 0.384E-01 0.281E-01 0.206E-01 0.151E-01 0.110E-01 0.808E-02 0.591E-02 0.433E-02	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.620E-01 0.445E-01 0.308E-01 0.225E-01 0.165E-01 0.121E-01 0.884E-02 0.647E-02 0.474E-02 0.347E-02	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.113E 00 0.822E-01 0.655E-01 0.384E-01 0.281E-01 0.206E-01 0.151E-01 0.110E-01 0.808E-02 0.591E-02 0.433E-02 0.317E-02	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.764E 00 0.754E 00 0.754E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.620E-01 0.445E-01 0.308E-01 0.225E-01 0.165E-01 0.121E-01 0.884E-02 0.647E-02 0.474E-02 0.347E-02 0.347E-02 0.254E-02	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.754E 00 0.679E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.144E 00 0.113E 00 0.822E-01 0.655E-01 0.384E-01 0.281E-01 0.206E-01 0.151E-01 0.110E-01 0.808E-02 0.591E-02 0.433E-02	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.620E-01 0.445E-01 0.308E-01 0.225E-01 0.165E-01 0.121E-01 0.884E-02 0.647E-02 0.474E-02 0.347E-02	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.144E 00 0.113E 00 0.822E-01 0.655E-01 0.384E-01 0.281E-01 0.206E-01 0.151E-01 0.110E-01 0.808E-02 0.591E-02 0.433E-02 0.433E-02 0.433E-02 0.317E-02 0.232E-02 0.170E-02 0.124E-02	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.445E-01 0.308E-01 0.225E-01 0.165E-01 0.121E-01 0.884E-02 0.647E-02 0.474E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.754E 00 0.679E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.75 5.00 5.25 5.50	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.144E 00 0.113E 00 0.822E-01 0.655E-01 0.384E-01 0.281E-01 0.206E-01 0.151E-01 0.110E-01 0.808E-02 0.591E-02 0.433E-02 0.433E-02 0.433E-02 0.170E-02 0.124E-02 0.909E-03	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.812E 00 0.754E 00 0.679E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.445E-01 0.308E-01 0.225E-01 0.165E-01 0.121E-01 0.884E-02 0.647E-02 0.474E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.754E 00 0.679E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 5.25 5.50 5.75	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.144E 00 0.113E 00 0.822E-01 0.655E-01 0.384E-01 0.281E-01 0.206E-01 0.151E-01 0.110E-01 0.808E-02 0.591E-02 0.433E-02 0.317E-02 0.232E-02 0.170E-02 0.124E-02 0.909E-03 0.665E-03	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.812E 00 0.764E 00 0.754E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.620E-01 0.445E-01 0.308E-01 0.225E-01 0.165E-01 0.165E-01 0.121E-01 0.884E-02 0.647E-02 0.474E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.754E 00 0.754E 00 0.679E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	0. 0.25 0.50 0.75 1.00 1.25 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.75 6.00 6.25	0.134E 04 0.464E 02 0.422E 01 0.576E 00 0.328E 00 0.206E 00 0.144E 00 0.113E 00 0.822E-01 0.655E-01 0.384E-01 0.281E-01 0.206E-01 0.151E-01 0.110E-01 0.808E-02 0.591E-02 0.433E-02 0.433E-02 0.433E-02 0.170E-02 0.124E-02 0.909E-03	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.812E 00 0.754E 00 0.679E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.445E-01 0.308E-01 0.225E-01 0.165E-01 0.121E-01 0.884E-02 0.647E-02 0.474E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-02	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.754E 00 0.679E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.75 6.00 6.25 6.50	0.134E C4 C.464E C2 O.422E O1 C.576E OO C.328E OO O.206E CO O.144E CO O.113E OO O.822E-O1 C.655E-O1 C.384E-O1 O.281E-O1 O.151E-O1 O.151E-O1 O.110E-O1 C.808E-C2 O.591E-C2 O.433E-O2 O.433E-O2 O.437E-O2 O.232E-O2 O.170E-O2 O.124E-O2 O.124E-O2 O.909E-O3 C.665E-O3 C.487E-C3 O.356E-O3 O.261E-O3	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.783E 00 0.764E 00 0.754E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.620E-01 0.445E-01 0.308E-01 0.165E-01 0.165E-01 0.165E-01 0.121E-01 0.884E-02 0.474E-02 0.474E-02 0.347E-02 0.347E-02 0.186E-02 0.186E-02 0.186E-03 0.296E-03 0.209E-03	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.754E 00 0.801E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. 0.25 0.50 0.75 1.00 1.25 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.75 6.00 6.25	0.134E C4 C.464E C2 0.422E 01 0.576E 00 C.328E 00 0.206E C0 C.144E C0 0.113E 00 0.822E-01 C.655E-01 C.384E-01 C.206E-01 C.206E-01 C.151E-01 C.110E-01 C.808E-C2 C.591E-C2 C.433E-O2 C.3176E-O3 C.487E-C3 C.356E-O3	E0(D) 0.861E-01 0.136E 00 0.237E 00 0.604E 00 0.701E 00 0.812E 00 0.754E 00 0.801E 00	0.115E 03 0.630E 01 0.100E 01 0.348E 00 0.230E 00 0.161E 00 0.117E 00 0.860E-01 0.445E-01 0.308E-01 0.445E-01 0.165E-01 0.165E-01 0.121E-01 0.884E-02 0.474E-02 0.474E-02 0.474E-02 0.474E-02 0.347E-02 0.347E-02 0.347E-02 0.347E-03 0.390E-03 0.533E-03 0.390E-03 0.286E-03	0.861E-01 0.136E 00 0.237E 00 0.6C4E 00 0.701E 00 0.783E 00 0.812E 00 0.764E 00 0.754E 00 0.679E 00 0.801E 00

NO	E	N(E,.50)	** L=2.40 ** E0(D)	N(*E,.50)	E0(I)
1 2	∂. 0.25	0.238E 24 0.332E 02	0.713E-01 0.153E-00	0.179E 03 0.510E 01	0.7136-01 0.153E 00
3	0.50	0.364E C1	9.275E 00	0.100E 01	0.275E 00
4	0.75	0.763E 00	0.528E 00	0.403E GC	0.528E CO
5	1.00	0.433E 00	0.579E 00	0.251E 00	0.579E 00
6 7	1.25 1.50	0.251E 00 3.174E 00	0.651E 00 0.638E 00	0.163E 00 0.111E 00	0.651E 00 0.638E 00
ė	1.75	0.125E 00	0.602E 00	0.750E-01	0.602E 90
9	2.00	0.773E-G1	0.640E 00	0.495E-01	0.640E 00
15	2.25	0.533E-01	0.628E 00	0.335E-01	0.628E 00 0.649E 00
11 12	2.50 2.75	0.347E+01 0.236E+01	0.649E 00 0.649E 00	0.225E-01 0.153E-01	0.649E 00
13	3.00	0.16CE-01	0.649E 00	0.104E-01	0.649E 00
14	3.25	0.169E-01	0.649E 00	0.708E-02	0.649E 00
15	3.50	0.743E-02	0.6498 00	0.482E-C2	0.649E 00
16 17	3.75 4.00	0.505E-02 0.344E-02	0.649E 00 0.649E 00	0.328E-02 0.223E-02	0.649E 00 0.649E 00
18	4.25	0.234E-02	0.649E 00	0.1526-02	0.649E 00
19	4.50	0.159E-02	0.649E 00	0.103E-C2	0.649E 00
2:)	4.75	0.108E-02	0.649E 00	0.702E-03	0.649E 00
21 22	5.00 5.25	0.736E-03 0.501E-03	0.649E 00 0.649E 00	0.478E-03 0.325E-03	0.649E 00 0.649E 00
23	5.50	0.341E-03	0.649E 00	0.221E-03	0.649E 00
24	5.75	0.232E-03	0.649E 00	0.150E-03	0.649E 00
25	6.00	0.1585-03	0.649E 00	0.102E-03	0.649E 00
26 27	6.25 6.50	0.107E-03 0.730E-04	0.649E 00 0.649E 00	0.697E-04 C.474E-04	0.649E 00 0.649E 00
28	6.75	0.497E-04	0.649E 00	0.322E-04	0.649E 00
29	7.00	0.338E-04	0.649E 00	0.219E-04	0.649E 00
			## 1#2 EO ##		
NO	-	V/ 5 501	** L=2.50 **		53413
NO	E	N(E,.50)	EC(D)	N(*E,.50)	(1)63
1	0.	0.368E 04	EC(D) 0.626E-01	N(*E,.50) 0.230E 03	0.626E-01
1 2	0. 0.25	0.368E 04 0.244E 02	0.626E-01 0.173E 00	N(*E,.50) 0.230E 03 0.423E 01	0.626E-01 0.173E 00
1 2 3	0. 0.25 0.50	0.368E 04 0.244E 02 0.299E 01	0.626E-01 0.173E 00 0.334E 00	0.230E 03 0.423E 01 0.100E 01	0.626E-01 0.173E 00 0.334E 00
1 2	0. 0.25	0.368E 04 0.244E 02	0.626E-01 0.173E 00	N(*E,.50) 0.230E 03 0.423E 01	0.626E-01 0.173E 00
1 2 3 4 5	0. 0.25 0.50 0.75 1.00 1.25	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00	0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00
1 2 3 4 5 6 7	0. 0.25 0.50 0.75 1.00 1.25 1.50	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.184E 00	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00	0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.104E 00	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.184E 00	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.562E 00	0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.104E 00 0.668E-01	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.562E 00
1 2 3 4 5 6 7	0. 0.25 0.50 0.75 1.00 1.25 1.50	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.184E 00	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00	0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.104E 00	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00
1 2 3 4 5 6 7 8 9	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50	0.368E C4 0.244E 02 0.299E C1 0.106E 61 0.532E 00 0.305E 00 0.119E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.566E 00 0.566E 00	N(*E,.50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.104E 00 0.668E-01 0.428E-01 0.275E-01 0.176E-01	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.565E 00 0.565E 00
1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75	0.368E 04 0.244E 02 0.299E 01 0.106E 61 0.532E 00 0.305E 00 0.184E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.565E 00 0.563E 00 0.563E 00 0.563E 00	N(*E,.50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.104E 00 0.668E-01 0.428E-01 0.275E-01 0.176E-01 0.113E-01	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.565E 00 0.565E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.184E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01 0.201E-01 0.129E-01	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.5660E 00 0.563E 00 0.563E 00 0.563E 00	N(*E,.50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.165E 00 0.165E 00 0.668E-01 0.428E-01 0.275E-01 0.176E-01 0.113E-01 0.724E-02	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.565E 00 0.563E 00 0.563E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75	0.368E 04 0.244E 02 0.299E 01 0.106E 61 0.532E 00 0.305E 00 0.184E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.565E 00 0.563E 00 0.563E 00 0.563E 00	N(*E,.50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.104E 00 0.668E-01 0.428E-01 0.275E-01 0.176E-01 0.113E-01	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.565E 00 0.565E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01 0.201E-01 0.129E-01 0.825E-02 0.529E-02 0.339E-02	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.565E 00 0.565E 00 0.565E 00 0.563E 00	N(*E,.50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.165E 00 0.668E-01 0.428E-01 0.275E-01 0.176E-01 0.176E-02 0.465E-02 0.298E-02 0.191E-02	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.565E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01 0.201E-01 0.129E-01 0.825E-02 0.529E-02 0.339E-02 0.218E-02	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.565E 00 0.565E 00 0.565E 00 0.563E 00	N(*E,.50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.165E 00 0.668E-01 0.428E-01 0.275E-01 0.176E-01 0.176E-01 0.1724E-02 0.465E-02 0.298E-02 0.191E-02 0.123E-02	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.562E 00 0.565E 00 0.565E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01 0.201E-01 0.129E-01 0.825E-02 0.529E-02 0.339E-02 0.218E-02 0.218E-02	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.565E 00 0.565E 00 0.565E 00 0.563E 00	N(*E50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.165E 00 0.165E 00 0.166E-01 0.428E-01 0.275E-01 0.176E-01 0.113E-01 0.724E-02 0.465E-02 0.298E-02 0.191E-02 0.123E-02 0.787E-03	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.565E 00 0.565E 00 0.565E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01 0.201E-01 0.129E-01 0.825E-02 0.529E-02 0.339E-02 0.218E-02	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.548E 00 0.508E 00 0.565E 00 0.565E 00 0.563E 00	N(*E50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.104E 00 0.668E-01 0.428E-01 0.275E-01 0.176E-01 0.176E-01 0.13E-01 0.724E-02 0.465E-02 0.298E-02 0.191E-02 0.123E-02 0.787E-03 0.505E-03 0.324E-03	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.565E 00 0.565E 00 0.565E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	0.368E 04 0.244E 02 0.299E 01 0.106E 61 0.532E 00 0.305E 00 0.184E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01 0.201E-01 0.129E-01 0.825E-02 0.529E-02 0.339E-02 0.339E-02 0.218E-02 0.140E-02 0.896E-03 0.575E-03 0.369E-03	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.508E 00 0.508E 00 0.565E 00 0.565E 00 0.563E 00	N(*E50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.104E 00 0.668E-01 0.428E-01 0.275E-01 0.176E-01 0.176E-01 0.176E-02 0.298E-02 0.191E-02 0.123E-02 0.787E-03 0.505E-03 0.324E-03 0.208E-03	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25	0.368E 04 0.244E 02 0.299E 01 0.106E 61 0.532E 00 0.305E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01 0.201E-01 0.129E-01 0.825E-02 0.529E-02 0.339E-02 0.218E-02 0.218E-02 0.140E-02 0.896E-03 0.369E-03 0.369E-03 0.237E-03	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.563E 00	N(*E50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.104E 00 0.668E-01 0.275E-01 0.176E-01 0.176E-01 0.113E-01 0.724E-02 0.298E-02 0.191E-02 0.123E-02 0.787E-03 0.324E-03 0.208E-03 0.133E-03	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.562E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	0.368E 04 0.244E 02 0.299E 01 0.106E 61 0.532E 00 0.305E 00 0.184E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01 0.201E-01 0.129E-01 0.825E-02 0.529E-02 0.339E-02 0.339E-02 0.218E-02 0.140E-02 0.896E-03 0.575E-03 0.369E-03	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.508E 00 0.508E 00 0.565E 00 0.565E 00 0.563E 00	N(*E50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.104E 00 0.668E-01 0.428E-01 0.275E-01 0.176E-01 0.176E-01 0.176E-02 0.298E-02 0.191E-02 0.123E-02 0.787E-03 0.505E-03 0.324E-03 0.208E-03	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50 5.75 6.00	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.184E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01 0.201E-01 0.129E-01 0.825E-02 0.929E-02 0.339E-02 0.140E-02 0.896E-03 0.575E-03 0.575E-03 0.369E-03 0.237E-03 0.152E-03 0.973E-04 0.624E-04	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.562E 00 0.563E 00	N(*E,.50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.165E 00 0.165E 00 0.668E-01 0.428E-01 0.176E-01 0.176E-01 0.113E-01 0.724E-02 0.465E-02 0.298E-02 0.191E-02 0.787E-03 0.505E-03 0.324E-03 0.133E-03 0.133E-03 0.854E-04 0.548E-04	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00 6.25	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.184E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01 0.201E-01 0.129E-01 0.825E-02 0.529E-02 0.339E-02 0.140E-02 0.896E-03 0.575E-03 0.369E-03 0.237E-03 0.152E-03 0.973E-04 0.624E-04	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.563E 00	N(*E50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.165E 00 0.668E-01 0.428E-01 0.176E-01 0.113E-01 0.724E-02 0.465E-02 0.298E-02 0.191E-02 0.123E-03 0.505E-03 0.324E-03 0.324E-03 0.133E-03 0.854E-04 0.548E-04 0.226E-04	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.75 6.00 6.25 6.50	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.119E 00 0.119E 01 0.491E-01 0.313E-01 0.201E-01 0.129E-01 0.825E-02 0.529E-02 0.339E-02 0.140E-02 0.896E-03 0.575E-03 0.369E-03 0.575E-03 0.369E-03 0.152E-03 0.152E-03 0.973E-04 0.624E-04 0.400E-04	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.563E 00	N(*E50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.165E 00 0.165E 00 0.166E-01 0.428E-01 0.275E-01 0.176E-01 0.113E-01 0.724E-02 0.465E-02 0.298E-02 0.191E-02 0.123E-02 0.787E-03 0.324E-03 0.324E-03 0.324E-03 0.208E-03 0.133E-03 0.854E-04 0.548E-04 0.526E-04 0.226E-04 0.145E-04	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.563E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00 6.25	0.368E 04 0.244E 02 0.299E 01 0.106E 01 0.532E 00 0.305E 00 0.184E 00 0.119E 00 0.757E-01 0.491E-01 0.313E-01 0.201E-01 0.129E-01 0.825E-02 0.529E-02 0.339E-02 0.140E-02 0.896E-03 0.575E-03 0.369E-03 0.237E-03 0.152E-03 0.973E-04 0.624E-04	EC(D) 0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.563E 00	N(*E50) 0.230E 03 0.423E 01 0.100E 01 0.473E 00 0.270E 00 0.165E 00 0.165E 00 0.668E-01 0.428E-01 0.176E-01 0.113E-01 0.724E-02 0.465E-02 0.298E-02 0.191E-02 0.123E-03 0.505E-03 0.324E-03 0.324E-03 0.133E-03 0.854E-04 0.548E-04 0.226E-04	0.626E-01 0.173E 00 0.334E 00 0.446E 00 0.508E 00 0.542E 00 0.565E 00 0.565E 00 0.563E 00

			** L=2.60 **		
NO	E	N(E,.50)	E0(D)	N(#E,.50)	E0(1)
1	c.	C.532E 64	0.564E-01	C.300E 03	0.564E-01
2	0.25	0.181E 02	0.197E 00	C.356E C1	0.1976 00
3 4	0.50 0.75	0.277E 01 0.112E 01	0.361E 00 0.445E 00	0.100E 01 0.500E 00	0.361F 00 0.445E 00
5	1.00	0.596E 00	0.449E 00	0.285E 00	0.478E 00
6	1.25	0.328E 00	G.515E 00	0.169E 00	0.515F 00
7	1.50	C.202E 00	0.515E 00	0.104E 00	0.515E 00
8	1.75	0.123E CO	0.521E 00	0.640E-61	0.521± 00
9 10	2.00 2.25	0.800E-01 0.433E-01	0.495E 00 0.552E 00	0.396E-01 0.239E-01	0.495E 00 0.552E 00
11	2.50	0.298E-01	0.510E 00	0.152E-01	0.510E 00
12	2.75	0.183F-01	0.510E 00	C.931E-02	C.510E 00
1.3	3.00	0.1125-01	0.510E 00	0.570E-02	0.510E 00
14	3.25	0.6856-02	0.510E 00	0.349E-02	0.510E 00
15 16	3.50 3.75	0.420F-02 0.257F-02	0.510E 00 0.510E 00	0.214E-02 0.131E-02	0.510E 00 0.510E 00
17	4.00	0.157E-02	0.510E 00	0.803E-03	0.510E 00
18	4.25	0.964E-03	0.510E 00	0.492E-03	0.510E 00
19	4.50	0.591E-03	0.510E 00	0.301E-03	0.510E 00
20	4.75	C.362E03	0.510E CO	0.185E-03	0.5108 00
21 22	5.00 5.25	0.222E-03 0.136E-03	0.510E 00 0.510E 00	0.113E-03 0.692E-04	0.510E 00 0.510E 00
23	5.50	0.832E-04	0.510E 00	0.424E-04	0.510E 00
24	5.75	0.509E-04	0.510E 00	0.260E-04	0.510E 00
25	6.00	0.312E-04	0.510E 00	0.159E-04	0.510E 00
26	6.25	0.191E-04	0.510E 0C	0.975E-05	0.510E 00
27 28	6.50	0.117E-04 0.717E-35	0.510E 00 0.510E 00	0.597E-05 0.366E-05	0.510E 00 0.510E 00
20 29	6.75 7.00	0.439E-05	0.510E 00	0.224E-05	0.510E 00
			** L=2.70 **		
NO	E	N(E,.50)			E0(1)
NO 1	E	N(E,.5C)	** L=2.70 **		E0(1) 0.514E-01
1 2	°. 0.25	0.7/8E 04 0.139E 02	** L=2.70 ** E0(D) 0.514E-01 C.222E 00	N(*F50) 0.400E 03 0.309E 01	0.514E-01 0.222E 00
1 2 3	0. 0.25 0.50	0.7/8E 04 0.139E 02 0.262E 01	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00	N(*F50) 0.400E 03 0.309E 01 0.100E 01	0.514E-01 0.222E 00 0.382E 00
1 2 3 4	C. 0.25 0.50 C.75	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00	N(*F50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00	0.514E-01 0.222E 00 0.382E 00 0.452E 00
1 2 3 4 5	0.25 0.50 0.75 1.00	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00	N(*F50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00
1 2 3 4	C. 0.25 0.50 C.75	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00	N(*F50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.480E 00 0.483E 00
1 2 3 4 5 6 7 8	C. 0.25 0.50 0.75 1.00 1.25 1.50 1.75	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.215E 00 0.124E 00	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.480E 00 C.483E 00 C.500E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.480E 00 0.483E 00 0.500E 00
1 2 3 4 5 6 7 8	C. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.215E 00 0.124E 00 0.772E-01	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.480E 00 C.483E 00 C.500E 00 C.487E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.480E 00 0.483E 00 0.500E 00 0.487E 00
1 2 3 4 5 6 7 8 9	C. 0.25 C.50 C.75 1.00 1.25 1.50 1.75 2.00 2.25	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 C.467E 00 C.480E 00 C.483E C0 C.500E 00 C.487E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01 0.225E-01	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.486E 00 0.483E 00 0.500E 00 0.487E 00
1 2 3 4 5 6 7 8 9 10	C. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.282E-01	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.480E 00 C.483E 00 C.500E 00 C.487E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.480E 00 0.483E 00 0.500E 00 0.487E 00
1 2 3 4 5 6 7 8 9	C. 0.25 C.50 C.75 1.00 1.25 1.50 1.75 2.00 2.25	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.480E 00 C.483E C0 C.500F 00 C.487E 00 0.497E 00 0.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01 0.225E-01 0.136E-01	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.483E 00 0.500E 00 0.487E 00 0.497E 00 0.482E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13	C. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.282E-01 0.168E-01 0.106E-01 0.595E-02	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.480E 00 C.483E 00 C.483E 00 C.487E 00 C.497E 00 C.497E 00 C.482E 00 C.482E 00 C.482E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E+01 0.25E-01 0.136E-01 0.810E-02 0.482E-02 0.287E-02	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.483E 00 0.500E 00 0.487E 00 0.487E 00 0.497E 00 0.482E 00 0.482E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14	C. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.282E-01 0.168E-01 0.106E-01 0.595E-02 0.355E-02	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.480E 00 C.483E 00 C.500E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01 0.25E-01 0.136E-01 0.810E-02 0.482E-02 0.287E-02 0.171E-02	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.483E 00 0.500E 00 0.487E 00 0.487E 00 0.497E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	C. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.282E-01 0.168E-01 0.168E-01 0.100E-01 0.595E-02 0.355E-02 0.211E-02	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.480E 00 C.483E 00 C.500E 00 C.487E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01 0.225E-01 0.136E-01 0.810E-02 0.482E-02 0.287E-02 0.171E-02 0.102E-02	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.483E 00 0.500E 00 0.487E 00 0.497E 00 0.497E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16	C. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.282E-01 0.168E-01 0.100E-01 0.595E-02 0.355E-02 0.211E-02 0.126E-02	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.480E 00 C.483E 00 C.500E 00 C.487E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01 0.25E-01 0.136E-01 0.810E-02 0.482E-02 0.287E-02 0.171E-02	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.483E 00 0.500E 00 0.487E 00 0.487E 00 0.497E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	C. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.282E-01 0.168E-01 0.168E-01 0.100E-01 0.595E-02 0.355E-02 0.211E-02	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.480E 00 C.483E 00 C.500E 00 C.487E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50)	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.483E 00 0.500E 00 0.487E 00 0.487E 00 0.487E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	C. 0.25 C.50 C.75 1.00 1.25 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.282E-01 0.168E-01 0.160E-01 0.595E-02 0.355E-02 0.211E-02 0.2126E-02 0.749E-03 0.446E-03 0.265E-03	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 C.452E 00 C.483E C0 C.483E C0 C.483E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01 0.225E-01 0.136E-01 0.810E-02 0.482E-02 0.287E-02 0.171E-02 0.102E-02 0.606E-03 0.361E-03 0.215E-03 0.128E-03	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.483E 00 0.500E 00 0.487E 00 0.487E 00 0.487E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	C. 0.25 C.50 C.75 1.00 1.25 1.50 2.25 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.282E-01 0.168E-01 0.100E-01 0.595E-02 0.355E-02 0.211E-02 0.2126E-02 0.749E-03 0.446E-03 0.265E-03 0.158E-03	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 C.452E 00 C.483E C0 C.483E C0 C.483E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01 0.225E-01 0.136E-01 0.810E-02 0.482E-02 0.287E-02 0.171E-02 0.102E-02 0.606E-03 0.361E-03 0.215E-03 0.128E-03 0.762E-04	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.487E 00 0.500E 00 0.487E 00 0.497E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	C. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.215E 00 0.124E 00 0.124E 00 0.772E-01 0.453E-01 0.168E-01 0.168E-01 0.106E-01 0.595E-02 0.355E-02 0.211E-02 0.211E-02 0.749E-03 0.446E-03 0.265E-03 0.158E-03 0.941E-04	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 C.452E 00 C.483E C0 C.483E C0 C.487E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01 0.225E-01 0.136E-01 0.810E-02 0.482E-02 0.287E-02 0.171E-02 0.102E-02 0.606E-03 0.361E-03 0.215E-03 0.128E-03 0.762E-04 0.454E-04	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.487E 00 0.487E 00 0.487E 00 0.487E 00 0.487E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	C. 0.25 C.50 C.75 1.00 1.25 1.50 2.25 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.282E-01 0.168E-01 0.100E-01 0.595E-02 0.355E-02 0.211E-02 0.2126E-02 0.749E-03 0.446E-03 0.265E-03 0.158E-03	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 C.452E 00 C.483E C0 C.483E C0 C.483E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01 0.225E-01 0.136E-01 0.810E-02 0.482E-02 0.287E-02 0.171E-02 0.102E-02 0.606E-03 0.361E-03 0.215E-03 0.128E-03 0.762E-04	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.487E 00 0.500E 00 0.487E 00 0.497E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25	C. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.75 3.00 3.25 3.50 3.75 4.00 4.55 4.50 4.75 5.00 5.75 6.00	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.124E 00 0.772E-01 0.453E-01 0.168E-01 0.168E-01 0.106E-01 0.595E-02 0.211E-02 0.126E-02 0.749E-03 0.446E-03 0.265E-03 0.158E-03 0.941E-04 0.561E-04 0.334E-04	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.480E 00 C.483E 00 C.487E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.620E-01 0.376E-01 0.136E-01 0.810E-02 0.482E-02 0.287E-02 0.171E-02 0.102E-02 0.606E-03 0.361E-03 0.215E-03 0.128E-03 0.128E-04 0.454E-04 0.959E-05	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.483E 00 0.500E 00 0.487E 00 0.487E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	C. 0.25 0.50 0.75 1.00 1.25 1.75 2.00 2.25 2.50 2.75 3.00 3.55 3.50 4.75 4.00 4.75 5.00 5.55 5.75 6.25	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.168E-01 0.168E-01 0.168E-01 0.168E-02 0.355E-02 0.211E-02 0.749E-03 0.446E-03 0.265E-03 0.158E-03 0.941E-04 0.334E-04 0.199E-04	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.483E 00 C.483E 00 C.487E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.620E-01 0.376E-01 0.136E-01 0.810E-02 0.482E-02 0.287E-02 0.171E-02 0.102E-02 0.606E-03 0.361E-03 0.215E-03 0.128E-03 0.128E-03 0.128E-04 0.454E-04 0.270E-04 0.161E-04 0.959E-05 0.571E-05	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.483E 00 0.500E 00 0.487E 00 0.487E 00 0.487E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	C. 0.25 0.50 0.75 1.00 1.25 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.75 5.00 5.25 5.50 5.75 6.25	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.168E-01 0.168E-01 0.168E-02 0.355E-02 0.211E-02 0.126E-02 0.749E-03 0.446E-03 0.265E-03 0.158E-03 0.941E-04 0.334E-04 0.199E-04 0.118E-04 0.705F-05	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 C.452E 00 C.483E 00 C.483E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.104E 00 0.620E-01 0.376E-01 0.810E-02 0.482E-02 0.482E-02 0.171E-02 0.102E-02 0.606E-03 0.361E-03 0.215E-03 0.128E-03 0.215E-04 0.454E-04 0.270E-04 0.959E-05 0.571E-05 0.340E-05	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.483E 00 0.500E 00 0.487E 00 0.487E 00 0.482E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	C. 0.25 0.50 0.75 1.00 1.25 1.75 2.00 2.25 2.50 2.75 3.00 3.55 3.50 4.75 4.00 4.75 5.00 5.55 5.75 6.25	0.7/8E 04 0.139E 02 0.262E 01 0.115E 01 0.641E 00 0.364E 00 0.215E 00 0.124E 00 0.772E-01 0.453E-01 0.168E-01 0.168E-01 0.168E-01 0.168E-02 0.355E-02 0.211E-02 0.749E-03 0.446E-03 0.265E-03 0.158E-03 0.941E-04 0.334E-04 0.199E-04	** L=2.70 ** E0(D) 0.514E-01 C.222E 00 0.382E 00 C.452E 00 0.467E 00 C.483E 00 C.483E 00 C.487E 00 C.487E 00 C.487E 00 C.482E 00	N(*E,.50) 0.400E 03 0.309E 01 0.100E 01 0.520E 00 0.299E 00 0.175E 00 0.620E-01 0.376E-01 0.136E-01 0.810E-02 0.482E-02 0.287E-02 0.171E-02 0.102E-02 0.606E-03 0.361E-03 0.215E-03 0.128E-03 0.128E-03 0.128E-04 0.454E-04 0.270E-04 0.161E-04 0.959E-05 0.571E-05	0.514E-01 0.222E 00 0.382E 00 0.452E 00 0.467E 00 0.483E 00 0.500E 00 0.487E 00 0.487E 00 0.487E 00 0.482E 00

NO E N(E, 5C) C:01 N(*E, 5C) E:C(1) 1				** L=2.80 **		
2 C.25 C.11CE 02 C.249E 00 C.273E 01 C.379E 01 C.379E 02 3 C.5C 0.255F 11 C.393E 00 C.100E C1 0.393E 00 4 C.75 C.11LE 01 C.465E 00 C.572E 0C U.465E 00 5 1.02 O.654E 00 C.472E 00 O.309E 0C 0.472E 00 6 1.25 O.36CE 00 C.472E 00 C.10RE 00 O.472E 00 7 1.50 C.229E 00 C.472E 00 C.10RE 00 O.472E 00 8 1.75 C.134E 00 C.472E 00 C.10RE 00 O.472E 00 9 2.00 C.792E-01 C.476E 00 C.376E-01 O.476E 00 10 2.25 C.468E-01 O.474E 00 C.376E-01 O.474E 00 11 2.50 O.275E-01 C.476E 00 C.376E-01 O.476E 00 12 2.75 C.163E-01 O.476E 00 C.774E-02 C.476E 00 13 3.C0 C.963E-02 C.476E 00 C.536E-02 O.476E 00 14 3.25 O.569E-02 C.476E 00 C.476E-02 C.476E 00 15 3.50 C.336E-02 C.476E 00 C.476E-02 C.476E 00 16 3.75 C.199E-02 C.476E 00 C.476E-03 O.476E 00 17 4.C0 D.118E-02 O.476E 00 C.535E-03 O.476E 00 18 4.25 O.695E-03 C.476E 00 C.535E-03 O.476E 00 18 4.25 O.695E-03 C.476E 00 C.539E-03 O.476E 00 19 4.50 C.411E-03 O.476E 00 C.539E-03 O.476E 00 20 4.75 C.243E-03 C.476E 00 C.539E-03 O.476E 00 21 5.C0 D.144E-03 O.476E 00 C.539E-03 O.476E 00 22 5.25 O.889E-04 C.476E 00 C.595E-03 O.476E 00 23 5.50 C.502E-04 C.476E 00 C.116E-03 C.476E 00 24 5.75 C.243E-03 C.476E 00 C.116E-03 O.476E 00 25 5.25 C.889E-04 C.476E 00 C.116E-03 O.476E 00 26 6.25 C.104E-04 C.476E 00 C.116E-03 O.476E 00 27 6.50 C.502E-04 C.476E 00 C.116E-03 C.476E 00 28 6.75 O.362E-04 C.476E 00 C.116E-03 C.476E 00 29 7.00 C.214E-05 C.476E 00 C.59E-05 O.476E 00 29 7.00 C.214E-05 C.476E 00 C.59E-05 O.476E 00 20 6.25 C.886E 01 C.476E 00 C.59E-05 O.476E 00 20 6.25 C.886E 01 C.476E 00 C.59E-05 O.476E 00 21 5.C0 D.144E-03 C.476E 00 C.59E-05 O.476E 00 22 5.C0 D.144E-05 C.476E 00 C.59E-05 O.476E 00 23 5.50 O.502E-04 C.476E 00 C.59E-05 O.476E 00 24 5.75 C.29FE-04 C.476E 00 C.59E-05 O.476E 00 25 6.C0 C.175E-06 C.476E 00 C.59E-05 O.476E 00 26 6.25 C.104E-06 C.476E 00 C.59E-05 O.476E 00 27 6.50 O.69E-05 C.476E 00 C.59E-05 O.476E 00 28 6.75 O.362E-06 C.476E 00 C.59E-05 O.476E 00 29 7.00 C.214E-05 C.476E 00 C.59E-05 O.476E 00 29 7.00 C.214E-05 C.476E 00 C.59E-05 O.476E 00 20 6 1.25 C.49E-06 O.479E 00 C.59E-05 O.476	NO	£	N(E,.50)	ED(D)	N(*E,.5C)	E0(1)
2 C.25 C.11CE 02 C.249E 00 C.273E 01 C.379E 01 C.379E 02 3 C.5C 0.255F 11 C.393E 00 C.100E C1 0.393E 00 4 C.75 C.11LE 01 C.465E 00 C.572E 0C U.465E 00 5 1.02 O.654E 00 C.472E 00 O.309E 0C 0.472E 00 6 1.25 O.36CE 00 C.472E 00 C.10RE 00 O.472E 00 7 1.50 C.229E 00 C.472E 00 C.10RE 00 O.472E 00 8 1.75 C.134E 00 C.472E 00 C.10RE 00 O.472E 00 9 2.00 C.792E-01 C.476E 00 C.376E-01 O.476E 00 10 2.25 C.468E-01 O.474E 00 C.376E-01 O.474E 00 11 2.50 O.275E-01 C.476E 00 C.376E-01 O.476E 00 12 2.75 C.163E-01 O.476E 00 C.774E-02 C.476E 00 13 3.C0 C.963E-02 C.476E 00 C.536E-02 O.476E 00 14 3.25 O.569E-02 C.476E 00 C.476E-02 C.476E 00 15 3.50 C.336E-02 C.476E 00 C.476E-02 C.476E 00 16 3.75 C.199E-02 C.476E 00 C.476E-03 O.476E 00 17 4.C0 D.118E-02 O.476E 00 C.535E-03 O.476E 00 18 4.25 O.695E-03 C.476E 00 C.535E-03 O.476E 00 18 4.25 O.695E-03 C.476E 00 C.539E-03 O.476E 00 19 4.50 C.411E-03 O.476E 00 C.539E-03 O.476E 00 20 4.75 C.243E-03 C.476E 00 C.539E-03 O.476E 00 21 5.C0 D.144E-03 O.476E 00 C.539E-03 O.476E 00 22 5.25 O.889E-04 C.476E 00 C.595E-03 O.476E 00 23 5.50 C.502E-04 C.476E 00 C.116E-03 C.476E 00 24 5.75 C.243E-03 C.476E 00 C.116E-03 O.476E 00 25 5.25 C.889E-04 C.476E 00 C.116E-03 O.476E 00 26 6.25 C.104E-04 C.476E 00 C.116E-03 O.476E 00 27 6.50 C.502E-04 C.476E 00 C.116E-03 C.476E 00 28 6.75 O.362E-04 C.476E 00 C.116E-03 C.476E 00 29 7.00 C.214E-05 C.476E 00 C.59E-05 O.476E 00 29 7.00 C.214E-05 C.476E 00 C.59E-05 O.476E 00 20 6.25 C.886E 01 C.476E 00 C.59E-05 O.476E 00 20 6.25 C.886E 01 C.476E 00 C.59E-05 O.476E 00 21 5.C0 D.144E-03 C.476E 00 C.59E-05 O.476E 00 22 5.C0 D.144E-05 C.476E 00 C.59E-05 O.476E 00 23 5.50 O.502E-04 C.476E 00 C.59E-05 O.476E 00 24 5.75 C.29FE-04 C.476E 00 C.59E-05 O.476E 00 25 6.C0 C.175E-06 C.476E 00 C.59E-05 O.476E 00 26 6.25 C.104E-06 C.476E 00 C.59E-05 O.476E 00 27 6.50 O.69E-05 C.476E 00 C.59E-05 O.476E 00 28 6.75 O.362E-06 C.476E 00 C.59E-05 O.476E 00 29 7.00 C.214E-05 C.476E 00 C.59E-05 O.476E 00 29 7.00 C.214E-05 C.476E 00 C.59E-05 O.476E 00 20 6 1.25 C.49E-06 O.479E 00 C.59E-05 O.476	1	n.	0.102E 05	0.4826-01	€.490E €3	0.482E-01
4 C.75 C.114E 01 C.465E 00 C.592E CC U.465E 00 5 1.00 C.654E 00 C.472E CD C.309E CC U.472E 00 6 1.25 C.308CE CD C.472E 00 C.10RE 00 O.472E 00 8 1.75 C.134E 00 C.472E 00 C.10RE 00 O.472E 00 8 1.75 C.134E 00 C.472E 00 C.10RE 00 O.472E 00 9 2.00 C.792E-C1 C.474E 00 C.376E-C1 O.474E 00 10 2.25 C.468E-D1 C.474E 00 C.376E-C1 O.474E 00 11 2.50 C.278E-D1 C.474E 00 C.376E-C1 O.474E 00 12 2.75 C.163E-D1 O.476E 00 C.774E-D2 O.476E 00 12 2.75 C.163E-D1 O.476E 00 C.774E-D2 O.476E 00 13 3.C0 C.963E-C2 C.476E 00 C.475E-C2 O.476E 00 14 3.25 C.569E-C2 U.476E 00 C.475E-C2 O.476E 00 15 3.50 C.336E-D2 C.476E 00 C.475E-C2 O.476E 00 16 3.75 C.199E-D2 C.476E 00 C.945E-C3 O.476E 00 17 4.C0 D.118E-C2 O.476E 00 C.959E-O3 O.476E 00 18 4.25 D.695E-D3 C.476E 00 C.959E-O3 O.476E 00 18 4.25 D.695E-D3 C.476E 00 C.936E-C3 O.476E 00 19 4.50 C.411E-O3 O.476E 00 C.938E-O3 O.476E 00 20 4.75 C.243E-O3 C.476E 00 C.938E-O3 O.476E 00 21 5.00 D.411E-O3 O.476E 00 C.938E-O3 O.476E 00 22 5.25 D.849E-O4 C.476E 00 C.938E-O3 O.476E 00 23 5.50 C.502E-O4 C.476E 00 C.938E-O3 O.476E 00 24 5.75 C.297E-C4 C.476E 00 C.938E-O3 O.476E 00 25 6.CC C.175E-O4 C.476E 00 C.638E-O4 C.476E 00 26 6.25 C.104E-O4 C.476E 00 C.638E-O4 C.476E 00 27 6.50 C.638E-O3 C.476E 00 C.638E-O4 C.476E 00 28 6.75 D.362E-O2 C.476E 00 C.638E-O4 C.476E 00 29 7.00 C.214E-O5 C.476E 00 C.638E-O5 C.476E 00 29 2.00 C.658E-O1 C.476E 00 C.638E-O1 C.476E 00 29 2.00 C.658E-O1 C.476E 00 C.668E-O1 C.476E 00 29 2.00 C.668E-O1 C.476E 00 C.676E-O1 C.476E 00 29 2.00 C.668E-O1 C.476E 00 C.668E-						
5 1.0C	3					
6 1.25 0.38CE CO C.479E OC C.10RE OC 0.477E OO 8 1.75 0.138E OC 0.474E OC						
7 1.50						
8 1.75						
9 2.00						
11 2.50 0.275E-01 C.476E 0C C.131E-01 O.476E 0D 12 2.75 0.163E-01 0.476E 0D C.774E-02 O.476E 0D 13 3.C0 0.963E-02 C.476E 0D C.476E-02 0.476E 0D 15 3.50 0.536E-02 C.476E 0D C.427E-02 0.476E 0D 16 3.75 0.199E-02 C.476E 0C C.971E-02 0.476E 0D 17 4.C0 0.118E-02 0.476E 0C C.966E-03 0.476E 0D 18 4.25 0.695E-03 C.476E 0C C.966E-03 0.476E 0D 18 4.25 0.695E-03 C.476E 0C 0.559E-03 0.476E 0D 19 4.50 0.411E-03 0.476E 0D 0.195E-03 0.476E 0D 20 4.75 0.243E-03 C.476E 0C 0.331E-03 0.476E 0D 21 5.00 0.414E-03 0.476E 0D 0.195E-03 0.476E 0D 22 5.25 0.849E-04 0.476E 0D 0.683E-04 0.476E 0D 23 5.50 0.502E-04 0.476E 0D 0.683E-04 0.476E 0D 24 5.75 0.297E-04 0.476E 0D 0.468E-04 0.476E 0D 25 6.00 0.115E-04 0.476E 0D 0.468E-05 0.476E 0D 26 6.25 0.104E-04 0.476E 0D 0.498E-05 0.476E 0D 27 6.50 0.613E-05 0.476E 0D 0.493E-05 0.476E 0D 28 6.75 0.362E-05 0.476E 0D 0.493E-05 0.476E 0D 29 7.00 0.214E-05 0.476E 0D 0.495E-05 0.476E 0D 20 0.476E 0D 0.476E 0D 0.495E-05 0.476E 0D 21 0.25 0.886E 01 0.278E 0D 0.102E-05 0.476E 0D 29 7.00 0.214E-05 0.476E 0D 0.102E-05 0.476E 0D 20 0.923E-05 0.476E 0D 0.102E-05 0.476E 0D 20 0.25 0.886E 01 0.278E 0D 0.100E 01 0.409E 0D 20 0.923E-01 0.456E 0D 0.100E 01 0.409E 0D 21 0.25 0.492E 0D 0.472E 0D 0.100E 01 0.409E 0D 22 0.25 0.886E 01 0.278E 0D 0.100E 01 0.409E 0D 22 0.25 0.498E-01 0.478E 0D 0.138E-01 0.479E 0D 22 0.25 0.498E-01 0.478E 0D 0.138E-01 0.479E 0D 22 0.25 0.498E-01 0.478E 0D 0.138E-01 0.479E 0D 22 0.00 0.923E-01 0.479E 0D 0.161E-01 0.479E 0D 22 0.00 0.923E-01 0.479E 0D 0.415E-01 0.479E 0D 22 0.00 0.923E-01 0.479E 0D 0.415E-01 0.479E 0D 22 0.479E 0D 0.479E 0D 0.479E 0D 0.479E 0D 23 5.50 0.498E-04 0.479E 0D 0.161E-03 0.479E 0D 24 5.75 0.135E-02 0.479E 0D 0.161E-03 0.479E 0D 25 0.498E-04 0.479E 0D 0.160E-04 0.479E 0D 26 6.25 0.198E-04 0.479E 0D 0.160E-04 0.479E 0D 26 6.25 0.198E-04 0.479E 0D 0.160E-04 0.479E 0D 26 6.25 0.414E-05 0.479E 0D 0.160E-05 0.479E 0D 26 6.50						0.474E 00
12	10	2.25	C.468E-01			
13 3.CO						
14 3.25 0.569E-02 0.476E 00 C.271E-02 0.476E 00 15 3.50 0.336E-02 C.476E 00 0.160E-02 0.476E 00 16 3.75 0.199E-02 0.476E 00 0.946E-03 0.476E 00 17 4.00 9.118E-02 0.476E 00 0.595E-03 0.476E 00 18 4.25 0.695E-03 0.476E 00 0.331E-03 0.476E 00 19 4.50 0.411E-03 0.476E 00 0.195E-03 0.476E 00 20 4.75 0.243E-03 0.476E 00 0.195E-03 0.476E 00 21 5.00 0.144E-03 0.476E 00 0.195E-03 0.476E 00 22 5.25 0.849E-04 0.476E 00 0.683E-04 0.476E 00 23 5.50 0.502E-04 0.476E 00 0.683E-04 0.476E 00 24 5.75 0.297E-04 0.476E 00 0.404E-04 0.476E 00 25 6.00 0.15E-04 0.476E 00 0.403E-05 0.476E 00 26 6.25 0.104E-04 0.476E 00 0.493E-05 0.476E 00 27 6.50 0.613E-05 0.476E 00 0.292E-05 0.476E 00 28 6.75 0.362E-05 0.476E 00 0.292E-05 0.476E 00 29 7.00 0.214E-05 0.476E 00 0.292E-05 0.476E 00 29 7.00 0.214E-05 0.476E 00 0.292E-05 0.476E 00 29 7.00 0.214E-06 0.476E 00 0.292E-05 0.476E 00 29 7.00 0.214E-06 0.476E 00 0.292E-05 0.476E 00 20 0.476E 00 0.476E 00 0.292E-05 0.476E 00 21 0.25 0.886E 01 0.278E 00 0.102E-05 0.476E 00 20 0.476E 00 0.476E 00 0.102E-05 0.476E 00 21 0.25 0.886E 01 0.278E 00 0.100E 01 0.278E 00 21 0.25 0.886E 01 0.278E 00 0.246E 01 0.278E 00 21 0.25 0.432E 00 0.465E 00 0.100E 01 0.469E 00 22 0.25 0.432E 00 0.459E 00 0.100E 01 0.469E 00 23 0.50 0.294E 01 0.465E 00 0.136E 00 0.469E 00 24 0.75 0.117E 01 0.465E 00 0.136E 00 0.469E 00 25 0.432E 00 0.454E 00 0.100E 01 0.278E 00 26 1.25 0.432E 00 0.454E 00 0.196E 00 0.469E 00 27 0.100 0.93E-01 0.450E 00 0.415E-01 0.479E 00 28 1.75 0.125E 00 0.479E 00 0.415E-01 0.479E 00 29 2.00 0.923E-01 0.450E 00 0.479E 00 0.479E 00 20 0.479E 00 0.479E 00 0.176E-02 0.479E 00 21 2.75 0.175E-01 0.479E 00 0.175E-02 0.479E 00 22 5.25 0.938E-01 0.479E 00 0.175E-02 0.479E 00 21 5.50 0.458E-03 0.479E 00 0.175E-03 0.479E 00 22 5.25 0.938E-04 0.479E 00 0.160E-04 0.479E 00 24 5.75 0.15E-02 0.479E 00 0.160E-04 0.479E 00 25 6.600 0.18E-03 0.479E 00 0.455E-04 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.160E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.160E-05 0.479E 00 27 6.50 0.18E-04 0.479E 00 0.160E-05 0.479E 00 28 6.						
15 3,50 0,336E-02 C.476E 00 C.946E-03 0.476E 00 17 4.C0 0,118E-C2 0.476E 00 C.946E-03 0.476E 00 17 4.C0 0,118E-C2 0.476E 00 C.946E-03 0.476E 00 18 4.25 0.695E-03 C.476E 00 0.595E-03 0.476E 00 19 4.50 0.411E-03 0.476E 00 0.195E-03 0.476E 00 20 4.75 0.243E-03 C.476E 00 0.195E-03 0.476E 00 21 5.C0 0.144E-03 0.476E 00 0.195E-03 0.476E 00 22 5.25 0.849E-04 0.476E 00 0.683E-04 0.476E 00 22 5.25 0.849E-04 0.476E 00 0.463E-04 0.476E 00 23 5.50 0.502E-04 0.476E 00 0.463E-04 0.476E 00 24 5.75 6.297E-04 0.476E 00 0.493E-05 0.476E 00 25 6.C0 0.175E-04 0.476E 00 0.493E-05 0.476E 00 26 6.25 0.104E-04 0.476E 00 0.493E-05 0.476E 00 27 6.50 0.613E-05 0.476E 00 0.292E-05 0.476E 00 28 6.75 0.362E-05 0.476E 00 0.292E-05 0.476E 00 29 7.00 0.214E-05 0.476E 00 0.102E-05 0.476E 00 29 7.00 0.214E-05 0.476E 00 0.102E-05 0.476E 00 20 0.25 0.886E 01 0.278E 00 0.102E-05 0.476E 00 3 0.50 0.244E 01 0.465E 00 0.102E-05 0.476E 00 4 0.75 0.117E 01 0.465E 00 0.543E 00 0.456E 00 5 1.00 0.610E 00 0.520E 00 0.109E 01 0.469E 00 5 1.00 0.610E 00 0.520E 00 0.317E 00 0.456E 00 6 1.25 0.432E 00 0.476E 00 0.196E 01 0.456E 00 6 1.25 0.432E 00 0.456E 00 0.196E 01 0.456E 00 7 1.50 0.246E 01 0.456E 00 0.196E 01 0.456E 00 11 2.50 0.496E 01 0.456E 00 0.196E 01 0.456E 00 11 2.50 0.496E 01 0.456E 00 0.196E 01 0.456E 00 11 2.50 0.496E 01 0.456E 00 0.196E 01 0.456E 00 11 2.50 0.496E-01 0.450E 00 0.196E 01 0.456E 00 11 2.50 0.496E-01 0.450E 00 0.196E 01 0.456E 00 11 2.50 0.496E-01 0.450E 00 0.118E 00 0.476E 00 11 2.50 0.296E-01 0.450E 00 0.196E 01 0.459E 00 11 2.50 0.296E-01 0.450E 00 0.196E-01 0.459E 00 11 2.50 0.296E-01 0.479E 00 0.106E-01 0.479E 00 12 2.75 0.175E-01 0.479E 00 0.106E-01 0.479E 00 13 3.00 0.106E-01 0.479E 00 0.107E-03 0.479E 00 14 3.25 0.156E-02 0.479E 00 0.127E-03 0.479E 00 15 3.50 0.365E-02 0.479E 00 0.127E-03 0.479E 00 24 4.75 0.269E-03 0.479E 00 0.127E-03 0.479E 00 25 5.25 0.948E-04 0.479E 00 0.156E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.156E-05 0.479E 00 27 5.50 0.698E-03 0.479E 00 0.156E-05 0.479E 00 28 6.75 0.498E-04 0.479E 00 0.566E-05						
16 3.75 C.199E-02 C.476E 00 C.946E-03 0.476E 00 17 4.C0 9.118E-02 0.476E 00 0.559E-03 0.476E 00 18 4.25 0.695E-U3 0.476E 00 0.331E-03 0.476E 00 19 4.50 0.411E-03 0.476E 00 0.195E-03 0.476E 00 20 4.75 0.243E-03 0.476E 00 0.195E-03 0.476E 00 21 5.00 0.144E-03 0.476E 00 0.683E-04 0.476E 00 22 5.25 0.849E-04 0.476E 00 0.683E-04 0.476E 00 23 5.50 0.502E-04 0.476E 00 0.464E-04 0.476E 00 24 5.75 0.297E-04 0.476E 00 0.494E-03 0.476E 00 25 6.CC 0.175E-04 0.476E 00 0.493E-05 0.476E 00 26 6.25 0.104E-03 0.476E 00 0.493E-05 0.476E 00 27 6.50 0.613E-05 0.476E 00 0.292E-05 0.476E 00 28 6.75 0.362E-05 0.476E 00 0.292E-05 0.476E 00 29 7.00 0.214E-05 0.476E 00 0.172E-05 0.476E 00 29 7.00 0.214E-05 0.476E 00 0.292E-05 0.476E 00 29 7.00 0.214E-05 0.476E 00 0.172E-05 0.476E 00 20 0.476E 00 0.476E 00 0.476E 00 0.476E 00 21 0.476E 00 0.476E 00 0.476E 00 0.476E 00 22 0.25 0.886E 01 0.278E 00 0.476E 01 0.478E 00 23 0.50 0.244E 01 0.465E 00 0.246E 01 0.278E 00 24 0.75 0.117E 01 0.465E 00 0.317E 00 0.469E 00 25 0.402E 00 0.472E 00 0.454E 00 0.454E 00 26 0.240E 00 0.472E 00 0.454E 00 0.454E 00 27 1.50 0.240E 00 0.472E 00 0.113E 00 0.454E 00 28 1.75 0.125E 00 0.456E 00 0.317E 00 0.454E 00 29 2.00 0.923E-01 0.450E 00 0.418E-01 0.479E 00 29 2.00 0.923E-01 0.450E 00 0.418E-01 0.479E 00 20 0.25 0.496E-01 0.479E 00 0.113E 00 0.454E 00 21 2.25 0.498E-01 0.479E 00 0.113E 00 0.454E 00 22 0.25 0.498E-01 0.479E 00 0.113E 00 0.459E 00 23 0.294E-01 0.479E 00 0.415E-01 0.479E 00 24 0.75 0.117E 01 0.469E 00 0.106E 01 0.479E 00 25 0.476E 00 0.479E 00 0.479E 00 0.479E 00 26 0.256 0.456E-03 0.479E 00 0.479E 00 0.479E 00 27 0.00 0.456E-03 0.479E 00 0.479E 00 0.479E 00 28 0.75 0.175E-01 0.479E 00 0.479E 00 0.479E 00 29 2.00 0.923E-01 0.479E 00 0.479E 00 0.479E 00 20 0.479E 00 0.479E 00 0.479E 00 0.479E 00 21 5.00 0.160E-03 0.479E 00 0.456E-04 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.456E-04 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.456E-05 0.479E 00 23 5.50 0.468E-05 0.479E 00 0.456E-05 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.456E-05 0.479E 00 25 6.00 0.479E-0						
17						
10 4.50						
20 4.75			0.695E-03	G.476E 00	0.331E-03	
21 5.00 0.144E-03 C.476E 00 0.683E-04 0.476E 00 22 5.25 0.849E-04 0.476E 00 0.404E-04 0.476E 00 23 5.50 0.502E-04 0.476E 00 0.239E-04 0.476E 00 24 5.75 0.297E-04 0.476E 00 0.141E-04 0.476E 00 25 6.00 0.175E-04 0.476E 00 0.141E-04 0.476E 00 26 6.25 0.104E-04 0.476E 00 0.439E-05 0.476E 00 27 6.50 0.613E-05 0.476E 00 0.292E-05 0.476E 00 28 6.75 0.362E-05 0.476E 00 0.292E-05 0.476E 00 29 7.00 0.214E-05 0.476E 00 0.292E-05 0.476E 00 29 7.00 0.214E-05 0.476E 00 0.172E-05 0.476E 00 29 7.00 0.214E-05 0.476E 00 0.102E-05 0.476E 00 20 0.25 0.886E 01 0.278E 00 0.246E 01 0.278E 00 3 0.50 0.244E 01 0.469E 00 0.100E 01 0.469E 00 3 0.50 0.244E 01 0.469E 00 0.100E 01 0.469E 00 5 1.00 0.610E 00 0.520E 00 0.317E 00 0.465E 00 5 1.00 0.610E 00 0.520E 00 0.317E 00 0.456E 00 6 1.25 0.432E 00 0.454E 00 0.196E 00 0.454E 00 7 1.50 0.432E 00 0.454E 00 0.196E 00 0.454E 00 9 2.00 0.923E-01 0.450E 00 0.415E-01 0.450E 00 10 2.25 0.498E-01 0.479E 00 0.415E-01 0.479E 00 11 2.50 0.294E-01 0.479E 00 0.415E-01 0.479E 00 12 2.75 0.175E-01 0.479E 00 0.141E-01 0.479E 00 13 3.00 0.104E-01 0.479E 00 0.141E-01 0.479E 00 14 3.25 0.615E-02 0.479E 00 0.196E-02 0.479E 00 15 3.50 0.365E-02 0.479E 00 0.197E-02 0.479E 00 16 3.75 0.217E-02 0.479E 00 0.197E-02 0.479E 00 17 4.00 0.129E-02 0.479E 00 0.106E-03 0.479E 00 20 4.75 0.34E-04 0.479E 00 0.106E-03 0.479E 00 21 5.00 0.498E-04 0.479E 00 0.467E-04 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.456E-04 0.479E 00 23 5.50 0.662E-04 0.479E 00 0.466E-04 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.466E-05 0.479E 00 25 6.00 0.948E-04 0.479E 00 0.466E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.765E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.765E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.535E-05 0.479E 00 28 6.75 0.414E-05 0.6479E 00 0.765E-05 0.479E 00 28 6.75 0.414E-05 0.479E 00 0.535E-05						
22 5.25						
23						
24 5.75						
25 6.0C						
26 6.25			-			0.476E 00
28 6.75	26					
NO E N(E 1.5C) C.476E 00 C.102E-C5 C.476E 00						
** L=2.90 ** ** L=2.90 ** ** L=2.90 ** ** E(0) N(*E, 50) EC(1) 1 C. C.975E 04 C.477E-01 C.465E 03 0.477E-01 2 0.25 C.886E 01 0.278E 00 C.246E 01 0.278E 00 3 0.50 C.244E 01 C.409E 00 0.100E 01 0.409E 00 4 0.75 0.117E 01 0.465E 00 0.543E 00 0.465E 00 5 1.00 0.610E 00 0.520E 00 C.317E 00 0.520E 00 6 1.25 C.432E 00 0.454E 00 0.196E 00 0.454E 00 7 1.50 C.246E 01 0.472E 00 0.113E 00 0.472E 00 8 1.75 0.125E C0 0.530E 00 0.665E-01 0.530E 00 9 2.00 0.923E-01 0.450E 00 0.415E-01 0.450E 00 10 2.25 0.498E-01 0.478E 00 0.238E-01 0.479E 00 11 2.50 0.294E-01 0.479E 00 0.141E-01 0.479E 00 12 2.75 0.175E-01 0.479E 00 0.837E-02 0.479E 00 13 3.00 0.104E-01 0.479E 00 0.837E-02 0.479E 00 14 3.25 0.615E-02 0.479E 00 0.295E-02 0.479E 00 15 3.50 0.365E-02 0.479E 00 0.175E-02 0.479E 00 16 3.75 0.217E-02 0.479E 00 0.104E-02 0.479E 00 16 3.75 0.217E-02 0.479E 00 0.104E-02 0.479E 00 17 4.00 0.129E-02 C.479E 00 0.617E-03 0.479E 00 18 4.25 0.764E-63 C.479E 00 0.366E-03 0.479E 00 20 4.75 0.269E-03 0.479E 00 0.217E-C3 0.479E 00 21 5.00 0.453E-03 0.479E 00 0.217E-C3 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.217E-C3 0.479E 00 23 5.50 0.562E-04 0.479E 00 0.765E-04 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.765E-04 0.479E 00 25 6.00 0.198E-04 0.479E 00 0.765E-04 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.950E-05 0.479E 00 26 6.55 0.118E-04 0.479E 00 0.950E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.950E-05 0.479E 00 28 6.75 0.414E-05 0.479E 00 0.5335E-05 0.479E 00						
NO E N(E, 5C) EC(0) N(*E, 5C) EC(1)	29	7.00	U.214t=UD	0.4/66 00	0.1026-03	0.4 (OE 00
1 C. C.975E 04 C.477E-01 C.465E 03 O.477E-01 2 O.25 C.886E 01 O.278E 00 C.246E 01 O.278E 00 3 C.50 C.244E 01 C.409E 00 O.100E 01 O.409E 00 4 O.75 O.117E 01 O.465E 00 O.543E 00 O.465E 00 5 1.00 O.610E 00 O.520E 00 C.317E 00 O.520E 00 6 1.25 C.432E 00 O.454E 00 O.196E 00 O.454E 00 7 1.50 C.240E 00 O.472E 00 O.113E 00 O.472E 00 8 1.75 O.125E CO O.530E 00 O.665E-01 O.530E 00 9 2.00 O.923E-01 O.450E 00 O.415E-01 C.450E 00 10 2.25 C.498E-01 O.479E 00 O.238E-01 C.478E 00 11 2.50 O.294E-01 O.479E 00 O.38TE-02 O.479E 00 12 2.75 O.175E-01 O.479E 00 O.837E-02 O.479E 00 13 3.00 O.104E-01 O.479E 00 O.837E-02 O.479E 00 14 3.25 C.615E-02 C.479E 00 O.295E-02 O.479E 00 15 3.50 O.365E-02 O.479E 00 C.175E-02 O.479E 00 16 3.75 O.217E-02 O.479E 00 O.104E-02 O.479E 00 17 4.00 O.129E-02 C.479E 00 O.104E-02 O.479E 00 18 4.25 O.764E-03 O.479E 00 O.104E-02 O.479E 00 19 4.50 O.453E-03 O.479E 00 O.104E-02 O.479E 00 19 4.50 O.453E-03 O.479E 00 O.217E-03 O.479E 00 20 4.75 O.269E-03 O.479E 00 O.217E-03 O.479E 00 21 5.00 O.160E-03 O.479E 00 O.217E-03 O.479E 00 22 5.25 O.948E-04 O.479E 00 O.129E-03 O.479E 00 23 5.50 O.365E-04 O.479E 00 O.129E-03 O.479E 00 24 5.75 O.334E-04 O.479E 00 O.129E-03 O.479E 00 25 6.00 O.198E-04 O.479E 00 O.765E-04 O.479E 00 26 6.25 O.118E-04 O.479E 00 O.950E-05 O.479E 00 27 6.50 O.698E-05 O.479E 00 O.950E-05 O.479E 00 28 6.75 O.414E-05 O.479E 00 C.335E-05 O.479E 00				1 - 2 00		
2	NΩ	E	N(E. 50)		•	FC(1)
3	NO		N(E , .50)		•	EC(1)
4 0.75 0.117E 01 0.465E 00 0.543E 00 0.465E 00 5 1.00 0.610E 00 0.520E 00 0.317E 00 0.520E 00 6 1.25 0.432E 00 0.454E 00 0.196E 00 0.454E 00 7 1.50 0.240E 00 0.472E 00 0.113E 00 0.472E 00 8 1.75 0.125E 00 0.530E 00 0.665E-01 0.530E 00 9 2.00 0.923E-01 0.450E 00 0.415E-01 0.450E 00 10 2.25 0.498E-01 0.478E 00 0.238E-01 0.478E 00 11 2.50 0.294E-01 0.479E 00 0.141E-01 0.479E 00 12 2.75 0.175E-01 0.479E 00 0.837E-02 0.479E 00 13 3.00 0.104E-01 0.479E 00 0.497E-02 0.479E 00 14 3.25 0.615E-02 0.479E 00 0.295E-02 0.479E 00 15 3.50 0.365E-02 0.479E 00 0.104E-02 0.479E 00 17 4.00 0.129E-02 0.479E 00 0.617E-03 0.479E 00	1	€.	0.975E 04	EC(D) C.477E-01	N(#E, \$50) 0.465E 03	0.477E-01
5 1.00 0.610E 00 0.520E 00 0.317E 00 0.520E 00 6 1.25 0.432E 00 0.454E 00 0.196E 00 0.454E 00 7 1.50 C.240E 00 0.472E 00 0.113E 00 0.472E 00 8 1.75 0.125E C0 0.530E 00 0.665E-01 0.530E 00 9 2.00 0.923E-01 0.450E 00 0.415E-01 0.450E 00 10 2.25 0.498E-01 0.478E 00 0.238E-01 0.478E 00 11 2.50 0.294E-01 0.479E 00 0.141E-01 0.479E 00 12 2.75 0.175E-01 0.479E 00 0.837E-02 0.479E 00 13 3.00 0.104E-01 0.479E 00 0.837E-02 0.479E 00 14 3.25 0.615E-02 0.479E 00 0.295E-02 0.479E 00 15 3.50 0.365E-02 0.479E 00 0.175E-02 0.479E 00 16 3.75 0.217E-02 0.479E 00 0.104E-02 0.479E 00 17 4.00 0.129E-02 0.479E 00 0.104E-02 0.479E 00 18 4.25 0.764E-63 0.479E 00 0.617E-03 0.479E 00 19 4.50 0.453E-03 0.479E 00 0.217E-03 0.479E 00 20 4.75 0.269E-03 0.479E 00 0.129E-03 0.479E 00 21 5.00 0.160E-03 0.479E 00 0.129E-03 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.765E-04 0.479E 00 23 5.50 0.562E-04 0.479E 00 0.454E-04 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.765E-04 0.479E 00 25 6.00 0.198E-04 0.479E 00 0.564E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.950E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.536E-05 0.479E 00 28 6.75 0.414E-05 0.479E 00 0.535E-05 0.479E 00	1 2	0. 0.25	0.975E 04 0.886E 01	EC(D) C.477E-01 O.278E 00	N(#E, 50) 	0.477E-01 0.278E 00
6 1.25	1 2 3	0. 0.25 0.50	0.975E 04 0.886E 01 0.244E 01	EC(D) C.477E-01 0.278E 00 C.409E 00	N(*E, .50) 0.465E 03 0.246E 01 0.100E 01	0.477E-01 0.278E 00 0.409E 00
7 1.50 C.240E 00 0.472E 00 0.113E 00 0.472E 00 8 1.75 0.125E C0 0.530E 00 0.665E-C1 0.530E 00 9 2.00 0.923E-01 0.450E 00 0.415E-01 C.450E 00 10 2.25 0.498E-01 0.478E 00 0.238E-01 0.478E 00 11 2.50 0.294E-01 0.479E 00 0.141E-01 0.479E 00 12 2.75 0.175E-01 0.479E 00 0.837E-02 0.479E 00 13 3.00 0.104E-01 0.479E 00 0.837E-02 0.479E 00 14 3.25 0.615E-02 0.479E 00 0.295E-02 0.479E 00 15 3.50 0.365E-02 0.479E 00 0.175E-02 0.479E 00 16 3.75 0.217E-02 0.479E 00 0.104E-02 0.479E 00 17 4.00 0.129E-02 0.479E 00 0.617E-03 0.479E 00 18 4.25 0.764E-03 0.479E 00 0.366E-03 0.479E 00 20 4.75 0.269E-03 0.479E 00 0.129E-03 0.479E 00 </td <td>1 2 3 4</td> <td>0. 0.25 0.50 0.75</td> <td>0.975E 04 0.886E 01 0.244E 01 0.117E 01</td> <td>EC(D) C.477E-01 0.278E 00 C.409E 00 0.465E 00</td> <td>N(*E, 50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00</td> <td>0.477E-01 0.278E 00 0.409E 00 0.465E 00</td>	1 2 3 4	0. 0.25 0.50 0.75	0.975E 04 0.886E 01 0.244E 01 0.117E 01	EC(D) C.477E-01 0.278E 00 C.409E 00 0.465E 00	N(*E, 50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00	0.477E-01 0.278E 00 0.409E 00 0.465E 00
9 2.00 0.923E-01 0.450E 00 0.415E-01 C.450E 0C 10 2.25 0.498E-01 0.478E 00 0.238E-01 0.478E 00 11 2.50 0.294E-01 0.479E 00 0.141E-01 0.479E 00 12 2.75 0.175E-01 0.479E 00 0.837E-02 0.479E 00 13 3.0C 0.104E-01 0.479E 00 0.497E-02 0.479E 00 14 3.25 0.615E-02 0.479E 00 0.295E-02 0.479E 00 15 3.50 0.365E-02 0.479E 00 0.175E-02 0.479E 00 16 3.75 0.217E-02 0.479E 00 0.104E-02 0.479E 00 17 4.00 0.129E-02 0.479E 00 0.617E-03 0.479E 00 18 4.25 0.764E-03 0.479E 00 0.617E-03 0.479E 00 19 4.50 0.453E-03 0.479E 00 0.217E-03 0.479E 00 20 4.75 0.269E-03 0.479E 00 0.129E-03 0.479E 00 21 5.00 0.160E-03 0.479E 00 0.129E-03 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.765E-04 0.479E 00 23 5.50 0.562E-04 0.479E 00 0.270E-04 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.950E-05 0.479E 00 25 6.00 0.198E-04 0.479E 00 0.950E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.9564E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.335E-05 0.479E 00	1 2 3 4 5	0. 0.25 0.50 0.75 1.00	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00	EC(D) C.477E-01 O.278E 00 C.409E 00 O.465E 00 O.520E 00	N(*E, 50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.317E 00	0.477E-C1 0.278E 00 0.409E 00 0.465E 00 0.520E 00
10 2.25 0.498E-01 0.478E 00 0.238E-01 0.478E 00 11 2.50 0.294E-01 0.479E 00 0.141E-01 0.479E 00 12 2.75 0.175E-01 0.479E 00 0.837E-02 0.479E 00 13 3.00 0.104E-01 0.479E 00 0.497E-02 0.479E 00 14 3.25 0.615E-02 0.479E 00 0.295E-02 0.479E 00 15 3.50 0.365E-02 0.479E 00 0.175E-02 0.479E 00 16 3.75 0.217E-02 0.479E 00 0.104E-02 0.479E 00 17 4.00 0.129E-02 0.479E 00 0.617E-03 0.479E 00 18 4.25 0.764E-63 0.479E 00 0.617E-03 0.479E 00 19 4.50 0.453E-03 0.479E 00 0.217E-03 0.479E 00 20 4.75 0.269E-03 0.479E 00 0.129E-03 0.479E 00 21 5.00 0.160E-03 0.479E 00 0.765E-04 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.270E-04 0.479E 00	1 2 3 4 5	0. 0.25 0.50 0.75 1.00	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00	C.477E-01 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00	N(*E, 50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.317E 00 0.196E 00	0.477E-01 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00
11 2.50 0.294E-01 0.479E 00 0.141E-01 0.479E 00 12 2.75 0.175E-01 0.479E 00 0.837E-02 0.479E 00 13 3.00 0.104E-01 0.479E 00 0.497E-02 0.479E 00 14 3.25 0.615E-02 0.479E 00 0.295E-02 0.479E 00 15 3.50 0.365E-02 0.479E 00 0.104E-02 0.479E 00 16 3.75 0.217E-02 0.479E 00 0.104E-02 0.479E 00 17 4.00 0.129E-02 0.479E 00 0.617E-03 0.479E 00 18 4.25 0.764E-63 0.479E 00 0.366E-03 0.479E 00 19 4.50 0.453E-03 0.479E 00 0.217E-03 0.479E 00 20 4.75 0.269E-03 0.479E 00 0.129E-03 0.479E 00 21 5.00 0.160E-03 0.479E 00 0.765E-04 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.765E-04 0.479E 00 23 5.50 0.562E-04 0.479E 00 0.270E-04 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.950E-05 0.479E 00 25 6.00 0.198E-04 0.479E 00 0.950E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.564E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.335E-05 0.479E 00	1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00	EC(0) C.477E-01 0.278E 00 C.409E 00 0.465E 00 0.520E 00 C.454E 00 0.472E 00 0.530E 00	N(*E, 50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.317E 00 0.196E 00 0.113E 00 0.665E-01	0.477E-C1 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00
12 2.75 0.175E-01 0.479E 00 0.837E-02 0.479E 00 13 3.00 0.104E-01 0.479E 00 0.497E-02 0.479E 00 14 3.25 0.615E-02 0.479E 00 0.295E-02 0.479E 00 15 3.50 0.365E-02 0.479E 00 0.175E-02 0.479E 00 16 3.75 0.217E-02 0.479E 00 0.104E-02 0.479E 00 17 4.00 0.129E-02 0.479E 00 0.617E-03 0.479E 00 18 4.25 0.764E-63 0.479E 00 0.366E-03 0.479E 00 19 4.50 0.453E-03 0.479E 00 0.217E-03 0.479E 00 20 4.75 0.269E-03 0.479E 00 0.129E-03 0.479E 00 21 5.00 0.160E-03 0.479E 00 0.765E-04 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.270E-04 0.479E	1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01	EC(0) C.477E-01 0.278E 00 C.409E 00 0.465E 00 0.520E 00 C.454E 00 0.472E 00 0.539E 00 0.450E 00	N(*E, 50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.317E 00 0.196E 00 0.113E 00 0.665E-01 0.415E-01	0.477E-C1 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00 0.450E 00
13 3.00 0.104E-01 0.479E 00 0.497E-02 0.479E 00 14 3.25	1 2 3 4 5 6 7 8 9	C. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01 0.498E-01	EC(D) C.477E-01 0.278E 00 C.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00 0.450E 00 0.478E 00	N(*E, 50) C.465E 03 C.246E 01 O.100E 01 C.543E 00 C.317E 00 O.196E 00 O.113E 00 O.665E-01 O.415E-01 O.238E-01	0.477E-C1 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00 0.450E 00 0.478E 00
14 3.25 C.615E-O2 C.479E OO C.295E-O2 O.479E OO 15 3.50 O.365E-O2 O.479E OO C.175E-O2 O.479E OO 16 3.75 O.217E-O2 O.479E OO O.104E-O2 O.479E OO 17 4.00 O.129E-O2 C.479E OO O.617E-O3 O.479E OO 18 4.25 O.764E-G3 C.479E OO C.366E-O3 O.479E OO 19 4.50 O.453E-O3 O.479E OO O.217E-O3 O.479E OO 20 4.75 O.269E-O3 O.479E OO O.129E-O3 O.479E OO 21 5.00 O.160E-O3 O.479E OO O.765E-O4 O.479E OO 22 5.25 O.948E-O4 O.479E OO O.454E-O4 O.479E OO 23 5.50 O.562E-O4 O.479E OO O.270E-O4 O.479E OO 24 5.75 O.334E-O4 O.479E OO O.950E-O5 O.479E	1 2 3 4 5 6 7 8 9 10	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01 0.498E-01 0.294E-01	EC(D) C.477E-01 0.278E 00 C.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00 0.450E 00 0.478E 00 0.479E 00	N(*E, .50) C. 465E 03 C. 246E 01 C. 100E 01 C. 543E 00 C. 317E 00 C. 196E 00 C. 113E 00 C. 665E-C1 C. 415E-O1 C. 238E-O1 C. 141E-O1	0.477E-C1 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.470E 00 0.478E 00 0.479E 00
16 3.75 0.217E-02 0.479E 00 0.104E-02 0.479E 00 17 4.00 0.129E-02 0.479E 00 0.617E-03 0.479E 00 18 4.25 0.764E-03 0.479E 00 0.366E-03 0.479E 00 19 4.50 0.453E-03 0.479E 00 0.217E-03 0.479E 00 20 4.75 0.269E-03 0.479E 00 0.129E-03 0.479E 00 21 5.00 0.160E-03 0.479E 00 0.765E-04 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.454E-04 0.479E 00 23 5.50 0.562E-04 0.479E 00 0.270E-04 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.160E-04 0.479E 00 25 6.00 0.198E-04 0.479E 00 0.950E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.564E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.335E-05 0.479E 00 28 6.75 0.414E-05 0.479E 00 0.199E-05 0.479E 00	1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01 0.498E-01 0.294E-01 0.175E-01	EC(D) C.477E-01 0.278E 00 C.4C9E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00 0.450E 00 0.478E 00 0.479E 00 0.479E 00	N(*E, 50) C.465E 03 C.246E 01 C.100E 01 C.543E 00 C.317E 00 C.196E 00 C.113E 00 C.665E-C1 C.415E-O1 C.238E-O1 C.141E-O1 C.837E-O2	0.477E-C1 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.470E 00 0.479E 00 0.479E 00
17	1 2 3 4 5 6 7 8 9 10 11 12	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.432E 00 0.125E 00 0.923E-01 0.498E-01 0.294E-01 0.175E-01 0.104E-01	EC(D) C.477E-01 0.278E 00 C.4C9E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.430E 00 0.478E 00 0.479E 00 0.479E 00 0.479E 00	N(*E, 50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.317E 00 0.196E 00 0.113E 00 0.665E-01 0.415E-01 0.238E-01 0.141E-01 0.837E-02 0.497E-02	0.477E-C1 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00 0.450E 00 0.479E 00 0.479E 00 0.479E 00
18 4.25 0.764E-G3 C.479E 00 C.366E-U3 0.479E 00 19 4.50 0.453E-U3 0.479E 00 0.217E-U3 0.479E 00 20 4.75 0.269E-U3 0.479E 00 0.129E-U3 0.479E 00 21 5.00 0.160E-U3 0.479E 00 0.765E-U4 0.479E 00 22 5.25 0.948E-U4 0.479E 00 0.454E-U4 0.479E 00 23 5.50 0.562E-U4 0.479E 00 0.270E-U4 0.479E 00 24 5.75 0.334E-U4 0.479E 00 0.160E-U4 0.479E 00 25 6.00 0.198E-U4 0.479E 00 0.950E-U5 0.479E 00 26 6.25 0.118E-U4 0.479E 00 0.564E-U5 0.479E 00 27 6.50 0.698E-U5 0.479E 00 0.335E-U5 0.479E 00 28 6.75 0.414E-U5 0.479E 00 0.199E-U5 0.479E 00	1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01 0.498E-01 0.175E-01 0.104E-01 0.104E-01	EC(D) C.477E-01 0.278E 00 C.4C9E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00 0.450E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00	N(*E, 50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.317E 00 0.196E 00 0.113E 00 0.665E-01 0.415E-01 0.238E-01 0.141E-01 0.837E-02 0.497E-02 0.295E-02 0.175E-02	0.477E-C1 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00
19 4.50 0.453E-03 0.479E 00 0.217E-03 0.479E 00 20 4.75 0.269E-03 0.479E 00 0.129E-03 0.479E 00 21 5.00 0.160E-03 0.479E 00 0.765E-04 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.454E-04 0.479E 00 23 5.50 0.562E-04 0.479E 00 0.270E-04 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.160E-04 0.479E 00 25 6.00 0.198E-04 0.479E 00 0.950E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.564E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.335E-05 0.479E 00 28 6.75 0.414E-05 0.479E 00 0.199E-05 0.479E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01 0.498E-01 0.175E-01 0.104E-01 0.104E-01 0.615E-02 0.365E-02 0.217E-02	EC(D) C.477E-01 0.278E 00 C.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.472E 00 0.450E 00 0.479E 00	N(*E, .50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.317E 00 0.196E 00 0.113E 00 0.665E-01 0.415E-01 0.238E-01 0.141E-01 0.837E-02 0.497E-02 0.295E-02 0.175E-02 0.104E-02	0.477E-01 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00 0.478E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00
20 4.75 0.269E-03 0.479E 00 0.129E-03 0.479E 00 21 5.00 0.160E-03 0.479E 00 0.765E-04 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.454E-04 0.479E 00 23 5.50 0.562E-04 0.479E 00 0.270E-04 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.160E-04 0.479E 00 25 6.00 0.198E-04 0.479E 00 0.950E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.564E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.335E-05 0.479E 00 28 6.75 0.414E-05 0.479E 00 0.199E-05 0.479E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01 0.498E-01 0.175E-01 0.175E-01 0.104E-01 0.104E-01 0.615E-02 0.365E-02 0.217E-02 0.129E-02	EC(D) C.477E-01 0.278E 00 C.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.472E 00 0.478E 00 0.479E 00	N(*E,.50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.317E 00 0.196E 00 0.113E 00 0.665E-01 0.415E-01 0.238E-01 0.141E-01 0.837E-02 0.497E-02 0.295E-02 0.175E-02 0.104E-02 0.617E-03	0.477E-01 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00 0.450E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00
21 5.00 0.160E-03 0.479E 00 0.765E-04 0.479E 00 22 5.25 0.948E-04 0.479E 00 0.454E-04 0.479E 00 23 5.50 0.562E-04 0.479E 00 0.270E-04 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.160E-04 0.479E 00 25 6.00 0.198E-04 0.479E 00 0.950E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.564E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.335E-05 0.479E 00 28 6.75 0.414E-05 0.479E 00 0.199E-05 0.479E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01 0.498E-01 0.498E-01 0.175E-01 0.104E-01 0.104E-01 0.615E-02 0.365E-02 0.217E-02 0.129E-02 0.764E-03	EC(D) C.477E-01 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.472E 00 0.472E 00 0.479E 00	N(*E, .50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.17E 00 0.196E 00 0.113E 00 0.665E-01 0.415E-01 0.238E-01 0.141E-01 0.837E-02 0.497E-02 0.295E-02 0.175E-02 0.104E-02 0.617E-03 0.366E-03	0.477E-01 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.530E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00
22 5.25 0.948E-04 0.479E 00 0.454E-04 0.479E 00 23 5.50 0.562E-04 0.479E 00 0.270E-04 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.160E-04 0.479E 00 25 6.00 0.198E-04 0.479E 00 0.950E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.564E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.335E-05 0.479E 00 28 6.75 0.414E-05 0.479E 00 0.199E-05 0.479E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.125E 00 0.923E-01 0.498E-01 0.175E-01 0.175E-01 0.104E-01 0.615E-02 0.365E-02 0.217E-02 0.129E-02 0.129E-02 0.764E-03 0.453E-03	EC(D) C.477E-01 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.450E 00 0.479E 00	N(*E, 50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.317E 00 0.196E 00 0.113E 00 0.665E-01 0.415E-01 0.238E-01 0.141E-01 0.837E-02 0.497E-02 0.295E-02 0.175E-02 0.104E-02 0.617E-03 0.366E-03 0.217E-03	0.477E-C1 0.278E 00 0.469E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00 0.479E 00
23 5.50 0.562E-04 0.479E 00 0.270E-04 0.479E 00 24 5.75 0.334E-04 0.479E 00 0.160E-04 0.479E 00 25 6.00 0.198E-04 0.479E 00 0.950E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.564E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.335E-05 0.479E 00 28 6.75 0.414E-05 0.479E 00 0.199E-05 0.479E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	0. 0.25 0.50 0.75 1.00 1.25 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01 0.498E-01 0.175E-01 0.175E-01 0.104E-01 0.104E-01 0.365E-02 0.365E-02 0.217E-02 0.129E-02 0.129E-03 0.453E-03 0.269E-03	EC(D) C.477E-01 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.478E 00 0.479E 00	N(*E,.50) C.465E 03 C.246E 01 O.100E 01 O.543E 00 C.317E 00 O.196E 00 O.113E 00 O.665E-01 O.415E-01 O.238E-01 O.141E-01 O.837E-02 O.497E-02 C.295E-02 C.175E-02 O.104E-02 O.617E-03 C.366E-03 O.217E-03 C.129E-03	0.477E-C1 0.278E 00 0.469E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.479E 00
25 6.00 0.198E-04 0.479E 00 0.950E-05 0.479E 00 26 6.25 0.118E-04 0.479E 00 0.564E-05 0.479E 00 27 6.50 0.698E-05 0.479E 00 0.335E-05 0.479E 00 28 6.75 0.414E-05 0.479E 00 0.199E-05 0.479E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	0.25 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 3.75 3.00 3.55 4.00 4.25 4.50 4.75 5.00	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.125E 00 0.125E 00 0.923E-01 0.498E-01 0.175E-01 0.175E-01 0.104E-01 0.104E-01 0.365E-02 0.365E-02 0.217E-02 0.129E-02 0.129E-03 0.160E-03	EC(D) C.477E-01 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.478E 00 0.479E 00	N(*E, .50) C. 465E 03 C. 246E 01 O. 100E 01 O. 543E 00 C. 317E 00 O. 196E 00 O. 113E 00 O. 665E-01 O. 415E-01 O. 238E-01 O. 141E-01 O. 837E-02 O. 497E-02 C. 295E-02 C. 175E-02 O. 104E-02 O. 617E-03 C. 366E-03 O. 217E-03 O. 129E-03 O. 765E-04	0.477E-C1 0.278E 00 0.469E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.479E 00
26 6.25 C.118E-04 O.479E OO	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 3.75 3.00 3.50 3.75 4.00 4.50 4.75 5.00 5.25	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01 0.498E-01 0.175E-01 0.104E-01 0.104E-01 0.615E-02 0.365E-02 0.217E-02 0.129E-02 0.129E-03 0.453E-03 0.453E-03 0.460E-03 0.948E-04	EC(D) C.477E-01 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.478E 00 0.479E 00	N(*E, .50) C. 465E 03 C. 246E 01 C. 100E 01 C. 543E 00 C. 317E 00 C. 196E 00 C. 113E 00 C. 415E-01 C. 238E-01 C. 141E-01 C. 837E-02 C. 295E-02 C. 175E-02 C. 175E-02 C. 175E-02 C. 175E-03 C. 366E-03 C. 129E-03 C. 129E-03 C. 765E-04 C. 270E-04	0.477E-C1 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.479E 00
27 6.50 0.698E-05 0.479E 00 C.335E-05 0.479E 00 28 6.75 0.414E-05 0.479E 00 C.199E-05 0.479E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	0. 0.25 0.50 0.75 1.00 1.55 1.50 2.50 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.75 5.00 5.75	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01 0.498E-01 0.175E-01 0.104E-01 0.615E-02 0.365E-02 0.217E-02 0.129E-02 0.764E-03 0.453E-03 0.269E-03 0.160E-03 0.948E-04 0.562E-04 0.334E-04	EC(D) C.477E-01 0.278E 00 C.4C9E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.479E 00	N(*E, .50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.196E 00 0.113E 00 0.665E-01 0.415E-01 0.238E-01 0.141E-01 0.837E-02 0.497E-02 0.295E-02 0.175E-02 0.104E-02 0.617E-03 0.366E-03 0.217E-03 0.129E-03 0.765E-04 0.454E-04 0.270E-04	0.477E-C1 0.278E OG 0.409E GO 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.479E 00
28 6.75 0.414E-05 0.479E 00 C.199E-05 0.479E 00	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25	0. 0.25 0.50 0.75 1.00 1.55 1.50 2.50 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.75 5.00 5.75 6.00	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E 00 0.923E-01 0.498E-01 0.175E-01 0.104E-01 0.615E-02 0.365E-02 0.217E-02 0.129E-02 0.764E-03 0.453E-03 0.453E-03 0.460E-03 0.948E-04 0.562E-04 0.334E-04 0.198E-04	EC(D) C.477E-01 0.278E 00 C.4C9E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.479E 00	N(*E, 50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.317E 00 0.196E 00 0.113E 00 0.665E-01 0.415E-01 0.238E-01 0.141E-01 0.837E-02 0.497E-02 0.497E-02 0.175E-02 0.104E-02 0.617E-03 0.366E-03 0.217E-03 0.129E-03 0.765E-04 0.454E-04 0.270E-04 0.160E-04 0.950E-05	0.477E-C1 0.278E OG 0.465E OO 0.465E OO 0.520E OO 0.454E OO 0.472E OO 0.479E OO
	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. 0.25 0.50 0.75 1.00 1.55 1.50 2.50 2.50 2.75 3.00 3.25 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00 6.25	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.240E 00 0.125E C0 0.923E-01 0.498E-01 0.175E-01 0.104E-01 0.615E-02 0.365E-02 0.217E-02 0.129E-02 0.764E-G3 0.453E-03 0.453E-03 0.460E-03 0.948E-04 0.562E-04 0.334E-04 0.198E-04 0.118E-04	EC(D) C.477E-01 0.278E 00 C.4C9E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.479E 00	N(*E, 50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.196E 00 0.113E 00 0.665E-01 0.415E-01 0.238E-01 0.141E-01 0.837E-02 0.497E-02 0.295E-02 0.175E-02 0.104E-02 0.617E-03 0.366E-03 0.217E-03 0.129E-03 0.765E-04 0.454E-04 0.950E-05 0.564E-05	0.477E-C1 0.278E OG 0.409E GO 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.479E 00
	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	0. 0.25 0.50 0.75 1.00 1.55 1.50 2.50 2.50 2.50 3.25 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.75 6.00 6.25 6.50	0.975E 04 0.886E 01 0.244E 01 0.117E 01 0.610E 00 0.432E 00 0.125E 00 0.923E-01 0.498E-01 0.175E-01 0.104E-01 0.615E-02 0.365E-02 0.217E-02 0.129E-03 0.453E-03 0.453E-03 0.269E-03 0.160E-03 0.948E-04 0.562E-04 0.334E-04 0.198E-04 0.198E-04 0.698E-05	EC(D) C.477E-01 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.479E 00	N(*E, .50) 0.465E 03 0.246E 01 0.100E 01 0.543E 00 0.113E 00 0.113E 00 0.665E-01 0.415E-01 0.238E-01 0.141E-01 0.837E-02 0.497E-02 0.295E-02 0.175E-02 0.104E-02 0.617E-03 0.366E-03 0.217E-03 0.129E-03 0.765E-04 0.454E-04 0.270E-04 0.160E-04 0.950E-05 0.564E-05 0.335E-05	0.477E-C1 0.278E 00 0.409E 00 0.465E 00 0.520E 00 0.454E 00 0.472E 00 0.479E 00

NO	E	N(E+.5C)	** L=3.00 ** E0(D)	N(*E,.50)	(1)03
1	0.	0.680E 04	0.500E-01	C.340E 03	0.500E-01
2	0.25 0.50	0.759E 01	0.302E 00	0.229E 01	0.302E 00
3 4	0.75	0.238E 01 0.118E 01	0.421E 00 0.467E 00	0.100E 01 0.552E 00	0.421E 00
5	1.00	0.575E 00	0.467E 00	0.323E 00	0.467E 00 0.562E 00
6	1.25	0.458E CC	0.452E 00	C.207E 00	0.452E 00
7	1.50	J.247E 00	0.481E 00	0.119E 00	0.481E 00
8 9	1.75 2.00	0.125E 00 0.107E 00	0.568E 00	0.708E-01	0.568£ 00
10	2.25	0.476E-01	0.427F 00 0.534E 00	0.456E-01 0.254E-01	0.427E 00 0.534E 00
11	2.50	0.328E-01	0.485E 00	0.159E-01	0.485E 00
12	2.75	0.196E-01	0.485E 00	0.949E-02	0.485E 00
13 14	3.00	0.117E-01	C.485E 00	0.567E-02	0.485E 00
15	3.25 3.50	C.698E-02 C.417E-02	0.485E 00 0.485E 00	0.338E-02 0.202E-02	0.485E 00 0.485E 00
16	3.75	C-249E-02	0.485E 00	0.121E-02	0.485E 00
17	4.0C	C.149E-02	0.485E 00	0.720E-03	0.485E 00
18	4.25	0.887E-03	0.485E 00	0.430E-03	0.485E 00
19 20	4 • 50 4 • 75	0.529E-03 0.316E-03	0.485E 00 0.485E 00	0.257E-03 0.153E-03	0.485E 00 0.485E 00
21	5.00	0.189E-03	0.485E 00	0.155E~05	0.485F 00
22	5.25	0.113E-03	0.485E 00	0.546E-04	0.485E 00
23	5.50	0.673E-04	0.485E 00	0.326E-04	0.485E 00
24 25	5.75 6.00	0.402E-04 0.240E-04	C.485E GC	0.195E-04	0.485E 00
26	6.25	0.143E-04	0.485E OC 0.485E OQ	0.116E-04 0.694E-05	0.485E 00 0.485E 00
27	6.50	0.855E-05	0.485E 00	0.414E-05	0.485E 00
28	6.75	0.51CE-05	0.485E 00	0.247E-05	0.485E CC
29	7.00	0.305E-05	0.485E 00	C.148E-05	0.485E 00
NO	E	N(E50)	** L=3.20 ** EC(D)	N(#E,.50)	E0(I)
			EC(D)		
1	C.	0.216E 04	EC(D) 0.602E-01	C.130E C3	G.602E-01
1 2 3	0. 0.25 0.50	0.216E 04 0.589E 01 0.223E 01	EC(D) 0.602E-01 0.348E 00 0.448E 00	C.130E C3 C.205E C1 C.100E C1	0.602E-01 0.348E 00 0.448E 00
1 2 3 4	0. 0.25 0.50 0.75	0.216E 04 0.589E 01 0.223E 01 0.119E 01	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00	C.130E C3 C.205E C1 C.100E C1 C.572E OO	0.602E-01 0.348E 00 0.448E 00 0.481E 00
1 2 3 4 5	C. C.25 O.50 C.75 1.00	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00	C.130E C3 C.205E C1 C.100E C1 C.572E OO C.340E CO	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00
1 2 3 4	0. 0.25 0.50 0.75	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00	C.130E C3 C.205E C1 C.100E C1 C.572E OO C.340E CO C.227E CO	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.474E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481F 00 0.619E 00 0.474E 00 0.515E 00 0.595E 00	C.130E C3 C.205E C1 C.100E C1 C.572E OO C.340E OO C.227E OC C.134E CO	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.474E 00 0.515E 00 0.595E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.26CE 00 0.139E 0C 0.105E 00	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.474E 00 0.515E 00 0.595E 00	C.130E C3 C.205E C1 C.100E C1 C.572E OO C.340E OO C.227E OC C.134E CO O.825E-O1 C.542E-O1	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.474E 00 0.515E 00 0.595E 00 0.516E 00
1 2 3 4 5 6 7 8 9	C. 25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.260E 00 0.139E 00 0.105E 00 0.620E-01	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.474E 00 0.515E 00 0.595E 00 0.516E 00	C.130E C3 C.205E C1 C.100E C1 C.572E OO C.340E OO C.227E CC C.134E CO C.134E CO C.825E-O1 C.542E-O1 C.334E-C1	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.474E 00 0.515E 00 0.595E 00 0.516E 00 0.539E 00
1 2 3 4 5 6 7 8	C. 25 0.50 C.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.26CE 00 0.139E CC 0.105E 00 0.62CE-01 0.410E-01	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.474E 00 0.515E 00 0.595E 00 0.539E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E OO C.340E OO C.227E OC C.134E CO O.825E-O1 C.542E-O1	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.474E 00 0.515E 00 0.595E 00 0.516E 00
1 2 3 4 5 6 7 8 9	C. 25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.260E 00 0.139E 00 0.105E 00 0.620E-01	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.474E 00 0.515E 00 0.595E 00 0.516E 00	C.130E C3 C.205E C1 C.100E C1 C.572E 00 G.340E 00 C.227E 00 C.134E 00 O.825E-01 C.542E-01 C.334E-C1 O.210E-01	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.474E 00 0.515E 00 0.595E 00 0.539E 00 0.539E 00
1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.260E 00 0.139E 00 0.105E 00 0.620E-01 0.410E-01 0.252E-01 0.154E-01 0.948E-02	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481F 00 0.619E 00 0.515E 00 0.595E 00 0.513E 00 0.512E 00 0.512E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E 00 C.340E 00 C.227E 00 C.134E 00 C.825E-01 C.542E-01 C.542E-01 C.334E-G1 C.210E-C1 C.129E-C1 C.791E-C2 C.486E-O2	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.474E 00 0.515E 00 0.595E 00 0.516E 00 0.539E C0 0.512E 00 0.512E 00 0.512E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.260E 00 0.139E 00 0.105E 00 0.620E-01 0.410E-01 0.252E-01 0.154E-01 0.948E-02 0.582E-02	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481F 00 0.619E 00 0.515E 00 0.595E 00 0.516E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E 00 C.340E 00 C.227E 00 C.134E 00 C.825E-01 C.542E-01 C.542E-01 C.334E-C1 C.210E-C1 C.129E-C1 C.791E-C2 C.486E-O2 C.298E-O2	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.515E 00 0.539E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.260E 00 0.139E 00 0.105E 00 0.620E-01 0.410E-01 0.252E-01 0.154E-01 0.948E-02 0.582E-02 0.357E-02	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481F 00 0.619E 00 0.515E 00 0.595E 00 0.516E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E 00 C.340E 00 C.227E 00 C.134E 00 0.825E-01 0.542E-01 0.542E-01 0.542E-01 0.542E-01 0.129E-01 0.129E-01 C.791E-02 0.486E-02 C.298E-02 0.183E-02	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.515E 00 0.516E 00 0.539E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.260E 00 0.139E 00 0.105E 00 0.620E-01 0.410E-01 0.252E-01 0.154E-01 0.948E-02 0.582E-02	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481F 00 0.619E 00 0.515E 00 0.595E 00 0.516E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E 00 C.340E 00 C.227E 00 C.134E 00 C.825E-01 C.542E-01 C.542E-01 C.334E-C1 C.210E-C1 C.129E-C1 C.791E-C2 C.486E-O2 C.298E-O2	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.515E 00 0.539E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	C. 25 0.50 C.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.75 4.00 4.25 4.50	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.139E 00 0.105E 00 0.105E 00 0.620E-01 0.410E-01 0.252E-01 0.154E-01 0.948E-02 0.582E-02 0.582E-02 0.357E-02 0.219E-02 0.826E-03	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.595E 00 0.516E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E OO C.340E OO C.227E OC C.134E CO O.825E-O1 C.542E-O1 C.542E-O1 C.334E-C1 O.210E-O1 C.791E-O2 C.486E-O2 C.298E-O2 C.298E-O2 C.112E-O2 C.112E-O2 C.689E-O3 C.423E-O3	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.515E 00 0.516E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	C. 25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.260E 00 0.139E 00 0.105E 00 0.620E-01 0.410E-01 0.252E-01 0.154E-01 0.948E-02 0.582E-02 0.582E-02 0.357E-02 0.219E-02 0.135E-02 0.826E-03 0.507E-03	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.595E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E OO C.340E OO C.227E CC C.134E CO C.134E CO C.134E-C1 C.542E-C1 C.334E-C1 C.210E-C1 C.791E-C2 C.486E-O2 C.29E-C2 C.29E-C2 C.183E-C2 C.112E-C2 C.689E-C3 C.423E-C3 C.423E-C3 C.423E-C3	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.515E 00 0.516E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	C. 25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.75 4.00 4.75 5.00	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.260E 00 0.139E 00 0.105E 00 0.620E-01 0.410E-01 0.252E-01 0.154E-01 0.948E-02 0.582E-02 0.357E-02 0.219E-02 0.135E-02 0.135E-02 0.826E-03 0.507E-03 0.311E-03	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.474E 00 0.515E 00 0.595E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E 00 C.340E 00 C.227E 00 C.134E 00 O.825E-01 C.542E-01 C.334E-C1 C.334E-C1 C.210E-C1 C.791E-C2 C.486E-O2 C.298E-O2 C.129E-O2 C.129E-O2 C.298E-O2 C.298E-O2 C.129E-O3 C.129E-O3 C.129E-O3 C.129E-O3 C.129E-O3 C.129E-O3 C.129E-O3 C.129E-O3 C.129E-O3 C.129E-O3 C.129E-O3 C.129E-O3	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.515E 00 0.516E 00 0.512E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	C. 25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.260E 00 0.139E 00 0.105E 00 0.620E-01 0.410E-01 0.252E-01 0.154E-01 0.948E-02 0.582E-02 0.582E-02 0.357E-02 0.219E-02 0.135E-02 0.826E-03 0.507E-03	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.595E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E OO C.340E OO C.227E CC C.134E CO C.134E CO C.134E-C1 C.542E-C1 C.334E-C1 C.210E-C1 C.791E-C2 C.486E-O2 C.29E-C2 C.29E-C2 C.183E-C2 C.112E-C2 C.689E-C3 C.423E-C3 C.423E-C3 C.423E-C3	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.515E 00 0.516E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00 0.512E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.75 3.00 2.75 3.50 3.75 4.00 4.75 5.00 5.25 5.50 5.75	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.139E 00 0.105E 00 0.105E 00 0.620E-01 0.410E-01 0.252E-01 0.154E-01 0.948E-02 0.582E-02 0.357E-02 0.219E-02 0.135E-02 0.826E-03 0.507E-03 0.311E-03 0.191E-03 0.719E-04	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.474E 00 0.515E 00 0.515E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E 00 G.340E 00 G.227E 00 C.134E C0 O.825E-O1 C.542E-O1 C.334E-G1 O.210E-O1 O.129E-O1 C.791E-O2 C.486E-O2 G.298E-O2 C.112E-O2 C.112E-O2 C.689E-O3 C.423E-C3 G.260E-O3 G.159E-O3 G.159E-O4 O.368E-C4	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.515E 00 0.512E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.02 2.75 3.25 3.75 4.00 4.75 4.50 4.75 5.00 5.75 6.00	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.139E 00 0.105E 00 0.105E 00 0.620E-01 0.410E-01 0.252E-01 0.154E-01 0.948E-02 0.582E-02 0.357E-02 0.219E-02 0.135E-02 0.826E-03 0.507E-03 0.507E-03 0.117E-03 0.117E-03 0.719E-04 0.441E-04	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.474E 00 0.515E 00 0.515E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E 00 G.340E 00 G.227E 00 G.34E-01 G.134E-01 G.542E-01 G.334E-01 G.210E-01 G.791E-02 G.486E-02 G.298E-02 G.298E-02 G.112E-02 G.689E-03 G.423E-03 G.423E-03 G.159E-03 G.159E-03 G.978E-04 G.600E-04 G.368E-C4 G.26E-04	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.515E 00 0.512E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.025 2.75 3.25 3.75 4.00 4.75 5.00 5.75 6.00 6.25	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.139E 0C 0.105E 0C 0.105E 0C 0.62CE-G1 0.410E-G1 0.252E-G1 0.154E-G1 0.948E-02 0.582E-02 0.357E-02 0.219E-02 0.135E-02 0.826E-03 0.507E-03 0.311E-03 0.117E-03 0.719E-04 0.441E-04 0.271E-04	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.474E 00 0.515E 00 0.515E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E 00 C.340E 00 C.227E 00 C.134E 00 C.825E-01 C.542E-01 C.542E-01 C.210E-01 C.129E-01 C.791E-02 C.486E-02 C.298E-02 C.112E-02 C.689E-03 C.423E-03 C.423E-03 C.423E-03 C.423E-03 C.423E-03 C.423E-03 C.423E-04 C.600E-04 C.368E-04 C.368E-04 C.368E-04 C.26E-04 C.139E-04	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.515E 00 0.512E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.02 2.75 3.25 3.75 4.00 4.75 4.50 4.75 5.00 5.75 6.00	0.216E 04 0.589E 01 0.223E 01 0.119E 01 0.549E 00 0.479E 00 0.139E 00 0.105E 00 0.105E 00 0.620E-01 0.410E-01 0.252E-01 0.154E-01 0.948E-02 0.582E-02 0.357E-02 0.219E-02 0.135E-02 0.826E-03 0.507E-03 0.507E-03 0.117E-03 0.117E-03 0.719E-04 0.441E-04	EC(D) 0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.474E 00 0.515E 00 0.515E 00 0.512E 00	C.130E C3 C.205E C1 C.100E C1 C.572E 00 G.340E 00 G.227E 00 G.34E-01 G.134E-01 G.542E-01 G.334E-01 G.210E-01 G.791E-02 G.486E-02 G.298E-02 G.298E-02 G.112E-02 G.689E-03 G.423E-03 G.423E-03 G.159E-03 G.159E-03 G.978E-04 G.600E-04 G.368E-C4 G.26E-04	0.602E-01 0.348E 00 0.448E 00 0.481E 00 0.619E 00 0.515E 00 0.515E 00 0.512E 00

			** L=3.40 **		
NU	£	N(E,.50)	EC(D)	N(*E,.50)	EG(I)
1	3.	0.650E 03	0.769E-01	0.500E 02	0.769E-01
2	0.25	0.514E C1	0.377E 00	0.194E 01	0.377E 00
3	0.50	0.211E 01	0.474E 00	0.100E 01	0.474E CO
4	C.75	0.115E 01	0.515E 00	0.590E 00	0.515E 00
5	1.00	0.577E 00	0.629E 00	0.363E 00	0.629E 00
6 7	1.25 1.50	0.462E CO 0.261E OC	0.528E 00 0.583E 00	C.244E GO G.152E GO	0.528E 00 0.583E 00
8	1.75	0.201E 90	0.573E CO	0.990E-01	0.573E 00
9	2.00	0.113E 00	0.568E 00	C.640E-01	0.568E 00
10	2.25	0.696E-G1	0.592E 00	0.412E-C1	0.592E 00
11	2.5C	0.488E-01	C.553E 00	0.270E-01	0.553E 00
12	2.75	0.311E-01	0.553E 00	C-172E-01	0.553E 00
13	3.00	0.198E-01	0.553E 00	0.109E+01	0.553E 00
14	3.25	0.126E-01	0.553E 00 0.553E 00	0.696E-02 0.443E-02	0.553E 00 0.553E 00
15 16	3.50 3.75	0.801E-02 0.510E-02	0.553E 00	C. 282E-02	0.553E 00
17	4.00	0.324E-02	0.553E 00	0.179E-02	0.553E 00
18	4.25	0.206E-02	0.553E 00	0.114E-02	0.553E 00
19	4.50	0.131E-02	0.553E 00	C.727E-G3	0.553E 00
20	4.75	0.836E-03	0.553E 00	0.463E-C3	0.553E 00
21	5.CO	0.532E-03	0.553E 00	0.294E-03	0.553E 00
22	5.25	0.339E-03	0.553E 00	C.187E-03	0.553E 00
23	5.5C	0.216E-03	0.553E 00 0.553E 00	0.119E-03 C.759E-04	0.553E 00 0.553E 00
24 25	5.75 6.00	0.137E-03 0.873E-04	0.553E 00	C.483E-C4	0.553E 00
26	6.25	0.556E-C4	0.553E 00	0.307E-04	0.553E 00
27	6.5C	0.354E-04	C.553E 00	0.196E-C4	0.553E 00
28	6.75	C.225E-C4	0.553E 00	C-125E-G4	0.553E 00
29	7.60	C.143E-04	0.553E 00	0.793E-05	0.553E 00
		CALTUE OF	C. 333E 30	,52 05	0.5556 60
	1.50	C11452 04	** L=3.60 **	•	
NO	E	N(E,.56)			E0(I)
			** L=3.60 **	•	EG(I) 0.108E 00
NO 1 2	E 0. 0.25	N(E,.50) C.166E C3 C.528E G1	** L=3.60 ** E0(D) 0.108E 00 0.372E 00	N(*E50) 0.200E 02 0.196E 01	0.108E 00 0.372E 00
NO1	0. 0.25 0.50	N(E,.50) C.166E C3 C.528E G1 C.194E C1	** L=3.60 ** E0(D) 0.108E 00 0.372E 00 0.514E 00	N(*E,.50) 0.200E 02 0.196E 01 0.100E 01	EG(I) 0.108E 00 0.372E 00 0.514E 00
NO 1 2 3 4	0. 0.25 0.50 0.75	N(E,.50) C.166E C3 C.528E C1 C.194E C1 C.11GE C1	** L=3.60 ** E0(D) 0.108E 00 0.372E 00 0.514E 00 0.561E 00	N(*E,.50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00	EG(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00
NO 1 2 3 4 5	0. 0.25 0.50 6.75 1.00	N(E,.50) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.68UE CC	** L=3.60 ** E0(D) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00	N(*E,.50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00	EG(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00
NO 1 2 3 4 5 6	0. 0.25 0.50 0.75 1.00 1.25	N(E,.50) C.166E C3 C.528E 01 C.194E C1 C.11GE 31 C.68UE CC C.419E CC	** L=3.60 ** E0(D) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00	N(*E,.50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.256E 00	EG(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00
NO 1 2 3 4 5 6 7	0. 0.25 0.50 0.75 1.00 1.25 1.50	N(E,.50) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.68UE CC C.419E CC C.284E CC	** L=3.60 ** E0(D) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 6.599E 00	N(*E,.50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00	EG(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00
NO 1 2 3 4 5 6	0. 0.25 0.50 0.75 1.00 1.25 1.50	N(E,.50) C.166E C3 C.528E 01 C.194E C1 C.11GE 31 C.68UE CC C.419E CC	** L=3.60 ** E0(D) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00	N(*E,.50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.256E 00 0.170E 00	EG(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00
NO 1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50	N(E,.50) C.166E C3 C.528E 01 C.194E 01 C.11GE 31 C.68UE 00 C.419E 00 C.284E G0 C.198E C0	** L=3.60 ** E0(D) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00	N(*E,.50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.256E 00 0.170E 00 0.112E 00	0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.586E 00
NO 1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00	N(E,.50) C.166E C3 C.528E 01 C.194E 01 C.11GE 31 C.680E 00 C.419E 00 C.284E G0 C.198E CC C.123E G0	** L=3.60 ** E0(D) 0.108E 00 0.372E 0C 0.514E 00 0.561E 00 0.580E 00 0.611E 00 6.599E 00 0.566E 00 0.566E 00 0.569E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.256E 00 0.170E 00 0.112E C0 0.720E-01 0.470E-01 0.303E-01	0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.60 2.25 2.50 2.75	N(E,.50) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.680E C0 C.419E C0 C.284E G0 C.198E CC C.123E GC C.825E-G1	** L=3.60 ** E0(D) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.586E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.170E 00 0.112E 00 0.720E-01 0.470E-01 0.303E-01 0.199E-01	E0(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.569E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.110E G1 C.680E OC C.419E OC C.284E GO C.198E CC C.123E GC C.825E-G1 C.511E-O1 C.335E-C1 C.220E-C1	** L=3.60 ** E0(D) 0.108E 00 0.372E 0C 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.586E 00 0.586E 00 0.586E 00 0.593E 00 0.593E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.256E 00 0.170E 00 0.112E 00 0.720E-01 0.470E-01 0.303E-01 0.199E-01 0.130E-01	0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.593E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.680E C0 C.419E C0 C.284E CO C.198E CC C.123E CO C.825E-G1 C.511E-O1 C.335E-C1 C.220E-C1 C.144E-C1	** L=3.60 ** E0(D) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.569E 00 0.593E 00 0.593E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.170E 00 0.112E 00 0.720E-01 0.470E-01 0.303E-01 0.199E-01 0.130E-01 0.855E-02	EG(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.569E 00 0.593E 00 0.593E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.68UE C0 C.419E C0 C.284E G0 C.198E CC C.123E G0 C.825E-G1 C.511E-O1 C.335E-C1 C.220E-C1 C.144E-G1 C.946E-C2	** L=3.60 ** E0(D) 0.108E 00 0.372E 0C 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.170E 00 0.112E 00 0.720E-01 0.470E-01 0.303E-01 0.199E-C1 0.130E-C1 0.855E-02 0.561E-02	EG(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.569E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.11GE G1 C.68UE C0 C.419E C0 C.419E C0 C.284E G0 C.198E C0 C.193E C0 C.825E-G1 C.511E-O1 C.335E-C1 C.22CE-C1 C.144E-C1 C.946E-C2 C.621E-C2	** L=3.60 ** E0(D) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.586E 00 0.586E 00 0.586E 00 0.586E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.256E 00 0.170E 00 0.112E 00 0.720E-01 0.470E-01 0.303E-01 0.199E-01 0.130E-01 0.855E-02 0.561E-02 0.368E-02	EG(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.569E 00 0.593E 00 0.593E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17	C. 25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	N(E,.56) C.166E C3 C.528E 01 C.194E C1 C.11GE 31 C.68UE CO C.419E CO C.284E CO C.123E CO C.123E CO C.825E-C1 C.511E-C1 C.335E-C1 C.22CE-C1 C.144E-C1 C.946E-C2 C.621E-C2 C.407E-O2	** L=3.60 ** E0(D) 0.108E 00 0.372E 0C 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.170E 00 0.112E 00 0.720E-01 0.470E-01 0.303E-01 0.199E-C1 0.130E-C1 0.855E-02 0.561E-02	EG(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.68UE CC C.419E CC C.284E CC C.123E	** L=3.60 ** E0(D) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.256E 00 0.170E 00 0.112E C0 0.720E-01 0.470E-01 0.303E-01 0.199E-C1 0.130E-C1 0.855E-C2 0.561E-02 0.368E-02 0.241E-02 0.158E-02 0.104E-02	EG(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.569E 00 0.569E 00 0.593E 00
NO	C. 25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25	N(E,.56) C.166E C3 C.528E 01 C.194E C1 C.11GE 31 C.680E CC C.419E CC C.419E CC C.123E CC C.123E CC C.123E CC C.123E CC C.123E CC C.123E CC C.124E-C1 C.511E-C1 C.335E-C1 C.22CE-C1 C.144E-C1 C.946E-C2 C.621E-C2 C.407E-C2 C.175E-C2 C.175E-C2 C.115E-C2	** L=3.60 ** E0(0) 0.108E 00 0.372E 0C 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.256E 00 0.170E 00 0.112E C0 0.720E-01 0.470E-01 0.303E-01 0.199E-C1 0.130E-C1 0.855E-C2 0.561E-02 0.368E-02 C.241E-02 C.158E-02 C.681E-03	0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	C. 25 C. 25 C. 50 C. 75 1.00 1.25 1.50 1.75 2.60 2.25 2.50 2.75 3.60 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.68UE OC C.419E CO C.284E GO C.123E GO C.123E GO C.123E-C1 C.511E-O1 C.335E-C1 C.22CE-C1 C.144E-G1 C.946E-C2 C.407E-C2 C.407E-C2 C.175E-O2 C.175E-O2 C.175E-O2 C.754E-O3	** L=3.60 ** E0(0) 0.108E 00 0.372E 0C 0.514E 00 0.561E 0C 0.580E 00 0.611E 00 0.599E 0C 0.566E 00 0.569E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.170E 00 0.112E C0 0.720E-01 0.470E-01 0.303E-01 0.199E-C1 0.130E-C1 0.855E-C2 0.561E-02 0.368E-02 C.241E-02 C.158E-02 C.681E-03 C.447E-C3	E0(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.516E 00 0.599E 00 0.566E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.68UE OC C.419E CO C.284E GO C.123E GO C.123E GO C.123E GO C.123E-C1 C.511E-O1 C.335E-C1 C.22CE-C1 C.144E-G1 C.946E-C2 C.407E-C2 C.407E-C2 C.175E-O2 C.175E-O2 C.754E-O3 C.494E-O3	** L=3.60 ** E0(D) 0.108E 00 0.372E 0C 0.514E 00 0.561E 0C 0.580E 00 0.611E 00 0.599E 0C 0.566E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.170E 00 0.112E C0 0.720E-01 0.470E-01 0.303E-01 0.199E-C1 0.130E-C1 0.855E-C2 0.561E-02 0.368E-02 0.241E-02 0.158E-02 0.158E-02 0.104E-02 0.681E-03 0.447E-03 0.293E-03	0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.00	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.11GE G1 C.680E OC C.419E CO C.284E GO C.123E GO C.123E GO C.825E-G1 C.511E-O1 C.335E-C1 C.22CE-C1 C.144E-O1 C.946E-C2 C.407E-C2 C.407E-C2 C.175E-O2 C.175E-O2 C.175E-O2 C.754E-O3 C.494E-O3 C.324E-O3	** L=3.60 ** E0(D) 0.108E 00 0.372E 0C 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.586E 00 0.586E 00 0.586E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.170E 00 0.112E 00 0.720E-01 0.470E-01 0.303E-01 0.199E-01 0.130E-01 0.855E-02 0.561E-02 0.368E-02 0.241E-02 0.158E-02 0.158E-02 0.104E-02 0.681E-03 0.447E-03 0.293E-03	E0(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50 5.75	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.68UE OC C.419E CO C.284E GO C.198E CO C.123E GO C.825E-G1 C.511E-O1 C.335E-C1 C.22CE-C1 C.144E-O1 C.946E-C2 C.4C7E-C2 C.4C7E-C2 C.175E-O2 C.175E-O2 C.754E-O3 C.324E-O3 C.324E-O3 C.324E-O3 C.324E-O3	** L=3.60 ** E0(D) 0.108E 00 0.372E 0C 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.586E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.170E 00 0.112E 00 0.720E-01 0.470E-01 0.303E-01 0.199E-C1 0.130E-C1 0.855E-C2 0.561E-02 0.368E-02 0.241E-02 0.158E-02 0.158E-02 0.104E-02 0.681E-03 0.447E-03 0.192E-03 0.126E-03	E0(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.68UE CO C.419E CO C.284E GO C.198E CO C.123E GO C.825E-G1 C.511E-O1 C.335E-C1 C.220E-C1 C.144E-O1 C.946E-C2 C.407E-C2 C.407E-C2 C.175E-O2 C.175E-O2 C.175E-O2 C.175E-O2 C.175E-O3 C.494E-O3 C.324E-O3 C.324E-O3 C.324E-O3 C.140E-O3	** L=3.60 ** E0(D) 0.108E 00 0.372E 0C 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.586E 00 0.586E 00 0.586E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.170E 00 0.112E 00 0.720E-01 0.470E-01 0.303E-01 0.199E-01 0.130E-01 0.855E-02 0.561E-02 0.368E-02 0.241E-02 0.158E-02 0.158E-02 0.104E-02 0.681E-03 0.447E-03 0.293E-03	E0(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 6.75 6.00 6.25	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.68UE OC C.419E CO C.284E GO C.198E CO C.123E GO C.825E-G1 C.511E-O1 C.335E-C1 C.22CE-C1 C.144E-O1 C.946E-C2 C.4C7E-C2 C.4C7E-C2 C.175E-O2 C.175E-O2 C.754E-O3 C.324E-O3 C.324E-O3 C.324E-O3 C.324E-O3	** L=3.60 ** E0(0) 0.108E 00 0.372E 0C 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.170E 00 0.112E 00 0.720E-01 0.470E-01 0.303E-01 0.199E-01 0.130E-01 0.855E-02 0.561E-02 0.368E-02 0.561E-02 0.158E-02 0.158E-02 0.158E-02 0.681E-03 0.447E-03 0.293E-03 0.192E-03 0.827E-04	E0(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.593E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.60 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00	N(E,.56) C.166E C3 C.528E G1 C.194E G1 C.11GE 31 C.68UE C0 C.419E C0 C.419E C0 C.128E C0 C.123E C0 C.511E-01 C.335E-C1 C.511E-01 C.335E-C1 C.220E-C1 C.144E-C1 C.946E-C2 C.407E-C2 C.175E-C2 C.175E-C2 C.175E-C2 C.175E-C2 C.175E-C3 C.494E-C3 C.324E-C3	** L=3.60 ** E0(D) 0.108E 00 0.372E 0C 0.514E 00 0.561E 00 0.580E 00 0.611E 00 0.599E 00 0.566E 00 0.566E 00 0.569E 00 0.593E 00	N(*E50) 0.200E 02 0.196E 01 0.100E 01 0.615E 00 0.394E 00 0.170E 00 0.112E 00 0.720E-01 0.470E-01 0.303E-01 0.199E-01 0.130E-01 0.855E-02 0.561E-02 0.368E-02 0.561E-02 0.368E-02 0.158E-02 0.158E-02 0.681E-03 0.447E-03 0.447E-03 0.447E-03 0.447E-03 0.543E-04 0.543E-04	EG(I) 0.108E 00 0.372E 00 0.514E 00 0.561E 00 0.561E 00 0.586E 00 0.566E 00 0.568E 00 0.569E 00 0.593E 00

				** L=3.80 **	•	
	vO	E	N(E+.50)	EC(D)	N(#E,.50)	(1) ö3
	1 0.		.583E C2	0.163E 00	0.950E 01	0.163E 00
			589E 01	0.348E 00	0.205E 01	0.348E CO
	-			C.532E 00	0.100F 01	0.532E 00
			.104E 01 .746E 00	0.603E 00 0.554E 00	0.625E 00 0.413E 00	0.603E 00 0.554E 00
			•423E CO	0.622E 00	0.413E 00	0.622E 00
			.281E 00	0.625E 00	C.176E 00	0.625F 00
			.214E 00	0.552E 00	C.118E 00	0.552E 00
_				0.585E GO	0.750E-01	0.585E 00
				0.585E 00	C.489E-01	0.585E 00
				0.598E 00 0.598E 00	C.319E-01 O.210E-01	0.598E 00 0.598E 00
				0.598E 00	0.210E-01 0.138E-01	0.598F 00
				0.598E 00	0.911E-02	0.598E 00
1	15 3.			0.598E 00	C.600E-02	0.598E 00
				0.598E 00	0.395E-02	0.598E 00
				0.598E 00	C.260E-02	0.598E 00
				0.598E 00	0.171E-02	0.598E 00
				0.598E 00 0.598E 00	0.113E-02 0.743E-03	0.598E 00
				0.598E 00	0.489E-03	0.598E 00
				0.598E 00	0.322E-03	0.598E 00
			.355E-G3	C.598E 00	0.212E-03	0.598E 00
				0.598E 00	C.140E-03	0.598E 0C
				0.598E 00	0.921E-04	0.598E 00
				0.598E 00	0.606E-04 0.399E-04	0.598E 00 0.598E 00
				0.598E 00	0.263E-04	0.598E 00
				0.598E 00	0.173E-04	0.598E 00
				** L=4.00 **	+	
N	10	E	N(E,.50)	EO(D)	N(*E,.50)	EO(I)
	1 c.			0.185E 00	0.638E 01	0.226E 00
	2 0.	25 0	.806E 01	0.185E 00	0.638E 01 C.211E 01	0.336E 00
	2 0.	25 0 50 0	.806E 01 .212E 01	0.185E 00 0.298E 00	0.638E 01 0.211E 01 0.100E 01	0.336E 00 0.539E 00
	2 0. 3 0. 4 0.	25 0 50 0 75 0	.806E 01 .212E 01 .108E 01	0.185E 00 0.298E 00 0.575E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00	0.336E 00 0.539E 00 0.584E 00
	2 0. 3 0. 4 0. 5 1.	25 0 50 0 75 0 00 0	.806E 01 .212E 01 .108E 01 .700E 00	0.185E 00 0.298E 00 0.575E 00 0.584E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00	0.336E 00 0.539E 00 0.584E 00 0.587E 00
	2 0. 3 0. 4 0. 5 1. 6 1.	25 0 50 0 75 0 00 0 25 0	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00	0.185E 00 0.298E 00 0.575E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00	0.336E 00 0.539E 00 0.584E 00
	2 0. 3 0. 4 0. 5 1. 6 1. 7 1. 8 1.	25 0 50 0 75 0 00 0 25 0 50 0 75 0	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00	0.185E 00 0.298E 00 0.575E 00 0.584E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00	0.336E 00 0.539E 00 0.584E 00 0.587E 00 0.587E 00
	2 0. 3 0. 4 0. 5 1. 6 1. 7 1. 8 1. 9 2.	25 0 50 0 75 0 00 0 25 0 50 0 75 0	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00	0.185E 00 0.298E 00 0.575E 00 0.584E 00 0.587E 00 0.587E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01	0.336E 00 0.539E 00 0.584E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00
1	2 0. 3 0. 4 0. 5 1. 6 1. 7 1. 8 1. 9 2. 0 2.	25 0 50 0 75 0 00 0 25 0 50 0 75 0 00 0 25 0	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E 00 .830E-01	0.185E 00 0.298E 00 0.575E 00 0.584E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01	0.336E 00 0.539E 00 0.584E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00
1	2 0. 3 0. 4 0. 5 1. 6 1. 7 1. 8 1. 9 2. 0 2. 1 2.	25 0 50 0 75 0 00 0 25 0 50 0 75 0 00 0 25 0 50 0	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E 00 .830E-01	0.185E 00 0.298E 00 0.575E 00 0.584E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.318E-01	0.336E 00 0.539E 00 0.584E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00
1 1 1	2 0.3 0.4 0.5 1.6 1.7 1.8 1.9 2.0 2.1 2.2 2.	25 0 50 0 75 0 00 0 25 0 50 0 75 0 75 0 75 0	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E 00 .830E-01 .542E-01	0.185E 00 0.298E 00 0.575E 00 0.584E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.318E-01 0.208E-01	0.336E 00 0.539E 00 0.584E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00
1 1 1 1	2 0.3 0.4 0.5 1.6 1.7 1.8 1.9 2.1 2.2 2.3 3.3	25 0 50 0 75 0 00 0 25 0 75 0 00 0 25 0 75 0 00 0 75 0 00 0 00 0	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E 00 .830E-01 .542E-01 .354E-01	0.185E 00 0.298E 00 0.575E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.318E-01 0.208E-01 0.136E-01	0.336E 00 0.539E 00 0.584E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00
1 1 1 1	2 0. 3 0. 4 0. 5 1. 6 1. 7 1. 8 1. 9 2. 0 2. 1 2. 2 3. 3 4. 3 3.	25 0 50 0 75 0 00 0 25 0 50 0 75 0 00 0 25 0 50 0 75 0 00 0 25 0 50 0 75 0 00 0 25 0 00 00 0 00	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E 00 .830E-01 .542E-01 .354E-01 .231E-01	0.185E 00 0.298E 00 0.575E 00 0.584E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.318E-01 0.208E-01	0.336E 00 0.539E 00 0.584E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00
1 1 1 1 1 1	2 0. 3 0. 4 0. 5 1. 6 1. 7 1. 8 1. 9 2. 0 2. 1 2. 2 3. 3 4. 3 5. 6 3.	25 0 50 0 75 0 00 0 25 0 75 0 00 0 25 0 75 0 00 0 25 0 75 0 00 0 25 0 75 0 00 0 75 0 00 00 0 00	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E 00 .830E-01 .542E-01 .354E-01 .231E-01 .988E-02	0.185E 00 0.298E 00 0.575E 00 0.584E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.318E-01 0.208E-01 0.136E-01 0.888E-02	0.336E 00 0.539E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00 0.587E 00
1 1 1 1 1 1 1	2 0. 3 0. 4 0. 5 1. 6 1. 7 1. 8 1. 9 2. 0 2. 1 2. 2 3. 3 3. 6 3. 7 4.	25 0 50 0 75 0 00 0 25 0 50 0 75 0 00 0 25 0 50 0 75 0 00 0 25 0 50 0 75 0 00 0 25 0 00 00 0 00	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .127E 00 .830E-01 .542E-01 .354E-01 .231E-01 .988E-02 .645E-02	0.185E 00 0.298E 00 0.575E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.318E-01 0.208E-01 0.136E-01 0.888E-02 0.580E-02 0.379E-02 0.248E-02	0.336E 00 0.539E 00 0.587E 00
1 1 1 1 1 1 1	2 0. 3 0. 4 0. 5 1. 6 1. 7 1. 8 1. 9 2. 0 2. 1 2. 2 3. 3 3. 5 3. 6 7 4. 8 4.	25 0 50 0 75 0 00 0 25 0 00 0 25 0 00 00 0 00 00 0 00 00 0 00 00 0 00 0 00 00 0 00	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E C0 .195E 00 .127E 00 .830E-01 .542E-01 .354E-01 .354E-01 .988E-02 .425E-02 .425E-02	0.185E 00 0.298E 00 0.575E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.318E-01 0.208E-01 0.136E-01 0.888E-02 0.580E-02 0.379E-02 0.248E-02 0.162E-02	0.336E 00 0.539E 00 0.587E 00
1 1 1 1 1 1 1 1	2 0. 3 0. 4 0. 5 1. 6 1. 7 1. 8 1. 9 2. 0 2. 1 2. 2 3. 3 3. 5 3. 6 3. 7 4. 8 4. 9 4.	25 0 50 0 75 0 00 0 25 0 50 0 50 0 75 0 00 0 25 0 50 0 50 0 75 0 60 0 75 0 60 0 75 0 60 0 75 0 60 0 75 0	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E C0 .127E 00 .830E-01 .542E-01 .354E-01 .31E-01 .151E-01 .988E-C2 .645E-C2 .422E-02 .275E-02 .180E-02	0.185E 00 0.298E 00 0.575E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.318E-01 0.208E-01 0.136E-01 0.888E-02 0.580E-02 0.379E-02 0.248E-02 0.162E-02 0.166E-02	0.336E 00 0.539E 00 0.587E 00
1 1 1 1 1 1 1 1 1 2	2 0. 3 0. 4 0. 5 1. 6 1. 7 1. 8 1. 9 2. 0 2. 1 2. 2 3. 3 3. 5 3. 6 7 4. 8 9 4. 9 4.	25 0 50 0 75 0 00 0 25 0 50 0 75 0	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E C0 .195E 00 .127E 00 .830E-01 .542E-01 .354E-01 .231E-01 .151E-01 .988E-C2 .645E-C2 .422E-02 .275E-02 .180E-02 .118E-02	0.185E 00 0.298E 00 0.575E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.318E-01 0.208E-01 0.136E-01 0.888E-02 0.580E-02 0.379E-02 0.248E-02 0.162E-02 0.166E-02 0.690E-03	0.336E 00 0.539E 00 0.587E 00
1 1 1 1 1 1 1 1 2 2 2	2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	25 0 50 0 75 0 00 25 0 50 0 75 0 00 0 25 0 75 0 00 0 25 0 00 00 0 00 00 0 00	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E C0 .195E 00 .127E 00 .830E-01 .542E-01 .354E-01 .311E-01 .988E-C2 .422E-02 .422E-02 .275E-02 .180E-02 .180E-02 .18E-02 .768E-03	0.185E 00 0.298E 00 0.575E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.318E-01 0.208E-01 0.136E-01 0.888E-02 0.580E-02 0.379E-02 0.248E-02 0.162E-02 0.166E-02	0.336E 00 0.539E 00 0.587E 00
1 1 1 1 1 1 1 1 2 2 2 2	2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	25 0 50 0 75 0 00 0 25 0 00 0 25 0 00 00 0 00 00 0 00 00 0 00	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E 00 .830E-01 .542E-01 .354E-01 .231E-01 .151E-01 .988E-02 .422E-02 .275E-02 .180E-02 .180E-02 .18E-03 .501E-03 .501E-03	0.185E 00 0.298E 00 0.575E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.318E-01 0.208E-01 0.136E-01 0.888E-02 0.580E-02 0.580E-02 0.248E-02 0.166E-02 0.166E-02 0.690E-03 0.451E-03 0.294E-03 0.192E-03	0.336E 00 0.539E 00 0.587E 00
1 1 1 1 1 1 1 1 2 2 2 2 2	2 3 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	25 0 50 0 75 0 00 0 25 0 00 00 0 00 00 0 00 00 0 00	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E 00 .830E-01 .542E-01 .354E-01 .231E-01 .151E-01 .988E-02 .645E-02 .422E-02 .275E-02 .118E-02 .768E-03 .501E-03 .328E-03 .214E-03	0.185E 00 0.298E 00 0.575E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.318E-01 0.318E-01 0.208E-01 0.136E-01 0.888E-02 0.580E-02 0.580E-02 0.162E-02 0.162E-02 0.166E-02 0.690E-03 0.451E-03 0.192E-03 0.126E-03	0.336E 00 0.539E 00 0.587E 00
1 1 1 1 1 1 1 1 2 2 2 2 2 2	2 3 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	25 0 50 0 75 0 00 0 25 0 50 0 75 0 00 0 75 0 00 0 75 0 00 00 0 00 00 0 00 00 0 00	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E 00 .830E-01 .542E-01 .354E-01 .231E-01 .151E-01 .988E-02 .645E-02 .422E-02 .275E-02 .118E-02 .768E-03 .501E-03 .328E-03 .214E-03 .140E-03	0.185E 00 0.298E 00 0.575E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.318E-01 0.208E-01 0.136E-01 0.888E-02 0.580E-02 0.580E-02 0.162E-02 0.162E-02 0.690E-03 0.451E-03 0.192E-03 0.126E-03 0.821E-04	0.336E 00 0.539E 00 0.587E 00
1 1 1 1 1 1 1 1 2 2 2 2 2 2 2	2 3 4 5 6 7 8 9 9 0 1 2 2 3 4 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	25 0 50 0 75 0 00 25 0 75 0 00 0 25 0 00 0 25 0 00 00 0 00 00 0 00 00 0 00	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E-01 .542E-01 .354E-01 .231E-01 .151E-01 .988E-02 .645E-02 .422E-02 .275E-02 .186E-02 .186E-03 .501E-03 .328E-03 .214E-03 .140E-03 .913E-04	0.185E 00 0.298E 00 0.575E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.208E-01 0.136E-01 0.888E-02 0.580E-02 0.580E-02 0.162E-02 0.162E-02 0.162E-02 0.162E-03 0.451E-03 0.49E-03 0.192E-03 0.126E-03 0.821E-04	0.336E 00 0.539E 00 0.587E 00
1 1 1 1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2	2 3 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	25 0 50 0 75 0 00 25 0 50 0 75 0 00 0 25 0 50 0 75 0 00 25 0 50 0 75 0 00 25 0 50 0 75 0 00 0 25 0 50 0 50 0 75 0 00 0 25 0 50	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E 00 .830E-01 .354E-01 .354E-01 .354E-01 .231E-01 .988E-02 .645E-02 .422E-02 .186E-02 .186E-02 .186E-03 .501E-03 .328E-03 .214E-03 .140E-03 .913E-04	0.185E 00 0.298E 00 0.575E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.318E-01 0.208E-01 0.136E-01 0.888E-02 0.580E-02 0.580E-02 0.379E-02 0.248E-02 0.162E-02 0.162E-02 0.690E-03 0.451E-03 0.294E-03 0.192E-03 0.192E-03 0.821E-04 0.536E-04	0.336E 00 0.539E 00 0.587E 00
1 1 1 1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2	2 3 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	25 0 50 0 75 0 00 25 0 50 0 75 0 00 0 25 0 50 0 75 0 00 25 0 50 0 75 0 00 25 0 50 0 75 0 00 25 0 50 0 75 0 00 0 25 0 00 0 25 0 00 0 00 0 25 0 00 00 0 00 00 0 00 00 0 00 00 0 00 00 0 00	.806E 01 .212E 01 .108E 01 .700E 00 .456F 00 .298E 00 .195E 00 .127E 00 .830E-01 .542E-01 .354E-01 .231E-01 .988E-02 .645E-02 .422E-02 .275E-02 .180E-02 .18E-02 .18E-03 .501E-03 .328E-03 .214E-03 .140E-03 .913E-04 .597E-04	0.185E 00 0.298E 00 0.575E 00 0.587E 00	0.638E 01 0.211E 01 0.100E 01 0.629E 00 0.410E 00 0.268E 00 0.175E 00 0.114E 00 0.746E-01 0.488E-01 0.208E-01 0.136E-01 0.888E-02 0.580E-02 0.580E-02 0.162E-02 0.162E-02 0.162E-02 0.162E-03 0.451E-03 0.49E-03 0.192E-03 0.126E-03 0.821E-04	0.336E 00 0.539E 00 0.587E 00

			** L=4.20 **		
NO	E	N(E,.56)	EC(D)	N(#E,.50)	EO(I)
1	C.	0.228E 02	0.250F 00	0.570E G1	0.25.0E 00
2	2.25	0.623F 01	0.337E 00	0.210E 01	0.337E 00
3	0.50	0.201F 01	0.497E 00	0.100E 01	0.497E 00
4	0.75	0.126E C1	0.482E 00	0.605E 00	0.482E 00
5	1.00 1.25	0.696E 00 0.409E 00	0.517E 00 0.542E 00	0.360E 00 0.222E 00	0.517E 00 0.542E 00
6 7	1.50	0.287E 00	0.488E CC	0.140E 00	0.488E 00
8	1.75	0.167E 00	0.502E 00	0.839E-01	0.502E 00
9	2.90	0.863E-01	0.591E 00	0.510E-01	0.591E 00
10	2.25	0.665E-01	0.502E 00	0.334E-01	0.502E 00
11	2.50	0.376E-01	0.540E 00	0.203E-01	0.5405 00
12 13	2.75 3.00	0.237F-J1 0.149E-C1	0.540E 00 0.540E 00	0.128E-01 0.805E-02	0.540E 00 0.540E 00
13	3.25	0.149E-01 0.938E-02	0.540E 00	0.507E-02	0.540E 00
15	3.50	0.590E-02	0.540E 00	0.319E-02	0.540E 00
16	3.75	0.372E-02	0.540E 00	0.201E-02	0.540E 00
17	4.CO	0.234E-02	0.540E 00	0.126E-02	0.540E 00
18	4.25	0.147E-02	0.540E 00	0.796E-03	0.540E 00
19	4.50	0.928E-03	0.540E 00	0.501E-03	0.540£ 00
20 21	4.75 5.00	0.584E-03 0.368E-03	0.540E 00 0.540E 00	0.316E-03 0.199E-03	0.540E 00 0.540E 00
22	5.25	0.232E-03	0.540E 00	0.125E-03	0.540E 00
23	5.50	0.146E-03	0.540E 00	0.788E-04	0.540E 00
24	5.75	0.918E-04	0.540€ 00	G.496E-G4	0.540E 00
25	6.00	0.578E-04	0.540E 00	0.312E-04	0.540E 00
26	6.25	0.364E-04	C.540E 00	0.197E-04	0.540E 00
27	6.50	0.229E-04	0.540E 00	0.124E-64	0.540E 00
28 29	6.75 7.00	0.144E-04 0.908E-05	0.540E 00 0.540E 00	0.779E-05 0.491E-05	0.540E 00 0.540E 00
٠,					
NO	E	N(E,.50)	** L=4.40 ** EC(D)		E0(1)
	E	N(E,.50)	** L=4.40 ** EC(D)	N(*E,.5C)	E0(1)
1	E 0•	N(E,.50)	** L=4.40 ** EC(D) 0.276E 00		
	E	N(E,.50)	** L=4.40 ** EC(D)	N(*E,.50) G.520E 01	E0(1)
1 2 3 4	E 0• 0•25	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01	6.276E 00 0.276E 00 0.337E 00 0.438E 00 0.447E 00	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00	E0(I) 0.276E G0 0.337E G0 0.438E 00 0.447E 00
1 2 3 4 5	0. 0.25 0.50 0.75 1.00	N(E,.50) 0.189E 02 0.623E 01 0.228E 01 0.126E 01 0.692E 00	6.276E 00 0.276E 00 0.337E 00 0.438E 00 0.447E 00 0.467E 00	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00	0.276E GO 0.337E GO 0.438E GO 0.447E GO 0.467E GO
1 2 3 4 5	0. 0.25 0.50 0.75 1.00 1.25	N(E,.50) 0.189E 02 0.623E 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00	6.276E 00 0.337E 00 0.438E 00 0.447E 00 0.467E 00 0.470E 00	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO
1 2 3 4 5 6 7	0. 0.25 0.50 0.75 1.00 1.25 1.50	N(E,.50) 0.189E 02 0.623E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00	6.276E 00 0.337E 00 0.438E 00 0.447E 00 0.467E 00 0.470E 00 0.441E 00	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00	E0(I) 0.276E G0 0.337E G0 0.438E 00 0.447E 00 0.467E 90 0.470E 00 0.441E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50	N(E,.50) 0.189E 02 0.623E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E 60	6.276E 00 0.337E 00 0.438E 00 0.447E 00 0.467E 00 0.470E 00 0.441E 00 0.458E 00	N(*E,.50) G.520E 01 G.210E 01 0.100E 01 0.565E 00 G.323E 00 C.189E 00 G.111E 00 G.630E-01	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50	N(E,.50) 0.189E 02 0.623E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00	6.276E 00 0.337E 00 0.438E 00 0.447E 00 0.467E 00 0.470E 00 0.441E 00	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO 0.441E OO 0.458E OO
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00	N(E,.50) 0.189E G2 0.623E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1	6.276E 00 0.337E 00 0.438E 00 0.447E 00 0.467E 00 0.470E 00 0.441E 00 0.458E 00 0.464E 00	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-01 0.125E-01	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO 0.441E OO 0.458E GO 0.464E CO 0.469E OO
1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E 00 0.786E-01 0.454E-01 0.268E-01 0.157E-01	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-01 0.125E-01 0.731E-02	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO 0.441E OO 0.458E GO 0.464E CO 0.469E OO 0.466E OO
1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-01 0.125E-01 0.731E-02 0.427E-02	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO 0.441E OO 0.458E GO 0.464E CO 0.469E OO 0.466E OO 0.466E OO
1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90 3.25	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02 0.536E-02	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-01 0.125E-01 0.731E-02 0.427E-02 0.250E-02	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO 0.441E OO 0.458E OO 0.464E CO 0.469E OO 0.466E OO 0.466E OO
1 2 3 4 5 6 7 8 9 10 11 12 13 14	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90 3.25 3.50	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02 0.536E-02 0.314E-02	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-C1 0.125E-01 0.731E-02 0.427E-02 0.250E-02 0.146E-02	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO 0.458E GO 0.458E GO 0.464E CO 0.469E OO 0.466E OO 0.466E OO 0.466E OO
1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90 3.25 3.50 3.75	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E 00 0.786E-01 0.454E-01 0.268E-01 0.157E-01 0.917E-02 0.536E-02 0.314E-02 0.183E-02	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-01 0.125E-01 0.731E-02 0.427E-02 0.250E-02	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO 0.441E OO 0.458E OO 0.464E CO 0.469E OO 0.466E OO 0.466E OO
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90 3.25 3.50	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02 0.536E-02 0.314E-02	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-01 0.125E-01 0.731E-02 0.427E-02 0.250E-02 0.146E-02 0.854E-03 0.499E-03 0.292E-03	0.276E 00 0.337E 00 0.438E 00 0.447E 00 0.467E 00 0.470E 00 0.458E 00 0.464E 00 0.466E 00 0.466E 00 0.466E 00 0.466E 00 0.466E 00 0.466E 00 0.466E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90 3.25 3.50 3.75 4.00 4.25 4.50	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-01 0.454E-01 0.268E-01 0.157E-01 0.917E-02 0.536E-02 0.314E-02 0.183E-02 0.107E-02 0.626E-03 0.366E-03	## L=4.40 ## EC(D) 0.276E 00 0.337E 00 0.438E 00 0.447E 00 0.467E 00 0.441E 00 0.458E 00 0.466E 00	N(*E50) G.520E 01 G.210E 01 0.100E 01 0.565E 00 G.323E 00 G.11E 00 G.630E-01 G.365E-01 G.213E-C1 G.125E-01 G.731E-02 G.427E-C2 G.250E-02 G.146E-02 G.854E-03 G.499E-03 G.292E-03 G.171E-03	E0(I) 0.276E G0 0.337E G0 0.438E 00 0.447E 00 0.467E 90 0.470E 00 0.458E 00 0.464E 00 0.466E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90 3.25 3.50 3.75 4.00 4.25 4.50 4.75	N(E,.50) 0.189E 02 0.623E 01 0.126E 01 0.692E 00 0.402E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02 0.536E-02 0.314E-02 0.183E-02 0.167E-02 0.626E-03 0.366E-03 0.214E-03	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-01 0.125E-01 0.731E-02 0.427E-02 0.250E-02 0.146E-02 0.854E-03 0.499E-03 0.292E-03 0.171E-03 0.997E-04	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO 0.441E OO 0.458E GO 0.464E CO 0.466E OO 0.466E OO 0.466E OO 0.466E OO 0.466E OO 0.466E OO 0.466E OO 0.466E OO
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	N(E,.50) 0.189E 02 0.623E 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02 0.536E-02 0.183E-02 0.183E-02 0.107E-02 0.626E-03 0.366E-03 0.214E-03 0.125E-03	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.213E-01 0.125E-01 0.125E-01 0.731E-02 0.427E-02 0.250E-02 0.146E-02 0.854E-03 0.499E-03 0.292E-03 0.171E-03 0.997E-04 0.583E-04	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO 0.441E OO 0.441E OO 0.464E OO 0.466E OO
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25	N(E,.50) 0.189E 02 0.623E 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02 0.536E-02 0.183E-02 0.183E-02 0.183E-02 0.183E-02 0.167E-02 0.626E-03 0.366E-03 0.214E-03 0.125E-03 0.732E-04	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.213E-01 0.125E-01 0.125E-01 0.731E-02 0.427E-02 0.250E-02 0.146E-02 0.854E-03 0.499E-03 0.292E-03 0.171E-03 0.997E-04 0.583E-04 0.341E-04	E0(I) 0.276E G0 0.337E G0 0.438E 00 0.447E 00 0.467E 00 0.467E 00 0.464E C0 0.466E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	N(E,.50) 0.189E 02 0.623E 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02 0.536E-02 0.183E-02 0.183E-02 0.107E-02 0.626E-03 0.366E-03 0.214E-03 0.125E-03	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.213E-01 0.125E-01 0.125E-01 0.731E-02 0.427E-02 0.250E-02 0.146E-02 0.854E-03 0.499E-03 0.292E-03 0.171E-03 0.997E-04 0.583E-04	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.467E OO 0.470E OO 0.441E OO 0.441E OO 0.464E OO 0.466E OO
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02 0.536E-02 0.314E-02 0.183E-02 0.183E-02 0.107E-02 0.626E-03 0.366E-03 0.214E-03 0.125E-03 0.732E-04 0.428E-04	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-C1 0.125E-01 0.731E-02 0.427E-02 0.250E-02 0.146E-02 0.854E-03 0.499E-03 0.292E-03 0.171E-03 0.997E-04 0.583E-04 0.341E-04 0.199E-04 0.116E-04 0.681E-05	E0(I)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00 6.25	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02 0.536E-02 0.314E-02 0.183E+02 0.107E-02 0.626E-03 0.366E-03 0.366E-03 0.214E-03 0.125E-03 0.732E-04 0.428E-04 0.250E-04 0.854E-05	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-01 0.125E-01 0.731E-02 0.427E-02 0.250E-02 0.146E-02 0.854E-03 0.499E-03 0.292E-03 0.171E-03 0.997E-04 0.583E-04 0.341E-04 0.199E-04 0.116E-04 0.681E-05 0.398E-05	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.447E OO 0.470E OO 0.458E OO 0.464E OO 0.466E OO
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.55 5.50 5.75 6.00 6.25 6.50	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02 0.536E-02 0.314E-02 0.183E+02 0.107E-02 0.626E-03 0.366E-03 0.214E-03 0.125E-03 0.732E-04 0.428E-04 0.250E-04 0.146E-04 0.854E-05 0.50GE-05	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-C1 0.125E-01 0.731E-02 0.427E-02 0.250E-02 0.146E-02 0.854E-03 0.499E-03 0.292E-03 0.171E-03 0.997E-04 0.583E-04 0.199E-04 0.116E-04 0.681E-05 0.398E-05 0.233E-05	0.276E GO 0.337E OO 0.438E OO 0.447E OO 0.467E OO 0.470E OO 0.458E OO 0.464E OO 0.466E OO
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.90 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00 6.25	N(E,.50) 0.189E 02 0.623F 01 0.228E 01 0.126E 01 0.692E 00 0.402E 00 0.251E 00 0.138E GC 0.786E-C1 0.454E-01 0.268E-01 0.157E-C1 0.917E-02 0.536E-02 0.314E-02 0.183E+02 0.107E-02 0.626E-03 0.366E-03 0.366E-03 0.214E-03 0.125E-03 0.732E-04 0.428E-04 0.250E-04 0.854E-05	** L=4.40 **	N(*E,.50) 0.520E 01 0.210E 01 0.100E 01 0.565E 00 0.323E 00 0.189E 00 0.111E 00 0.630E-01 0.365E-01 0.213E-01 0.125E-01 0.731E-02 0.427E-02 0.250E-02 0.146E-02 0.854E-03 0.499E-03 0.292E-03 0.171E-03 0.997E-04 0.583E-04 0.341E-04 0.199E-04 0.116E-04 0.681E-05 0.398E-05	0.276E GO 0.337E GO 0.438E OO 0.447E OO 0.447E OO 0.470E OO 0.458E OO 0.464E OO 0.466E OO

NO.	E	N(E50)	** L=4.60 **	NINE COL	55.44
~~~~			EG(D)	N(*E,.50)	(I) 03
1	Ç.,	0.174E 02	0.288E 00	0.500E 01	0.288E 00
2 3	0.25 0.50	0.623E 01 0.246E 01	0.337E 00	0.210E 01	0.337E 00
4	0.75	0.132E 01	0.406E 00 0.409E 00	0.100E 01 0.540E 00	0.406E 00 0.409E 00
5	1.00	C.687E CO	0.426E 00	0.293E 00	0.426E 00
6	1.25	0.395F 00	0.413E 00	0.163E 00	0.413E 00
7 8	1.50 1.75	0.209£ 00	0.426E 00	0.890E-01	0.426[ 00
9	2.00	0.115E 00 0.680E-01	0.431E 00 0.408E 00	0.495E-01 C.277E-01	0.431E 00 0.408E 00
10	2.25	0.370E-01	0.406E 00	0.1508-01	0.406E 00
11	2.50	0.194E-01	0.416E 00	0.810E-02	0.416E 00
12 13	2.75 3.00	0.107E-01	0.416E 00	C.444E-02	0.416E 00
14	3.25	0.585E-02 0.321E-02	0.416E 00 0.416E 00	0.244E-02 0.134E-02	0.416E 00 0.416E 00
15	3.50	0.176E-02	0.416E 00	0.734E-03	0.416E 00
16	3.75	0.967E-03	0.416E 00	0.403E-03	0.416E 00
17	4.00	0.531E-03	0.416F 00	0.221E-03	0.416E 00
18 19	4.25 4.50	0.291E-03 0.160E-03	0.416E 00 0.416E 00	0.121E-03 0.665E-04	0.416E 00 0.416E 00
20	4.75	0.876E-04	0.416E 00	0.365E-04	0.416E 00
21	5.CO	0.481E-04	0.416E 00	C.200E-C4	0.416E 00
22	5.25	0.264E-04	0.416E 00	0.110E-04	0.416E 00
23 24	5.50 5.75	0.145E-04 0.794E-05	0.416E 00 0.416E 00	0.603E-05 0.331E-05	0.416E 00 0.416E 00
25	6.00	0.436E-05	0.416E 00	0.182E-05	0.416E 00
26	6.25	0.239E-C5	0.416F 00	0.996E-06	0.416E 00
27	6.50	0.131E-05	0.416E 00	0.546E-06	0.416E 00
28 29	6.75 7.00	0.720E-06 0.395E-06	0.416E 00 0.416F 00	0.300E-06 0.165E-06	0.416E 00 0.416E 00
		000,771.00	0.4101 00	0.000 -00	A. 4105 00
			## 1=4_8C ##		
NO	É	N(E,.50)	** L=4.80 ** E0(D)	N(*E,.50)	EO(1)
1	c.	N(E,.50)		N(*E,.50) 	EO(1) 
1 2	0. 0.25	0.170F G2 0.623E 01	E0(D) 0.292E 00 0.337E 00	0.495E 01 0.210E 01	0.292E 00 0.337E 00
1 2 3	0. 0.25 0.50	0.170F G2 0.623E 01 0.262E 01	0.292E 00 0.337E 00 0.382E 00	0.495E 01 0.210E 01 0.100E 01	0.292E 00 0.337E 00 0.382E 00
1 2 3 4	0. 0.25 0.50 0.75	0.170F G2 0.623E 01 0.262E 01 0.138E 01	E0(D) 0.292E 00 0.337E 00 0.382E 00 (.377E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00	0.292E 00 0.337E 00 0.382E 00 0.377E 00
1 2 3 4 5 6	0. 0.25 0.50 0.75 1.00 1.25	0.170F G2 0.623E 01 0.262E 01	0.292E 00 0.337E 00 0.382E 00	0.495E 01 0.210E 01 0.100E 01	0.292E 00 0.337E 00 0.382E 00
1 2 3 4 5 6 7	0. 0.25 0.50 0.75 1.00 1.25 1.50	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190E 00	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 C.388E 00 0.390E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190E 00 0.958E-01	0.292E 00 0.337E 00 0.382E 00 0.389E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00
1 2 3 4 5 6 7 8	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 00 0.958E-01	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00 0.373E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00 0.373E 00
1 2 3 4 5 6 7 8 9 10	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190E 00 0.958E-01	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00 0.407E 00 0.373E 00 0.381E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00
1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 0C 0.958E-01 0.565E-01 0.284E-01 0.145E-01 0.759E-02	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.388E 00 0.390E 00 0.407E 00 0.407E 00 0.373E 00 0.381E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01 0.108E-01	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00 0.373E 00 0.381E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 0C 0.958E-C1 0.565E-01 0.284E-01 0.145E-01 0.759E-02 0.397E-02	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00 0.407E 00 0.381E 00 0.387E 00 0.387E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00 0.373E 00 0.381E 00 0.387E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 0C 0.958E-01 0.565E-01 0.284E-01 0.145E-01 0.759E-02 0.397E-02 0.208E-02	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.388E 00 0.390E 00 0.407E 00 0.407E 00 0.407E 00 0.381E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.390E 00 0.407E 00 0.373E 00 0.381E 00 0.387E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 0C 0.958E-C1 0.565E-01 0.284E-01 0.145E-01 0.759E-02 0.397E-02	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00 0.407E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03 0.422E-03	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00 0.373E 00 0.381E 00 0.387E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 0C 0.958E-C1 0.565E-01 0.284E-01 0.145E-01 0.145E-01 0.759E-02 0.397E-02 0.208E-02 0.109E-02 0.572E-03 0.300E-03	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.390E 00 0.407E 00 0.407E 00 0.373E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03 0.422E-03 0.221E-03 0.116E-03	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.390E 00 0.407E 00 0.373F 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25	0.170F G2 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190E 0C 0.958E-C1 0.565E-01 0.284E-01 0.145E-01 0.759E-C2 0.397E-02 0.208E-C2 0.109E-02 0.572E-03 0.300E-03 0.157E-03	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.389E 00 0.389E 00 0.390E 00 0.407E 00 0.373E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03 0.422E-03 0.422E-03 0.116E-03 0.607E-04	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.390E 00 0.407E 00 0.373F 00 0.381E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50	0.170F G2 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 0C 0.958E-C1 0.565E-01 0.284E-01 0.145E-01 0.759E-C2 0.397E-02 0.208E-02 0.109E-02 0.572E-03 0.30GE-03 0.157E-03	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.388E 00 0.390E 00 0.407E 00 0.373E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03 0.422E-03 0.422E-03 0.211E-04 0.318E-04	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.389E 00 0.390E 00 0.407E 00 0.373E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25	0.170F G2 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190E 0C 0.958E-C1 0.565E-01 0.284E-01 0.145E-01 0.759E-C2 0.397E-02 0.208E-C2 0.109E-02 0.572E-03 0.300E-03 0.157E-03	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.389E 00 0.389E 00 0.390E 00 0.407E 00 0.373E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03 0.422E-03 0.422E-03 0.116E-03 0.607E-04	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.390E 00 0.407E 00 0.373F 00 0.381E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.75 3.00 3.75 4.00 4.25 4.50 4.75 5.00 5.25	0.170F G2 0.623E 01 0.262E 01 0.138E G1 0.688E 00 0.364E 00 0.190F 0C 0.958E-C1 0.565E-01 0.284E-01 0.145E-01 0.759E-02 0.397E-02 0.397E-02 0.208E-C2 0.109E-02 0.572E-03 0.300E-03 0.157E-03 0.822E-04 0.431E-04 0.226E-04 0.118E-04	E0(D)  0.292E 00 0.337E 00 0.387E 00 0.389E 00 0.389E 00 0.380E 00 0.407E 00 0.373E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03 0.422E-03 0.211E-03 0.116E-03 0.607E-04 0.318E-04 0.167E-04 0.873E-05 0.457E-05	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.389E 00 0.390E 00 0.373E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.75 4.00 4.50 4.50 4.50 5.25 5.50	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 0C 0.958E-C1 0.565E-01 0.284E-01 0.145E-01 0.759E-02 0.397E-02 0.397E-02 0.109E-02 0.572E-03 0.30GE-03 0.157E-03 0.822E-04 0.431E-04 0.226E-04 0.118E-04 0.620E-05	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.389E 00 0.390E 00 0.407E 00 0.373E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03 0.422E-03 0.16E-03 0.422E-03 0.16E-03 0.607E-04 0.318E-04 0.167E-04 0.873E-05 0.426E-05	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.389E 00 0.390E 00 0.397E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.75 3.00 3.75 4.00 4.25 4.50 4.75 5.00 5.25	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 0C 0.958E-C1 0.565E-01 0.284E-01 0.145E-01 0.759E-02 0.397E-02 0.397E-02 0.208E-02 0.109E-02 0.572E-03 0.300E-03 0.157E-03 0.822E-04 0.431E-04 0.226E-04 0.118E-04 0.620E-05 0.325E-05	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.389E 00 0.390E 00 0.407E 00 0.373E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03 0.422E-03 0.422E-03 0.116E-03 0.607E-04 0.318E-04 0.167E-04 0.873E-05 0.457E-05 0.240E-05	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.388E 00 0.390E 00 0.390E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.025 2.75 3.00 2.75 3.75 4.00 4.75 5.00 4.75 5.00 5.75 6.00 6.25	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 0C 0.958E-C1 0.565E-01 0.284E-01 0.145E-01 0.759E-02 0.397E-02 0.397E-02 0.109E-02 0.572E-03 0.30GE-03 0.157E-03 0.822E-04 0.431E-04 0.226E-04 0.118E-04 0.620E-05	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.389E 00 0.390E 00 0.407E 00 0.373E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03 0.422E-03 0.16E-03 0.422E-03 0.16E-03 0.607E-04 0.318E-04 0.167E-04 0.873E-05 0.426E-05	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.389E 00 0.390E 00 0.397E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	0.25 0.25 0.75 1.00 1.250 1.75 2.00 2.75 3.25 2.75 3.50 4.75 4.50 4.75 5.25 5.75 6.25 6.50	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 0C 0.958E-C1 0.565E-01 0.284E-01 0.145E-01 0.759E-02 0.397F-02 0.397F-02 0.208E-02 0.109E-02 0.572E-03 0.300E-03 0.157E-03 0.822E-04 0.431E-04 0.26E-04 0.118E-04 0.26E-05 0.325E-05 0.170E-05 0.891E-06 0.467E-06	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.387E 00 0.388E 00 0.390E 00 0.407E 00 0.373E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.52CE 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03 0.422E-03 0.422E-03 0.422E-03 0.422E-03 0.16E-03 0.607E-04 0.318E-04 0.167E-04 0.873E-05 0.457E-05 0.457E-05 0.240E-05 0.658E-06 0.345E-06 0.181E-06	0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.390E 00 0.390E 00 0.397E 00 0.387E 00
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.025 2.75 3.00 2.75 3.75 4.00 4.75 5.00 4.75 5.00 5.75 6.00 6.25	0.170F 02 0.623E 01 0.262E 01 0.138E 01 0.688E 00 0.364E 00 0.190F 0C 0.958E-01 0.565E-01 0.284E-01 0.145E-01 0.759E-02 0.397F-02 0.397F-02 0.208E-02 0.109E-02 0.572E-03 0.300E-03 0.157E-03 0.822E-04 0.431E-04 0.226E-04 0.118E-04 0.620E-05 0.325E-05 0.170E-05 0.891E-06	E0(D)  0.292E 00 0.337E 00 0.382E 00 0.377E 00 0.389E 00 0.388E 00 0.390E 00 0.407E 00 0.387E 00	0.495E 01 0.210E 01 0.100E 01 0.520E 00 0.268E 00 0.141E 00 0.740E-01 0.390E-01 0.211E-01 0.108E-01 0.560E-02 0.293E-02 0.154E-02 0.805E-03 0.422E-03 0.422E-03 0.422E-03 0.422E-03 0.116E-03 0.607E-04 0.1873E-05 0.457E-05 0.240E-05 0.126E-05 0.658E-06 0.345E-06	0.292E 00 0.337E 00 0.387E 00 0.387E 00 0.389E 00 0.389E 00 0.389E 00 0.397E 00 0.387E 00

N:O	c	NIE E'N	** L=5.00 **	MARE EAS	ECITA
NO	E	N(E,.50)	E0(D)	N(*E,.50)	EC(I)
1	Ů.	0.186E 02	C-245E 00	0.504E 01	0.289E 00
2	0.25	0.671F 01	0.289E 00	0.212E 01	0.332E 00
3 4	0.50 0.75	0.283E 61 0.139E 01	0.352E.00 0.352E.00	0.100E 01 0.494E 00	0.354E 00 0.356E 00
5	1.00	C.683E 00	0.352E 00	0.245E CO	0.361E 00
6	1.25	0.336E 00	0.365E 00	0.123E 00	0.365E 00
7	1.50	0.169E CO	0.365E 00	G.618E-C1	0.365E CO
8	1.75	0.853E-01	0.365E 00	0.311E-01	0.365E CO
9	2.00	C.430E-C1	0.365E 00	C-157E-01	0.365E 00
10	2.25	0.217E-01 0.109E-01	0.365F 00	0.791E-02 0.399E-02	0.365E 00
11 12	2.50 2.75	0.109E-01	0.365E 00 0.365E 00	0.399E-02	0.365E 00 0.365E 00
13	3.00	0.278E-02	0.365E 00	0.101E-02	0.365E 00
14	3.25	C-140E-02	0.365E 00	0.511E-03	0.365E 00
15	3.50	0.706E-03	0.365E 00	0.258E-03	0.365E 00
16	3.75	0.356F-03	0.365E 00	0.130E-03	0.365E 00
17	4.00	0.179E-03	0.365E 00	0.655E-04	0.365E CO
18 19	4.25 4.50	0.905E-04 0.456E-04	C.365F 00 C.365E 00	0.330E-04 0.166E-04	0.365E 00 0.365E 00
20	4.75	0.430E-04	0.365E 00	C.839E-05	0.365E 00
21	5.00	0.116E-04	0.365E CO	G.423E-05	0.365E 00
22	5.25	0.584E-05	0.365E 00	G.213E-05	0.365E 00
23	5.50	0.295E-05	0.365E 00	0.108E-05	0.365E 00
24	5.75	C.148F-05	0.365E 00	C.542E-06	0.365E 00
25	6.00	0.749E-06	0.365E 00	0.273E-06	0.365E CO
26 27	6.25 6.50	C.377F-06 O.190E-06	0.365E 00 0.365E 00	0.138E-06 0.695E-07	0.365E 00 0.365E 00
28	6.75	0.170E 00	0.365E 00	0.350E-07	0.365E 00
			G.365E 00	0.177E-07	
29	7.00	0.484E-07	0.302E 00	O. T.I.F. O.I.	0.365E 00
29	7.00	U.464E-07	** L=5.20 **	0.1111.51	0.3635 00
NO	F	N(E,.50)		N(*E,.50)	60(1)
			** L=5.20 ##		
NO1	0. 0.25	N(E,.50)	** L=5.20 ** EC(D) 0.274E 00 0.323E 00	N(*E,.50) 0.540E 01 0.217E 01	0.274E 00 0.323E 00
NO 1 2 3	0. 0.25 0.50	N(E,.50) 0.197E 02- 0.672E 01 0.306E 01	** L=5.20 ** EC(0) 0.274E 00 0.323E 00 0.326E 00	N(*E,.50) 0.540E 01 0.217E 01 0.130E 01	0.274E 00 0.323E 00 0.326E 00
NO 1 2 3 4	0. 0.25 0.50 0.75	N(E,.50) 0.197E 02- 0.672E 01 0.306E 01 0.139E 01	** L=5.20 ** EC(D) 0.274E 00 0.323E 00 0.326E 00 0.334E 00	N(*E,.50) 0.540E 01 0.217E 01 0.100E 01 0.465E 00	0.274E 00 0.323E 00 0.326E 00 0.334E 00
NO 1 2 3 4 5	0. 0.25 0.50 0.75 1.00	N(E,.50) 0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00	** L=5.20 ** EC(D) 0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00
NO 1 2 3 4 5 6	0. 0.25 0.50 0.75 1.00	N(E,.50)  0.197E C2 0.672E C1 0.306E C1 0.139E C1 0.651E CC	** L=5.20 ** EC(D) 0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.333E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.333E 00
NO 1 2 3 4 5	0. 0.25 0.50 0.75 1.00	N(E,.50) 0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00	** L=5.20 ** EC(D) 0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00 0.496E-01 0.236E-01	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00
NO	0. 0.25 0.50 0.75 1.C0 1.25 1.50 1.75 2.00	N(E,.50)  0.197E C2- 0.672E C1 0.306E C1 0.139E C1 0.651E C0 0.315E CC 0.147E CO	** L=5.20 ** EC(D) 0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.333E 00 0.337F 00 0.335E 00 0.352E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.333E 00 0.337E 00 0.335E 00 0.352E 00
NO	0. 0.25 0.50 0.75 1.C0 1.25 1.50 1.75 2.00	N(E,.50)  0.197E 02  0.672E 01  0.306E 01  0.139E 01  0.651E 00  0.315E 00  0.147E 00  0.704E-01  0.319E-01  0.165E-01	** L=5.20 ** EC(D) 0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337F 00 0.335E 00 0.335E 00 0.335E 00	N(*E,.50) 0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-02	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.335E 00 0.352E 00 0.334E 00
NO	0. 0.25 0.50 0.75 1.C0 1.25 1.50 1.75 2.C0 2.25 2.50	N(E,.50)  0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00 0.315E 00 0.147E 00 0.704E-01 0.319E-01 0.165E-01	** L=5.20 ** EC(D) 0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337F 00 0.335E 00 0.335E 00 0.335E 00 0.335E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.105E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-02 0.260E-02	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.335E 00 0.352E 00 0.34E 00
NO	0. 0.25 0.50 0.75 1.C0 1.25 1.50 1.75 2.C0 2.25 2.50 2.75	N(E,.50)  0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00 0.315E 00 0.147E 00 0.704E-01 0.319E-01 0.165E-01 0.749E-02 0.364E-02	** L=5.20 ** EC(D) 0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337F 00 0.335E 00 0.352E 00 0.334E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.105E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-02 0.260E-02 0.127E-02	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.335E 00 0.352E 00 0.352E 00 0.352E 00 0.347E 00
NO  1 2 3 4 5 6 7 8 9 10 11 12 13	0. 0.25 0.50 0.75 1.C0 1.25 1.50 1.75 2.C0 2.25 2.50 2.75 3.00	N(E,.50)  0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00 0.315E 00 0.147E 00 0.704E-01 0.319E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02	** L=5.20 ** EC(D) 0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337F 00 0.335E 00 0.335E 00 0.335E 00 0.335E 00 0.347E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.105E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-02 0.260E-02 0.127E-02 0.616E-03	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.337E 00 0.352E 00 0.352E 00 0.352E 00 0.347E 00 0.347E 00
NO	0. 0.25 0.50 0.75 1.C0 1.25 1.50 1.75 2.C0 2.25 2.50 2.75	N(E,.50)  0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00 0.315E 00 0.147E 00 0.704E-01 0.319E-01 0.165E-01 0.749E-02 0.364E-02	** L=5.20 ** EC(D) 0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337F 00 0.335E 00 0.352E 00 0.334E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.105E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-02 0.260E-02 0.127E-02	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.335E 00 0.352E 00 0.352E 00 0.352E 00 0.347E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25	N(E,.50)  0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00 0.315E 00 0.147E 00 0.704E-01 0.319E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02 0.864E-03	** L=5.20 ** EC(D) 0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337F 00 0.335E 00 0.35E 00 0.35E 00 0.34E 00 0.347E 00 0.347E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-02 0.260E-02 0.127E-02 0.616E-03 0.300E-03	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.337E 00 0.352E 00 0.352E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	N(E,.50)  0.197E C2- 0.672E C1 0.306E C1 0.139E O1 0.651E 00 0.315E CC 0.147E CO 0.704E-01 0.319E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02 0.864E-03 0.420E-03 0.205E-03	** L=5.20 ** EC(D)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.333E 00 0.337F 00 0.335E 00 0.352E 00 0.352E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-02 0.260E-02 0.127E-02 0.616E-03 0.300E-03 0.146E-03 0.711E-04 0.346E-64	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.337E 00 0.352E 00 0.352E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.75 4.00 4.25	N(E,.50)  0.197E C2- 0.672E C1 0.306E C1 0.139E O1 0.651E 00 0.315E CC 0.147E C0 0.704E-01 0.319E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02 0.864E-03 0.420E-03 0.420E-03 0.996E-04 0.485E-04	** L=5.20 ** EC(D)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.333E 00 0.337F 00 0.335E 00 0.352E 00 0.352E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-02 0.260E-02 0.127E-02 0.616E-03 0.300E-03 0.146E-03 0.711E-04 0.346E-04 0.168E-04	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.335E 00 0.352E 00 0.352E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.50 3.75 4.00 4.25 4.50	N(E,.50)  0.197E C2- 0.672E C1 0.306E C1 0.139E O1 0.651E 00 0.315E CC 0.147E C0 0.704E-01 0.319E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02 0.864E-03 0.420E-03 0.420E-03 0.996E-04 0.485E-04	** L=5.20 ** EC(D)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.333E 00 0.337F 00 0.335E 00 0.352E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00 0.496E-01 0.112E-01 0.550E-02 0.60E-02 0.127E-02 0.616E-03 0.300E-03 0.146E-03 0.711E-04 0.346E-04 0.820E-05	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.337E 00 0.352E 00 0.352E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	N(E,.50)  0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00 0.315E 00 0.147F 00 0.704E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02 0.864E-03 0.420E-03 0.420E-03 0.996E-04 0.485E-04 0.236E-04	** L=5.20 **     EC(D)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.335E 00 0.335E 00 0.335E 00 0.335E 00 0.347E 00	N(*E,.50)	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.335E 00 0.352E 00 0.352E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00 0.347E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.50 3.75 4.00 4.25 4.50	N(E,.50)  0.197E C2- 0.672E C1 0.306E C1 0.139E O1 0.651E 00 0.315E CC 0.147E C0 0.704E-01 0.319E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02 0.864E-03 0.420E-03 0.420E-03 0.996E-04 0.485E-04	** L=5.20 **     EC(D)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.337F 00 0.337F 00 0.335E 00 0.335E 00 0.334E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00 0.496E-01 0.112E-01 0.550E-02 0.60E-02 0.127E-02 0.616E-03 0.300E-03 0.146E-03 0.711E-04 0.346E-04 0.820E-05	60(I)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.335E 00 0.352E 00 0.347E 00
NO  1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.75 5.00	N(E,.50)  0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00 0.315E 00 0.147F 00 0.704E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02 0.864E-03 0.420E-03 0.205E-03 0.996E-04 0.436E-04 0.15E-04 0.559E-05	** L=5.20 **     EC(D)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.337F 00 0.337F 00 0.337E 00 0.337E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-02 0.260E-02 0.127E-02 0.616E-03 0.300E-03 0.146E-03 0.711E-04 0.346E-04 0.346E-04 0.168E-04 0.168E-05 0.399E-05 0.194E-05 0.946E-06 0.460E-06	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.337E 00 0.352E 00 0.352E 00 0.347E 00
NO  1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.75 4.00 4.75 5.00 5.75	N(E,.50)  0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00 0.315E 00 0.147E 00 0.704E-01 0.319E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02 0.864E-03 0.420E-03 0.996E-04 0.485E-04 0.236E-04 0.115E-04 0.559E-05 0.272E-05 0.133E-05 0.645E-06	** L=5.20 **     EC(D)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.337F 00 0.337F 00 0.335E 00 0.352E 00 0.334E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-02 0.260E-02 0.127E-02 0.616E-03 0.300E-03 0.146E-03 0.711E-04 0.346E-04 0.168E-04 0.168E-04 0.194E-05 0.399E-05 0.194E-06 0.460E-06 0.224E-06	60(I)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.337E 00 0.337E 00 0.352E 00 0.352E 00 0.347E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00	N(E,.50)  0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00 0.315E 00 0.147E 00 0.704E-01 0.319E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02 0.864E-03 0.420E-03 0.996E-04 0.485E-04 0.236E-04 0.115E-04 0.559E-05 0.272E-05 0.133E-05 0.645E-06 0.314E-06	** L=5.20 **     EC(D)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.337F 00 0.335E 00 0.335E 00 0.352E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-C2 0.260E-C2 0.127E-02 0.616E-03 0.300E-03 0.146E-03 0.711E-04 0.346E-04 0.168E-04 0.820E-05 0.399E-05 0.194E-05 0.460E-06 0.224E-06 0.109E-06	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.337E 00 0.352E 00 0.352E 00 0.347E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.50 2.75 2.50 2.75 3.50 3.25 3.50 3.75 4.00 4.75 5.00 5.25 5.75 6.00 6.25	N(E,.50)  0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00 0.315E 00 0.147E 00 0.704E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02 0.864E-03 0.420E-03 0.205E-03 0.996E-04 0.485E-04 0.559E-05 0.272E-05 0.133E-05 0.645E-06 0.314E-06 0.153E-06	** L=5.20 **     EC(D)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.337F 00 0.337F 00 0.352E 00 0.352E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-C2 0.260E-C2 0.127E-02 0.616E-03 0.300E-03 0.146E-03 0.711E-04 0.346E-04 0.168E-04 0.820E-05 0.399E-05 0.194E-05 0.946E-06 0.224E-06 0.109E-06 0.531E-07	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.335E 00 0.352E 00 0.352E 00 0.347E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00	N(E,.50)  0.197E 02- 0.672E 01 0.306E 01 0.139E 01 0.651E 00 0.315E 00 0.147E 00 0.704E-01 0.319E-01 0.165E-01 0.749E-02 0.364E-02 0.177E-02 0.864E-03 0.420E-03 0.996E-04 0.485E-04 0.236E-04 0.115E-04 0.559E-05 0.272E-05 0.133E-05 0.645E-06 0.314E-06	** L=5.20 **     EC(D)  0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.337F 00 0.335E 00 0.335E 00 0.352E 00 0.347E 00	N(*E,.50)  0.540E 01 0.217E 01 0.100E 01 0.465E 00 0.220E 00 0.105E 00 0.496E-01 0.236E-01 0.112E-01 0.550E-C2 0.260E-C2 0.127E-02 0.616E-03 0.300E-03 0.146E-03 0.711E-04 0.346E-04 0.168E-04 0.820E-05 0.399E-05 0.194E-05 0.460E-06 0.224E-06 0.109E-06	0.274E 00 0.323E 00 0.326E 00 0.334E 00 0.338E 00 0.337E 00 0.337E 00 0.352E 00 0.352E 00 0.347E 00

NO	Е	N(E, •5C)	** L=5.40 ** EC(D)	N(*E,.50)	E0(1)
1	0.	0.235E 02	C.255E CC	0.600E C1	0.255E 00
2		0.730F 01	0.308E 00	0.225E 01	0.308E GO
3	0.50 0.75	0.329E 01 0.142E 01	0.304E 00 0.308E 00	0.100E 01 0.439E 00	0.304E 00 0.308E 00
5	1.00	0.612E 00	0.319E CO	0.195E 00	0.319E 00
6	1.25	0.289E 00	C.308E 00	C.890E-01	0.308E 00
7 8	1.50 1.75	0.124E 00 0.602E-01	0.318E 00 0.299E 00	0.395E-01 0.180E-01	0.318E 00 C.299E 00
9		G.224E-01	C-348F CC	0.780E-02	0.348E 00
10	2.25	0.122E-01	C.311E 00	0.380E-02	0.311E 00
11	2.50	0.497E-02	0.342E 00	0.170E-02	6.342E 00
12 13	2.75 3.00	0.239E-02 0.115E-02	0.342E 00 0.342E 00	0.818E-03 0.394E-03	0.342E 00 0.342E 00
14	3.25	0.554E-03	0.342E CO	0.189E-03	0.342E 00
15		0.267E-03	0.342E 00	0.911E-04	0.342E 00
16	3.75	0.128E-03	0.342E 00	0.438E~04	0.342E 00
17 18	4.00 4.25	0.617E-04 0.297E-04	0.342E 00 0.342E 00	0.211E-04 0.101E-04	0.342E 00 0.342E 00
19	4.50	0.143E-04	0.342E 00	0.488E-05	0.342E 00
20	4.75	0.687E-05	0.342E 00	0.235E-05	0.342E 00
21 22	5.00 5.25	0.331E-05 0.159E-05	0.342E 00 0.342E 00	0.113E-05	0.342E 00
23		0.766E+06	0.342E 00	0.544E-06 0.202E-06	0.342E 00 0.342E 00
24	5.75	0.368F-06	0.342E 00	0.126E-06	0.342E 00
25	6.00	0.177E-06	0.342E 00	0.606E-07	0.342E 00
26 27	6.25 6.50	0.853E-07 0.410E-07	0.342E 00 0.342E 00	0.291E-07	0.342E 00 0.342E 00
28	6.75	0.197E-07	0.342E 00	0.140E-07 0.675E-08	0.342E 00
29	7.00	0.950E-08	0.342E 00	0.325E-08	0.342E 00
			** L=5.60 **		
29 NO	7•00 E	0.950E-08 N(E,.50)		0.325E-08 N(*E,.50)	0.342E 00 E0(1)
NO 1	E	N(E,.50) 	** L=5.60 ** E0(D) 0.240E 00	N(*E,.50)	E0(1)
NO 1 2	E 0. 0.25	N(E,.50) 	** L=5.60 ** E0(D) 0.240E 00 0.288E 00	N(*E,.50) 0.675E 01 0.238E 01	E0(1) 0.240E 00 0.288E 00
NO 1 2 3	0. 0.25 0.50	N(E,.50) 	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.289E 00	N(*E,.5C)  0.675E 01 0.238E 01 0.100E 01	E0(1) 0.240E 00 0.288E 00 0.280E 00
NO 1 2	E 0. 0.25	N(E,.50) 	** L=5.60 ** E0(D) 0.240E 00 0.288E 00	N(*E,.50) 0.675E 01 0.238E 01	E0(1) 0.240E 00 0.288E 00
NO 1 2 3 4 5	0. 0.25 0.50 0.75 1.00	N(E,.50) 0.281E 02 0.825E 01 0.357E 01 0.144E 01 0.566F 00 0.258E 00	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.287E 00	N(*E,.5C)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-C1	E0(1) 0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.287E 00
NO 2 3 4 5 6 7	0. 0.25 0.50 0.75 1.00 1.25	N(E,.50) 0.281E 02 0.825E 01 0.357E 01 0.144E 01 0.566F 00 0.258E 00 0.105E 00	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.287E 00 0.295F 00	N(*E,.5C)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-C1 0.310E-01	0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.287E 00 0.295E 00
NO 	0. 0.25 0.50 0.75 1.00 1.25 1.50	N(E,.50) 	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.287E 00 0.295F 00 0.277E 00	N(*E,.5C)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-C1 0.310E-01 0.133E-01	E0(1)  0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.287E 00 0.295E 00 0.277E 00
NO 2 3 4 5 6 7	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25	N(E,.50) 0.281E 02 0.825E 01 0.357E 01 0.144E 01 0.566F 00 0.258E 00 0.105E 00	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.287E 00 0.295F 00	N(*E,.5C)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-C1 0.310E-01	0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.287E 00 0.295E 00
NO 1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50	N(E,.50) 0.281E 02 0.825E 01 0.357E 01 0.144E 01 0.566F 00 0.258E 00 0.105E 00 0.480E-01 0.166E-01 0.803E-02 0.803E-03	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.289E 00 0.284E 00 0.301E 00 0.287E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01	N(*E50)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-C1 0.310E-01 0.133E-01 0.540E-02 0.250E-02 0.112E-02	E0(1) 0.240E 00 0.288E 00 0.280E 00 0.301E 00 0.287E 00 0.295E 00 0.325E 00 0.311E 00 0.140E 01
NO 1 2 3 4 5 6 7 8 9 10 11 12	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75	N(E,.50) 0.281E 02 0.825E 01 0.357E 01 0.144E 01 0.566E 00 0.258E 00 0.105E 00 0.480E-01 0.166E-01 0.803E-02 0.803E-03 0.671E-03	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.289E 00 0.301E 00 0.287E 00 0.295F 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01	N(*E50)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-01 0.310E-01 0.133E-01 0.540E-02 0.250E-02 0.112E-02 0.936E-03	E0(1)  0.240E 00 0.288E 00 0.280E 00 0.301E 00 0.287E 00 0.295E 00 0.277E 00 0.325E C0 0.311E 00 0.140E 01 0.140E 01
NO 1 2 3 4 5 6 7 8 9 10 11	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50	N(E,.50) 0.281E 02 0.825E 01 0.357E 01 0.144E 01 0.566F 00 0.258E 00 0.105E 00 0.480E-01 0.166E-01 0.803E-02 0.803E-03	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.289E 00 0.284E 00 0.301E 00 0.287E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01	N(*E50)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-C1 0.310E-01 0.133E-01 0.540E-02 0.250E-02 0.112E-02	E0(1) 0.240E 00 0.288E 00 0.280E 00 0.301E 00 0.287E 00 0.295E 00 0.325E 00 0.311E 00 0.140E 01
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50	N(E,.50)  0.281E 02 0.825E 01 0.357E 01 0.144E 01 0.566E 00 0.258E 00 0.105E 00 0.480E-01 0.166E-01 0.803E-02 0.803E-03 0.671E-03 0.561E-03	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.280E 00 0.301E 00 0.287E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.311E 00 0.140E 01 0.140E 01 0.140E 01 0.140E 01	N(*E50)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-01 0.310E-01 0.540E-02 0.250E-02 0.112E-02 0.936E-03 0.783E-03	E0(1)  0.240E 00 0.288E 00 0.280E 00 0.301E 00 0.287E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01 0.140E 01
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	N(E,.50)	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.280E 00 0.287E 00 0.297E 00 0.277E 00 0.325E 00 0.311E 00 0.311E 00 0.311E 00 0.311E 01 0.140E 01 0.140E 01 0.140E 01 0.140E 01	N(*E,.5C)	E0(1) 0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.287E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01 0.140E 01 0.140E 01 0.140E 01 0.140E 01
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	N(E,.50)	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.280E 00 0.287E 00 0.295F 00 0.277E 00 0.277E 00 0.325E 00 0.311E 00 0.3140E 01 0.140E 01 0.140E 01 0.140E 01 0.140E 01 0.140E 01	N(*E,.5C)	E0(1) 0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.287E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	N(E,.50)	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.288E 00 0.284E 00 0.301E 00 0.295F 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01 0.140E 01 0.140E 01 0.140E 01 0.140E 01 0.140E 01 0.140E 01 0.140E 01	N(*E,.5C)	E0(1) 0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.287E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01 0.140E 01 0.140E 01 0.140E 01 0.140E 01
NO 11 2 3 4 4 5 6 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	N(E,.50)  0.281E 02 0.825E 01 0.357E 01 0.144E 01 0.566F 00 0.258E 00 0.105E 00 0.480E-01 0.166E-01 0.803E-02 0.803E-03 0.671E-03 0.561E-03 0.469E-03 0.328E-03 0.274E-03 0.274E-03 0.29E-03 0.191E-03 0.160E-03	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.288E 00 0.284E 00 0.301E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01 0.140E 01	N(*E50)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-01 0.310E-01 0.540E-02 0.250E-02 0.112E-02 0.936E-03 0.783E-03 0.654E-03 0.547E-03 0.320E-03 0.320E-03 0.223E-03	E0(1)  0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	N(E,.50)  0.281E 02 0.825E 01 0.357E 01 0.144E 01 0.566F 00 0.258E 00 0.105E 00 0.480E-01 0.166E-01 0.803E-02 0.803E-03 0.671E-03 0.561E-03 0.469E-03 0.392E-03 0.392E-03 0.274E-03 0.274E-03 0.29E-03 0.191E-03 0.160E+03	** L=5.60 ** E0(D) 0.240E 00 0.288E 00 0.288E 00 0.284E 00 0.301E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01 0.140E 01	N(*E50)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-C1 0.310E-01 0.540E-02 0.250E-02 0.112E-02 0.936E-03 0.783E-03 0.654E-03 0.547E-03 0.457E-03 0.382E-03 0.382E-03 0.320E-03 0.223E-03 0.223E-03	E0(1)  0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01
NO 11 2 3 4 4 5 6 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	N(E,.50)  0.281E 02 0.825E 01 0.357E 01 0.144E 01 0.566E 00 0.258E 00 0.105E 00 0.480E-01 0.803E-02 0.803E-03 0.671E-03 0.561E-03 0.469E-03 0.328E-03 0.274E-03 0.274E-03 0.191E-03 0.134E-03 0.134E-03	** L=5.60 ** E0(D)  0.240E 00 0.288E 00 0.288E 00 0.284E 00 0.301E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01	N(*E50)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-C1 0.310E-01 0.133E-01 0.540E-02 0.250E-02 0.112E-02 0.936E-03 0.783E-03 0.654E-03 0.547E-03 0.382E-03 0.382E-03 0.382E-03 0.320E-03 0.223E-03 0.156E-03	E0(1)  0.240E 00  0.288E 00  0.280E 00  0.287E 00  0.287E 00  0.277E 00  0.325E 00  0.311E 00  0.140E 01
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.75 4.00 4.25 4.50 4.75 5.00 5.25	N(E,.50)  0.281E 02 0.825E 01 0.357E 01 0.144E 01 0.566F 00 0.258E 00 0.105E 00 0.480E-01 0.166E-01 0.803E-02 0.803E-03 0.671E-03 0.561E-03 0.469E-03 0.392E-03 0.392E-03 0.274E-03 0.274E-03 0.29E-03 0.191E-03 0.160E+03	** L=5.60 ** E0(D)  0.240E 00 0.288E 00 0.287E 00 0.301E 00 0.295F 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01	N(*E50)  0.675E 01 0.238E 01 0.100E 01 0.410E 00 0.170E 00 0.740E-C1 0.310E-01 0.540E-02 0.250E-02 0.112E-02 0.936E-03 0.783E-03 0.654E-03 0.547E-03 0.457E-03 0.382E-03 0.382E-03 0.320E-03 0.223E-03 0.223E-03	E0(1)  0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00	N(E,.50)	** L=5.60 ** E0(D)  0.240E 00 0.288E 00 0.287E 00 0.301E 00 0.295F 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01	N(*E50)	E0(1)  0.240E 00 0.288E 00 0.280E 00 0.287E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00 6.25	N(E,.50)	** L=5.60 ** E0(D)  0.240E 00 0.288E 00 0.283E 00 0.301E 00 0.287E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01	N(*E50)	E0(1)  0.240E 00 0.288E 00 0.280E 00 0.284E 00 0.301E 00 0.295E 00 0.277E 00 0.375E 00 0.311E 00 0.140E 01
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00	N(E,.50)	** L=5.60 ** E0(D)  0.240E 00 0.288E 00 0.287E 00 0.301E 00 0.295F 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01	N(*E50)	E0(1)  0.240E 00 0.288E 00 0.280E 00 0.287E 00 0.295E 00 0.277E 00 0.325E 00 0.311E 00 0.140E 01

# TABLE 3 (CONCLUDED)

			** L=5.80 **		
NO	E	N(E,.50)	EC(D)	N(*E50)	E0(I)
1	0.	0.348E 02	0.223E 00	0.778E 01	0.223E 00
2 3	0.25 0.50	0.947E 01 0.378E 01	0.268E 00 0.265E 00	0.254E 01 0.100E 01	0.268E 00
4	0.75	0.147E 01	0.264E 00	0.100E 01 0.389E 00	0.265E 00 0.264E 00
5	1.00	0.543E CO	G.278E 00	0.151E 00	0.278E 00
6	1.25	0.366E CO	C.168E CO	0.615E-01	0.168E 00
7	1.50	0.194E-01	0.715E CO	0.139E-01	0.715E 00
8 9	1.75 2.00	0.382E-01	0.257E 00 0.281E 00	0.980E-02	0.257E 00
13	2.25	0.132E-01 0.438E-02	0.261E 00	0.370E-02 0.152E-02	0.281E 00 0.347E 00
11	2.50	0.218E-02	0.339E 00	0.740E-03	0.339E 00
12	2.75	0.104E-02	0.339E 00	0.354E-03	0.339E 00
13	3.00	0.499E-03	0.339E 00	0.169E-03	0.339E 00
14	3.25	0.239E-03	0.339E 00	0.809E-04	0.339E 00
15 16	3.50 3.75	0.114E-03 0.546E-04	0.339E 00 0.339E 00	0.387E-C4 0.185E-04	0.339E 00 0.339E 00
17	4.CO	0.261E-04	0.339E 00	0.885E-05	0.339E 00
18	4.25	0.125E-04	0.339E 00	0.423E-05	0.339E 00
19	4.5C	0.597E-05	0.339E 00	0.202E-05	0.339E 00
20	4.75	0.286E-05	0.339E 00	0.968E-06	0.339E 00
21 22	5.00 5.25	0.137E-05 0.653E-06	0.339E 00 C.339E 00	0.463E-06 0.221E-06	0.339E 00 0.339E 00
23	5.50	0.312E-06	0.339E 00	0.106E-06	0.339E 00
24	5.75	0.149E-06	0.339E 00	0.5C6E-07	0.339E 00
25	6.00	C.714E-07	0.339E 00	0.242E-07	0.339E 00
26	6.25	0.342E-07	0.339E 00	0.116E-07	0.339E 00
27 28	6.50 6.75	0.163E-G7 C.781E-C8	0.339E 00 0.339E 00	C.554E-08 O.265E-08	0.339E 00 0.339E 00
29	7.00	0.374E-C8	0.339E 00	0.127E-08	0.339E 00
	,	OF STAFF OR	U • 337E UU	0 • 1 2 1 L · 0 0	0.5576 00
	1.00	0.5142 00	** L=6.00 **	0.1272-08	0.3376 00
NO	E	N(E,.50)		N(*E,.50)	E0(1)
NO 1			** L=6.00 **		E0(1)
NO 1 2	ē 0. 0.25	N(E,.50) 0.492E 02 0.108E 02	** L=6.00 ** EC(D) 0.165E 00 0.250E 00	N(*E,.50) 0.905E 01 0.271E 01	E0(1) 0.208E 00 0.250E 00
NO 1 2 3	0. 0.25 0.50	N(E,.50) 0.492E 02 0.108E 02 0.399E 01	** L=6.00 ** EC(D) 0.165E 00 0.250E 00 0.250E 00	N(*E,.50) 0.905E 01 0.271E 01 0.100E 01	E0(1) 0.208E 00 0.250E 00 0.250E 00
NO 1 2 3 4	0. 0.25 0.50 0.75	N(E,.50) 0.492E 02 0.108E 02 0.399E 01 0.147E 01	** L=6.00 ** EC(D) 0.165E 00 0.250E 00 0.250E 00 0.250E 00	N(*E,.50) 0.905E 01 0.271E 01 0.100E 01 0.368E 00	E0(1) 0.208E 00 0.250E 00 0.250E 00 0.250E 00
NO 1 2 3	0. 0.25 0.50	N(E,.50) 0.492E 02 0.108E 02 0.399E 01	** L=6.00 ** EC(D) 0.165E 00 0.250E 00 0.250E 00	N(*E,.50) 0.905E 01 0.271E 01 0.100E 01	E0(1) 0.208E 00 0.250E 00 0.250E 00
NO 1 2 3 4 5	0. 0.25 0.50 0.75 1.00	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 C.147E 01 C.542E C0	## L=6.00 ## EG(D) 0.165E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00	N(*E,.50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01	E0(I) 0.208E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01	## L=6.00 ## EG(D) 0.165E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00	N(*E,.50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02	E0(1)  0.208E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01 0.100E-01	## L=6.00 ## EG(D) 0.165E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00	N(*E,.50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02	E0(I)  0.208E 00 0.250E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01 0.100E-01 0.368E-02	## L=6.00 ## EG(D) 0.165E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00	N(*E,.50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03	E0(I)  0.208E 00 0.250E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01 0.100E-01	## L=6.00 ## EG(D) 0.165E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00 0.250E 00	N(*E,.50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02	E0(I)  0.208E 00 0.250E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 C.147E 01 C.542E C0 C.2CCE C0 C.736E-01 G.271E-C1 G.100E-01 G.368E-02 C.136E-02 C.500E-03 0.184E-03	** L=6.00 ** EC(D)  0.165E 00 0.250E 00	N(*E50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-G1 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04	E0(1)  0.208E 00 0.250E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14	E 0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01 0.100E-01 0.368E-02 0.136E-02 0.136E-02 0.500E-03 0.184E-03 0.679E-04	** L=6.00 ** EC(D)  0.165E 00 0.250E 00	N(*E,.50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04	E0(1)  0.208E 00 0.250E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	E 0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01 0.100E-01 0.368E-02 0.136E-02 0.136E-02 0.136E-02 0.136E-02 0.184E-03 0.679E-04 0.250E-04	** L=6.00 ** EC(D)  0.165E 00 0.250E 00	N(*E,.50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04 0.626E-05	E0(1)  0.208E 00 0.250E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16	E  0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 3.75 3.00 3.25 3.50 3.75	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01 0.100E-01 0.368E-02 0.136E-02 0.136E-02 0.136E-03 0.184E-03 0.679E-04 0.922E-05	** L=6.00 ** EC(D)  0.165E 00 0.250E 00	N(*E,.50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04 0.626E-05 0.231E-05	E0(1)  0.208E 00 0.250E 00
NO 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	E 0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01 0.100E-01 0.368E-02 0.136E-02 0.136E-02 0.136E-02 0.136E-02 0.184E-03 0.679E-04 0.250E-04	** L=6.00 ** EC(D)  0.165E 00 0.250E 00	N(*E,.50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04 0.626E-05	E0(1)  0.208E 00 0.250E 00
NO	0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.100E-01 0.368E-02 0.136E-02 0.136E-02 0.500E-03 0.184E-03 0.679E-04 0.922E-05 0.340E-05 0.125E-05 0.461E-06	** L=6.00 ** EC(D)  0.165E 00 0.250E 00	N(*E,.50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04 0.626E-05 0.231E-05 0.851E-06 0.313E-06 0.115E-06	E0(1)  0.208E 00 0.250E 00
NO  1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	E 0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.100E-01 0.368E-02 0.136E-02 0.136E-02 0.500E-03 0.184E-03 0.679E-04 0.250E-04 0.922E-05 0.340E-05 0.125E-05 0.461E-06 0.170E-06	** L=6.00 ** EC(D)  0.165E 00 0.250E 00	N(*E50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04 0.626E-05 0.231E-05 0.851E-06 0.313E-06 0.115E-06 0.426E-07	E0(1)  0.208E 00 0.250E 00
NO	E 0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 C.147E 01 C.542E C0 C.2CCE C0 C.736E-01 0.271E-C1 0.100E-01 0.368E-02 C.136E-02 C.500E-03 0.184E-03 0.679E-04 0.250E-04 0.922E-05 0.340E-05 0.125E-05 0.461E-06 C.170E-06 C.626E-07	** L=6.00 ** EC(D)  0.165E 00 0.250E 00	N(*E50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04 0.626E-05 0.231E-05 0.851E-06 0.313E-06 0.115E-06 0.426E-07 0.157E-07	E0(1)  0.208E 00 0.250E 00
NO	E 0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.75 5.00 5.25	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.100E-01 0.368E-02 0.136E-02 0.136E-02 0.500E-03 0.184E-03 0.679E-04 0.250E-04 0.922E-05 0.340E-05 0.125E-05 0.461E-06 0.170E-06	** L=6.00 ** EC(D)  0.165E 00 0.250E 00	N(*E50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04 0.626E-05 0.231E-05 0.851E-06 0.313E-06 0.115E-06 0.426E-07	E0(1)  0.208E 00 0.250E 00
NO	E 0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01 0.100E-01 0.368E-02 0.136E-02 0.136E-02 0.136E-03 0.184E-03 0.679E-04 0.922E-05 0.340E-05 0.125E-05 0.461E-06 0.170E-06 0.626E-07 0.231E-07	** L=6.00 ** EC(D)  0.165E 00 0.250E 00	N(*E50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-G1 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04 0.626E-05 0.231E-05 0.851E-06 0.313E-06 0.115E-07 0.157E-07 0.578E-08 0.213E-08 0.786E-09	E0(1)  0.208E 00 0.250E 00
NO	E 0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01 0.100E-01 0.368E-02 0.136E-02 0.136E-02 0.136E-02 0.136E-02 0.136E-05 0.184E-03 0.679E-04 0.922E-05 0.340E-05 0.125E-05 0.461E-06 0.170E-06 0.626E-07 0.231E-07 0.850E-08 0.313E-08 0.115E-08	** L=6.00 **     EC(D)  0.165E 00 0.250E 00	N(*E50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04 0.626E-05 0.231E-05 0.851E-06 0.313E-06 0.115E-06 0.426E-07 0.157E-07 0.578E-08 0.213E-08 0.786E-09 0.294E-09	E0(1)  0.208E 00 0.250E 00
NO	E 0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.75 6.00 6.25	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01 0.100E-01 0.368E-02 0.136E-02 0.136E-02 0.136E-02 0.136E-02 0.136E-05 0.184E-03 0.679E-04 0.922E-05 0.340E-05 0.125E-05 0.461E-06 0.170E-06 0.626E-07 0.231E-07 0.850E-08 0.313E-08 0.115E-08 0.425E-09	** L=6.00 **     EC(D)  0.165E 00 0.250E 00	N(*E50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04 0.626E-05 0.231E-05 0.851E-06 0.313E-06 0.115E-06 0.426E-07 0.157E-07 0.578E-08 0.213E-08 0.786E-09 0.294E-09 0.110E-09	E0(1)  0.208E 00 0.250E 00
NO	E 0. 0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.75 6.00	N(E,.50)  0.492E 02 0.108E 02 0.399E 01 0.147E 01 0.542E 00 0.20CE 00 0.736E-01 0.271E-01 0.100E-01 0.368E-02 0.136E-02 0.136E-02 0.136E-02 0.136E-02 0.136E-05 0.184E-03 0.679E-04 0.922E-05 0.340E-05 0.125E-05 0.461E-06 0.170E-06 0.626E-07 0.231E-07 0.850E-08 0.313E-08 0.115E-08	** L=6.00 **     EC(D)  0.165E 00 0.250E 00	N(*E50)  0.905E 01 0.271E 01 0.100E 01 0.368E 00 0.136E 00 0.500E-01 0.184E-01 0.679E-02 0.250E-02 0.922E-03 0.340E-03 0.125E-03 0.461E-04 0.170E-04 0.626E-05 0.231E-05 0.851E-06 0.313E-06 0.115E-06 0.426E-07 0.157E-07 0.578E-08 0.213E-08 0.786E-09 0.294E-09	E0(1)  0.208E 00 0.250E 00

TABLE 5

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 1.00 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.00100	1.00E 00	6	•22000	1.00E 00
2	.10000	1.00E OC	7	.23000	1.00E 00
3	.19000	1.00F 00	8	.31165	1.GOE GO
4	.2000 <b>0</b>	1.0CE 00	9	.38000	1.00E 00
5	.21000	1.0.E OC	10	•9990ü	1.00E 00

** L = 1.10 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.14000	4.60E 08	15	.20000	1.78E 04
2	.15000	7.10E 06	16	.20200	4.85E 03
3	.16000	4.75E 06	17	-20400	4.30E 03
4	.17000	2.25E 06	18	.20600	2.72E 03
5	.18000	9.70E 05	19	.20800	1.83E 03
6	.18200	6.72E 05	20	.21000	1.38E 03
7	.18400	4.92E 05	21	.21200	1.10E 03
8	.18600	2.96E 05	22	.21400	8.00E 02
9	.18800	2.30E 05	23	.21600	3.50E 02
10	.19000	1.52E 05	24	.21800	2.65E 02
11	.19260	5.52E 04	25	.22000	1.66E 02
12	.19400	4.50E 04	26	.23000	3.05E 01
13	.19600	3.80E 04	27	.23415	1.00E 00
14	.19800	2.1CE 04	28	-24000	1.00E 00

** L = 1.15 **

NO.	В	UMNI FLUX	NO.	В	OMNI FLUX
1	.13000	1.80E 09	19	.20400	3.95E 04
2	.14000	3.40E 08	20	.20492	3.50E 04
3	.15000	1.43E 07	21	.20600	3.00E 04
4	.16000	9.70E 06	22	.20800	2.30E 04
5	.17000	4.95E 06	23	.21000	1.71E 04
6	.17500	3.30E 06	24	.21200	1.23E 04
7	.18000	2.77E 06	25	.21400	8.00E 03
8	.18200	2.08E 06	26	.21600	5.20E 03
9	-18400	1.60E 06	27	.21800	3.35E 03
10	.18600	1.11F 06	28	.22000	2.07E 03
11	.18800	8.7CE 05	29	.2220C	1.21E 03
12	.19000	6.40E 05	30	.22400	7.20E 02
13	.19200	2.95E 05	31	-23000	1.18E 02
14	.19400	2.45E 05	32	.23500	1.85E 01
15	-19600	1.95E 05	33	-24000	2.09E 00
16	.19800	1.30E 05	34	-24500	1.00E 00
17	•20000	6.90E 04	35	-99900	1.00E 00
18	.20200	5.20E 04			

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

#### ** L = 1.18 **

NO.	8	DMNI FLUX	NO.	В	OMNI FLUX
1	.12000	2.58E 09	20	-20400	1.55E 05
2	.13000	1.25E 09	21	-20600	1.06E 05
3	.14000	2.87E 08	22	.20800	7.00E 04
4	.15000	2.15E 07	23	.21000	4.85E 04
5	.16000	1.48E 07	24	.21200	3.42E 04
6	.17000	8.00E 06	25	-21400	2.40E 04
7	.17500	7.98E 06	26	.21600	1.60E 04
8	.18000	5.20E 06	27	.21800	1.03E 04
9	.18200	4.10E 06	28	.22003	6.95E 03
10	.18400	3.38E 06	29	.22200	4.50E 03
11	.18600	2.55E 06	30	-22400	2.75E 03
12	.18800	1.93E 06	31	.22600	1.70E 03
13	.18958	1.55E 06	32	<b>.2280</b> C	1.00E 03
14	.19200	1.11F 06	33	·23000	5.70E 02
15	.19400	8.20E 05	34	.23500	1.15E G2
16	.19600	6.00E 05	35	-24000	1.59E 01
17	.19800	4.40E 05	36	·2450G	1.70E 00
18	-20000	3.15E 05	37	.25000	1.00E 00
19	.25200	2.23E 05	38	.99900	1.00E 00

#### ** L = 1.20 **

NO.	В	OMNI FLUX	NO.	8	OMNI FLUX
1	.12000	1.98E 09	20	-20400	3.30E 05
2	.13000	9.60E 08	21	.20600	2.30E 05
3	.14000	2.54E 08	22	.20800	1.58E 05
4	-15000	2.82F 07	23	.21000	1.08E 05
5	.16000	1.98E 07	24	-21200	7.30E 04
6	.17000	1.09E 07	25	-21400	4.90E 04
7	.17500	9.65E 06	26	-21600	3.23E 04
8	.18035	7.70E 06	27	.21800	2.13E 04
9	.18200	6.30E 06	28	-22000	1.40E 04
10	.18400	5.10E 06	29	-22200	8.90E 03
11	.18600	4.15F 06	30	.22400	5.90E 03
12	.18800	3.30E 06	31	.22600	3.79E 03
13	.19000	2.63E 06	32	-22800	2.40E 03
14	.19200	2.00E 06	33	-23000	1.50E 03
15	.19400	1.55E 06	34	.23200	9.00E 02
16	.19600	1.17E 06	35	.23500	2.95E 02
17	.19800	8.70E 05	36	-24000	3.25E 01
18	.20000	6.50E 05	37	-25000	1.00E 00
19	.20200	4.65E 05	38	•99900	1.00E 00

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 1.25 **

NO • .	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.11000	1.45E 09	19	.21200	5.80E 05
2	.12000	1.00E 09	20	-21400	3.98E 05
3	.13000	5.23€ 08	21	.21600	2.63E 05
4	.14000	1.89E C8	22	.21800	1.68E 05
5	.15000	5.62E 07	23	.22000	1.07E G5
6	.15957	3.98E 07	24	-22200	6.80E 04
7	.17000	3.15E 07	25	.22400	4.15E 04
8	.17500	2.74E 07	26	.22600	2.50E 04
9	.18000	2.25E 07	27	.22800	1.50E 04
10	.18500	1.75E Q7	28	.23000	9.00E 03
11	.19000	1.22E 07	29	.23200	5.80E 03
12	.19500	7.50E 06	30	-23400	3.35E 03
13	.20000	3.70E 06	31	.23600	1.86E 03
14	.20200	2.78E 06	32	.23800	1.00E 03
15	.20400	2.05E 06	33	.24000	4.90E 02
16	·20600	1.52E 06	34	.25 <b>0</b> 00	1.05E 01
17	-20800	1.13E 06	35	.25500	1.00E 90
18	.21000	8.20E 05	36	•99900	1.00E 00

** L = 1.30 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.10000	7.00E 08	21	•2140°	1.31E 06
2	.11000	6.90E 08	22	.21600	1.60E 06
3	·12000	5.10E 08	23	.21800	7.40E 05
4	.13060	1.74E 08	24	.22000	5.60E 05
5	.14185	1.38E 08	25	-2220G	4.00E 05
6	.14500	1.27F 08	26	.22400	2.75E 05
7	.15000	1.12E 08	27	.22600	1.75E 05
8	.15500	9.60E 07	28	.22800	1.08E 05
9	·16000	8.0GE 07	29	-23 <b>0</b> 00	6.40E 04
10	.16500	6.60E 07	30	.2320û	3.85E 04
11	.17000	5.25E 07	31	.23400	2.20E 04
12	.17500	4.15E 07	32	.23600	1.23E 04
13	.18000	3.15E 07	33	-23800	7.00E 03
14	.18500	2.30E 07	34	.24000	3.99E 03
15	.19600	1.60E 07	35	.24200	2.32E 03
16	.19500	1.10E 07	36	-24400	1.30E 03
17	-20000	6.90E 06	37	.24600	6.40E 02
18	.20500	4.05E 06	38	.25000	1.13E 02
19		2.25E 06	39	.26000	1.48E 00
20	.21200	1.73E 06	40	.26500	1.00E 00

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

#### ** L = 1.35 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.09000	3.60E 08	24	.22200	9.40E 05
2	.10000	3.50E 08	25	-22400	
3	-11000	3.43E 08	26	-22600	5.43E 05
4	.12000	2.13E 08	27	.22800	3.90E 05
5	.12667	1.80E 08	28	.23000	2.59E 05
6	.13000	1.65E 08	29	.23200	1.75E 05
7	-14000	1.26E 08	30	-23400	1.13E 05
8	.14500	1.07E 08	31	-23600	
9	.15000	9.13E 07	32	.23800	
10	.15500	7.80E 07	33	-24000	2.50E 04
11	.16000	6.61E 07	34	·24200	1.40E 04
12	.16500	5.45E 07	35	.24400	8.00E 03
13	.17000	4.40E 07	36	-24600	4.75E 03
14	.17500	3.50E 07	37	.24800	2.65E 03
15	.18000	2.71E 07	38	.25000	1.39E 03
16	.18500	2.05E 07	39	.25200	
17	.19000	1.49E 07	40	-25400	3.80E 02
18	•19500	1.05E 07	41	·25600	1.85E 02
19	.20000	7.30E 06	42	.25800	8.50E 01
20	.20500	5.00F 06	43	-26000	3.25E 01
21	-21000	3.25E 06	44	-26500	3.25E 00
22	.21500	2.05E 06	45	-27000	1.00E 0G
23	-22000	1.19E 06	46	-99900	1.00E 00

#### ** L = 1.40 **

ND.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.07000	2.35E 08	24	-21500	2.30E 06
2	<b>00080</b>	2.10E 08	25	.22000	
3	.09000	2.00E 08	26	-22500	•
4	.10000	1.88E 08	27	.23000	
5	-11000	1.71E 08	28	.23200	
6	.11358	1.59E 08	29	.23400	
7	.12000	1.38E 08	36	.23600	
8	.13000	1.06E 08	31	.23800	
9	.14000	7.90E 07	32	.24000	
10	.14500	6.82E 07	33	.24200	
11	.15000		34	.24400	
12	.15500	4.90E 07	35	-24600	
13	.16000	4.05E G7	36	.24800	
14	<b>.</b> 16500	3.35E 07	37	.25000	
15	.17000	2.74E 07	38	.25200	
16	.17500	2.22E G7	39	.25400	
17	.18000	1.81E 07	40	-25600	
18	-18500	1.45E 07	41	.25800	5.00E 02
19	.19000	1.14E C7	42	•26 <b>0</b> 00	
20	.19500	8.90E 06	43	.26500	2.10E 01
21	-25000	6.70E 06	44	.27000	
22		4.90E 06	45		
23	-21000	3.45E 06	46	•99900	

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 1.50 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.06000	1.19E 08	20	.23000	4.16E 05
2	.07000	9.63E 07	21	.23500	2.50E 05
3	.08000	7.90E 07	22	.24000	1.44E 05
4	•09000	6.35E 07	23	-24500	8.40E 04
5	.09234	6.03E 07	24	.25000	4.65E 04
6	.16600	5.15E 07	25	.25200	3.68E 04
7	.11000	4.16E 07	26	.25400	2.88E 04
8	.12000	3.33E 07	27	.25600	2.16E 04
9	.13000	2.63E 07	28	-25800	1.60E 04
10	.14000	2.06E 07	29	.26000	1.07E 04
11	.15000	1.60E 07	30	.26200	5.80E 03
12	.16000	1.22E 07	31	-26400	2.50E 03
13	.17000	9.16E 06	32	.26600	9.80E 02
14	.18000	6.68E 06	33	-26800	3.70E 02
15	.19000	4.65E 06	34	.27000	1.50E 02
16	.20000	3.10E 06	35	.27500	1.50E 01
17	.21000	1.85£ 06	36	.28000	1.58E 00
18	.22000	9.80E 05	37	-28500	1.00E 00
19	.22500	6.60E 05	38	•99900	1.00E 00

** L = 1.60 **

NO.	В	UMNI FLUX	NO.	В	OMNI FLUX
1	.05000	6.00E 07	18	.21000	7.60E 05
2	.06000	4.60E 07	19	-22000	4.70E 05
3	.07000	3.50E 07	20	-23000	2.56E 05
4	.07609	3.00E 07	21	.24000	1.29E 05
5	.08000	2.70E 07	22	·25000	5.99E 04
6	.09000	2.05E 07	23	.25500	3.95E 04
7	-10000	1.59E 07	24	-26000	2.54E 04
8	.11000	1.20E 07	25	-26500	1.62E 04
9	.12000	9.28E 06	26	-27000	9.40E 03
10	.13000	7.10E 06	27	.27200	3.70E 03
11	.14000	5.5CE 06	28	.27400	1.30E 03
12	.15000	4.28E 06	29	.27600	4.50E 02
13	.16000	3.35E 06	30	.27800	1.60E C2
14	.17000	2.59E 06	31	.28000	6.20E 01
15	.18000	2.00E 06	32	.28500	5.10E 00
16	.19000	1.50E 06	33	-29000	1.00E 00
17	.20000	1.09E 06	34	.99900	1.00E 00

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 1.70 **

NO.	8	OMNI FLUX	NO.	В	OMNI FLUX
1	.04000	3.08E 07	20	•22 <b>0</b> 00	1.98E 05
2	.05000	2.33E 07	21	-23000	1.31E C5
3	.06000	1.75E 07	22	.24000	8.20E 04
4	•€o343	1.60E 07	23	-25000	5.00E 04
5	.07000	1.31E 07	24	.26000	3.00E 04
6	.08000	9.90E 06	25	.27000	1.52E 04
7	.09000	7.40E 06	26	.27200	1.30E 04
8	.10000	5.55E 06	27	-27400	1.05E 04
9	.'1000	4.13E 06	28	<b>.2760</b> 0	7.50E 03
10	.12000	3.07F 06	29	.27800	3.80E 03
11	.13000	2.32E 06	30	-28000	1.50E 03
12	<b>.14000</b>	1.78E 06	31	.28200	6.60E 02
13	·1500G	1.39E 06	32	.28400	3.00E 02
14	.16000	1.10E 06	33	.28600	1.47E 02
15	.17000	8.60E 05	34	-28800	7.00E 01
16	.18000	6.70E 05	35	.29000	3.30E 01
17	.19000	5.10E 05	36	-29500	5.10E 00
18	.20000	3.82E 05	37	•30000	1.00E 0G
19	.21000	2.80E 05	38	•99900	1.00E 00

** L = 1.80 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.03000	2.07E 07	21	-22000	8.60E 04
2	.04000	1.47E 07	22	-23000	6.40E 04
3	.05000	1.02E 07	23	.24000	4.70E G4
4	.05344	9.15E 06	24	.25000	3.39E 04
5	<b>.06000</b>	7.15E 06	25	.26000	2.33E 04
6	.07000	5.08E 06	26	.27000	1.37E 04
7	.08000	3.65E 06	27	.2720C	1.19E 04
8	.09000	2.68E 06	28	.27400	1.02E 04
9	-10000	2.00E 06	29	.27600	8.00E 03
10	.11000	1.50E 06	30	.27800	5.95E 03
11	.12000	1.14E 06	31	.28000	4.00E 03
12	.13000	8.70E 05	32	.28200	2.60E 03
13	.14000	6.75E 05	33	-28400	1.42E 03
14	.15000	5.23E 05	34	-28600	7.00E 02
15	.16000	4.10E 05	35	.28800	3.15E 02
16	.17000	3.20E 05	36	.29000	1.30E 02
17	-18000	2.53E 05	37	.29500	1.40E 01
18	-19000	1.97E 05	38	-30000	1.60E 00
19	-20000	1.52E 05	39	.30500	1.00E 00
20	-21000	1.15E 05	40	.99900	1.00E GO

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 1.90 **

NO.	В	UMNI FLUX	NO.	В	OMNI FLUX
1	.02000	1.16E 07	19	.19000	9.90E 04
2	.03000	8.20E 06	20	.20000	8.20E 04
3	.04000	5.78E 06	21	.21000	6.45E 04
4	.04544	4.78E 06	22	.22000	4.90E 04
5	.05000	4.1CE 06	23	.23000	3.58E 04
6	.06000	2.93E 06	24	.24000	2.58E 04
7	.07000	2.10E 06	25	.25000	1.80E 04
8	.08000	1.53E 06	26	.26000	1.23E 04
9	•09000	1.11E 06	27	.27000	7.00E 03
10	.10000	8.15E 05	28	.27500	4.70E 03
11	-11000	6.09E 05	29	.28000	2.97E 03
12	.12300	4.60E 05	30	.28500	1.64E 03
13	.13000	3.58E 05	31	.29000	7.50E 02
14	.14000	2.80E 05	32	.29500	1.10E 02
15	.15000	2.23E 05	33	.30000	1.30E 01
16	•16000	1.80E 05	34	.30500	1.61E 00
17	-17000	1.46E 05	35	.31000	1.00E 00
18	.18000	1.19E 05	36	•9990¢	1.00E 00

** L = 2.00 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.01000	9.70E 06	19	.18000	6.65E 04
2	.02000	6.43E 06	20	.19000	5.31E 04
3	.03000	4.2CE 06	21	.20000	4.15E 04
4	.03896	2.94E 06	22	.21000	3.19E 04
5	.04000	2.77E 06	23	.22000	2.41E 04
6	•05000	1.85E 06	24	.23000	1.82E 04
7	.06000	1.25E 06	25	.24000	1.35E 04
8	.07000	8.7CE 05	26	.25000	1.00E 04
9	.08000	6.20E 05	27	.26000	6.95E 03
10	•09000	4.57E 05	28	.27000	4.61E 03
11	.10000	3.56E 05	29	-28000	2.74E 03
12	.11000	2.78E 05	30	.29000	1.10E 03
13	.12000	2.30E 05	31	.29500	2.72E 02
14	-13000	1.89E 05	32	.30000	4.80E 01
15	-14000	1.54E 05	33	.31000	1.60E 00
16	.15000	1.25E 05	34	.31500	1.00E 00
17	-16000	1.02E C5	35	-99900	1.00E 00
18	-17000	8.25E 04			

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 2.10 **

NO.	В	OMNI FLUX	NO.	8	OMNI FLUX
1	.01000	5.05E C6	19	.18000	3.33E 04
2	.02000	3.25E 06	20	.19000	2.54E 04
3	-03000	2.06E 06	21	-20000	2.06E 04
4	.03365	1.74E 06	22	.21000	1.63E 04
5	.04000	1.29E 06	23	.22005	1.27E 04
6	.05660	8.38E 05	24	.23000	9.85E 03
7	.06000	5.69E 05	25	.24000	7.75E 03
8	.07000	4.08E 05	26	.25000	6.02E 03
9	.08000	3.06E 05	27	.26000	4.70E 03
10	.09000	2.46E 05	28	.27000	3.60E 03
11	.10000	1.98E 05	29	.28000	2.68E 03
12	·11000	1.51E 05	30	.29000	1.30E 03
13	.12000	1.29E 05	31	.29500	3.94E 02
14	·1300C	1.04E 05	32	-30000	9.45E 01
15	-14000	8.35E 04	33	.31000	5.30E 00
16	.1500C	6.63E 04	34	.32000	1.00E 00
17	.16000	5.32E 04	35	.99900	1.00E CG
18	-17000	4.22E 04			

** L = 2.20 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	•0050C	3.95E 06	19	.18000	1.75E 04
2	-01000	2.98E 06	20	.19000	1.40E 04
3	.02000	1.72E 06	21	.20000	1.14E 04
4	.02927	1.00E 06	22	.21000	9.20E 03
5	-04000	5.98E 05	23	.22000	7.60E 03
6	.05000	4.00E 05	24	.23000	6.27E 03
7	.06000	2.84E 05	25	.24000	5.20E 03
8	.07000	2.14E 05	26	.25000	4.38E 03
9	.08000	1.65E 05	27	.26000	3.70E 03
10	.09000	1.27E 05	28	.27000	3.00E 03
11	.10000	1.00E 05	29	.28000	1.99E 03
12	-11000	7.90E 04	30	.29000	1.00E 03
13	.12000	6.35E 04	31	.29500	3.80E 02
14	.13000	5.05E 04	32	.30000	1.15E 02
15	.14000	4.09E 04	33	.31000	1.05E 01
16	-15000	3.28E 04	34	.32000	1.00E 00
17	-16000	2.68E 04	35	.99900	1.GOE 00
18	-17000	2.15E 04			

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 2.30 **

NO.	8	OMNI FLUX	NO.	В	OMNI FLUX
1	.00500	1.57E 06	20	.17000	1.18E 04
2	.01000	1.21E 06	21	.18000	1.00E 04
3	.01500	9.70E 05	22	-19000	8.70E 03
4	.02000	7.70E 05	23	·20 <b>0</b> 00	7.50E 03
5	.02561	5.90E 05	24	.21000	6.50E 03
6	.03000	4.75E 05	25	.22000	5.60E 03
7	.04000	2.98E 05	26	.23000	4.90E 03
8	.05000	2.00E 05	27	-24000	4.25E 03
9	•06000	1.39E 05	28	.25000	3.53E 03
10	.07000	1.02E 05	29	.26000	2.82E 03
11	.08000	7.80E 04	30	.27000	2.04E 03
12	.09000	6.09E 04	31	-28000	1.25E 03
13	.10000	4.86F 04	32	.29000	6.40E 02
14	.11000	3.90E 04	33	.29500	4.50E 02
15	.12000	3.19E 04	34	.30000	3.23E 02
16	.13000	2.58E 04	35	.31000	4.40E 01
17	.14000	2.10E 04	36	.32000	3.50E 00
18	.15000	1.71E 04	37	.32500	1.00E 00
19	.16000	1.42E 04	38	•99900	1.00E 00

#### ** L = 2.40 **

NO.	В	UMNI FLUX	NO.	8	OMNI FLUX
1	.00500	9.30E 05	19	.16000	8.45E 03
2	.01000	6.92E 05	20	-17000	7.20E 03
3	.01500	5.20E 05	21	.18000	6.09E 03
4	.02000	3.96E 05	- 22	.19000	5.20E 03
5	.02254	3.42E 05	23	.20000	4.20E 03
6	.03000	2.30E 05	24	-21000	3.80E 03
7	.04000	1.50E 05	25	.22000	3.25E 03
8	.05000	1.00E 05	26	.23000	2.72E 03
9	•06000	7.40E 04	27	-24 <b>0</b> 00	2.19E 03
10	.07000	5.60E 04	28	.25000	1.69E 03
11	.08000	4.30E 04	29	.26000	1.27E 03
12	.09000	3.39E 04	30	.27000	9.20E 02
13	.10000	2.69E 04	31	.28000	6.35E 02
14	•11000	2.18E 04	32	.29000	4.17E 02
15	.12000	1.78E 04	33	-30000	2.65E 02
16	•13000	1.46E 04	34	.31000	5.98E 01
17	-14000	1.21E 04	35	•32 <b>0</b> 00	7.70E 00
18	.15000	1.00E 04	36	-33000	1.00E 00

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 2.50 **

NO.	В	OMNI FLUX	ND.	8	OMNI FLUX
1	.00500	4.35E 05	19	.17000	4.28E 03
2	.01000	3.34E 05	20	-18000	3.67E 03
3	.01500	2.60E 05	21	.19000	3.10E 03
4	•01995	2.01E 05	22	-20000	2.62E 03
5	.03000	1-23E 05	23	.21000	2.20E 03
6	•04000	8.15E 04	24	.22000	1.83E 03
7	.05000	5.72E 04	25	-23000	1.50E 03
8	•06000	4.21E 04	26	-24000	1.21E 03
9	.07000	3.15E 04	27	.25000	9.30E 02
16	.08000	2.41E 04	28	.26000	7.10E 02
11	.09000	1.89E 04	29	.27000	5.37E 02
12	.10000	1.51E 04	30	.28000	4.00E 02
13	.11000	1.23t 04	31	.29000	2.93E 02
14	.12000	1.01E 04	32	.30000	2.18E 02
15	•13000	8.3CE 03	33	.32000	1.34E 01
16	.14000	6.99E G3	34	.34000	1.00E 00
17	.15000	5.8CE 03	35	.99900	1.00E 00
18	.16000	5.00E 03			

#### ** L = 2.60 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	•03500	2.03E Q5	15	.1400C	4.00E 03
2	-01000	1.65E 05	16	.16000	2.89E 03
3	.01500	1.35E 05	17	-18000	2.13E 03
4	.01773	1.22E 05	18	.20000	1.54E 03
5	.02000	1.13E 05	19	.22000	1.08E 03
6	.0300C	7.3LE 04	20	-24000	7.10E 02
7	.04000	4.95E 04	21	.26000	4.26E 02
8	•05000	3.43E 04	22	.28000	2.42E 02
9	.06000	2.41E C4	23	.30000	1.33E 02
10	-07000	1.78E 04	24	.32000	1.47E 01
11	.08030	1.35E C4	25	.34000	1.05E 00
12	•09000	1.06E 04	26	.34500	1.00E 00
13	-10060	8.55E 03	27	.99900	1.00E 00
14	.12000	5.73E 03			

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 2.70 **

NO.	В	UMNI FLUX	NO.	В	OMNI FLUX
1	.00500	1.13E 05	14	.14000	2.22E 03
2	.01000	9.25E 04	15	.16000	1.59E 03
3	.01500	7.55E 04	16	.18000	1.15E 03
4	.01583	6.60E 04	17	.20000	8.45E 02
5	.02000	6.20E 04	18	-22000	6.00E 02
6	.03000	4.13E 04	19	.24000	4.15E 02
7	.04000	2.83E 04	20	.26000	2.69E 02
8	.05000	1.96E 04	21	.28000	1.59E 02
9	.06000	1.40E 04	22	.30000	6.32E 01
1 C	.07000	1.02E 04	23	.32000	1.07E 01
11	.08000	7.60E 03	24	.34003	1.80E 00
12	.10000	4.80E 03	25	.35000	1.00E 00
13	.12000	3.20E 03	26	.99900	1.00E 00

** L = 2.80 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.00100	7.70E 04	13	.14000	1.33E 03
2	.00500	6.60E 04	14	.16000	9.60E 02
3	.01000	5.30E 04	15	.18000	6.99E 02
4	.01420	4.50E 04	16	.20000	5.13E 02
5	.02000	3.56E 04	17	-22000	3.80E 02
6	.03000	2.42E 04	18	-24000	2.86E 02
7	.04000	1.66E 04	19	.26000	2.13E 02
8	.05000	1.16E 04	20	.28000	1.62E 02
9	.06000	8.30E 03	21	.30000	1.22E 02
10	.08000	4.59E 03	22	.32000	2.25E 01
11	.10000	2.85E 03	23	.34000	3.44E 00
12	.12000	1.91E 03	24	.36000	1.00E 00

** L = 2.90 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.06100	7.60E 04	13	.14000	2.21E 03
2	.00500	6.50E 04	14	.16000	1.56E 03
3	.01000	5.40E 04	15	.18000	1.13E 03
4	.01278	4.90E 04	16	.20000	8.10E 02
5	.02000	3.75E 04	17	.22000	6.00E 02
6	.03000	2.65E 04	18	.24000	4.48E 02
7	.04000	1.93F 04	19	.26000	3.25E 02
8	.05000	1.46E 04	20	.28000	2.42E 02
9	-06000	1.13F 04	21	.30000	1.83E 02
10	.08000	7.20E 03	22	.32000	3.84E 01
11	.10000	4.70E 03	23	.34000	6.25E 00
12	.12000	3.20E 03	24	.36000	1.00E 00

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 3.00 **

NO.	В	UMNI FLUX	NO.	В	OMNI FLUX
1	.00100	1.00E 05	13	.16000	3.00E 03
2	.00500	8.60E G4	14	.18000	2.25E 03
3	.01006	7.10E 04	15	.20000	1.70E 03
4	.01154	6.7CE 04	16	-22000	1.29E 03
5	<b>.02000</b>	4.86E 04	17	.24000	9.50E 02
6	.03000	3.50E 04	18	.26000	6-90E 02
7	.04000	2.43E 04	19	-28000	4.95E 02
8	.06000	1.53E 04	20	.31100	3.00E 02
9	.08000	1.09E-04	21	.32000	1.53E 02
10	.10000	7.60E 03	22	.34000	2.00E C1
11	-12000	5.50E 03	23	.36000	2.74E 00
12	.14000	4.03E 03	24	.37000	1.50E 00

** L = 3.20 **

NO.	В	UMNI FLUX	NO.	В	OMNI FLUX
1	.00100	1.45E 05	13	-20000	6.08E 03
2	.00500	1.32F 05	14	·22000	4.84E 03
3	•00951	1.18E 05	15	-24000	3.70E 03
4	-02050	9.10E 04	16	.26000	2.79E 03
5	.04000	5.83F 04	17	.28000	2.06E 03
6	.06000	3.80E 04	18	.30000	1.51E 03
7	.08000	2.58E 04	19	.32700	1.00E 03
8	.10000	1.86E 04	20	-34000	4.24E 02
9	.12000	1.43E 04	21	.36000	5.63E 01
10	.14000	1.12E 04	22	.38000	7.40E 00
11	-16000	9.00E 03	23	.40000	1.00E 00
12	.18000	7.38E 03	24	.99900	1.00E 00

** L = 3.40 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.00100	2.36E 05	13	.18000	2.57E C4
2	.00500	2.22E 05	14	.20000	1.90E 04
3	.00793	2.13E 05	15	.22000	1.55E 04
4	.01000	2.04E 05	16	.24000	1.25E 04
5	.02000	1.75E 05	17	.26000	1.00E 04
6	-04000	1.30E 05	18	.28000	8.00E 03
7	.06000	9.90E 04	19	.30000	6.30E 03
8	.08000	7.45E 04	20	.32000	4.80E 03
9	.10000	5.58E 04	21	.35500	3.00E 03
10	.12000	4.40E 04	22	.36000	2.45E 03
11	.14000	3.51E 04	23	.38000	3.35E 02
12	<b>.</b> 16000	2.85E 04	24	-99900	1.00E 00

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 3.60 **								
NO.	В	OMNI FLUX	NO.	В	OMNI FLUX			
1	.00100	3.84E 05	9	.20000	6.03E 04			
2	•00668	3.68E 05	1Ó	•24 <b>0</b> 00	4.19E 04			
3	.01000	3.60E 05	11	.28000	2.89E 04			
4	.02000	3.34E 05	12	.32000	1.97E 04			
5	.04000	2.77E 05	13	-40000	1.00E 04			
6	.08000	1.85E 05	14	-42000	5.00E 03			
7	.12000	1.28E 05	15	.48000	1.36E 00			
8	- 16000	8-87F 04	16	50000	1.00F 00			

#### ** L = 3.80 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.00100	6.4JE 05	11	.28000	9.60E 04
2	.00568	6.39E 05	12	.32000	6.40E C4
3	.01000	6.3CE 05	13	.36000	4.18E 04
4	.02000	6.15E 05	14	-40000	2.72E 04
5	.04000	5.65E C5	15	-44000	1.75E 04
6	.08000	4.73F 05	16	.49200	1.00E C4
7	.12000	3.75E 05	17	•50000	8.30E 03
8	.16000	2.85E Q5	18	.54000	1.50E 02
9	.20000	2.04E 05	19	.56000	1.00E 00
10	.24000	1-41E 05	20	•99900	1.00E 00

#### ** L = 4.00 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.00100	1.15E C6	11	.28000	2.41E 05
2	.00487	1.14E 06	12	.32000	1.67E 05
3	.01000	1.12E 06	13	.36000	1.10E 05
4	.02000	1.08E 06	14	.40000	6.99E 04
5	.04000	1.00E 06	15	.44000	4.18E 04
6	.08000	8.70E 05	16	.48000	2.47E 04
7	.12000	7.31F 05	17	.55000	1.00E 04
8	<b>.</b> 16000	5.75E 05	18	.56000	3.55E 03
9	.20000	4.43E 05	19	.60000	1.00E 00
10	·24000	3.37E 05	20	•99900	1.00E 00

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 4.20 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.00100	1.59E 06	11	.32000	2.68E 05
2	.00421	1.59E 06	12	•36000	1.79E 05
3	.02000	1.54E 06	13	-40000	1.24E 05
4	.04000	1.48E 06	14	.44000	7.65E 04
5	.08000	1.34E 06	15	.48000	4.15E 04
6	.12000	1.16€ 06	ió	.52000	2-20E 04
7	.16000	9.35E 05	17	<b>.</b> 56700	1.00E 04
8	.20000	7.10E 05	18	-60000	1.00E 00
9	.24000	5.28E 05	19	.99905	1.00F 00
16	-2800C	3.8CE 05	-		

#### ** L = 4.40 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.00100	2.49E 06	11	.3200C	3.16E 05
2	.00366	2.48E C6	12	-36000	2.09E 05
3	.02000	2.31E 06	13	-40000	1.40E 05
4	.C400C	2.14E 06	14	.44000	8.65E 04
5	.08000	1.85E 06	15	.48000	4.68E 04
6	.12000	1.54E 06	16	•52000	2.48E 04
7	.16000	1.24E 06	17	.57800	1.00E 04
8	-20000	9.32E 05	18	.60000	1.00E 00
9	.24000	6.65E 05	19	.99900	1.00E 00
10	.28G0C	4.65E 05			

#### ** L = 4.60 **

NO.	В	UMNI FLUX	NO.	В	DMNI FLUX
1	.00100	2.40E 06	11	.32000	3.10E 05
Ž	.00320	2.40E 06	12	.36000	2.00E 05
3	.02000	2.37E 06	13	.40000	1.26E 05
4	.04000	2.30E 06	14	.44000	7.65E 04
5	.0800C	2.09E C6	15	.48000	4.34E 04
6	.12000	1.73E 06	16	.52000	2.39E 04
7	-16000	1.33E 06	17	.57500	1.00E 04
8	.20000	9.90E 05	18	.60000	1.00E 00
9	-24000	7.10E 05	19	.99900	1.00E 00
10	-28000	4.85F 05			

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

#### ** L = 4.80 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.00100	2.40E 06	11	.32000	2.68E 05
2	.0G282	2.40E 06	12	.36000	1.75E 05
3	•02000	2.37E 06	13	-40000	1.10E 05
4	.04000	2.30E 06	14	.44000	6.70E 04
5	.08000	2.09E 06	15	.4800C	3.93E 04
6	.12000	1.73E 06	16	.52000	2.19E 04
7	-16000	1.31E 06	17	•56450	1.00E 04
8	.20000	9.40E 05	18	.60000	1.00E 00
9	.24000	6.38E 05	19	.99900	1.00E 00
1.0	.28000	4.10E 05			

#### ** L = 5.00 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.00106	2.52E 06	11	.32000	2.06E 05
2	.00249	2.52E 06	12	.3600G	1.32E 05
3	.02000	2.49E 06	13	.40000	8.55E 04
4	.04000	2.38E 06	14	.44000	5.42E 04
5	.08000	2.01E 06	15	.48000	3.35E 04
6	.12000	1.55E 06	16	.52000	1.91E 04
7	.16000	1.13E 06	17	.56000	1.00E 04
8	.20000	7.75E 05	18	.60000	1.00E 00
9	.24000	5.00E 05	19	.99900	1.00E 00
10	.28000	3.28E 05			

#### ** L = 5.20 **

NO.	8	OMNI FLUX	NO.	В	OMNI FLUX
1	.00100	2.00E 06	11	.32000	1.60E 05
2	.00222	2.00E 06	12	.36000	1.07E 05
3	.02000	1.93E 06	13	-40000	7.48E 04
4	.04000	1.86E 06	14	.44000	5.00E 04
5	.08000	1.6CE 06	15	.48000	3.19E 04
6	-12000	1.24E 06	16	.52000	1.83E 04
7	.16000	8.80E 05	17	.55950	1.00E 04
8	.200CG	5.95E 05	18	-60000	1.00E 00
9	-24000	3.90E 05	19	.99900	1.00E 00
lû	·28000	2.48E 05			

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 5.40 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.00100	1.72E 06	11	.32000	1.27E 05
ž	.00198	1.72E 06	12	.36000	8.50E 04
3	.02000	1.64E 06	13	.40000	5.80E 04
4	+04000	1.55E 06	14	.44000	3.90E 04
5	.08000	1.27E 06	15	.48000	2.50E 04
6	.12000	9.4JE 05	16	•55000	1.30E D4
7	.16000	6.65E C5	17	•56 <b>0</b> 00	2.00E 03
8	.20000	4.55E 05	18	.60000	1.00E CD
9	-24000	3:00E 05	19	•99900	1.00E 00
10	.28066	1.98E C5			

** L = 5.60 **

NO.	В	OMNI FLUX	ND.	В	DMNI FLUX
1	.00100	1.38E 06	11	.32000	9.60E 04
2	.00171	1.38E 06	12	.36000	6.25E 04
3	.02000	1.30E 06	13	.40000	4.15E 04
4	.04000	1.21E 06	14	.44000	2.83E 04
5	.08000	9.63E 05	15	.48000	1.85E 04
6	.12000	7.23F 05	16	.53500	1.00E 04
7	.16500	5.13E 05	17	.54000	7.70E 03
8	.20000	3.38E 05	18	.60000	1.00E 00
9	.24000	2.23E 05	19	.99900	1.00E 00
10	.28000	1.48E 05			

** L = 5.80 **

NO.	в	OMNI FLUX	NO.	В	OMNI FLUX
1	.00160	1.10E 06	11	.32000	6.10E 04
2	.00160	1.10E 06	12	.36000	3.88E 04
3	-02000	1.03E 06	13	.40000	2.56E 04
4	.04000	9.48E 05	14	.44000	1.69E 04
5	-08000	7.20E 05	15	-49000	1.00E 54
6	•12000	5.15E 05	16	.52000	1.05E 03
7	•160GO	3.55E 05	17	.56000	3.18E 01
8	.20000	2.38E 05	18	.60000	1.00E 00
9	-24000	1.53E 05	19	.99900	1.00E 00
10	-28000	9.85E 04			

### TABLE 5 (CONCLUDED)

#### ELECTRON MAP AE2 AUGUST 1964 ENERGY ABOVE 0.5 MEV

** L = 6.00 · +

NO.	В	ÚMNI FLUX	NO.	В	OMNI FLUX
1	.03100	8.70E 05	11	.32000	3.73E 04
2	·00144	8.68E 05	12	.36000	2.36E U4
3	.02000	8.00E 05	13	.40000	1.53E 04
4	-04060	7.08E 05	14	.44000	1.00E 04
5	.08000	5.28E 05	15	.48 <b>0</b> 00	1.31E 03
6	.12500	3.60E 05	16	.52000	1.21E J2
7	.16000	2.32E 05	17	.56000	1.08E 01
8	-20000	1.48E 05	18	.60000	1.00E 00
9	.24000	9.40E 04	19	.99900	1.00E 00
10	.28000	5.95E 04			

#### ** L = 6.20 **

NO.	В	OMNI FLUX	NO.	В	OMNI FLUX
1	.00100	6.00E 05	11	.32000	1.94E 04
2	.00131	6.00E 05	12	.37500	1.00E 04
3	.02000	5.46E 05	13	.40 <b>00</b> 0	3.86E 03
4	.04000	4.73L 05	14	<b>.440</b> 00	7.60L 02
5	.08000	3.38E 05	15	.48000	1.42E 02
6	.12000	2.2UE 05	16	.52000	2.70E 01
7	.16000	1.37E 05	17	. 56000	5.10E 00
8	.20000	8.40E 04	18	.60000	1.00E 00
9	.24000	5.19E 04	19	.99900	1.00E 00
10	.28000	3.19E 04			

#### ** L = 6.30 **

NO •	В	UMNI FLUX	NO.	В	OMNI FLUX
1	.0:125	5.0LE 05	5	.24700	3.00E 04
2	.06700	3.00E 05	6	.32900	1.00E 04
3	.1000C	2.00F 05	7	.60000	1.00E 00
4	•15300	1.00L 05	8	.99900	1.30E 00

#### ** L = 9.99 **

NO.	8	OMNI FLUX	NO.	В	OMNI FLUX
1	.00010	1.00E 00	3	.61006	1.00E 00
2	.00106	1.00F 00	4	•9990€	1.0GE 00

TABLE 6 ORBITAL INTEGRATION MAP AE2

URBIT ALTITUDE .. 150 N MI

TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ENFI			DEG DEG	ORRITA 30	L FLUX DEG	ORBITA 60	L FLIJX DEG	CRBITA 90	
E1	E2	*£1	E1-E2	<b>∗</b> E1	E1-E2	<b>*</b> E1	£1-E2	<b>+</b> E1	E1-E2
0.	G • 25	0.	0.	4.86E C8	2.23E 08	2.17E C9	1.42E 09	1.95E 09	1.26E 0
0.25	0.50	C.	0.	2.63E 08	8.53E 07	7.49E C8	3.55E 08	6.81E 08	3.30E 0
0.50	0.75	0.	0.	1.78E 08	4.90E 07	3.94E C8	1.46F 08	3.51E 08	1.36E 0
0.75	1.00	c.	n.	1.29E 08	3.31E 07	2.48E CB	8.11E 07	2.15E 08	7.50E 0
1.00	1.25	9.	ņ,	9.56E 07	2.45E 07	1.67E C8	5.03E 07	1.40E 08	4.48E 0
1.25	1.50	0.	0.	7.11F 07	1.85E 07	1.17E C8	3.33E 07	9.53E 07	2.85E C
1.50	1.75	0.	0.	5.26E C7	1.41E 07	8.35E C7	2.34E 07	6.68E 07	1.95E 0
1.75	2.00	С.	9.	3.85E 07	1.03E 07	6.01E 07	1.62E 37	4.73E 07	1.32E 0
2.00	2.25	C.	0.	2.83E C7	7.25£ 06	4.39E C7	1.15E 07	3.41E 07	9.09E 0
2.25	2.50	0.	÷.	2.10E 07	5.85E C6	3.24E C7	8.65E 06	2.51E 07	6.83E 0
2.50	2.75	0.	0.	1.52E C7	3.58E 06	2.38E 07	6.00E 96	1.82£ 07	4.64E 0
2.75	3.00	Ċ.	ð.	1.16E C7	2.75E 06	1.78E 07	4.47E 06	1.36F 07	3.44E 0
3.00	3.25	0.	o.	8.85E 06	2.10E 06	1.33E C7	3.32E 06	1.01E 07	2.55E 0
3.25	3.50	0.	ō.	6.75E C6	1.58E 06	9.98E C6	2.46E 06	7.59E 06	1.88E 0
3.50	3.75	0.	0.	5.17E C6	1.218 06	7.52F C6	1.84E 06	5.72E 06	1.49E 0
3.75	4.00	0.	J.	3.96E 06	9.21E 05	5.67E C6	1.38E 06	4.31E 06	1.05E 0
4.00	4.25	0.	c.	3.04E 06	7.04E 05	4.29E C6	1.04E 06	3.26F 06	7.87E 0
4.25	4.50	0.	0.	2.33E 06	5.38E 05	3.25E C6	7.83E 05	2.47E 06	5.94E 0
4.50	4.75	0.	0.	1.8CE 06	4.16E 05	2.47E C6	5.94E 05	1.88E 06	4.51E 0
4.75	5.00	0.	0.	1.38E 06	3.16E 05	1.88E C6	4.47E 05	1.43E 06	3.39E 0
5.09	5.25	0.	9.	1.06E 06	2.45E 05	1.43E C6	3.42E 05	1.09F 06	2.60E 0
5.25	5.50	C.	0.	8.19E 05	1.87E 05	1.C9E C6	2.57E 05	8.27E 05	1.95E 0
5.50	5.75	0.	0.	6.32E 05	1.44E 05	8.31E 05	1.96E 05	6.35E 05	1.50E 0
5.75	6.00	G.	o.	4.88E 05	1.11E 05	6.34E C5	1.50E 05	4.85E 05	1.14E 0
6.00	6.25	0.	0.	3.76E 05	8.66E 04	4.85E C5	1.15E 05	3.71E 05	8.79E 0
6.25	6.50	o.	0.	2.90E C5	6.61E 04	3.70E C5	8.69E 04	2.83E 05	6.63E 0
6.50	6.75	0.	0.	2.23E 05	5.11E 04	2.83E 05	6.64E 04	2.17E 05	5.08E 0
6.75	7.00	0.	o.	1.72E C5	3.91E 04	2.16E C5	5.05E 04	1.66E 05	3.86E 0
7.00		0.	0.	1.33E 05	1.33€ 05	1.66E C5	1.66E 05	1.28E 05	1.28E 0

DRBIT ALTITUDE.. 300 N MI

TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ENE!	RG Y V	ORBITA O D	L FLUX EG	ORBITAL 30	DEG	60 1	DEG	90	DEG
€1	E2	#E1	E1-E2				E1-E2		E1-E2
0.	0.25	8.59E 06	1.11E 06	3.28E 1C	1.50E 10	1.92E 10	1.02E 10	1.58E 10	8.43E 09
0.25	0.50	7.48E 06	1.11E 06	1.78E 10	5.79E 09	9.09E 09		7.41E 09	2.76E 09
0.50	0.75	6.37E 06	1.11E 06		3.32E 09	5.78E C9	1.71E C9		1.41E 09
0.75	1.00	5.26E 06	1.11E 06	8.68E C9	2.23E 09	4.07F 09	1.09E 09		8.87E 08
1.00	1.25	4.16E 06	1.11E 06	6.45E Ü9	1.65E 09	2.97F C9	7.76E 08		6.19E 08
1.25	1.50	3.05E 06	1.03E 06	4.80E 09	1.24E 09	2.20E 09	5.70F 08	1.73E 09	4.49E 08
1.50	1.75	2.02F 06	7.78E 05	3.56E 09	9.44E 08	1.63E C9	4.28E 08	1.28E 09	3.34E 08
1.75	2.00	1.245 06	4.89E 05	2.62E 09	6.96E 08	1.20E C9	3.12E 08	9.49E 08	2.43E 08
2.00	2.25	7.498 05	2.95E 05	1.92E C9	4.92E 08	8.875 C8	2.24E 08	7.07E 08	1.76E 08
2.25	2.50	4.54E 05	1.79E 05	1.43E 09	4.01E 08	6.63E C8	1.78E 08	5.31E 08	1.38E 08
2.50	2.75	2.75€ 05	1.09E 05	1.03E 09	2.40E 08	4.85E C8	1.15E 08	3.93E 08	9.29E 07
2.75	3.00	1.66E 05	6.56E C4	7.88E 08	1.85E 08	3.70E C8	8.82E C7	3.CCE 08	7.11E 07
3.00	3.25	1.01E 05	3.97E 04	6.03E 08	1.42E 08	2.82E 08	6.71E 07	2.29E 08	5.41E 07
3.25	3.50	6.08F 04	2.40E 04	4.62E 08	1.08E 08	2.15E CB	5.07E 07	1.75E 08	4.10E 07
3.50	3.75	3.68E 04	1.45E C4	3.54E C8	8.20E 07	1.64E C8	3.86E 07	1.34E 08	3.13E 07
3.75	4.00	2.23E 04	8.79E 63	2.72E 08	6.29E 07	1.26E C8	2.94E C7	1.02E 08	2.39E 07
4.00	4.25	1.35E 04	5.32E C3	2.C9E 08	4.83E 07	9.61E C7	2.25E 07	7.85E 07	1.83E 07
4.25	4.50	8.14E 03	3.22E 03	1.61E 08	3.69E 07	7.37E 07	1.71E 07	6.G2E 07	1.40E 07
4.50	4.75	4.93E 03	1.95E C3	1.24E 08	2.86E 07	5.65E 07	1.32E 07	4.63E 07	1.07E 07
4.75	5.00	2.98E 03	1.18E C3	9.51E 07	2.18E 07	4.33E C7	1.00E 07	3.56E 07	8.19E 06
5.00	5.25	1.80E 03	7.12E C2	7.33E C7	1.68E C7	3.33E C7	7.73E 06	2.74E 07	6.32E 06
5.25	5.50	1.09E 03	4.31E G2	5.65E C7	1.29E 07	2.56E 07	5.89E 06	2.10E 07	4.83E 06
5.50	5.75	6.59E 02	2.60E 02	4.36E C7	9.95E 06	1.97E C7	4.54E 06	1.62E 07	3.72E 06
5.75	6.00	3.99E 02	1.58E 02	3.36E C7	7.68E 06	1.52E C7	3.49E 06	1.25E 07	2.87E 06
6.00	6.25	2.41E 02	9.54E 01	2.59E 07	5.96E 06	1.17E C7	2.70F 06	9.63E 06	2.22E 06
6.25	6.50	1.46E 02		2.GOE G7	4.56E 06	8.97E 06	2.06E 06	7.41E 06	1.70E 06
6.50	6.75	8.84E 01		1.54E C7	3.53E 06	6.90E C6	1.59E 06	5.71E 06	1.31E C
6.75	7.00	5.34E 01		1.19E C7		5.31E C6	1.22E 06		1.00E 06
7.00	7.00			9.19E 06	9.19E 06	4.10E C6	4.10E 06		3.39E 06

#### ORBITAL INTEGRATION MAP AE2

URBIT ALTITUDE .. 450 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1. MINUTES

ENE! ME!		CRBITA O D		ORBITA 30			L FLUX DEG	ORBITAL 90	
E 1	E2	*£1	E1-£2	*E1	E1-E2	*F1	F1-E2	#F1	£1-£2
С.	0.25	1.25E 10	2.88E 09	2.55E 11	1.13E 11	1.215 11	5.80E 10	9.74E 10	4.55E
0.25	0.50	9.65E 09	1.84E 09	1.42F 11	4.45E 10	6.35E 10	2.11F 10	5.19E 10	1.69E
0.50	0.75	7.81E 09	1.53E 09	9.74E 10	2.62E 10	4.24E 10	1.18F 10	3.50E 10	9.60E
0.75	1.00	6.28E 09	1.37E 09	7.13E 10	1.80E 10	3.06E 10	7.92E 09	2.54F 10	6.52E
1.00	1.25	4.91E 09	1.29E 09	5.33E 10	1.37E 10	2.27E 10	5.87E 09	1.89E 10	4.88E (
1.25	1.50	3.62E 09	1.16E 09	3.96E 10	1.05E 10	1.68E 10	4.45E 09	1.40E 10	3.74E
1.50	1.75	2.45F 09	8.82E Q8	2.91E 10	8.04E 09	1.24E 10	3.37E 09	1.03E 10	2.83E
1.75	2.00	1.57E 09	5.82E 08	2.10E 10	5.88E 09	8.98E 09	2.43E 09	7.44E 09	2.05E
2.00	2.25	9.90E 08	3.59E 08	1.52E 10	4.C7E 09	6.55E C9	1.715 09	5.39E 09	1.43E
2.25	2.50	6.31E 08	2.46E 08	1.11F 10	3.32E 09	4.84E C9	1.368 09	3.96E 09	1.13E
2.50	2.75	3.85€ 08	1.28E 08	7.78F 09	1.85E 09	3.485 09	8.38E 08	2.83F 09	6.82E
2.75	3.00	2,57E 08	8.35E 07	5.93E 09	1.42E 09	2.65E 09	6.38E 08	2.15E 09	5.18E
3.00	3.25	1.738 08	5.51E 07	4.51E C9	1.08E 09	2.01E C9	4.82E 08	1.63E 09	3.92E
3.25	3.5℃	1.18E 08	3.66E 07	3.43E 09	8.15E 08	1.53E 09	3.63E 08	1.24E 09	2.95E
3.50	3.75	8.16E 07	2.43F 07	2.62F C9	6.15E 08	1.16E C9	2.74E 08	9.45E 08	2.23E
3.75	4.00	5.73E 07	1.66F 07	2.00E 09	4.69E 08	8.89E 08	2.09F 08	7.23E 08	1.69E
4.00	4.25	4.07E 07	1.15E 07	1.53E C9	3.58E 08	6.80E C8	1.590 08	5.53F 08	1.29E
4.25	4.50	2.92E 07	7.97E 06	1.18E C9	2.73E 08	5.21E C8	1.21E 08	4.24E 08	9.83E
4.50	4.75	2.12E 07	5.77E 06	9.03E C8	2.11E 08	4.00E 08	9.34E 07	3.26E 08	7.59E
4.75	5.00	1.545 07	4.03E 06	6.91E 08	1.59E 08	3.07E C8	7.07E 07	2.50E 08	5.75E
5.00	5.25	1.14E 07	2.91E 06	5.32E C8	1.23E 08	2.36E C8	5.46E 07	1.92E 08	4.44E
5.25	5.50	8.49E 06	2.18E 06	4.09E Q8	9.43E 07	1.815 08	4.16E 07	1.48F 08	3.40E
5.50	5.75	6.31E 06	1.57E 06	3.15€ 08	7.24E 07	1.40E 08	3.21E 07	1.14E 08	2.61E
5.75	6.00	4.74E 06	1.17E 06	2.42E 08	5.57E 07	1.080 08	2.47E 07	8.78E 07	2.01E
6.00	6.25	3.57E 06	8.84E 05	1.86E C8	4.33E 07	8.28F C7	1.92E 07	6.77E 07	1.56E
6.25	6.50	2.68E 06	6.46E 05	1.43E 08	3.29E 07	6.36E C7	1.46F 07	5.21E 07	1.19E
6.50	6.75	2.04E 06	4.99E 05	1.10F 08	2.556 07	4.90E C7	1.13F 07	4.01F 07	9.21E
6.75	7.00	1.545 06	3.67E 05	8.49E 07	1.94E 07	3.78F 07	8.61E 06	3.09E 07	7.04E
7.00		1.17E 06	1.17E 06	6.55E C7	6.55E 07	2.92E C7	2.92E 07	2.39E 07	2.39E

ORBIT ALTITUDE.. 600 N MI TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ME		0 D	EG	30	DEG	ORBITA 60	DEG	90	
£1						*E1			
0.	0.25	6.54E 11		9.68E 11	4.50E 11	4.64F 11	2.18E 11	3.74E 11	1.73E 11
0.25	0.50	4.208 11		5.18E 11	1.71E 11	2.46E 11	8.15€ 10		6.54E 10
0.50	C.75	3.10E 11	7.35E 10	3.47E 11	9.73E 1C	1.65E 11	4.61E 10	1.35E 11	3.74E 10
0.75	1.00	2.37E 11	5.60E 10	2.50E 11	6.49E 10	1.19E 11	3.07E 10	9.80E 10	2.52E 10
1.00	1.25	1.81E 11	4.66E 10	1.85E 11	4.72E 10	8.78E 10	2.25E 10	7.28E 10	1.87E 10
1.25	1.50	1.34E 11	3.86E 10	1.38E 11	3.51E 10	6.53E 10	1.68E 10	5.41E 10	1.41E 10
1.50	1.75	9.58E 10	2.92E 10	1.C3E 11	2.69E 10	4.85E 10	1.28E 10	4.00E 10	1.08E 10
1.75	2.00	6.66E 10	2.06E 10	7.58E 10	1.98E 10	3.57E 10	9.49E 09	2.92E 10	7.96E 09
2.00	2.25	4.60E 10	1.36E 10	5.60E 10	1.41E 10	2.62E 10	6.71F 09	2.12E 10	5.56E 09
2.25	2.50	3.24E 10	1.04E 10	4.19E 10	1.17E 10	1.95E 10	5.54E 09	1.56E 10	4.59E 09
2.50	2.75	2.20E 10	5.68E 09	3.02E 10	6.97E 09	1.40F 10	3.23E 09	1.10E 10	2.59E 09
2.75	3.00	1.63E 10	4.13E 09	2.33E 10	5.43E 09	1.07E 10	2.51E 09	8.46E 09	2.00E 09
3.00	3.25	1.21F 10	3.04E 09	1.78E 10	4.18E 09	8.22E C9	1.93E 09	6.46E 09	1.53E 09
3.25	3.50	9.11E 09	2.25E 09	1.36E 10	3.17E 09	6.30F 09	1.47E 09	4.93E 09	1.16E 09
3.50	3.75	6.86E 09	1.65E 09	1.05E 10	2.43E 09	4.83E C9	1.125 09		8.81E 08
3.75	4.00	5.21E 09	1.24E 09	8.05E C9	1.86E 09	3.71E C9	8.59E 08		6.74E 08
4.00	4.25	3.97E 09	9.39E 68	6.19E C9	1.43E 09	2.85E 09	6.59E 98		5-16E 08
4.25	4.50	3.03E 09	7.07E 08	4.76E 09	1.09E 09	2.19E C9	5.04E 08		3.93E 08
4.50	4.75	2.32E 09	5.45E 08	3.67E 09	8.48E 08	1.69E C9	3.91E 08	1.31E 09	3.05E 08
4.75	5.00	1.78E 09	4.10E 08	2.82E 09	6.43E 08	1.30E 09	2.97E 08	1.00E 09	2.31E 08
5.00	5.25	1.37E 09	3.13E 08	2.17E 09	5.00E 08	10.00E 08	2.30E 08	7.72E 08	1.78E 08
5 - 25	5.50	1.05E 09	2.43E 08	1.67E 09	3.81E 08	7.70E C8	1.76E 08	5.94E 08	1.37E 08
5.50	5.75	8.10E 08	1.85E 08	1.29E 09	2.95E 08	5.94E CR	1.36E 08	4.57E 08	1.05E 08
5.75	6.00	6.25E 08	1.43E 08	9.98E 08	2.28E 08	4.58E 08	1.05E 08	3.52E 08	8.09E 07
6.00	6.25	4.82E 08	1.10E 08	7.70E G8	1.78E 08	3.53E C8	8.14E 07		6.29E 07
6.25	6.50	3.72E 08	8.48E C7	5.93E 08	1.35E 08	2.72E C8	6.216 07		4.78E 07
6.50	6.75	2.87E 08	6.56E 07	4.58E 08	1.05E 08	2.10F C8	4.81E 07		3.70E 07
6.75	7.00	2.22E 08		3.53E 08	8.00E 07	1.62E C8	3.67E 07		2.82E 07
7.00		1.71F 08	1.71F 08	2.73E 08	2.73E 08	1.25E C8	1.25E 08		

#### ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE.. 800 N MI

TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ME	RGY /	O CI		ORBITA 30	DES	ORBITA 60		CRBITAI 90 i	
£1	E?	<b>*</b> £1	E1-E2	<b>+</b> €1	E1 <b>-</b> E2	*E1	<b>E1-</b> E2	<b>+</b> E1	E1-E2
0.	0.25	6.228 12	2.76E 12	4.04E 12	1.95E 12	1.92E 12	9.18E 11	1.61E 12	7.70E 1
0.25	0.50	3.46E 12	1.10E 12	2.09E 12	7.20E 11	9.98E 11	3.41E 11	8.42E 11	2.87E 1
0.50	0.75	2.36E 12	6.49E 11	1.37E 12	3.99E 11	6.57E 11	1.90E 11	5.55E 11	1.60E 1
0.75	1.00	1.718 12	4.40E 11	9.69E 11	2.58E 11	4.678 11	1.24E 11	3.95E 11	1.95E 1
1.00	1.25	1.275 12	3.22E 11	7.11E 11	1.81€ 11	3.44E 11	8.74F 10	2.91E 11	7.38E 1
1.25	1.50	9.515 11	2.41E 11	5.30E 11	1.30E 11	2.56E 11	6.36F 10	2.17E 11	5.37E 1
1.50	1.75	7.09E 11	1.84E 11	4.00E 11	9.97E 10	1.93E 11	4.81E 10	1.63E 11	4.07E 1
1.75	2.00	5.26E 11	1.35E 11	3.C1E 11	7.30E 10	1.45E 11	3.56E 10	1.22E 11	3.01E 1
2.00	2.25	3.90E 11	9.68E 10	2.28€ 11	5.40E 10	1.098 11	2.61E 10	9.23E 10	2.21E 1
2.25	2.50	2.93E 11	7.93E 10	1.74E 11	4.39E 10	8.29E 10	2.12E 10	7.02E 10	1.80E 1
2.50	2.75	2.14E 11	4.89E 10	1.30E 11	2.95E 10	6.17E 10	1.40E 10	5.23E 10	1.19E 1
2.75	3.00	1.65E 11	3.81E 10	1.00E 11	2.31E 10	4.76E 10	1.10E 10	4.04E 10	9.28E 0
3.00	3.25	1.27E 11	2.93E 10	7.73E 10	1.78E 10	3.67E 10	8.45E 09	3.11F 10	7.16E 0
3.25	3.50	9.78E 10	2.24E 10	5.95E 10	1.36E 10	2.82F 10	6.47E 09	2.39E 10	5.4RE 0
3.50	3.75	7.54E 10	1.72E 10	4.59E 10	1.05E 10	2.18E 10	4.98E 09	1.85E 10	4.22E 0
3.75	4.30	5.82E 10	1.33E 10	3.54E 10	8.09E 09	1.68E 10	3.84E 09	1.42E 10	3.25€ 0
4.00	4.25	4.50E 10	1.02E 10	2.73E 10	6.23E 09	1.298 10	2.95t 09	1.10E 10	2.50E 0
4.25	4.50	3.47E 10	7.86€ ù9	2.10E 10	4.79E 09	9.99E C9	2.27E 09	8.48E 09	1.93E 0
4.50	4.75	2.69E 10	6.12E 09	1.62E 10	3.71E 09	7.72E C9	1.76E 09	6.56E 09	1.50E 0
4.75	5.00	2.08E 1C	4.68E 09	1.25E 10	2.84E 09	5.95E C9	1.35E 09	5.06E 09	1.15E 0
5.00	5.25	1.61E 10	3.64E 09	9.69E C9	2.21E 09	4.61E C9	1.05E 09	3.92F 09	8.91E 0
5.25	5.50	1.248 10	2.80E 09	7.48E 09	1.69E 09	3.56E 09	8.04E 08	3.02E 09	6.83E 0
5.50	5.75	9.65E 09	2.17E 09	5.79E 09	1.31E 09	2.75E 09	6.23E 08	2.34E 09	5.30E 0
5.75	6.00	7.48E 09	1.68E 09	4.47E 09	1.01E 09	2.13E C9	4.82E 08	1.81E 09	4-10E 0
6.00	6.25	5.79E 09	1.31E 69	3.46E 09	7.90E 08	1.65E C9	3.75E 08	1.40E 09	3.19E 0
6.25	6.50	4.48E 09	1.01E 09	2.67E 09	6.06E 08	1.27E 09	2.89E 08	1.08E 09	2.45E 0
6.50	6.75	3.47E G9	7.83E 08	2.06E 09	4.68E 08	9.84E C8	2.23E 08	8.38E 08	1.90E 0
6.75 7.00	7.00	2.69E 09 2.09E 09	6.02E 08	1.60E 09 1.24E 09	3.60E 08 1.24E 09	7.61E C8 5.89E C8	1.71E 08 5.89E 08	6.48E 08 5.02E 08	1.46E 0

ORBIT ALTITUDE..1000 N MI TOTAL TIME.. 24.HGURS TIME INTERVAL.. 1.MINUTES

ENE: ME			AL FLUX DEG	30 (	DEG	60		90 (	
E1	E2	*E1	E1-E2						E1-E2
0.	0.25	1.97E 13	9.54E 12	8.88E 12	4.46E 12	4.52E 12	2.28E 12	3.86E 12	1.94E 1
0.25	0.50	1.01E 13	3.50E 12	4.41E 12	1.59E 12	2.24E 12	8.04E 11	1.92E 12	6.88E 1
0.50	0.75	6.62E 12	1.94F 12	2.83E 12	8.50E 11	1.44F 12	4.32E 11	1.23E 12	3.70E
0.75	1.00	4.67E 12	1.26E 12	1.98E 12	5.39E 11	1.01E 12	2.74E 11	8.63E 11	2.35E
1.00	1.25	3.42E 12	8.69E 11	1.44E 12	3.68E 11	7.33E 11	1.87E 11	6.28E 11	1.60E
1.25	1.50	2.55€ 12	6.15E 11	1.C7E 12	2.59E 11	5.46E 11	1.31F 11	4.68E 11	1.13E
1.50	1.75	1.93E 12	4.74E 11	8.13E 11	1.97E 11	4.14E 11	1.00E 11	3.55E 11	8.60E
1.75	2.00	1.46E 12	3.51E 11	6.16E 11	1.45E 11	3.14E 11	7.39E 10	2.69E 11	6.34E
2.00	2.25	1.11€ 12	2.60E 11	4.71E 11	1.09E 11	2.40E 11	5.55E 10	2.06E 11	4.76E
2.25	2.50	8.48F 11	2.19E 11	3.62E 11	8.918 10	1.84E 11	4.57E 10	1.58E 11	3.93E
2.50	2.75	6.29E 11	1.41E 11	2.73E 11	6.20E 10	1.39E 11	3.14E 10	1.19E 11	2.69E
2.75	3.90	4.88E 11	1.12E 11	2.11F 11	4.87E 10	1.07E 11	2.47E 10	9.19E 10	2.128
3.00	3.25	3.76E 11	8.67E 10	1.62E 11	3.76E 10	8.25E 10	1.91E 10	7.07E 10	1.64E
3.25	3.50	2.90E 11	6.62F 10	1.24E 11	2.86E 10	6.34F 10	1.46E 10	5.43E 10	1.25E
3.50	3.75	2.24E 11	5.12E 10	9.57E 10	2.21F 10	4.88E 10	1.12E 10	4.19E 10	9.63E
3.75	4.70	1.72E 11	3.94E 10	7.36E 10	1.70E 10	3.76E 10	8.645 09	3.22E 10	7.41E
4.00	4.25	1.33E 11	3.03E 10	5.67E 10	1.30E 10	2.89E 10	6.63E 09	2.48E 10	5.69E
4.25	4.50	1.03E 11	2.33E 10	4.36E 10	1.00E 10	2.23E 10	5.10E 09	1.91E 10	4.38E
4.50	4.75	7.93E 10	1.82E 10	3.36E 10	7.74E 09	1.72E 10	3.95E 09	1.48E 1C	3.39E
4.75	5.20	6.11E 10		2.59E 10	5.91E 09	1.32E 10	3.01E 09	1.14E 10	2.59E
5.00	5.25	4.73E 10		2.00F 10	4.60E 09	1.02E 10	2.35E 09	8.78E 09	2.02E
5.25	5.50	3.65E 10		1.54E 10	3.49E 09	7.87E C9	1.78E 09	6.77E 09	1.53E
5.50	5.75	2.83F 10		1.19E 10	2.71E 09	6.09E C9	1.39E 09	5.24E 09	1-19E
5.75	6.00	2.18E 10		9.17E C9	2.09E 09	4.70E C9	1.07F 09	4.04E 09	9.20E
6.00	6.25	1.69F 10		7.08E 09	1.63E 09	3.63E 09	8.36F 08	3.12E 09	7.18E
6.25	6.50	1.30E 10		5.45E 09	1.24E 09	2.80E C9	6.37E 08	2.41E 09	5.47E
6.50	6.75	1.01E 10		4.20E 09	9.50E 08	2.16E C9	4.92E 08	1.86E 09	4.23E
6.75	7.00	7.78F 09		3.24E 09	7.36E 08	1.67E C9	3.77F 08	1.43E 09	3.24E
7.00		6.03E 09		2.51E 09	2.51E 09	1.29E 09	1.29F 09	1.11E 09	1.11E

# ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE .. 1250 N MI

TOTAL TIME.. 24. HOURS TIME INTERVAL.. 1. MINUTES

ENE ME		ATIBED ID D	L FLUX EG	ORBITA 30		ATTEND 1 06	L FLUX DEG	CRBITAL 90 (	
E 1	E 2	*E1	€1-E2	*El	E1-E2	*E1	E1-62	*£1	E1-E2
0.	2.25	3.43E 13	1.81E 13	1.28E 13	6.74E 12	6.77F 12	3.59E 12	5.81E 12	3.07E 12
0.25	2.50	1.638 13	6.10E 12	6.02F 12	2.28E 12	3.19E 12	1.21E 12	2.74E 12	1.04E 12
0.50	0.75	1.025 13	3.17E 12	3.74E 12	1.16E 12	1.98E 12	6.17E 11	1.70E 12	5.31E 11
0.75	1.00	6.798 12	1.97E 12	2.58E 12	7.19E 11	1.368 12	3.80E 11	1.17E 12	3.28E 11
1.00	1.25	5.02E 12	1.30E 12	1.86E 12	4.81E 11	9.82E 11	2.548 11	8.46E 11	2.19E 11
1.25	1.50	3.72F 12	8.77E 11	1.38E 12	3.33E 11	7.28E 11	1.76E 11	6.27E 11	1.51E 11
1.50	1.75	2.85€ 12	6.79E 11	1.05E 12	2.526 11	5.52E 11	1.335 11	4.76E 11	1.14E 11
1.75	2.00	2.178 12	4.94E 11	7.94F 11	1.85E 11	4.20E 11	9.75E 10	3.62E 11	8.40E 10
2.00	2.25	1.67E 12	3.795 11	6.09E 11	1.41E 11	3.225 11	7.43E 10	2.78E 11	6.40E 10
2.25	2.50	1.29F 12	3.17F 11	4.68E 11	1.13E 11	2.48E 11	5.99E 10	2.14E 11	5.15E 10
2.50	2.75	9.778 11	2.22E 11	3.55E 11	8.22E 10	1.88E 11	4.34E 10	1.62E 11	3.74E 10
2.75	3.00	7.545 11	1.77€ 11	2.72E 11	6.41E 10	1.448 11	3.39E 10	1.25E 11	2.92E 10
3.00	3.25	5.785 11	1.36€ 11	2.08E 11	4.92E 10	1.116 11	2.616 10	9.53E 10	2.25E 10
3.25	3.50	4.41E 11	1.73E 11	1.59E 11	3.72E 10	8.45E 10	1.97E 10	7.29E 10	1.70E 10
3.50	3.75	3.39E 11	7.93E 10	1.22E 11	2.86E 10	6.47E 10	1.52E 10	5.59E 10	1.318 10
3.75	4.00	2.59F 11	6.078 10	9.31E 10	2.19E 10	4.95E 10	1.168 10	4.28E 10	1.00E 10
4.00	4.25	1.998 11	4.62E 10	7.12E 10	1.67E 10	3.79E 10	8.86E 09	3.27E 10	7.64E 09
4.25	4.50	1.52F 11	3.54E 10	5.46E 10	1.28E 10	2.91E 10	6.78E 09	2.51E 10	5.85E 09
4.50	4.75	1.176 11	2.736 10	4.18E 10	9.798 09	2.23E 10	5.218 09	1.93E 10	4.50E 09
4.75	5.00	8.975 10	2.07E 10	3.20E 10	7.44E 09	1.71F 10	3.968 09	1.48E 10	3.42E 09
5.00	5.25	6.90ē 10	1.62E 10	2.46E 10	5.77E 09	1.31E 10	3.07F 09	1.13E 10	2.65E 09
5.25	5.50	5.28E 10	1.20E 10	1.88E 10	4.34E 09	1.01E 10	2.316 09	8.68E 09	2.00E 09
5.50	5.75	4.08E 10	9.43E 09	1.45E 10	3.36E 09	7.74E 09	1.80E 09	6.69E 09	1.55E 09
5.75	6.0 <b>0</b>	3.13€ 10	7.24E 09	1.11F 10	2.58E 09	5.95E C9	1.38E 09	5.14E 09	1.19E 09
6.00	6.25	2.415 10	5.67E 09	8.53E C9	2.00E 09	4.57E C9	1.07E 09	3.95E 09	9.23E 08
6.25	6.50	1.84% 10	4.24F 09	6.53E U9	1.51E 09	3.50E 09	8.10E 08	3.02E 09	6.99E 08
6.50	6.75	1.428 10	3.29E 09	5.01E C9	1.16E 09	2.69E 09	6.23E 08	2.32E 09	5.38E 08
6.75	7.00	1.09E 10	2.50E 09	3.85E 09	8.88E 09	2.07E C9	4.75E 08	1.79E 09	4.11E 08
7.00		8.41E 09	8.41E C9	2.96E 09	2.96E 09	1.59E C9	1.595 09	1.37E 09	1.37E 09

ORBIT ALTITUDE..1500 N MI TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ENE!	RGY <b>V</b>	AT1850 D 0	EG		L FLUX DEG	60 t	DEG	90 (	DEG
E1	E2	*E1			E1-E2		E1-E2		
0.	0.25	2.64E 13	1.42E 13	1.03E 13	5.73E 12	5.48E 12	3.04E 12	4.68E 12	2.60E 12
0.25	0.50	1.21E 13		4.60E 12	1.84E 12	2.43E 12	9.74E 11	2.09E 12	8.34E 11
0.50	0.75	7.415 12	2.33E 12	2.76E 12	8.79E 11	1.46E 12	4.65E 11	1.25E 12	3.99E 11
0.75	1.00	5.08E 12	1.42E 12	1.88E 12	5.27E 11	9.94E 11	2.79E 11	8.54E 11	2.40E 11
1.00	1.25	3.67E 12	9.60E 11	1.35E 12	3.56E 11	7.15E 11	1.88E 11	6.148 11	1.62E 11
1.25	1.50	2.71E 12	6.84E 11	9.98F 11	2.53E 11	5.27E 11	1.33E 11	4.53E 11	1.15E 11
1.50	1.75	2.02E 12	5.01E 11	7.45E 11	1.86E 11	3.93E 11	9.81E 10	3.38E 11	8.43E 10
1.75	2.00	1.52E 12	3.72E 11	5.59E 11	1.38E 11	2.95F 11	7.25E 10	2.54E 11	6.23E 10
2.00	2.25	1.15E 12	2.80E 11	4.21E 11	1.03E 11	2.27E 11	5.45E 10	1.91E 11	4.69E 10
2.25	2.50	8.69E 11	2.12E 11	3.18E 11	7.87E 10	1.68E 11	4.15E 10	1.45E 11	3.57E 10
2.50	2.75	6.57E 11	1.60E 11	2.39E 11	5.86E 10	1.26E 11	3.09E 10	1.09E 11	2.66E 10
2.75	3.00	4.97E 11	1.21E 11	1.81E 11	4.44E 10	9.55E 10	2.34E 10	8.23E 10	2.02E 10
3.00	3.25	3.76E 11	9.15E 10	1.36E 11	3.35E 10	7.21E 10	1.77E 10	6.21E 10	1.52E 10
3.25	3.50	2.84E 11	6.92E 10	1.03E 11	2.52E 10	5.44E 10	1.33E 10	4.69E 10	1.15E 10
3.50	3.75	2.15F 11	5.23E 10	7.76F 10	1.90E 10	4.11E 10	1.01E 10	3.55E 10	8.66E 09
3.75	4.00	1.63E 11	3.96E 10	5.86E 10	1.43E 10	3.11E 10	7.59E 09		6.54E 09
4.00	4 - 25	1.23E 11	3.00E 10	4.42E 10	1-08E 10	2.35E 10	5.73E 09		4.94E 09
4.25	4.50	9.33E 10	2.27E 10	3.34E 10	8.16E 09	1.77E 10	4.33E 09	1.53€ 10	3.73E 09
4.50	4.75	7.075 10	1.71E 10	2.53E 10	6.16E 09	1.34E 10	3.27E 09	1.16E 10	2.82E 09
4.75	5.00	5.35E 10	1.30E 10	1.91E 10	4.65E 09	1.01E 10	2.47E 09	8.77E 09	2.13E 09
5.00	5.25	4.06E 10	9.83E 09	1.44E 10	3.52E 09	7.68E C9	1.87E 09	6.64E 09	1.62E 09
5.25	5.50	3.07E 10	7.44E 09	1.09E 10	2.65E 09	5.81E C9	1.41E 09	5.02E 09	1.22E C9
5.50	5.75	2.33E 10	5.64E 09	8.27E 09	2.01E 09	4.41E C9	1.07E 09	3.81E 09	9.24E 08
5.75	6.00	1.76E 10	4.27E 09	6.26E 09	1.52E 09	3.34E 09	8.08E 08	2.88E 09	6.99E 08
6.00	6.25	1.34€ 10	3.24E 09	4.74E 09	1.15E 09	2.53E C9	6.14E 08	2.19E 09	5.31E 08
6.25	6.50	1.01E 10	2.45E 09	3.59E 09	8.69E 08	1.91E C9	4.63E 08	1.66E 09	4.00E 08
6.50	6.75	7.69E 09	1.86E 09	2.72E 09	6.58E 08	1.45E C9	3.51E 08		3.03E 08
6.75	7.00	5.83F 09	1.41E 09	2.06E 09	4.98E 08	1.10E 09	2.65E 08		2.30E 08
7.00		4.42E 09		1.56E C9	1.56E 09	8.35E C8	8.35E 08		7.22E 08

#### ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE .. 1750 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL. 1. MINUTES

ENE	RGY V	ATTENSO 0 0	f:G	ORBITAL 3C I	L FLUX DEG	DRBITA 60		CRBITAL 90 L	DEG
El	F.2	#E!			£1-E2	<b>+</b> E1	E1-E2		
0.	0.25	1.53E 13	8.73E 12	6.87E 12	4.16E 12	3.64E 12	2.20E 12	3.14E 12	1.89E 1
9.25	6.50	6.55F 12	2.69E 12	2.71E 12	1.22E 12	1.446 12	6.37E 11	1.25E 12	5.52E 1
0.50	0.75	3.86€ 12	1.22€ 12	1.49E 12	5.08F 11	8.00E 11	2.69E 11	7.01F 11	2.35E 1
0.75	1.90	2.64£ 12	7.28E 11	9.84E 11	2.82E 11	5.31E 11	1.52E 11	4.66E 11	1.33E 1
1.00	1.25	1.915 12	5.09E 11	7.02E 11	1.90E 11	3.79E 11	1.03E 11	3.33E 11	8.99E I
1.25	1.50	1.40E 12	3.72E 11	5.12E 11	1.36E 11	2.77E 11	7.375 10	2.43E 11	6.46E 1
1.50	1.75	1.03E 12	2.73E 11	3.76E 11	9-92F 10	2.03E 11	5.37E 10	1.79E 11	4.71E 1
1.75	2.30	7.59E 11	2.00E 11	2.77E 11	7.28E 10	1.49E 11	3.93E 10	1.32E 11	3.45E 1
2.00	2 - 25	5.58E 11	1.47E 11	2.04E ll	5.36E 10	1.10E 11	2.89E 10	9.70E 10	2.54E
2.25	2.50	4.118 11	1.086 11	1.516 11	3.95E 10	8.10F 10	2.13E 10	7.16E 10	1.87E 1
2.50	2.75	3.03F 11	7.97E 10	1.118 11	2.91E 10	5.97E 10	1.57E 10	5.29E 10	1.38E 1
2.75	3.00	2.23E 11	5.88E 10	8.20E 10	2.15E 10	4.40E 10	1.15E 10	3.91E 10	1.02E
3.00	3.25	1.64E 11	4.32E 10	6.05E 10	1.58E 10	3.25E 10	8.51E 09	2.89E 10	7.53E C
3.25	3.50	1.218 11	3.18E 10	4.47E 10	1.176 10	2.40E 10	6.27E 09	2.14E 10	5.56E (
3.5ú	3.75	8.91E 10	2.35E 10	3.30E 10	8.62E 09	1.77E 10	4.63E 09	1.58E 10	4.11E
3.75	4.00	6.568 10	1.73E 10	2.44E 10	6.37E 09	1.31E 10	3.42E 09	1.17E 10	3.04E C
4.00	4.25	4.83E 10	1.278 10	1.80E 10	4.70E 09	9.65E C9	2.52E 09	8.65E 09	2.25E (
4.25	4.50	3.568 10	9.37E 09	1.33F 10	3.47E 09	7.13E 09	1.86E 09	6.41E 09	1.66E (
4.50	4.75	2.63E 10	6.31E 09	9.87E 09	2.57E 09	5.27E C9	1.37E 09	4.75E 09	1.23E C
4.75	5.00	1.94E 10	5.09E 09	7.30E 69	1.90E 09	3.90E 09	1.01E 09	3.52E 09	9.09E (
5.00	5.25	1.43E 10	3.75E 69	5.40E 09	1.40E 09	2.88E C9	7.50E 08	2.61E 09	6.74E (
5.25	5.50	1-05E 10	2.76E 69	4.COF 39	1.04E 09	2.13E 09	5.54E 08	1.93E 09	4.99E
5.50	5.75	7.75F 09	2.94E 09	2.96E C9	7.69E 08	1.58E 09	4.11E 08	1.43E 09	3.71E C
5.75	6.00	5.71E 09	1.50E 09	2.19E C9	5.68E 08	1.17E C9	3.03E 08	1.06E 09	2.74E
6.00	6.25	4.215 09	1.11E 09	1.63E 09	4.21E 08	8.64E C8	2.24E 08	7.88E 08	2.03E (
6.25	6.50	3.10E 09	8.15E 08	1.21E 09	3.12E 08	6.49E C8	1.66E 08	5.85E 08	1.51E (
6.50	6.75	2.298 09	6.01E 08	8.94E 08	2.31E 08	4.74E C8	1.23E 08	4.35E 08	1.12E (
6.75	7.00	1.69E 09	4.43E 08	6.63E 08	1.71E 08	3.51E C8	9.09E 07	3.23E 08	8.29E
7.00		1.24F 09	1.24E 09	4.92E 08	4.92E 08	2.60E 08	2.60E 08	2.40E 08	2.40E (

ORBIT ALTITUDE..2000 N MI TOTAL TIME.. 24-HOURS TIME INTERVAL.. 1.MINUTES

ENE!		ORBITAL O DI		ORBITAL 30 I		ORBITA 60	L FLUX DEG	CRBITA 90	
E 1	E2	*E1		*E1		<b>+</b> €1	£1-F2	<b>+</b> E1	E1-E2
0.	0.25	1.28E 13	8.215 12	5.64E 12	3.73E 12	3.04E 12	2.01E 12	2.58E 12	1.71E 1
0.25	0.50	4.55E 12	2.30E 12	1.92E 12	1.00E 12	1.C3E 12	5.33E 11	8.76E 11	4.54E 1
0.50	0.75	2.26E 12	8.66E 11	9.16E 11	3.60E 11	4.93E 11	1.94E 11	4.22E 11	1.65E 1
0.75	1.00	1.39E 12	4.35E 11	5.56E 11	1.73E 11	3.00E 11	9.38E 10	2.57E 11	8.01E 1
1.00	1.25	9.55E 11	2.75E 11	3.83E 11	1.08E 11	2.06E 11	5.88E 10	1.77E 11	5.03E 10
1 - 25	1.50	6.80F 11	1.91E 11	2.75E 11	7.54E 10	1.47E 11	4.08E 10	1.26E 11	3.49E 16
1.50	1.75	4.89E 11	1.36E 11	1.99E 11	5.43E 10	1.06E 11	2.92E 10	9.14E 10	2.51E 19
1.75	2.00	3.53E 11	9.86E 10	1.45E 11	3.95E 10	7.72E 10	2.11E 10	6.64E 10	1.82E 1
2.00	2.25	2.548 11	7.10E 10	1.C6E 11	2.87E 10	5.60E 10	1.53E 10	4.82E 10	1.32E 1
2 • 25	2.50	1.83E 11	5.12E 10	7.69E 10	2.09E 10	4.07E 10	1.11E 10	3.51E 10	9.56E 0
2.50	2.75	1.32E 11	3.69E 10	5.60E 10	1.52E 10	2.96E 10	8.06E 09	2.55E 10	6.94E 0
2.75	3.00	9.53E 10	2.66E 10	4.08E 10	1.11E 10	2.15E 10	5.87E 09	1.86E 10	5.06E 0
3.00	3.25	6.87E 10	1.91E 10	2.97E 10	8.05E 09	1.57E 10	4.26E 09	1.35E 10	3.67E 0
3,25	3.50	4.95E 10	1.38E 10	2.17E 10	5.87E 09	1.14E 10	3.10E 09	9.85E 09	2.68E 0
3.50	3.75	3.57E 10	9.96E 09	1.58E 10	4.27E 09	8.31E C9	2.26E 09	7.18E 09	1.95E 0
3.75	4.00	2.57E 10	7.19E 09	1.15E 10	3.12E 09	6.06E C9	1.65E 09	5.23E 09	1.42E 0
4.00	4.25	1.85E 10	5.18E 09	8.39E C9	2.27E 09	4.41E C9	1.19E 09	3.81F 09	1.03E 0
4.25	4.50	1.34E 10	3.73E 09	6.13E 09	1.65E 09	3.22E C9	8.71E 08	2.78E 09	7.52E 0
4.50	4.75	9.63E 09	2.69E 09	4.47E C9	1.21E 09	2.35E C9	6.36E 08	2.03E 09	5.49E 0
4.75	5.00	6.94E 09	1.94E 09	3.26E 09	8.79E 08	1.71E C9	4.62E 08	1.48E 09	3.99E 0
5.00	5 - 25	5.00E 09	1.40E 09	2.38E 09	6.43E 08	1.25E C9	3.38E 08	1.08E 09	2.92E 0
5.25	5.50	3.61E 09	1.01E 09	1.74E 09	4.68E 09	9.11E C8	2.46E 08	7.89E 08	2.12E 0
5.50	5.75	2.60E 09	7.26E 08	1.27E 09	3.42E 08	6.66E C8	1.80E 08	5.76E 08	1.55E 0
5.75	6.00	1.87E 09	5.23E 08	9.29F 08	2.49E 08	4.86E C8	1.31E 08	4.21E 08	1.13E 0
6.00	6.25	1.35E 09	3.78E 08	6.79E OR	1.83E 08	3.55E CB	9.57E 07	3.08E 08	8.29E 0
6.25	6.50	9.74E 08	2.72E 08	4.96E 08	1.33E 08	2.60E 08	6.98E 07	2.25E 08	6.04E 0
6.50	6.75	7.02E 08	1.96E 08	3.63E C8	9.76E 07	1.90E C8	5.10E 07	1.65E 08	4.42E 0
6.75	7.00	5.06E 08	1.41E 08	2.66E 08	7.12E 07	1.39E C8	3.72E 07	1.20E 08	3.22E 0
7.00		3.65E 08	3.65E 08	1.94E 08	1.94E 08	1.02E 08	1.02E 08	8.81E C7	8.81E 0

### ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE . . 2250 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1.MINUTES

ENERGY	1			DRBITAL			FLUX		
MEV		0 DE		30 (		60 0	)EG	90 (	DEG
£1	E 2	*E1		*E1		*E1	E1-E2	*E1	E1-E2
0. 0. 00 00 00 00 00 00 00 00 00 00 00 0	E2 -25 -25 -25 -25 -20 -25 -20 -25 -20 -25 -25 -25 -25 -25 -25 -25 -25 -25 -25	*E1  9.77E 12 3.24E 12 1.41E 12 7.77E 11 5.12E 11 3.59E 11 2.57E 11 1.86F 11 1.34F 11 9.67E 10 6.98E 10 5.04E 10 2.63E 10 1.90E 1C 1.37E 10 9.89E 09 7.14E 09 5.16E 09 2.69E 09 2.69E 09	6.53E 12 1.84E 12 6.31E 11 2.65E 11 1.53E 11 1.53E 11 7.18E 10 5.17E 10 2.69E 10 1.94E 10 1.94E 10 1.91E 10 7.32E 09 3.83E 09 3.83E 09 3.75E 09 1.98E 09 1.98E 09 1.94E 09 1.98E 09 1.94E 09 1.98E 09 1.94E 09 1.94E 09 7.49E 08	*E1 5.19E 12 1.47E 12 5.62E 11 2.87E 11 1.84E 11 1.29E 11 9.27E 10 6.71E 10 6.71E 10 2.56E 10 1.86E 10 1.35E 10 9.82E 09 7.14E 09 5.20E 09 3.77E 09 2.75E 09 2.00E 09 1.46F 09 1.67E 09	E1-E2  3.71E 12 9.11E 11 2.75E 11 1.03F 11 5.54E 10 3.62F 1C 2.56F 1C 1.85E 10 1.34E 10 9.68E 09 7.00E 09 5.11E 09 2.69E 09 1.94E 09 1.94E 09 1.94E 09 1.94E 09 1.94E 09 2.69E 08 3.67E 08 3.92E 08 3.88E 08	*E1 2.76F 12 7.97F 11 3.13E 11 1.62F 11 7.16F 10 5.10F 10 2.64F 10 1.38E 10 9.97E 09 7.21F 09 5.23E 09 3.79E 09 1.99E 09 1.99E 09 1.45F 09 7.65E 09 5.58E 08	1.97E 12 4.84E 11 1.51E 11 5.85E 10 3.19E 10 2.06E 10 1.44E 10 7.34E 09 3.80E 09 2.76E 09 3.80E 09 1.98E 09 1.94E 09 1.04E 09 1.04E 09 1.04E 09 2.76E 09 2.76E 09 2.76E 09 2.76E 09 2.76E 09 2.76E 09 3.80E 09 2.76E 09 3.80E 08 3.80E		E1-E2  1.65E 12 4.08E 11 1.28E 11 4.95E 10 2.70E 10 1.76E 10 1.23E 10 8.79E 09 6.31E 09 4.55E 09 3.27E 09 2.38E 09 1.71E 09 1.24E 09 8.95E 08 6.55E 08 4.70E 08 3.41E 08 2.50E 08 1.71E 08
5.25 5.50 5.75 6.00 6.25 6.50 6	5.25 5.75 5.00 5.25 5.50 5.75	2.69E 09 1.9F 09 1.41E 09 1.02E 09 7.36E 08 5.32E 08 3.84E 08 2.77E 08 2.01E 08	7.49E 08 5.38E 08 2.81E 08 2.05E 08 1.47E 08 1.07E 07 2.01E 08	1.C7E 09 7.77E 08 5.69E 08 4.16E 08 3.C5E 38 2.23E 08 1.64E 08 1.20E 08 8.83E C7	2.88E 08 2.09E 08 1.52E 08 1.11E 08 8.19E 07 5.96E 07 4.37E 07 8.83E 07	5.58E C8 4.06E C8 2.96E C8 2.17E C8 1.59E C8 1.16E C8 6.19E C7 4.54E C7	1.52E 78 1.10E 08 7.99F 07 5.80E 07 4.28E 07 3.11E 07 2.28E 07 1.65E 07 4.54E 07	4.82E 08 3.50E 08 2.56E 08 1.87E 08 9.96E 07 7.28E 07 5.32E 07 3.90E 07	1.47E 08 9.47E 07 6.90E 07 5.01E 07 3.69E 07 1.96E 07 1.42E 07 3.90E 07

ORBIT ALTITUDE .. 2500 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL. I.MINUIL

ENER MEV		ORBITA O C		ORBITA 30	L FLUX DEG		L FLUX DEG	ORBITA 90 i	
£1	E2	*£1	E1-E2	*E1	E 1-E 2	*F1	E1-E2	*E1	E1-E2
0.	0.25	9.80E 12	7.08E 12	5.26E 12	4.02E 12	2.79€ 12	2.116 12	2.35E 12	1.77E 1
0.25	0.50	2.71E 12	1.81E 12	1.24E 12	8.68E 11	6.828 11	4.67E 11	5.73E 11	3.93E
0.50	0.75	9.00E 11	5.16E 11	3.68E 11	2.18E 11	2.15€ 11	1.24E 11	1.80E 11	1.04F
0.75	1.00	3.84E 11	1.58E 11	1.508 11	6.19E 10	9.125 10	3.82E 10	7.56E 10	3.15E 1
1.00	1.25	2.26F 11	7.18E 10	8.80E 10	2.718 10	5.30€ 10	1.72E 10	4.41E 10	1.42E
1.25	1.50	1.54E 11	4.35E 10	6.08E 10	1.67E 10	3.58E 10	1.04E 10	2.99E 10	8.59E (
1.50	1.75	1.116 11	3.02E 10	4.42E 10	1.17E 10	2.54E 10	7.11E 09	2.13E 10	5.89E (
1.75	2.00	8.04E 10	2.18E 10	3 • 24 € 10	8.55E 09	1.83E 10	5.03E 09	1.54E 10	4.20E
2.00	2.25	5.86E 10	1.58E 10	2.39E 10	6.27E 09	1.33E 10	3.60E 09	1.12E 10	3.02E
2.25	2.50	4.28E 10	1.15E 10	1.76E 10	4.60E 09	9.66E C9	2.60E 09	8.19E 09	2.19E (
2.50	2.75	3.13E 10	8.37E 09	1.30E 10	3.38E 09	7.06E 39	1.88E 09	6.00E 09	1.59E
2.75	3.00	2.29E 10	6.22E 09	9.62E 09	2.51E 09	5.18E 09	1.38E 09	4.41E 09	1.17E
3.00	3.25	1.67E 10	4.44E 09	7.11E 09	1.83E 09	3.80E C9	9.97€ 08	3.23E 09	8.47E
3.25	3.50	1.22E 10	3.29E 09	5.28E 09	1.37E 09	2.80E C9	7.39E 08	2.39E 09	6.29E
3.50	3.75	8.95E 09	2.38E 09	3.91E 09	1.00E 09	2.068 09	5.37E 08	1.76E 09	4.57E
3.75	4.00	6.58E 09	1.78E Q9	2.91E 09	7.54E 08	1.52E C9	4.01E 08	1.30E 09	3.43E (
4.00	4.25	4.80E 09	1.28E 09	2.15E 09	5.47E 08	1.12E 09	2.89E 08	9.58E 08	2.47E
4.25	4.50	3.52E 09	9.34E 08	1.61E 09	4.08E 08	8.33E C8	2.15E 08	7.11E 08	1.83E
4.50	4.75	2.58E 09	6.96E 08	1.20E 09	3.07E 08	6.18E C8	1.61E 08	5.28E 08	1.37E
4.75	5.00	1.89E 09	4.95E 08	8.91E Q8	2.23E 08	4.58E 08	1.16E 08	3.91E 08	9.92E
5.00	5.25	1.39E 09	3.71E 08	6.67E 08	1.69E 08	3.41E 08	8.75E 07	2.91E 08	7.47E
5.25	5.50	1.02E 09	2.68E 08	4.99E 08	1.25E 08	2.54E 08	6.42E 07	2.17E 08	5.48E
5.50	5.75	7.51E 08	1.97E 08	3.74E 08	9.31E 07	1.90E C8	4.78E 07	1.62E 08	4.08E
5.75	6.00	5.53€ 08	1.44E 08	2.81E 08	6.94E 07	1.42E C8	3.55E 07	1.21E 08	3.03E
6.00	6.25	4.09€ 08	1.08E 08	2.12E 08	5.27E 07	1.06E 08	2.68E 07	9.07E 07	2.29E
6.25	6.50	3.01E 08	7.91E G7	1.59E 08	3.92E 07	7.96€ C7	1.99E 07	6.78E 07	1.70E
6.50	6.75	2.21E 08	5.86E 07	1.20E 08	2.96E 07	5.98E 07	1.49E 07	5.08E 07	1.27E
6.75	7.00	1.63E 08	4.26E 07	9.03E 07	2.2UE 07	4.48E 07	1.11E 07	3.81E 07	9.42E
7.00		1.20E 08	1.20E 08	6.83E 07	6.83E 07	3.38E C7	3.380 07	2.87E 07	2.87E

#### ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE .. 2750 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1.MINUTES

ENE+ ME\		ATIBRO O C	L FLUX EG	ORBITA 30	DEG	ORBITA 60		CRBITA 90 (	DEG
E 1	E 2	*£1					E1-E2		
0.	0.25	1.09E 13	8.55E 12	5.41E 12	4.40E 12	2.99E 12	2.42F 12	2.53E 12	2.04E 12
0.25	0.50	2.37E 12	1.78E 12	1.02E 12	7.80E 11	5.79E 11	4.32E 11	4.85E 11	3.64E 11
0.50	0.75	5.88E 11	3.88E 11	2.35E 11	1.54E 11	1.47E 11	9.16E 10	1.216 11	7.60E 10
0.75	1.00	2.00E 11	8.96E 10	8.10E 10	3.44E 10	5.58E 10	2.39E 10	4.45E 1C	1.91E 10
1.00	1.25	1.105 11	3.01E 10	4.66E 10	1.26E 10	3.18E 10	9.84E 09	2.54E 10	7.64E 09
1.25	1.50	8-02E 10	1.95E 10	3.39E 10	8.31E G9	2.20E 10	6.15E 09	1.78F 10	4.82E 09
1.50	1.75	6.05E 10	1.48E 10	2.56E 10	6.20E 09	1.59E 10	4.27F 09	1.30E 10	3.40E 09
1.75	2.00	4.57E 10	1.12E 10	1.94E 10	4.69E C9	1.16E 10	3.05E 09	9.56E 09	2.46E 09
2.00	2.25	3.45E 10	8.45E 09	1.47E 10	3.54E 09	8.54E C9	2.205 09	7.10E 09	1.79E 0
2.25	2.50	2.618 10	6.38E 09	1.12F 10	2.68E 09	6.34E 09	1.61E 09	5.31E 09	1.33E 09
2.50	2.75	1.975 10	4.82E 09	8.51E C9	2.03E 09	4.73E C9	1.18E 09	3.98E 09	9.84E 0
2.75	3.00	1.49E 10	3.64E 09	6.47E C9	1.53E 09	3.55E C9	8.71E 08	3.00E 09	7.29E 0
3.00	3.25	1.13E 10	2.75E 09	4.95F C9	1.17E 09	2.68E C9	6.56E 08	2.27E 09	5.52E 08
3.25	3.50	8.52E 09	2.07E 09	3.77E C9	8.94E 08	2.02E 09	4.93E 08	1.72E 09	4.16E 0
3.50	3.75	6.44E 09	1.57E 09	2.88E 09	6.80E 08	1.53E C9	3.70E 08	1.30E 09	3.14E 0
3.75	4.00	4.87E 09	1.19E 09	2.20E 09	5.20E 08	1.16E C9	2.80E 08	9.89E 08	2.38E 0
4.00	4.25	3.680 09	8.97E 08	1.68F C9	3.85E C8	8.79E C8	2.06E 08	7.51E 08	1.75E 08
4.25	4.50	2.79E 09	6.78E 08	1.29E 09	3.02E 08	6.73E C8	1.60F 08	5.76E 08	1.36E 08
4.50	4.75	2.11E 09	5.13E 08	9.92E C8	2.31E 08	5.13E C8	1.22F 08	4.39E 08	1.04E C
4.75	5.00	1.59E 09	3.88E 08	7.61E C8	1.76E 08	3.91E C8	9.21F 07	3.35E 08	7.87E C
5.00	5.25	1.21F 09	2.93E 08	5.85E 08	1.35E 08	2.99E F8	7.03E 07	2.57E 08	6.01E 0
5.25	5.50	9.14E 08	2.22E 08	4.50E 08	1.03E 08	2.29E C8	5.35E 07	1.97E 08	4.59E 0
5.50	5.75	6.92E 08	1.68E 08	3.46E G8	7.948 07	1.76E C8	4.09E 07	1.51E 08	3.50E 0
5.75	6.00	5.24F 08	1.27E 08	2.67F 08	6.09E 07	1.35E C8	3.12E 07	1.16E 08	2.68E 0
6.00	6.25	3.97E 08	9.62E 07	2.06E 08	4.69E 07	1.03E 08	2.39E 07	8.89E 07	2.05E 0
6.25	6.50	3.00E 08	7.28E 07	1.59E C8	3.61E 07	7.95E C7	1.83E 07	6.84E 07	1.57E 0
6.50	6.75	2.28F 08	5.51E 07	1.23E 08	2.78E 07	6.12E C7	1.41E 07	5.27E 07	1.21E 0
6.75	7.00	1.735 08	4.18E C7	9.51F 07	2.14E 07	4.71E 07	1.08± 07	4.06E 07	9.26E 0
7.00		1.31E 08	1.31E 08	7.37E C7	7.37E 07	3.64E 07	3.64F 07	3.13E 07	3.13E 07

ORBIT ALTITUDE .. 3000 N MI

TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ENE ME	RGY V	O C		30	DEG	60	L FLUX Deg	90	
E1	E2					<b>∗</b> El	E1-E2	<b>€</b> E 1	E1-E2
0.	0.25	1.26E 13	1.06E 13	5.15E 12	4.34E 12	2.82E 12		2.40E 12	
0.25	0.50	2.03E 12	1.64E 12	8.09E 11	6.53E 11	4.74F 11		3.91E 11	3.08E 11
0.50	0.75	3.81€ 11	2.61E 11	1.57E 11	1.C7E 11	1.09E 11		8.36E 10	5.44E 10
0.75	1.00	1.206 11		4.94E 10	1-99E 10	4.05E 10		2.92E 1C	1.21E 10
1.00	1.25	7.33E 10		2.95E 10	7.21E 09	2.34E 10		1.71E 10	4.86E 09
1.25	1.50	5.58E 10		2.23E 10	5.06E 09	1.62E 10		1.23E 10	3.19E 09
1.50	1.75	4.32€ 10	9.76E 09	1.72E 10	3.90E 09	1.16E 10		9.08E 09	2.29E 09
1.75	2.00	3.34F 10	7.55E 09	1.33E 10	3.02E 09	8.46E 09		6.79E 09	1.68E 09
2.00	2.25	2.58E 10	5.83E 09	1.03E 10	2.33E 09	6.25E C9	1.57E 09	5.11E C9	1.23E 09
2.25	2.50	2.00E 10	4.51E 09	7.97E 09	1.79E 09	4.68E C9	1.15E 09	3.88E 09	9.20E 08
2.50	2.75	1.55E 10	3.49E 09	6.19E 09	1.40E 09	3.52E 09	8.52E 08	2.96E 09	6.95E 08
2.75	3.00	1.20E 10	2.70E 09	4.79E 09	1.03E 09	2.67E C9	6.19E 08	2.27E 09	5.12E 08
3.00	3.25	9.31E 09	2.07E 09	3.76E 09	8.39E 08	2.05E 09	4.81E 09	1.75E 09	4.03E 08
3.25	3.50	7.22E 09	1.62E 09	2.92E 09	6.51E 08	1.57E 09	3.65E 08	1.35E 09	3.08E 08
3.50	3.75	5.60E 09	1.25E 09	2.27E 09	5.06E 08	1.21E 09	2.78E 08	1.04E 09	2.37E 08
3.75	4.00	4.35E 09	9.72E 08	1.76E C9	3.93E 08	9.31E C8	2.13E 08	8.06E 08	1.83E 08
4.00	4.25	3.37E 09	7.53E 08	1.37E 09	2.83E 08	7.18E C8	1.55E 08	6.23E 08	1.33E 08
4.25	4.50	2.62E 09	5.84E 08	1.09E 09	2.38E 08	5.63E 08	1.26E 08	4.90E 08	1.09E 08
4.50	4.75	2.04E 09	4.53E 08	8.50E C8	1.85E 08	4.37E C8	9.73E 07	3.81E 08	8.43E 07
4.75	5.00	1.58E 09	3.52E 08	6.65E 08	1.45E 08	3.40E 08	7.53E 07	2.96E 08	6.54E 07
5.00	5.25	1.23E 09	2.73E 08	5.20E 08	1-13E 08	2.64E C8	5.83F 07	2.31E 08	5.08E 07
5.25	5.50	9.58E 08	2.12E 08	4.C7E 08	8.82E 07	2.06E 08	4.53E 07	1.80E 08	3.95E 07
5.50	5.75	7.46E 08	1.65E 08	3.19E 08	6.89E 07	1.61F C8	3.52E 07	1.41E 08	3.07E 07
5.75	6.00	5.81E 08	1.28E 08	2.50E 08	5.38E 07	1.26E C8	2.74E 07	1.10E 08	2.39E 07
6.00	6.25	4.53F 08	9.98E 07	1.97E 08	4.21E 07	9.83E 07	2.13E 07	8.60E 07	1.87E 07
6.25	6.50	3.53E 08	7.76E 07	1.54E G8	3.30E 07	7.69E C7	1.67E 07	6.74E 07	1.46E 07
6.50	6.75	2.75E 08		1.21E 08	2.598 07	6.03E C7	1.30E 07	5.28E 07	1.14E 07
6.75	7.00	2.15E 08		9.54E C7	2.03E 07	4.73F 07	1.02F 07	4.14E 07	8.90E 06
7.00		1.68F 08		7.52E G7	7.52E 07	3.71E 07	3.71E 07	3.25E 07	3.25E 07

#### ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE .. 3500 N MI

TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ENE:		ATIBAU O C	L FLUX EG	ATTBRO 1 CE		ORBITAL 60 E		CRBITAL 90 (	
61	£2	*t1	F1-E2	*E1	E1-E2	#£1	E1-E2	*E1	E1-E2
0.	0.25	7.175 12	6.12E 12	3.65E 12	3.218 12	2.04E 12	1.758 12	1.66E 12	1.44E 12
0.25	0.50	1.05F 12	8.73E 11	4.42E 11	3.71E 11	2.91E 11	2.23E 11	2.21E 11	1.76E 11
0.50	0.75	1.735 11	1.24E 11,	7.11E 10	5.01E 1C	6.75E 10	4.05E 10	4.52E 10	2.85E 10
0.75	1.00	4.945 10	1.94E 10	2.10E 10	8.05E 09	2.70E 10	1.16F 10	1.67E 10	6.91E 09
1.00	1.25	3.00F 10	6.47E C9	1.29E 10	2.94E 09	1.54E 10	5.36E 09	9.78E 09	3.06E 09
1.25	1.50	2.35E 10	4.70E 09	9.99€ €9	2.14E 09	9.99E C9	3.20E 09	6.72E 09	1.92E 09
1.50	1.75	1.88E 10	3.74E 09	7.85E 09	1.65E 09	6.79E C9	2.02E 09	4.81E 09	1.28E 09
1.75	2.00	1.51E 10	3.07E C9	6.20E C9	1.34E 09	4.78E C9	1.35E 09	3.52E 09	9.10E 08
2.00	2.25	1.20F 10	2.42E 09	4.86E C9	1.03E 09	3.43E C9	9.00E 08	2.61E 09	6.37E 08
2.25	2.50	9.628 09	1.87E C9	3.83E 09	7.78E 08	2.53E C9	6.23E 08	1.97E 09	4.55E 08
2.50	2.75	7.75E 69	1.58E C9	3.05E 09	6.53E 08	1.91E C9	4.63E 08	1.52E 09	3.52E 08
2.75	3.00	6.17F 09	1.02E C9	2.4CE 69	3.95E 08	1.44E C9	2.83E 08	1.17E 09	2.17E 08
3.00	3.25	5.15F 09	1.02E 09	2.C1E 09	4.14E 08	1.16E 09	2.59€ 08	9.51E 08	2.06E 08
3.25	3.50	4.13E 09	8.25E 08	1.59E 09	3.31E 08	9.01E 08	1.99E 08	7.45E 08	1.60E 08
3.50	3.75	3.30E 09	6.65E 08	1.26E C9	2.64E 08	7. C2E C8	1.53E 08	5.84E 08	1.25E 08
3.75	4.00	2.64E 09	5.35E 08	9.98E 08	2.11E 08	5.49E 08	1.20F 08	4.59E 08	9.86E 07
4.00	4.25	2.10F 09	3.15E 08	7.87E 08	1.10E 08	4.29E CB	6.498 07	3.60E 08	5.36E 07
4.25	4.50	1.79E 09	3.47E 08	6.78E C8	1.35E 08	3.64E C8	7.39E 07	3.07E 08	6.16E 07
4.50	4.75	1.44E 09	2.79E C8	5.43E 08	1.08E 08	2.91E C8	5.84E 07	2.45E 08	4.89E 07
4.75	5.00	1.16E C9	2.25E 08	4.36E 08	8.63E 97	2.32E C8	4.65E 07	1.96E 08	3.91E 07
5.00	5.25	9.36E U8	1.81E 08	3.49E 08	6.90E 07	1.86E C8	3.69E 07	1.57E 08	3.11E 07
5.25	5.50	7.54E 08	1.46E 08	2.80E 08	5.55E 07	1.49E C8	2.96E 07	1.26E 08	2.50E 07
5.50	5.75	6.085 08	1.18E 08	2.25E 08	4.44E 07	1.19E C8	2.36E 07	1.01E 08	1.99E 07
5.75	6.00	4.90E 08	9.48E 07	1.81E C8	3.55E 07	9.56E 07	1.88E 07	8.10F 07	1.59E 07
6.00	6.25	3.96E 08	7.64E C7	1.45E 08	2.85E 07	7.68E 07	1.51E 07	6.51E 07	1.28E 07
6.25	6.50	3.19E 08	6.17E 07	1.17E 08	2.29E 07	6.17E C7	1.21E 07	5.23E 07	1.03E 07
6.50	6.75	2.57E 08	5.00E 07	9.37E 07	1.85E 07	4.96E C7	9.78E 06	4.20E 07	8.28E 06
6.75	7.00	2.075 08	4.00E 07	7.52F 07	1.47E 07	3.98E 07	7.78E 06	3.37E 07	6.59E C6
7.00	1.00	1.67E 08	1.67E 08	6.04E 07	6.04E 07	3.20E 07	3.20E 07	2.72E 07	2.72E 07
7.50				O O TE O I	O.04C 91	30 EVE 01	3 T E V E 3 1	0.	

ORBIT ALTITUDE .. 4500 N MI

TOTAL TIME.. 48.HOURS

TIME INTERVAL.. 2.MINUTES

ENERGY MEV	ORBITA O D	L FLUX EG	ORBITA 30	L FLUX DEG	ORBITAL 60 C		ORBITAL 90 (	
E1 F2	<b>+</b> E1	E1-E2	*E1	E1-E2	*E1	E1-E2	*E1	E1-E2
0. C.25 0.25 0.50 0.50 0.75 0.75 1.00 1.00 1.25 1.25 1.50 1.75 2.00 2.00 2.25 2.25 2.50 2.50 2.75 2.75 3.00 3.00 3.25	2.16E 11 3.65E 10 1.34E 10 5.8.64E 09 5.90E 09 4.19E 09 5.12E 09 1.50E 09 1.03E 09 7.39F 08 5.33E 08	4.66F 12 1.70E 11 2.31F 10 4.75E 09 2.75F 09 1.70E 09 1.19F 09 8.98E 08 6.22F 08 4.77E 08 2.90E 08 1.48E 08	2.62E 12 9.64E 10 2.12E 10 9.62E 09 6.06E 09 3.98E 09 2.69E 09 1.83E 09 8.88E 08 5.63E 08 3.89E 08 2.70E 08	2.52E 12 7.51E 10 1.16E 10 3.56E 09 2.09E 09 1.29E 09 8.60E 08 5.98E 09 3.03F 08 2.76E 08 1.74E 08 1.19E 08 8.17E 07	1.55E 12 1.25E 11 4.53E 10 2.24E 10 1.23E 10 7.04E 09 4.13E 09 4.13E 09 1.52E 09 9.45E 08 3.78E 08 2.45E 08	1.42E 12 7.99E 10 2.28E 10 1.01E 10 5.24E 09 2.91E 09 1.64E 09 9.75E 08 5.70E 08 3.57C 08 2.10C 08 1.32E 08 8.41E 07	1.24E 12 7.78E 10 2.55E 10 1.27E 10 7.22E 09 4.30E 09 2.63E 09 1.64E 09 1.63E 09 6.56E 08 4.17E 08 2.73E 08 1.81E 08	1.16E 12 5.24E 10 1.28E 10 5.44E 09 2.92E 09 1.67E 09 9.95E 08 6.12E 08 3.70E 08 2.39E 08 1.44E 08 9.24E 07 6.01E 07
3.25 3.50 3.50 3.75 4.00 4.25 4.25 4.50 4.50 4.75 5.00 5.25 5.25 5.50 5.50 5.75 6.00 6.25	2.78E 08 2.01E 08 1.45E 08 1.05E 08 7.61E 07 5.52E 07 4.00E 07 2.90E 07 2.11E 07 1.53F 07 1.11F 07	1.08E 08 7.70E 07 5.54E 07 4.00E 07 2.90E 07 1.52E 07 1.10E 07 7.95E 06 4.18E 06 4.18E 06 2.22E 06	1.88E 08 1.31E 08 9.24E 07 6.51E 07 4.61E 07 7.213E 07 1.67E 07 1.20E 07 8.61E 06 6.21E 06	5.66E 07 3.91E 07 2.72E 07 1.90E 07 1.34E 07 9.39E 06 6.65E 06 4.72E 06 3.36E 06 2.40E 06 1.72E 06	1.61E C8 1.07F C8 7.17E 07 4.84E C7 3.30E 07 2.26F C7 1.56E C7 1.08E 07 7.55E C6 5.29E C6 3.73E 06 2.64E 06	5.43E 07 3.53E 07 1.54E 07 1.54E 07 1.04E 07 6.99E 06 4.77E 06 3.27E 06 2.25E 06 1.56E 06 1.50E 05	1.71E 08 8.13E 07 5.52E 07 3.77E 07 2.59E 07 1.79E 07 1.25E 07 8.69E 06 6.10E 06 4.29E 06 3.04E 06 2.15E 06	3.96E 07 2.61E 07 1.75E 07 1.18E 07 8.02E 06 5.46E 06 2.60E 06 1.80E 06 1.26E 06 8.82E 05 6.17E 05
6.50 6.79 6.75 7.00 7.00	5 5.89E 06	1.60E 06 1.17E 06 3.12E 06	3.26E 06 2.37E 06 1.73E 06 1.26E 06	8.93E 05 6.43E 05 4.66E 05 1.26E 06	1.88E C6 1.34E C6 9.59E C5 6.89E C5	5.40E 05 3.81E 05 2.70E 05 6.89E 05	1.10E 06 7.85E 05 5.64E 05	3.11E 05 2.21E 05 5.64E 05

#### ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE .. 4000 N MI

TOTAL TIME.. 48.HOURS

TIME INTERVAL.. 2.MINUTES

ENER MEV		ORBITAI O C	_ FLUX EG	ORBITA 30	L FLUX DEG	ORBITA 60 I	L FLUX DEG	ORBITA 90	
E 1	E 2	<b>+</b> £1	E1-E2	<b>+</b> E1	E1-E2	<b>*</b> F1	E1-E2	*E1	£1 <b>−£2</b>
0.	0.25	5.778 12	5.18E 12	2.99E 12	2.76E 12	1.74E 12	1.54E 12	1.49E 12	1.26E 1
0.25	C.50	5.90E 11	5.11E 11	2.30E 11	1.958 11	1.95E 11	1.43E 11	1.37E 11	1.06E 1
0.50	0.75	7.97E 10	5.52E 10	3.51F 10	2.31E 10	5.26E 10	2.87E 10	3.10E 10	1.76E 1
0.75	1.00	2.45E 10	8.29E 09	1.20E 10	4.24E 09	2.39E 10	1.05E 10	1.34E 10	5.55E 0
1.00	1.25	1.625 10	3.92E 09	7.74E C9	2.11E 99	1.348 10	5.31E 09	7.89E 09	2.85E 0
1.25	1.50	1.23E 10	2.82E 09	5.63E 09	1.45F 19	8.11E C9	3.04E 09	5.04E 09	1.71E 0
1.50	1.75	9.45E 09	2.14E 09	4.18E 09	1.05E 09	5.07E C9	1.798 09	3.33E 09	1.07E 0
1.75	2.50	7.31E 09	1.70E 09	3.13E 09	8.05E 08	3.28E C9	1.11E 09	2.26E 09	7.07E 0
2.00	2.25	5.61F 09	1.29E 09	2.33E 09	5.85E 08	2.16E C9	6.92E 08	1.55E 09	4.60E 0
2.25	2.50	4.31E 09	9.79E 08	1.74E- 09	4.26E 08	1.47E C9	4.51E 08	1.09E 09	3.12E 0
2.50	2.75	3.34E 09	7.73E 08	1.32F 09	3.26E 08	1.02E 09	3.01F 98	7.81E 08	2.18E 0
2.75	3.00	2.565 09	5.04E 08	9.89E 08	1.96E 08	7.19F C8	1.79E 08	5.63E 08	1.31E 0
3.00	3.25	2.06F 09	4.66E 08	7.94E U8	1.885 08	5.40E 08	1.45E C8	4.33E 08	1-12E 0
3.25	3.50	1.59F 09	3.63E G8	6.06E 08	1.44E 08	3.94E 08	1.04E 08	3.21E 08	8.19E 0
3.50	3.75	1.23E 09	2.82E 08	4.615 08	1.10E 08	2.90E C8	7.53E 07	2.39E G8	6.04E 0
3.75	4.00	9.47E 08	2.19E 08	3.51E 08	8.46E 07	2.15E C8	5.53E 07	1.79E 08	4.50E 0
4.00	4.25	7.285 08	1.25E 08	2.67E 08	4.10E 07	1.60E 08	2.79E 07	1.34E 08	2.25€ C
4.25	4.50	6.03E 08	1.33E 08	2.26E U8	5.04E 07	1.32E C8	3.09E 07	1.11E 08	2.57E 0
4.50	4.75	4.70F 08	1.03E 08	1.75F 08	3.88E 07	1.01E C8	2.33E 07	8.56E C7	1.95E 0
4.75	5.00	3.67E 08	8.06E 07	1.36E 08	3.02E 07	7.78E C7	1.77F 07	6.62E 07	1.49E 0
5.00	5.25	2.86E 08	6.27E 07	1.66E 08	2.34E 07	6.00E 07	1.35E 07	5.12E 07	1.15E 0
5.25	5.50	2.23E 08	4.91E 67	8.29E G7	1.82E 07	4.65E C7	1.34E 07	3.98E 07	8.87E 0
5.50	5.75	1.74E 08	3.81E 07	6.47E 07	1.41E 07	3.61E 07	8.01E 96	3.09E 07	6.83E 0
5.75	6.00	1.36E 08	2.97E 07	5.05E C7	1.10E 07	2.80E C7	6.17E 06	2.41E 07	5.27E 0
6.00	6.25	1.06E 08	2.32E 07	3.96F 07	8.58E 76	2.19E 07	4.80E 06	1.88E 07	4.11E 0
6.25	6.50	8.32E 07	1.81E 07	3.10E C7	6.71E 06	1.71E 07	3.73E 06	1.47E 07	3.20E 0
6.50	6.75	6.50E 07	1.43E 07	2.43E 07	5.29E 06	1.33E C7	2.93E 06	1.15E 07	2.52E 0
6.75	7.00	5.08E 07	1.10E 07	1.90E C7	4.08E 06	1.04E 07	2.25E 06	8.96E 06	1.93E 0

ORBIT ALTITUDE .. 5000 N MI

TOTAL TIME.. 48.HOURS

TIME INTERVAL.. 2. MINUTES

ENE:		0 C	L FLUX DEG	30 (	DEG	60 (		ORBITAL 90 (	
E 1	€2		E1-E2						E1-E2
0.	0.25	3.74E 12	3.67E 12	2.03E 12	1.985 12	1.23E 12	1.13E 12	9.66E 11	9.08E 1
0 - 25	9.50	7.39E 10	5.70E 10	5.42E 10	3.53E 10	1.02E 11	5.86E 10	5.85E 10	3.43E 1
0.50	0.75	1.68E 10	9.14E 09	1.89E 10	8.455 09	4.33E 10	2.12E 10	2.42E 10	1.14E 1
0.75	1.00	7.71E 09	3.21E 09	1.05€ 10	4.055 09	2.21E 10	1.02E 10	1.28E 10	5.65E 0
1.00	1.25	4.49E 09	1.72E 09	6.43E C9	2.37E 09	1.19E 10	5.22E 09	7.13E 09	3.00E 0
1.25	1.50	2.77E 09	9.89E 08	4.06E C9	1.47E 09	6.63E C9	2.86E 09	4.13E 09	1.69E 0
1.50	1.75	1.78E 09	6.28E 08	2.60E C9	9.39E 08	3.77E C9	1.58E 09	2.44E 09	9.85E 0
1.75	2.00	1.16E 09	4.11E 08	1.66F G9	6.01E 08	2.19E C9	9.06E 98	1.45E 09	5.79E 0
2.00	2.25	7.45E 08	2.62E 08	1.06E C9	3.77E 08	1.29E 09	5.15E 08	8.74E 08	3.38E 0
2.25	2.50	4.83E 08	1.69E 08	6.79E C8	2.435 08	7.73E C8	3.08E 08	5.36E 08	2.08E 0
2.50	2.75	3.14E 08	1.09E 08	4.36E C8	1.55E 08	4.65E C8	1.80E 08	3.28E 08	1.24E 0
2.75	3.00	2.04E 08	7.12E 07	2.81E C8	9.97E 07	2.85E 08	1.09E 28	2.04E 08	7.65E 0
3.00	3.25	1.33E G8	4.62E 07	1.818 68	6.42E 07	1.76E C8	6.66E 07	1.27E 08	4.74E 0
3.25	3.50	8.69E 07	3.01E 07	1.17E CB	4.13E 07	1.09E C8	4.09E 07	8.C1E 07	2.95E 0
3.50	3.75	5.68E 07	1.96E 07	7.58E 07	2.67E 07	6.82E C7	2.53E 07	5.06E 07	1.85E C
3.75	4.00	3.71E 07	1.28E 07	4.91E C7	1.73E 07	4.29E 07	1.58E 07	3.21E 07	1.17E 0
4.00	4.25	2.43E 07	8.35E 06	3.19E 07	1.12E 07	2.71€ (7	9.9CE 06	2.04E 07	7.37E 0
4.25	4.50	1.59E 07	5.50E 06	2.07E C7	7.25E 06	1.72E C7	6.26E 06	1.31E 07	4.70E C
4.50	4.75	1.04E 07	3.58E 06	1.34E C7	4.69E 06	1.10E C7	3.95E 06	8.37E 06	2.99E 0
4.75	5.00	6.86E 06	2.35E 06	8.75E C6	3.04E 06	7.C2E C6	2.51E 06	5.38E 06	1.91E 0
5.00	5.25	4.51F 06	1.54E 06	5.71E C6	1.99E 06	4.51E C6	1.61E 06	3.47E 06	1.23E C
5.25	5.50	2.97E 06	1.01E 06	3.72E C6	1.29E 06	2.90E C6	1.03E 06	2.24E 06	7.90E 0
5.50	5.75	1.96E 06	6.68E 05	2.43E 06	8.42E 05	1.87E C6	6.61E 05	1.45E 06	5.10E C
5.75	6.00	1.29E 06	4.38E 05	1.59E C6	5.50E 05	1.21E 06	4.27E 05	9.38E 05	3.30E 0
6.00	6.25	8.52E 05	2.87E 05	1.C4E 06	3.57E 05	7.80E C5	2.74E 05	6.08E 05	2.12E C
6.25	6.50	5.64E 05	1.91E 05	6.79E 05	2.34E 05	5.07F C5	1.77E 05	3.96E 05	1.38E C
6.50	6.75	3.73E 05	1.26E 05	4.45E G5	1.53E 05	3.29E C5	1.15E 05	2.58E 05	8.99E (
6.75	7.00	2.47E 05	8.33E 04	2.92F 05	1.COF 05	2.14E 05	7.45E 04	1.68E 05	5.82E (
7.00		1.64E 05	1.64E 05	1.91E C5	1.91E 05	1.40E C5	1.4GE 05	1.1CE 05	1.10E C

#### ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE .. 5500 N MI

TOTAL TIME.. 48.HOURS

TIME INTERVAL.. 2.MINUTES

ENER		ORBITA O D		ORBITAL 30 U		DRBITA 00-		CRBITAL 90 i	
£ 1	F2	<b>+</b> 61	E1-E2	*E1	€1-€2	<b>+</b> £]	E1−F2	*£1	E1-E2
0.	0.25	2.62F 12	2.59E 12	1.65E 12	1.60E 12	1.016 12	9.12E 11	7.83E 11	7.28E
0.25	0.50	2.73F 10	1.93E 10	5.27E 10	2.92F 10	9.48E 10	5.24E 10	5.53E 10	3.03E
0.50	0.75	7.95E 09	3.94E 09	2.34E 10	9.968 09	4.25E 10	2.06F 10	2.50E 10	1.16E
0.75	1.00	4.02E 09	1.72E 09	1.35E 10	5.48E 09	2.198 10	1.02F 10	1.34E 10	5.97E (
1.00	1.25	2.30E 09	9.39E 08	7.98E 69	3.09E 09	1.17E 10	5.18E 09	7.47E 09	3.16E
1.25	1.50	1.36E Q9	5.33E 08	4.89E C9	1.89E 09	6.55E C9	2.845 09	4.31E 09	1.79E
1.50	1.75	8.29F 08	3.23E 08	3.01E C9	1.17E 09	3.71E C9	1.56E 09	2.52E 09	1.03E
1.75	2.00	5.06E 08	1.95E 08	1.84E 09	7.03E 08	2.15E C9	8.92F 08	1.48E 09	6.00E
2.00	2.25	3.11F 08	1.24E 08	1.13E 69	4.24E 08	1.26E C9	5.06E 08	8.84E 08	3.49E
2.25	2.50	1.87E 08	6.97E 07	7.09E 08	2.69E 08	7.52E CA	3.02E 08	5.36E 08	2.11F
2.50	2.75	1.18F 08	4.61E 07	4.40E 68	1.64F C8	4.50F C8	1.76E 08	3.24E 08	1.25E
2.75	3.00	7.16F 07	2.80E G7	2.75E 08	1.03E 08	2.74F (8	1.06F 08	1.99E 08	7.62E
3.00	3.25	4.36F 07	1.71E 07	1.73E G8	6.42E 07	1.68E C8	6.44E 07	1.23E 08	4.67E
3.25	3.50	2.65E C7	1.C4E 07	1.08F 08	4.01E 07	1.C4E C8	3.93E 07	7.65E 07	2.87E
3.50	3.75	1.62£ 07	6.32F 06	6.84E C7	2.52E 07	6.44F C7	2.41E 07	4.77E 07	1.78E
3.75	4.00	9.84E 06	3.84E Q6	4.32F C7	1.59F 07	4.03F 07	1.50E 07	3.00E 07	1.11F
4.00	4.25	5.99[ 06	2.34E U6	2.73E 07	9.98E 06	2.53E 07	9.34E 06	1.89E 07	6.94E
4.25	4.50	3.65E 06	1.43E 06	1.73E C7	6.33E 06	1.59E C7	5.86E 06	1.19E C7	4.37E
4.50	4.75	2.22E 06	8.64E 05	1.10E 07	4.00E 06	1.01E C7	3.68E 06	7.55E 06	2.75E
4.75	5.00	1.36E 06	5.32E 05	7.00E 06	2.54E 06	6.39E C6	2.32E 06	4.80E 06	1.74E
5.00	5.25	8.25E 05	3.22E 05	4.46F C6	1.62E 06	4.C7E C6	1.48E 06	3.06E 06	1.11E
5.25	5.50	5.03E 05	1.96E 05	2.85E 66	1.03E 06	2.59E (6	9.34F 05	1.95E C6	7.03E
5.50	5.75	3.07E 05	1.19E 05	1.82E C6	6.55E 05	1.66E C6	5.95E 05	1.25E 06	4.48E
5.75	6.00	1.87F 05	7.32E 04	1.16E 06	4.20E 05	1.06E 06	3.82E 05	8.02E 05	2.88E
6.00	6.25	1.14E 05	4.44E U4	7.44E 05	2.67E 05	6.81E C5	2.43E 05	5.14E 05	1.83E
6.25	6.50	6.95E 04	2.71E 04	4.77E 05	1.71E C5	4.38E C5	1.56E 05	3.31E 05	1.18E
6.50	6.75	4.24F 04	1.65E 04	3.06E 05	1.10E 05	2.82E C5	1.00E 05	2.13E 05	7.58E
6.75	7.00	2.59E 04	1.01F 04	1.96E 05	7.01E 04	1.82E C5	6.43E 04	1.37E 05	4.86E
7.00		1.58F 04	1.580 04	1.26E 05	1.26E 05	1.17E C5	1.17E 05	8.86E 04	8.86E

ORBIT ALTITUDE..6000 N MI TOTAL TIME.. 48.HOURS TIME INTERVAL.. 2.MINUTES

ENE? ME\		ORBITA O D		ORBITAL 30 L		ORBITA 60		ORBITA 90 i	
El	E2	#Ĕl	E1-E2	<b>*</b> E1	E1-E2	*E1	E1-E2	*E1	E1-E2
0.	0.25	1.96E 12	1.95E 12	1.37E 12	1.308 12	8.45F 11	7.49E 11	6.58E 11	6.00E 11
0.25	0.50	1.17€ 10	7.48E 09	6.64E 10	3.51E 10	9.59E 10	5.22E 10	5.74E 10	3.08E 10
0.50	0.75	4.24E 09	1.99E 09	3.13E 10	1.33€ 10	4.36F 10	2.11E 10	2.66E 10	1.23E 10
0.75	1.00	2.24F 09	9.40€ 08	1.79E 10	7.39E 09	2.25E 10	1.05€ 10	1.43E 10	6.35E 09
1.00	1.25	1.30E 09	5.28E 08	1.06F 10	4.165 09	1.21E 10	5.33E C9	7.97E 09	3.37E 09
1.25	1.50	7.76E 08	3.20E 08	6.39E 09	2.51F 09	6.74E 09	2.93E 09	4.60E 09	1.91E 09
1.50	1.75	4.57E Q8	1.87E 08	3.88E C9	1.52E 09	3.82E C9	1.61E 09	2.69E 09	1.10E 09
1.75	2.00	2.70F 08	1.08E 08	2.36E 09	9.14E 08	2.21E C9	9.17F 08	1.59E 09	6.41E 08
2.00	2.25	1.63E 08	6.69E 07	1.44E 09	5.51E 08	1.29E C9	5.20F 08	9.46F 08	3.72E 08
2.25	2.50	9.58E 07	3.88E C7	8.94E 08	3.43E 08	7.73E C8	3.11E 08	5.74E 08	2.26E 08
2.50	2.75	5.69E 07	2.32E U7	5.50E 08	2.07E 08	4.63E C8	1.80F 08	3.48E 08	1.34E 08
2.75	3.00	3.37E 07	1.38E 07	3.43E C8	1.29E 08	2.82E C8	1.09E 08	2.14E 08	8.17E 07
3.00	3.25	2.00E 07	8.15E 06	2.15E C8	8.01F 07	1.73E 08	6.63E 07	1.33E 08	5.01E 07
3.25	3.50	1.18E 07	4.83E 06	1.35E 08	4.998 07	1.07E C8	4.05E 07	8.25E 07	3.09E 07
3.50	3.75	7.02E 06	2.86E 06	8.50E C7	3.12E 07	6.66E C7	2.49E 07	5.16F 07	1.91E 07
3.75	4.00	4.16E 06	1.70E 06	5.38E C7	1.97E 07	4.17E C7	1.55E 07	3.25E 07	1.20E 07
4.00	4.25	2.47E 06	1.00E 06	3.41F G7	1.24F 07	2.62F 07	9.66E 06	2.05E 07	7.51E 06
4.25	4.50	1.46E 06	5.95E 05	2.17E 07	7.87E 06	1.65E 07	6.07E 96	1.30E 07	4.73E 06
4.50	4.75	8.66E 05	3.53E 05	1.38E C7	4.99E 06	1.05E C7	3.82E 06	8.22E 06	2.99E 06
4.75	5.00	5.13E 05	2.09E 05	8.82E C6	3.17E 06	6.66E 06	2.41E 06	5.24E 06	1.89E 06
5.00	5.25	3.04E 05	1.24E 05	5.65E C6	2.03E 06	4.25E C6	1.54E 06	3.35E 06	1.21E 06
5.25	5.50	1.80E 05	7.34E 04	3.62E C6	1.29E 06	2.72E C6	9.76E 05	2.14E 06	7.68E 05
5.50	5.75	1.07E C5	4.35E 04	2.32F C6	8.28E 05	1.74E C6	6.23E 05	1.37E 06	4.91E 05
5.75	6.00	6.33E 04	2.58E 04	1.49E 06	5.34E 05	1.12E C6	4.00E 05	8.81E 05	3.16E 05
6.00	6.25	3.75F 04	1.53E 04	9.59E 05	3.41E 05	7.17E C5	2.55E 05	5.66E 05	2.01F 05
6.25	6.50	2.22E C4	9.06E 03	6.19F 65	2.19E 05	4.62E C5	1.64E 05	3.65E 05	1.29E 05
6.50	6.75	1.32F 04	5.37E 03	3.99E 05	1.42E 05	2.98F 05	1.06E 05	2.35E 05	8.35E 04
6.75	7.00	7.81E 03	3.17E 03	2.58E C5	9.09E 04	1.92E C5	6.78F 04	1.52E 05	5.35E 04
7.00		4.64F 03	4.64E 03	1.67E 05	1.67E 05	1.24F C5	1.24E 05	9.81E C4	9.81E 04

#### ORBITAL INTEGRATION MAP AE2

GRBIT ALTITUDE .. 7000 N MI

TOTAL TIME.. 96.HOURS

TIME INTERVAL.. 4.MINUTES

ENE!		ORBITAL C De	FLUX G	ORBITAI 30 t	L FLUX DEG	ORBITA 60	L FLUX DFG	ORBITAI 90 (	
E 1	E2	*E1	E1-E2	*E1	E1-E2	•E1	E1-E2	+E1	E1-E2
0.	0.25	1.96E 12	1.94E 12	1.09E 12	9.76E 11	6.75E 11	5.72E 11	5.46E 11	4.70E 11
0 - 25	0.50	1.65E 10	9.01E 09	1.16E 11	5.72E 10	1.03E 11	5.55E 10	7.68E 10	4.12E 10
0.50	0.75	7.51E 09	3.31E 09	5.23E 10	2.30E 10	4.74E 10	2.26E 10	3.56E 10	1.67E 10
0.75	1.00	4.20E 09	1.73E 09	2.93E 10	1.25E 10	2.48E 10	1.14E 10	1.89E 10	8.51E 09
1.00	1.25	2.48E 09	8.63F 08	1-68E 10	6.81E 09	1.34E 10	5.83E 09	1.04E 10	4.43E 09
1.25	1.50	1.61E 09	6.75E 08	1.00E 10	4.02E 09	7.61E 09	3.25E 09	5.92E 09	2.50E 09
1.50	1.75	9.37E 08	3.72E C8	6.00E 09	2.39E 09	4.36E 09	1.81E 09	3.42E 09	1.41E 09
1.75	2.00	5.65E 08	1.98E 08	3.61E 09	1.42E 09	2.54E C9	1.04E 09	2.01E 09	8.15E 08
2.60	2.25	3.67F GB	1.54E 08	2.20E 09	8.41E 08	1.50E 09	5.98E 08	1.20E 09	4.72E 08
2.25	2.50	2.14E 08	7.96E 07	1.35E 09	5.21E 08	9.04E 08	3.59E 08	7.23E 08	2.85E 08
2.50	2.75	1.34E 08	5.27E U7	8.33E 08	3.14E 08	5.45E 08	2.11E 08	4.38E 08	1.68E G8
2.75	3.00	8.13E 07	3.21E 07	5.19E 08	1.95E 08	3.34E 08	1.28E 08	2.70E 08	1.03E 08
3.00	3.25	4.92E C7	1.96E G7	3.25E U8	1.21E 08	2.06E 08	7.83E 07	1.67E 08	6.31E 07
3.25	3.50	2.96E 07	1.17E 07	2.04E 08	7.53E 07	1.28E 08	4.81E C7	1.04E 08	3.88E 07
3.50	3.75	1.79E C7	7.08E 06	1.29E 08	4.71E 07	7.99E 07	2.97E 07	6.50E 07	2.41E 07
3.75	4.00	1.08E 07	4.28E 06	8.15E 07	2.98E 07	5.02E 07	1.86E 07	4.09E 07	1.51E Q7
4.00	4.25	6.54E C6	2.58E 06	5.17E 07	1.88E 07	3.16E 07	1.16E 07	2.58E 07	9.45E 06
4.25	4.50	3.97E C6	1.56E 06	3.30E 07	1.19E 07	2.00E 07	7.32E 06	1.64E G7	5.96E 06
4.50	4.75	2.41€ 06	9.49E 05	2.10E 07	7.58E 06	1.27E 07	4.62E 06	1.04E 07	3.77E 06
4.75	5.00	1.46E C6	5.77E C5	1.35E 07	4.82E C6	8.10E 06	2.92E 06	6.63E 06	2.39E 06
5.00	5.25	8.82E G5	3.43E 05	8.63E 06	3.10E 06	5.18E 06	1.87E 06	4.24E 06	1.53E 06
5.25	5.50	5.39E 05	2.15E 05	5.54E 06	1.98E 06	3.31E 06	1.19E 06	2.72E 06	9.73E 05
5.50	5.75	3.24E 05	1.28E 05	3.56E 06	1.27E 06	2.12E 06	7.59E 05	1.74E 06	6.22E 05
5.75	6.00	1.96E G5	7.81E C4	2.29E 06	8.18E 05	1.36E 06	4.88E 05	1.12E 06	4.00E 05
6.00	6.25	1.18E C5	4.65E 04	1.47E C6	5.23E 05	8.76E 05	3.11E 05	7.20E 05	2.56E Q5
6.25	6.50	7.16E 04	2.81E 04	9.51E 05	3.37E 05	5.64E 05	2.00E 05	4.64E 05	1.65E 05
6.50	6.75	4.35E 04	1.72E 04	6.15E 05	2.18E 05	3.64E 05	1.29€ 05	3.00E 05	1.06E 05
6.75	7.00	2.63E 04	1.02E 04	3.97E 05	1.40E 05	2.35E 05	8.30E 04	1.74E 05	6.83E 04
co		1.61E C4	1.61E 04	2.57E 05	2.57E 05	1.52E 05	1.52E 05	1.25E 05	1.25E 05

ORBIT ALTITUDE .. 8000 N MI

TOTAL TIME.. 96.HOURS TIME INTERVAL.. 4.MINUTES

ENERGY MEV		ORBITAL FLUX O DEG		ORBITAL FLUX 30 DEG		ORBITAL FLUX 60 DEG		ORBITAL FLUX 90 DEG	
E1	E2	*E1	E1-E2	<b>+</b> E1	E1-E2	<b>+</b> E1	E1-E2	<b>+</b> €1	E1-E2
0.	0.25	8.29E 11	7.94E 11	7.41E 11	5.78E 11	4.70E 11	3.55E 11	3.82E 11	2.92E 1
0.25	0.50	3.54E 10	1.72E 10	1.63E 11	8.55E 10	1.15E 11	6.18E 10	9.02E 10	4.82E 1
0.50	0.75	1.82E 10	7.38E 09	7.73E 10	3.44E 10	5.33E 10	2.51E 10	4.20E 10	1.95E 1
0.75	1.00	1.08E 10	4.11E 09	4.29E 10	1.83E 10	2.83E 10	1.27E 10	2.24E 10	1.00E 1
1.00	1.25	6.68E 09	2.22E 09	2.46E 10	1.00E 10	1.55E 10	6.64E 09	1.24E 10	5.26E 0
1.25	1.50	4.46E 09	1.65E 09	1.46E 10	5.83E 09	8.87E 09	3.73E 09	7.14E 09	2.97E 0
1.50	1.75	2.81E 09	9.78E 08	8.75E 09	3.44E 09	5.14E 09	2.10E 09	4.17E 09	1.69E 0
1.75	2.00	1.83E 09	6.47E 08	5.31E 09	2.08E 09	3.04E 09	1.23E 09	2.47E 09	9.96E D
2.00	2.25	1.18E 09	4.20E 08	3.22E 09	1.22E 09	1.81E 09	7.06E 08	1.48E 09	5.76E 0
2 • 25	2.50	7.61E 08	2.65E 08	2.00E 09	7.64E 08	1.10E 09	4.31E 08	9.01E 08	3.52E 0
2.50	2.75	4.96E 08	1.78E 08	1.23E 09	4.60E 08	6.69E 08	2.55E 08	5.50E 08	2.09E 0
2.75	3.00	3.18E 08	1.15E 08	7.75E 08	2.87E 08	4.14E 08	1.57E 08	3.41E 08	1.29E 0
3.00	3.25	2.02E 08	7.26E 07	4.88E 08	1.79E 08	2.57E 08	9.63E 07	2.12E 08	7.93E 0
3.25	3.50	1.30E 08	4.68E 07	3.08E 08	1.13E 08	1.61E 08	5.97E 07	1.33E 08	4.92E 0
3.50	3.75	8.31E 07	2.99E 07	1.96E 08	7.09E 07	1.01E 08	3.72E 07	8.34E 07	3.07E 0
3.75	4.00	5.32E 07	1.92E 07	1.25E 08	4.51E 07	6.38E 07	2.34E 07	5.28E 07	1.93E 0
4.00	4.25	3.40E 07	1.22E 07	7.97E 07	2.87E 07	4.04E 07	1.47E 07	3.35E 07	1.22E 0
4.25	4.50	2.18E 07	7.80E 06	5.10E 07	1.83E 07	2.57E 07	9.31E 06	2.13E 07	7.71E 0
4.50	4.75	1.40E 07	5.02E 06	3.28E 07	1.17E 07	1.64E 07	5.90E 06	1.36E 07	4.89E 0
4.75	5.00	8.96E 06	3.23E 06	2.11E 07	7.47E 06	1.05E 07	3.75E 06	8.69E 06	3.11E 0
5.00	5.25	5.73E 06	2.06E 06	1.36E 07	4.84E 06	6.71E 06	2.41E 06	5.58E 06	2.00E 0
5.25	5.50	3.67E 06	1.32E 06	8.76E 06	3.10E 06	4.30E 06	1.53E 06	3.58E 06	1.28E 0
5.50	5.75	2.35E 06	8.42E 05	5.66E 06	2.00E 06	2.77E 06	9.84E 05	2.30E 06	8.18E 0
5.75	6.00	1.51E 06	5.42E 05	3.66E 06	1.30E 06	1.78E 06	6.35E 05	1.49E 06	5.29E 0
6.00	6.25	9.69E 05	3.48E 05	2.37E 06	8.32E 05	1.15E 06	4.06E 05	9.57E 05	3.38E 0
6.25	6.50	6.21E 05	2.22E 05	1.53E 06	5.39E 05	7.41E 05	2.62E 05	6.18£ 05	2.18E 0
6.50	6.75	3.99E 05	1.43E 05	9.96E 05	3.50E 05	4.79E 05	1.70E 05	4.00E 05	1.41E 0
6.75	7.00	2.57E 05	9.25E 04	6.45E 05	2.26E 05	3.10E 05	1.09E 05	2.59E 05	9.10E 0
7.00		1.64E 05	1.64E 05	4.19E 05	4.19E 05	2.01E 05	2.01E 05	1.68E 05	1.68E 0

# ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE .. 9000 N MI

TOTAL TIME.. 96.HOURS

TIME INTERVAL.. 4.MINUTES

ENER		ORBITAL O DI		ORBITAI 30 I		ORBITA 60		ORBITAI 90 I	
Εl	E2	*E1	E1-E2	*E1	E1-E2	*E1	E1-E2	+£1	E1-E2
0.	0.25	2.63E 11	1.80E 11	6.49E 11	4.25E 11	3.82E 11	2.49E 11	3.09E 11	2.02E 1
0.25	0.50	8.25E 10	4.11E 10	2.24E 11	1.188 11	1.33E 11	7.13E 10	1.07E 11	5.74E 1
0.50	0.75	4.14E 10	1.58E 10	1.05E 11	4.69E 10	6.17E 10	2.87E 10	4.99E 10	2.30E 1
0.75	1.00	2.56E 10	9.01E 09	5.84E 10	2.50E 10	3.30E 10	1.47E 10	2.69E 10	1.19E I
1.00	1.25	1.66E 10	5.89E 09	3.35E 10	1.38E 10	1.83E 10	7.81E 09	1.50E 10	6.36E (
1.25	1.50	1.07E 10	3.57E 09	1.97E 10	7.83E 09	1.05E 10	4.33E 09	8.65E 09	3.55E (
1.50	1.75	7.13E 09	2.40E 09	1.19E 10	4.69E 09	6.14E 09	2.50E 09	5.10E 09	2.06E
1.75	2.00	4.73E 09	1.70E 09	7.18E 09	2.82E 09	3.65E 09	1.47E 09	3.04E 09	1.22E
2.00	2.25	3.02E 09	1.05E 09	4.35E 09	1.64E 09	2.17E 09	8.44E 08	1.82E 09	7.03E
2.25	2.50	1.97E 09	6.96E 08	2.71E 09	1.04E 09	1.33E 09	5.20E 08	1.12E 09	4.34E
2.50	2.75	1.28E 09	4.38E 08	1.67E 09	6.20E 08	8.10E 08	3.06E 08	6.81E 08	2.57E
2.75	3.00	8.40E 08	2.89E 08	1.05E 09	3.87E 08	5.04E 08	1.89E 08	4.25E 08	1.59E
3.00	3.25	5.51E 08	1.89E 08	6.65E 08	2.43E 08	3.15E 08	1.17E 08	2.66E 08	9.86E 0
3.25	3.50	3.62E 08	1.24E 08	4.21E 08	1.53E 08	1.98E 08	7.29E 07	1.67E 08	6.15E
3.50	3.75	2.38E 08	8.15E 07	2.69E 08	9.67E 07	1.25E 08	4.56E 07	1.06E 08	3.85E (
3.75	4.00	1.56E 08	5.36E 07	1.72E 08	6.17E 07	7.96E 07	2.89E 07	6.74E 07	2.44E (
4-00	4.25	1.03E 08	3.54E 07	1.10E 08	3.94E 07	5.07E 07	1.83E 07	4.30E 07	1.558 (
4.25	4.50	6.75€ 07	2.31E 07	7.07E 07	2.52E 07	3.24E 07	1.16E 07	2.75E 07	9.86E (
4.50	4.75	4.44E 07	1.52E 07	4.55E 07	1.62E 07	2.08E 07	7.42E 06	1.76E 07	6.29E
4.75	5.00	2.91E 07	9.92E 06	2.94E 07	1.04E 07	1.34E 07	4.73E 06	1.13E 07	4.02E
5.00	5.25	1.92E 07	6.61E 06	1.90E 07	6.73E 06	8.62E 06	3.07E 06	7.32E 06	2.60E
5.25	5.50	1.26E 07	4.31E 06	1.23E 07	4.32E 06	5.55E 06	1.96E 06	4.72E 06	1.67E
5.50	5.75	8.29E 06	2.84E 06	7.96E 06	2.80E 06	3.59E 06	1.27E 06	3.05E 06	1.08E
5.75	6.00	5.45E 06	1.88E 06	5.17E 06	1.82E 06	2.33E 06	8.22E 05	1.98E 06	6.99E
6.00	6.25	3.58E 06	1.22E 06	3.35E 06	1.17E 06	1.50E 06	5.28E 05	1.28E 06	4.49E
6.25	6.50	2.35E 06	8.07E 05	2.18E 06	7.61E 05	9.76E 05	3.42E 05	8.31E 05	2.91E
6.50	6.75	1.55E 06	5.30E 05	1.41E 06	4.96E 05	6.34E 05	2.23E 05	5.40E 05	1.89E
6.75	7.00	1.02E 06	3.49E 05	9.18E 05	3.20E 05	4-12E 05	1.44E 05	3.51E 05	1.22E
7.00		6.67E 05	6.67E 05	5.98E 05	5.98E 05	2.68E 05	2.68E 05	2.28E 05	2.28E

ORBIT ALTITUDE .. 10000 N MI

TOTAL TIME.. 96.HOURS TIME INTERVAL.. 4.MINUTES

ENE!		URBITA O Di	L FLUX	ORBITA 30		ORBITA 60	L FŁUX DEG	ORBITAI 90 I	
E1	E2	+E1	E1-E2	<b>+</b> €1		•E1	E1-E2	•E1	E1-E2
0.	0.25	6.21E 11	4.26E 11	8.26E 11	5.33E 11	4.30E 11	2.78E 11	3.55E 11	2.30E 11
0.25	0.50	1.95E 11	1.02E 11	2.93E 11	1.56E 11	1.52E 11	8.18E 10	1.25E 11	6.73E 10
0.50	0.75	9.29E 10	3.48E 10	1.37E 11	6.20E 10	7.02E 10	3.26E 10	5.81E 10	2.67E 10
0.75	1.00	5.80E 10	2.07E 10	7.50E 10	3.29E 10	3.76E 10	1.68E 10	3.13E 10	1.39E 10
1.00	1.25	3.74E 10	1.32E 10	4.21E 10	1.77E 10	2.08E 10	8.88E 09	1.74E 10	7.40E 09
1.25	1.50	2.41E 10	8.40E 09	2.44E 10	1.00E 10	1.19E 10	4.97E 09	1.00E 10	4.16E 09
1.50	1.75	1.57E 10	5.54E 09	1.44E 10	5.91E 09	6.93E 09	2.85E 09	5.88E 09	2.41E 09
1.75	2.00	1.02E 10	3.61E 09	8.45E 09	3.41E 09	4.07E 09	1.65E 09	3.47E 09	1.40E 09
2.00	2.25	6.58E 09	2.28E 09	5.04E 09	1.96E 09	2.43E 09	9.47E 08	2.07E 09	8.04E 08
2.25	2.50	4.30E 09	1.51E 09	3.08E 09	1.21E 09	1.48E 09	5.82E 08	1.27E 09	4.96E 08
2.50	2.75	2.79E 09	9.72E 08	1.86E 09	7.14E 08	8.96E 08	3.43E 08	7.70E 08	2.93E 08
2.75	3.00	1.82E 09	6.33E 08	1.15E 09	4.38E 08	5.54E 08	2.10E 08	4.77E 08	1.80E 08
3.00	3.25	1.18E 09	4.13E 08	7.12E 08	2.69E 08	3.44E 08	1.29E 08	2.97E 08	1.11E 08
3.25	3.50	7.70E 08	2.68E 08	4.44E 08	1.66E 08	2.15E 08	8.00E 07	1.86E 08	6.89E 07
3.50	3.75	5.02E 08	1.75E 08	2.77E 08	1.03E 08	1-35E 08	4.97E 07	1.17E 08	4.29E 07
3.75	4.00	3.27E 08	1.14E 08	1.75E 08	6.45E 07	8.50E 07	3.12E 07	7.37E 07	2.70E 07
4.00	4.25	2.13E 08	7.43E 07	1.10E 08	4.03E 07	5.38E 07	1.96E 07	4.67E 07	1.70E U
4.25	4.50	1.39E 08	4.84E 07	6.97E 07	2.55E 07	3.42E 07	1.24E 07	2.97E 07	1.08E 07
4.50	4.75	9.06E 07	3.15E 07	4.42E 07	1.61E 07	2.17E 07	7.85E 06	1.89E 07	6.82E 06
4.75	5.00	5.91E 07	2.05E 07	2.81E 07	1.02E 07	1.39E 07	5.00E 06	1.21E 07	4.34E 06
5.00	5.25	3.85E 07	1.34E 07	1.80E 07	6.49E 06	8.89E 06	3.20E 06	7.75E 06	2.78E 06
5.25	5.50	2.51E 07	8.73E 06	1.15E 07	4.12E 06	5.70E 06	2.04E 06	4.97E 06	1.77E 06
5.50	5.75	1.64E 07	5.70E 06	7.35E 06	2.63E 06	3.66E 06	1.31E 06	3.20E 06	1.14E 06
5.75	6.00	1.07E 07	3.73E 06	4.71E 06	1.69E 06	2.36E 06	8.40E 05	2.06E 06	7.33E 09
6.00	6.25	6.97E 06	2.42E 06	3.02E 06	1.08E 06	1.52E 06	5.38E 05	1.32E 06	4.69E 05
6.25	6.50	4.55E 06	1.58E 06	1.95E 06	6.92E 05	9.78E 05	3.47E 05	8.55E 05	3.03E 05
6.50	6.75	2.97E 06	1.03E 06	1.25E 06	4.46E 05	6.32E 05	2.24E 05	5.52E 05	1.96E 05
6.75	7.00	1.94E 06	6.72E 05	8.07E 05	2.86E 05	4.08E 05	1.44E 05	3.57E 05	1.26E 05
7.00		1.26E 06	1.26E 06	5.21E 05	5.21E 05	2.64E 05	2.64E 05	2.31E 05	2.31E 05

# ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE .- 11000 N MI

TOTAL TIME.. 96.HOURS

TIME INTERVAL .. 4.MINUTES

ENE		ORBITAL O DE		ORBITA 30 I		ORBITA		ORBITAI 90 i	
E1	E2	•E1	£1-E2	<b>+</b> E1	E1-E2	<b>+</b> E1	E1-E2	<b>+</b> E1	E1-E2
0.	0.25	1.05E 12	7.02E 11	8.96E 11	5.65E 11	4.62E 11	2.94E 11	3.84E 11	2.44E 1
0.25	0.50	3.48E 11	1.82E 11	3.32E 11	1.77E 11	1.69E 11	9.08E 10	1.40E 11	7.54E 1
0.50	0.75	1.66E 11	6.76E 10	1.55E 11	7.21E 10	7.79E 10	3.71E 10	6.49E 10	3.08E 1
0.75	1.00	9.81E 10	4.04E 10	8.25E 10	3.80E 10	4.08E 10	1.91E 10	3.41E 10	1.59E 1
1.00	1.25	5.77E 10	2-27E 10	4.45E 10	1.96E 10	2.18E 10	9.71E 09	1.82E 10	8.10E 0
1.25	1.50	3.50E 10	1.34E 10	2.49E 10	1.08F 10	1.20€ 10	5.29E 09	1.01E 10	4.42E 0
1.50	1.75	2.17E 10	8.87E 09	1.40E 10	6.17E 09	6.75E 09	2.98E 09	5.66E 09	2.50E 0
1.75	2.00	1.28E 10	5.11E 09	7.86E 09	3.38E 09	3.76E 09	1.63E 09	3.16E 09	1.37E 0
2.00	2.25	7.68E 09	2.79E 09	4.48E 09	1.87E 09	2.14E 09	8.84E 08	1.79E 09	7.41E 0
2.25	2.50	4.89E 09	1.94E 09	2.62E 09	1.12E 09	1.25E 09	5.34E 08	1.05E 09	4.48E 0
2.50	2.75	2.95E 09	1.12E 09	1.50E 09	6.18E 08	7.18E 08	2.95E 08	6.04€ 08	2.48E 0
2.75	3.00	1.83E 09	6.96E 08	8.80E 08	3.62E 08	4.23E 08	1.73E 08	3.56E 08	1.46E D
3.00	3.25	1.13E 09	4.30E 08	5.18E 08	2.11E 08	2.50E 08	1.01E 08	2.10E 08	8.52E 0
3.25	3.50	7.04E 08	2.67E 08	3.06E 08	1.24E 08	1.48E 08	5.99E 07	1.25E 08	5.04E 0
3.50	3.75	4.37E 08	1.65E 08	1.82E 08	7.30E 07	8.86E 07	3.54E 07	7.46E 07	2.98E 0
3.75	4.00	2.72E 08	1.03E 08	1.09E 08	4.38E 07	5.32E 07	2.13E 07	4.49E 07	1.79E 0
4.00	4.25	1.68E 08	6.33E 07	6.53E 07	2.58E 07	3.20E 07	1.26E 07	2.70E 07	1.06E 0
4.25	4.50	1.05E 08	3.97E 07	3.94E 07	1.56E 07	1.94E 07	7.63E 06	1.64E 07	6.43E 0
4.50	4.75	6.55E 07	2.46E 07	2.38E 07	9.36E 06	1.18E 07	4.59E 06	9.93E 06	3.88E 0
4.75	5.00	4.09E 07	1.54E 07	1.45E 07	5.67E 06	7.16E 06	2.79E 06	6.05E 06	2.36E 0
5.00	5.25	2.55€ 07	9.62E 06	8.81E 06	3.44E 06	4.37E 06	1.70E 06	3.69E 06	1.44E 0
5.25	5.50	1.59E 07	5.96E 06	5.37E 06	2.08E 06	2.67E 06	1.03E 06	2.26E 06	8.72E 0
5.50	5.75	9.94E 06	3.73E 06	3.28E 06	1.27E 06	1.64E 06	6.32E 05	1.38E 06	5.34E 0
5.75	6.00	6.20E 06	2.33E 06	2.01E 06	7.76E 05	1.01E 06	3.87E 05	8.51E 05	3.27E 0
6.00	6.25	3.88E 06	1.45E 06	1.24E 06	4.74E 05	6.20E 05	2.37E 05	5.24E 05	2.00E 0
6.25	6.50	2.43E 06	9.10E 05	7.63E 05	2.92E 05	3.83E 05	1.46E 05	3.24E 05	1.24E 0
6.50	6.75	1.52E 06	5.71E 05	4.71E 05	1.81E 05	2.37E 05	9.06E 04	2.01E 05	7.66E 0
6.75	7.00	9.50E 05	3.55E 05	2.91E 05	1.10€ 05	1.46E 05	5.55E 04	1.24E 05	4.70E 0
7.00		5.96E 05	5.96E 05	1.80E 05	1.80E 05	9.08E 04	9.08E 04	7.69E 04	7.69E 0

ORBIT ALTITUDE..12000 N MI TOTAL TIME.. 96.HOURS TIME INTERVAL.. 4.MINUTES

ENE!		ORBITA	NL FLUX DEG	ORBITAI 30 I	L FLUX Deg	ORBITA 60	L FLUX DEG	ORBITA 90	L FLUX DEG
E1	E2		E1-E2				E1-E2		£1-E2
0.	0.25	1.08E 12	6.43E 11	8.33E 11	5.05E 11	4.23E 11	2.58E 11		
0.25	0.50	4.38E 11	2.30E 11	3.28E 11		1.65E 11		1.39E 11	7.53E 10
0.50	0.75	2.09E 11	9.58E 10	1.52E 11	7.54E 10	7.57E 10		6.42E 10	3.19E 10
0.75	1.00	1.13E 11	5.15E 10	7.62E 10	3.73E 10	3.79E 10		3.22E 10	1.58E 10
1.00	1.25	6.14E 10	2.72E 10	3.88E 10	1.84E 10	1.93E 10		1.64E 10	7.78E 09
1.25	1.50	3.42E 10	1.54E 10	2.04E 10	9.72E 09	1.01E 10	4.84E 09	8.64E 09	4.12E 09
1.50	1.75	1.88E 10	8.38E 09	1.07E 10	4.98£ 09	5.30E 09	2.47E 09	4.53E 09	2.11E 09
1.75	2.00	1.04E 10	4.58E 09	5.67E 09	2.62E 09	2.83E 09	1.30E 09	2.42E 09	1.11E 09
2.00	2.25	5.87E 09	2.66E 09	3.05E 09	1.43E 09	1.53E 09	7.11E 08	1.31E 09	6.09E 08
2.25	2.50	3.21E 09	1.45E 09	1.62E 09	7.57E 08	8.14E 08	3.78E 08	6.98E 08	3.24E 08
2.50	2.75	1.76E 09	7.80E 08	8.65E 08	3.95E 08	4.36E 08	1.98E 08	3.74E 08	1.70E 08
2.75	3.00	9.77E 08	4.34E 08	4.70E 08	2.15E 08	2.38E 08	1.08E 08	2.04E 08	9.27E 07
3.00	3.25	5.43E 08	2.42E 08	2.55E 08	1.16E 08	1.30E 08	5.88E 07	1.11E 08	5.04E 0
3.25	3.50	3.01E 08	1.34E 08	1.39E 08	6.30E 07	7.07E 07	3.20E 07	6.06E 07	2.74E 0
3.50	3.75	1.67E 08	7.36E 07	7.55E 07	3.40E 07	3.87E 07	1.73E 07	3.32E 07	1.49E 0
3.75	4.00	9.35E 07	4.14E 07	4.15E 07	1.87E 07	2.14E 07	9.60E 06	1.83E 07	8.23E 0
4.00	4.25	5.21E 07	2.29E 07	2.28E 07	1.02E 07	1.18E 07	5.25E 06	1.01E 07	4.50E 0
4.25	4.50	2.93E 07	1.30E 07	1.26E 07	5.66E 06	6.54E 06	2.93E 06	5.60E 06	2.51E 00
4.50	4.75	1.63E 07		6.94E 06	3.09E 06	3.62E 06	1.60E 06	3.10E 06	1.37E 0
4.75	5.00	9.15E 06		3.85E 06	1.72E 06	2.01E 06	8.97E 05	1.72E 06	7.69E 0
5.00	5.25	5.10E 06	2.24E 06	2.13E 06	9.44E 05	1.12E 06	4.93E 05	9.56E 05	4.22E 0
5.25	5.50	2.86E 06	1.27E 06	1.18E 06	5.28E 05	6.23E 05	2.77E 05	5.33E 05	2.37E 0
5.50	5.75	1.59E 06		6.56E 05	2.90E 05	3.46E 05	1.53E 05	2.96E 05	1.31E 0
5.75	6.00	8.94E 05	3.92E 05	3.66E 05	1.61E 05	1.94E 05	8.50E 04	1.66E 05	7.27E 04
6.00	6.25	5.02E 05	2.22E 05	2.05E 05	9.06E 04	1.09E 05	4.80E 04	9.29E 04	4.10E 04
6.25	6.50	2.80E 05		1.14E 05	4.95E 04	6.07E 04	2.63E 04		2.25E 04
6.50	6.75	1.59E 05		6.44E 04	2.84E 04	3.44E 04	1.51E 04		1.29E 0
6.75	7.00	8.93E 04		3.61E 04	1.56E 04	1.93E 04		1.65E 04	
7.00		5.08E 04		2.05E 04	2.05E 04	1.10E 04	1.10E 04	9.37E 03	9.37E 03

#### ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE .. 13000 N MI

TOTAL TIME.. 96.HOURS

TIME INTERVAL.. 4.MINUTES

ENE F		DRBITA O D	L FLUX EG	ORBITA 30		ORBITA 60	L FLUX DEG	ORBITAL 90 (	
€1	£2	#E1	E1-E2	*E1	E1-E2	*E1	E1-E2	*E1	E1~E2
0.	0.25	1.058 12	6.04E 11	7.31E 11	4.43E 11	3.69E 11	2 • 24E 11	3.14E 11	1.91E 1
0.25	0.50	4.44E 11	2.33E 11	2.87E 11	1.578 11	1.446 11	7.89E 10	1.23E 11	6.72E 1
0.50	0.75	2.10E 11	1.03E 11	1.31E 11	6.85E 10	6.54E 10	3.43E 10	5.59E 10	2.92E 1
0.75	1.00	1.08E 11	5.28E 10	6.21E 10	3.23E 10	3.12E 10	1.62€ 10	2.66E 10	1.38E 1
1.00	1.25	5.49E 10	2.64E 10	2.99E 10	1.516 10	1.50E 10	7.59E 09	1.28E 10	6.49E
1.25	1.50	2.84E 10	1.37E 10	1.47E 10	7.51E 09	7.41E 09	3.77E 09	6.34E 09	3.23E 0
1.50	1.75	1.48E 10	7.08F 09	7.21E 09	3.58E 09	3.64E 09	1.80E 09	3.12E 09	1.54E
1.75	2.00	7.68E 09	3.60E 09	3.62E 09	1.79E 09	1.84E 09	9.04E 08	1.57E 09	7.75E 0
2.00	2.25	4.08E 09	2.00E 09	1.83E 09	9.12E 08	9.33E 08	4.64E 08	8.00E 08	3.98E (
2.25	2.50	2.08E 09	1.01E 09	9.19E 08	4.58E 08	4.69E 08	2.33E 08	4.02E 08	2.00E 0
2.50	2.75	1.07E 09	5.09E 08	4.61E 08	2.24t 08	2.36E 08	1.14E 08	2.02E 08	9.80E (
2.75	3.00	5.63E 08	2.72E 08	2.37E 08	1.17£ 08	1.22E 08	5.97E 07	1.04E 08	5.12E (
3.00	3.25	2.91€ 08	1.40E 08	1.20E 08	5.90E 07	6.196 07	3.03E 07	5.31E 07	2.60E (
3.25	3.50	1.51E 08	7.27E 07	6.13E 07	3.00E 07	3.16E 07	1.54E 07	2.71E 07	1.32E (
3.50	3.75	7.79E 07	3.70E 07	3.13E 07	1.51E 07	1.62E 07	7.80E 06	1.39E 07	6.69E (
3.75	4.00	4.09E 07	1.95E 07	1.61E 07	7.84E 06	8.36E 06	4.05E 06	7.16E 06	3.48E (
4.00	4.25	2.13E 07	1.03E 07	8.28E 06	4.05E 06	4.31E 06	2.10E 06	3.69E 06	1.80€ 0
4.25	4.50	1.11E 07	5.31E 06	4.24E 06	2.06E 06	2.21E 06	1.07E 06	1.89E 06	9.17E (
4.50	4.75	5.76E 06	2.77E 06	2.18E 06	1.06E 06	1.14E 06	5.52E 05	9.73E 05	4.73E C
4.75	5.00	2.99E 06	1.44E 06	1.12E 06	5.45E 05	5.85E 05	2.85E 05	5.01E 05	2.44E (
5.00	5.25	1.55E 06	7.44E 05	5.72E 05	2.78£ 05	3.00E 05	1.45F 05	2.57E 05	1.25E
5.25	5.50	8.04E 05	3.87E 05	2.94E 05	1.43E 05	1.54E 05	7.49E 04	1.32E 05	6.41E
5.50	5.75	4.17E 05	2.01E 05	1.51E 05	7.34E 04	7.94E 04	3.86E 04	6.80E 04	3.30E
5.75	6.00	2.16E 05	1.04E 05	7.74E 04	3.77E 04	4.08E 04	1.98E 04	3.49E 04	1.70E
6.00	6.25	1.12E 05	5.39E 04	3.97E 04	1.93E 04	2.10E 04	1.02E 04	1.80E 04	8.72E
6.25	6.50	5.80E 04	2.77E 04	2.04E 04	9.86E 03	1.08E 04	5.21E 03	9.24E 03	4.45E
6.50	6.75	3.02E 04	1.47E 04	1.06E 04	5.16E 03	5.60E 03	2.73E 03	4.79E 03	2.34E
6.75	7.00	1.56E 04	7.24E 03	5.41E 03	2.548 03	2.87E 03	1.34E 03	2.45E 03	1.15E (
7.00		8.34E 03	8.34E 03	2.87E 03	2.87E 03	1.52E 03	1.52E 03	1.30E 03	1.30E (

ORBIT ALTITUUE. . 14000 N MI

TOTAL TIME.. 432.HOURS

TIME INTERVAL .. 18. MINUTES

ENE:		ORBITAI O DI	L FLUX EG	ORBITA 30	L FLUX DEG	ORBITA 60	L FLUX DEG	ORBITAI 90 I	
E 1	E2	<b>+</b> E1	E1-E2	•E1	E1-E2	*E1	£1-£2	•E1	E1-E2
0.	0.25	9.71E 11	5.81E 11	6.26E 11	3.94E 11	3.04E 11	1.90E 11	2.57E 11	1.61E 11
0.25	0.50	3.91E 11	2.11E 11	2.32E 11	1.31E 11	1.13E 11	6.36F 10	9.62E 10	5.39E 10
0.50	0.75	1.80E 11	9.58E 10	1.01E 11	5.66E 10	4.99E 10	2.76E 10	4.24E 10	2.34E 10
0.75	1.00	8.42E 10	4.42E 10	4.49E 10	2.47E 10	2.22E 10	1.21E 10	1.89E 10	1.03E 10
1.00	1.25	4.00E 10	2.08E 10	2.02E 10	1.09E 10	1.01E 10	5.40E 09	8.60E 09	4.60E 09
1.25	1.50	1.92E 10	1.01E 10	9.36E 09	5.16E 09	4.69E 09	2.56F 09	4.01E 09	2.18E 09
1.50	1.75	9.18E 09	4.76E 09	4.20E 09	2.19E 09	2.14F 09	1.12E 09	1.83E 09	9.54E 08
1.75	2.00	4.42E 09	2.30E 09	2.01E 09	1.08E 09	1.02E 09	5.45E 08	8.73E 08	4.66E 08
2.00	2.25	2.11E 09	1.07E 09	9.30E 08	4.78E 08	4.76E Q8	2.44E 08	4.07E 08	2.09E 08
2.25	2.50	1.05E 09	5.44E 08	4.52E 08	2.37E 08	2.32E 08	1.21E 08	1.99E 08	1.04E 08
2.50	2.75	5.01E 08	2.56E 08	2.15E 08	1.10E 08	1.11E 08	5.64E 07	9.48E 07	4.84E 07
2.75	3.00	2.45E 08	1.25E 08	1.05E 08	5.39E 07	5.41E 07	2.77E 07	4.64E 07	2.37E 07
3.00	3.25	1.21E 08	6.15E 07	5.13E 07	2.62E 07	2.65E 07	1.35E 07	2.27E 07	1.16E 07
3.25	3.50	5.92E 07	2.98E 07	2.51E 07	1.27E 07	1.29E 07	6.56E 06	1.11E 07	5.62E 06
3.50	3.75	2.93E 07	1.49E 07	1.23E 07	6.30E 06	6.38E 06	3.25E 06	5.47E 06	2.79E 06
3.75	4.00	1.44E 07	7.34E 06	6.05E 06	3.09E 06	3.13E 06	1.60E 06	2.69E 06	1.37E 06
4.00	4.25	7.07E 06	3.61E 06	2.96E 06	1.51E 06	1.53E 06	7.83E 05	1.32E 06	6.72E 05
4.25	4.50	3.46E 06	1.75E 06	1.45E 06	7.34E 05	7.51E 05	3.81E 05	6.44E 05	3.27E 05
4.50	4.75	1.71E 06	8.66E 05	7.11E 05	3.62E 05	3.70E 05	1.88E 05	3.17E 05	1.61E 05
4.75	5.00	8.40E 05	4.29E 05	3.49E 05	1.78E 05	1.82E 05	9.27E 04	1.56E 05	7.96E 04
5.00	5.25	4.11E 05	2.09E 05	1.71E 05	8.70E 04	8.92E 04	4.53E 04	7.65E 04	3.89E 04
5.25	5.50	2.02E 05	1.02E 05	8.39E 04	4.25E 04	4.38E 04	2.22E 04	3.76E 04	1.90E 04
5.50	5.75	9.99E 04	5.07E 04	4.14E 04	2.10E 04	2.16E 04	1.10E 04	1.86E 04	9.43E 03
5.75	6.00	4.92E 04	2.50E 04	2.04E 04	1.04E 04	1.07E 04	5.43E 03	9.16E 03	4.66E 03
6.00	6.25	2.41E 04	1.22E 04	1.00E 04	5.07E 03	5.24E 03	2.65E 03	4.50E 03	2.28E 03
6.25	6.50	1.19F 04	5.99E 03	4.93E 03	2.49E 03	2.59E 03	1.31E 03	2.22E 03	1.12E 03
6.50	6.75	5.90F 03	2.99E 03	2.44E 03	1.25E 03	1.28E 03	6.53E 02	1.10E 03	5.61E 02
6.75	7.00	2.91E 03	1.46E 03	1.19E 03	5.95E 02	6.30E 02	3.14E 02	5.42E 02	2.70E 02
7.00		1.45E 03	1.45E 03	6.00E 02	6.00E 02	3.16E 02	3.16E 02	2.71E 02	2.71E 02

#### ORBITAL INTEGRATION MAP AE2

ORBIT ALTITUDE .. 15000 N MI

TOTAL TIME.. 576. HOURS

TIME INTERVAL..24.MINUTES

ENE?		ORBITAI O DI	L FLUX EG	ORBITAI 30 I		ORBITA 60		ORBITAI 90 I	
E1	E2	<b>*</b> E1	E1-E2	<b>+</b> E1	E1-E2	#El	E1-E2	<b>+</b> E1	£1-£2
0.	0.25	8.54E 11	5.40E 11	5.00E 11	3.29E 11	2.43E 11	1.58E 11	2.08E 11	1.35E 1
0.25	0.50	3.14E 11	1.77E 11	1.72E 11	1.00E 11	8.43E 10	4.90E 10	7.21E 10	4.19E 1
0.50	0.75	1.37E 11	7.81E 10	7.11E 10	4.18E 10	3.53E 10	2.06E 10	3.02E 10	1.77E 1
0.75	1.00	5.90E 10	3.33E 10	2.92E 10	1.70E 10	1.47E 10	8.49E 09	1.25E 10	7.26E 0
1.00	1.25	2.57E 10	1.41E 10	1.22E 10	6.91E 09	6.17E 09	3.48E 09	5.27E 09	2.97E 0
1.25	1.50	1.16E 10	6.51E 09	5.24E 09	3-14E 09	2.69E 09	1.58E 09	2.29E 09	1.36E 0
1.50	1.75	5.06E 09	2.79E 09	2.11E 09	1.15E 09	1.10E 00	6.01E 08	9.37E 08	5-10E 0
1.75	2.00	2.27E 09	1.30E 09	9.59E 08	5.61E 08	5.00E 08	2.91E 08	4.27E 08	2.48E 0
2.00	2.25	9.69E 08	5.02E 08	3.98E 08	2.13E 08	2.09E 08	1.11E 08	1.78E 08	9.48E 0
2.25	2.50	4.67E 08	2.58E 08	1.85E 08	1.02E 08	9.80E 07	5.43E 07	8.34F 07	4.62E 0
2.50	2.75	2.09E 08	1.05E 08	8.22E 07	4.22£ 07	4.37E 07	2.23E 07	3.72E 07	1.90E 0
2.75	3.00	1.04E 08	5.47E 07	4.00E 07	2.14E 07	2.14E 07	1.14E 07	1.82E 07	9.69E 0
3.00	3.25	4.91E 07	2.60E 07	1.86E 07	9.88E 06	9.99E 06	5.30E 06	8.51E 06	4.51E 0
3.25	3.50	2.31E 07	1.21E 07	8.75E 06	4.61E 06	4.69E 06	2.47E 06	4.00E 06	2.10E 0
3.50	3.75	1.10E 07	5.74E 06	4.14E 06	2.17E 06	2.23E 06	1.17E 06	1.90E 06	9.95E 0
3.75	4.00	5.23E 06	2.77E 06	1.96E 06	1.04E 06	1.06E 06	5.62E 05	9.02E 05	4.79E 0
4.00	4.25	2.46E 06	1.30E 06	9.21E 05	4.87E 05	4.96E 05	2.62E 05	4.23E 05	2.24E 0
4.25	4.50	1.16E 06	6.07E 05	4.34E 05	2.27E 05	2.34E 05	1.22E 05	1.99E 05	1.04E 0
4.50	4.75	5.53E 05	2.92E 05	2.06E 05	1.09E 05	1.11E 05	5.87E 04	9.50E 04	5.01E 0
4.75	5.00	2.62F 05	1.39E 05	9.75E 04	5.16E 04	5.26E 04	2.79E 04	4.49E 04	2.38E 0
5.00	5.25	1.23E 05	6.47E 04	4.59E 04	2.42E 04	2.47E 04	1.30E 04	2.11E 04	1.11E 0
5.25	5.50	5.82E 04	3.07E 04	2.17E 04	1.14E 04	1.17E 04	6.17E 03	9.99E 03	5.26E 0
5.50	5.75	2.75E 04	1.44E 04	1.03E 04	5.37E 03	5.54E 03	2.90E 03	4.73E 03	2.47E 0
5.75	6.00	1.31E 04	6.95E 03	4.89E 03	2.59E 03	2.64E 03	1.40E 03	2.25E 03	1.19E 0
6.00	6.25	6.18E 03	3.23E 03	2.31E 03	1.21E 03	1.24E 03	6.51E 02	1.06E 03	5.56E 0
6.25	6.50	2.95E 03	1.55E 03	1.10E 03	5.79E 02	5.94E 02	3.13E 02	5.07E 02	2.67E 0
6.50	6.75	1.40E 03	7.42E 02	5.20E 02	2.86E 02	2.81E 02	1.53E 02	2.40E 02	1.31E 0
6.75	7.00	6.55E 02	3.45E 02	2.34E 02	1.18E 02	1.28E 02	6.52E 01	1.09E 02	5.53E 0
7.00		3.11E 02	3.11E 02	1.16E 02	1.16E 02	6.28E 01	6.28E 01	5.36E 01	5.36E 0

ORBIT ALTITUDE .. 16000 N MI

TOTAL TIME.. 864.HOURS

TIME INTERVAL .. 36 . MINUTES

ENEF ME		URBITA O D	L FLUX EG	ORBITAL 30 L	DEG	ORBITAI 60 I		ORBITAI 90 I	
E 1	£2	*E1	E1-E2	<b>*</b> E1			E1-E2	•E1	E1-E2
0.	0.25	7.58E 11	5.10E 11	3.70E 11	2.51E 11	1.84E 11	1.25E 11	1.57E 11	1.07E 1
0.25	0.50	2.49E 11	1.50E 11	1.18E 11	7.23E 10	5.92E 10	3.60E 10	5.07E 10	3.09E 1
0.50	0.75	9.84E 10	5.99E 10	4.61E 10	2.83E 10	2.31E 10	1.42E 10	1.98E 10	1.21E I
0.75	1.00	3.85E 10	2.34E 10	1.78E 10	1.09E 10	8.96E 09	5.48E 09	7.68E 09	4.69E 0
1.00	1.25	1.51E 10	8.90E 09	6.91E 09	4.13E 09	3.49E 09	2.08E 09	2.99E 09	1.78E 0
1.25	1.50	6.19E 09	4.41E 09	2.77E 09	1.86E 09	1.41E 09	9.50E 08	1.21E 09	8.16E 0
1.50	1.75	1.78E 09	7.73E 08	9.11E 08	4.72E 08	4.58E 08	2.34E 08	3.90E 08	1.98E 0
1.75	2.00	1.00E 09	6.18E 08	4.38E 08	2.70E 08	2.24E 08	1.38E 08	1.92E 08	1.18E C
2.00	2.25	3.86E 08	2.23E 08	1.69E 08	9.81E 07	8.63E 07	5.00E 07	7.40E 07	4.29E 0
2.25	2.50	1.64E 08	8.72E 07	7.06E 07	3.92E 07	3.63E 07	2.01E 07	3.11E 07	1.71E 0
2.50	2.75	7.63E 07	4.05E 07	3.14E 07	1.71E 07	1.63E 07	8.82E 06	1.39E 07	7.56E 0
2.75	3.00	3.58E 07	1.96E 07	1.43E 07	7.91E 06	7.44E 06	4.11E 06	6.38E 06	3.53E (
3.00	3.25	1.62E 07	8.25E 06	6.35E 06	3.35E 06	3.33E 06	1.75E 06	2.85E 06	1.50E (
3.25	3.50	7.95E 06	4.16E 06	3.00E 06	1.60E 06	1.58E 06	8.39E 05	1.36E 06	7.21E 0
3.50	3.75	3.78E 06	1.99E 06	1.40E 06	7.45E 05	7.38E 05	3.93E 05	6.35E 05	3.38E (
3.75	4.00	1.79E 06	9.47E 05	6.52E 05	3.48E 05	3.46E 05	1.84E 05	2.97E 05	1.588 (
4.00	4.25	8.47E 05	4.46E 05	3.04E 05	1.62E 05	1.61E 05	8.58E 04	1.39E 05	7.39E (
4.25	4.50	4.00E 05	2.09E 05	1.42E 05	7.47E 04	7.56E 04	3.97E 04	6.51E 04	3.42E (
4.50	4.75	1.91E 05	1.01E 05	6.72E 04	3.57E 04	3.59E 04	1.90E 04	3.09E 04	1.64E (
4.75	5.00	9.08E 04	4.74E 04	3.15E 04	1.65E 04	1.68E 04	8.82E 03	1.45E 04	7.60E
5.00	5.25	4.34E 04	2.29E 04	1.50E 04	7.98E 03	8.02E 03	4.26E 03	6.92E 03	3.67E
5-25	5.50	2.05E 04	1.08E 04	7.03E 03	3.71E 03	3.76E 03	1.98E 03	3.24E 03	1.71E
5.50	5.75	9.71E 03	5.04E 03	3.32E 03	1.74E 03	1.78E 03	9.30E 02	1.53E 03	8.02E
5.75	6.00	4.67E 03	2.44E 03	1.59E 03	8.34E 02	8.49E 02	4.46E 02	7.32E 02	3.85E (
6.00	6.25	2.22E 03	1.16E 03	7.52E 02	3.94E 02	4.03E 02	2.11E 02	3.48E 02	1.82E
6.25	6.50	1.06E 03	5.63E 02	3.57E 02	1.90E 02	1.91E 02	1.02E 02	1.65E 02	8.79E
6.50	6.75	4.97E 02	3.27E 02	1.67E 02	1.06E 02	8.95E 01	5.66E 01	7.73E 01	4.90E
6.75	7.00	1.69E 02	5.54E 01	6.15E 01	2.35E 01	3.29E 01	1.25E 01	2.83E 01	1.06E
7.00		1.14E 02	1.14E 02	3.81E 01	3.81E 01	2.04E 01	2.04E 01	1.76E 01	1.76E

## TABLE 6 (CONCLUDED)

#### ORBITAL INTEGRATION MAP AE2

CRBIT ALTITUDE...17000 N MI

TOTAL TIME..1152.HOURS

TIME INTERVAL..48.MINUTES

ENEF ME/		CRALTAI O CI		ORBITAL 30 f				ORBITAL 90 L	
Εl	€2	•E1	E1-E2	*£1	E1-E2		El-E2	*E1	£1-E2
0. 0.25 0.5C 0.75 1.C0 1.25 1.50 1.75 2.C0 2.25 2.5C 3.25 3.5C 3.75 4.CC 4.25 4.5C 4.75 5.C0	0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.70 2.25 2.70 3.25 3.75 3.75 3.75 4.25 4.50 4.25 4.50 4.25 4.50 5.60 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75 6.75	6.00E 11 1.80E 11 6.63E 10 2.44E 10 9.00E 09 3.32E 09 1.22E 07 4.50E 08 6.12E 07 2.25E 07 8.30E 06 4.15E 05 5.64E 04 2.38E 04 7.66E 04 2.38E 04 7.66E 03 1.04E 03	4.20E 11 1.14E 11 4.19E 1C 1.54F 1C 5.69E 09 7.72E 08 2.84E 08 1.05C 08 3.86E 07 1.42E 07 5.24E 06 7.12E 05 2.62E 05 7.66E 04 1.31E 04 4.84E 03 1.78E 03 6.56E 02	2.47E 11 /.43E 10 2.75E 10 1.01E 10 3.75E 09 1.39E 09 5.01E 08 1.90E 08 7.01E 07 2.60E 07 9.78E 06 3.69E 06 1.39E 06 5.38E 05 2.09E 05 8.16E 04 4.23E 04 1.30E 04 5.31E 03 2.21E 03 9.36E 02	1.73E 11 4.69E 10 1.73E 10 6.40E 09 2.36E 09 8.86E 08 3.11E 08 1.20E 08 4.41E 07 1.62E 07 6.09E 06 2.30E 06 8.54E 05 3.29E 05 1.27E 05 4.93E 04 7.66E 03 3.10E 03 5.35E 02	1.28E 11 3.84E 10 1.42E 10 5.24E 09 1.93E 09 7.16E 08 2.59E 08 9.79E 07 3.61E 07 1.34E 07 5.03E 06 1.90E 06 7.14E 05 2.75E 05 1.06E 05 4.14E 04 6.51E 03 2.65E 03 1.10E 03 4.62E 02	8.93E 10 2.42E 10 8.95E 09 3.30E 09 1.22E 09 4.57E 08 1.61E 08 6.18E 07 2.27E 07 8.37E 06 3.14E 06 1.18E 06 1.18E 06 4.39E 05 6.48E 04 2.51E 04 9.78E 03 3.86E 03 1.55E 03 2.65E 02	1.10E 11 3.29E 10 1.22E 10 4.49E 09 1.66E 09 6.13E 08 2.22E 08 8.39E 07 1.15E 07 4.30E 06 1.62E 06 6.07E 05 2.33E 05 8.96E 04 3.48E 04 1.36E 04 5.42E 03 2.19E 03 9.02E 02 3.77E 02	7.66E 10 2.08E 10 7.67E 09 2.83E 09 1.04E 09 3.91E 08 1.38E 08 5.29E 07 7.17E 06 2.68E 06 1.01E 06 3.74E 05 1.43E 05 5.49E 04 2.11E 04 8.22E 03 3.23E 03 1.29E 03 5.25E 02 2.17E 02
5.25 5.50 5.75 6.00 6.25 6.50 6.75 7.00	5.50 5.75 6.00 6.25 6.50 6.75 7.00	3.83E 02 1.41E 02 5.21E 01 1.95E 01 7.27E 00 2.91E 00 1.16E 00 5.82E-01	2.42E 02 8.93E 01 3.26E 01 1.22E 01 4.36E 00 1.75E 00 5.82E-01	4.01E 02 1.74E 02 7.81E 01 3.53E 01 1.60E 01 7.34E 00 2.28E 00 1.67E 00	2.27E 02 9.62E 01 4.28E 01 1.93E 01 8.71E 00 5.06E 00 6.13E-01 1.67E 00	1.97E 02 8.50E 01 3.79E 01 1.71E 01 7.73E 00 3.53E 00 1.10E 00 8.01E-01	1.12E 02 4.71E 01 2.08E 01 9.33E 00 4.20E 00 2.43E 00 3.01E-01 8.01E-01	1.59E 02 6.86E 01 3.04E 01 1.36E 01 6.14E 00 2.79E 00 8.77E-01 6.33E-01	9.09E 01 3.82E 01 1.68E 01 7.47E 00 3.34E 00 1.92E 00 2.44E-01 6.33E-01

ORBIT ALTITUDE..18000 N MI

TCTAL TIME..2304.HOURS

TIME INTERVAL..96.MINUTES

ENERG PEV	Şγ	ORBITAL O C	_ FLUX EG	CRBITAL 30 (		ORBITAL 60 D		ORBITAL 90 D	
£1	£2	*E1	£1-E2	<b>*</b> E1	£1-£2	•E1	E1-E2	*E1	E1-E2
0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75	0.25 0.50 C.75 1.00 1.25 1.50 2.25 2.50 2.75 3.00 3.25 3.25 3.50 4.00 4.25 4.50 5.50 5.50 5.50 5.55 5.55 5.75	3.16E 11 9.47E 10 3.49E 10 1.29E 10 4.74E 09 1.75E 09 6.43E 08 2.37E 08 8.74E 07 3.22E 07 1.19E 07 4.37E 06 1.61E 06 5.93E 05 8.06E 04 2.97E 04 1.09E 04 4.03E 03 5.47E 02 2.02E 02 7.44E 01	2.21E 11 5.98E 1C 2.20E 1C 8.12E 09 2.99E 09 1.10E 09 4.06E 08 1.50E 08 5.52E 07 2.03E 07 7.49E 06 1.02E 06 3.75E 06 1.02E 06 1.02E 06 1.02E 06 3.75E 07 2.03E 07 2.76E 06 1.02E 06 3.75E 03 9.38E 02 3.46E 02 4.70E 01	1.16E 11 3.48E 10 1.28E 10 4.73E 09 1.74E 09 6.42E 08 8.71E 07 3.21E 07 1.18E 07 1.18E 06 1.61E 06 5.92E 05 2.18E 05 2.18E 05 2.18E 05 4.02E 03 1.48E 04 2.96E 04 1.09E 04 2.96E 04 2.96E 02 2.01E 02 7.42E 01 2.74E 01	8.13E 10 2.20E 1C 8.10E 09 2.99E 09 1.10E 09 4.05E 08 1.49E 08 5.50E 07 2.03E 07 7.47E 06 2.75E 06 1.01E 06 3.74E 05 1.38E 05 1.38E 05 1.87E 04 6.89E 03 2.54E 03 9.36E 02 3.45E 02 1.27E 02 4.68E 01 1.73E 01	6.05E 10 1.82E 10 6.69E 09 2.46E 09 9.08E 08 3.35E 08 1.23E 08 4.54E 07 1.67E 07 6.17E 06 2.27E 06 8.37E 05 3.09E 05 1.14E 05 4.19E 04 1.54E 04 5.69E 03 2.10E 03 2.10E 03 2.85E 02 1.05E 02 1.43E 01 1.43E 01	4.24E 10 1.15E 10 4.22E 09 1.56E 09 5.74E 08 2.11E 08 7.78E 07 2.87E 07 1.06E 07 3.70E 06 1.44E 06 5.29E 05 1.95E 05 7.18E 04 9.75E 03 3.59E 03 4.88E 02 4.80E 02 6.62E 01 2.44E 01 2.44E 01 2.44E 01	5.22E 10 1.57E 10 5.77E 09 2.13E 09 7.83E 08 1.06E 08 3.92E 07 1.44E 07 5.32E 06 1.96E 06 7.22E 05 2.66E 05 9.81E 04 4.91E 03 1.81E 03 6.66E 02 2.46E 02 9.05E 01 1.33E 01	3.66E 10 9.89E 09 3.64E 09 1.34E 09 4.95E 08 1.82E 08 6.71E 07 2.48E 07 9.12E 06 3.36E 06 1.24E 06 4.56E 05 1.68E 05 1.68E 05 6.19E 04 8.41E 03 3.10E 03 3.10E 03 1.14E 03 4.21E 02 1.55E 02 5.71E 01 2.10E 01 7.77E 00
6.25 6.50	6.00 6.25 6.50 6.75	2.74E 01 1.03E 01 3.83E 00 1.53E 00	1.72E 01 6.43E 00 2.30E CC 9.19E-01	1.01E 01 3.77E 00 1.41E C0 5.63E-01	6.31E 00 2.36E 00 8.44E-01 3.38E-01	5.25E 00 1.97E 00. 7.34E-01 2.94E-01	3.29E 00 1.23E 00 4.40E-01 1.76E-01	4.53E 00 1.70E 00 6.33E-01 2.53E-01	2.84E 00 1.06E 00 3.80E-01 1.52E-01
6.75 7.CC	7.00	6.13E-01 3.06E-01	3.06E-01 3.06E-01	2.25E-01 1.13E-01	1.13E-01 1.13E-01	1.17E-01 5.87E-02	5.87E-02 5.87E-02	1.01E-01 5.06E-02	5.06E-02 5.06E-02

TABLE 7 ORBITAL INTEGRATION FOR PROJECTED 1968 ELECTRON ENVIRONMENT

ORBIT ALTITUDE.. 150 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1.MINUTES

ENER MEV			AL FLUX DEG		L FLUX DEG		L FLUX DEG	ORBITAI 90 (	
E1	E2	*E1	E1-E2	<b>*</b> £1	E1-E2	<b>+</b> E1	E1-E2	*E1	£1-£2
0.	0.25	0.	0.	9.71E 08	8.16E 08	1.87E 10	1.31E 10	1.83E 10	1.28E 10
0.25	0.50	0.	0.	1.55E U8	1.30E 08	5.57E 09	3.32E 09	5.52E 09	3.32E 09
0.50	0.75	0.	0.	2.55E 07	2.11E 07	2.25E 09	1.05E 09	2.20E 09	1.07E 09
0.75	1.00	0.	0.	4.35E 06	3.58E 06	1.20E 09	5.21E 08	1.13E 09	5.18E 08
1.00	1.25	0.	0.	7.72E 05	5.51E 05	6.80E 08	2.89E 08	6.10E 08	2.73E 08
1.25	1.50	0.	0.	2.20E 05	6.85£ 04	3.91E 08	1.63E 08	3.37E 08	1.48E 08
1.50	1.75	0.	0.	1.52E 05	1.19E.04	2.29E 08	9.49E 07	1.89E 08	8.19E 07
1.75	2.00	0.	0.	1.40E 05	1.00E 04	1.34E 08	5.48E 07	1.07Ē 08	4.56E 07
2.00	2.25	0.	0.	1.30E 05	8.77E 03	7.88E 07	3.18E 07	6.10E 07	2.57E 07
2.25	2.50	0.	0.	1.21E 05	7.76E 03	4.70E 07	1.89E 07	3.53E 07	1.47E 07
2.50	2.75	0.	0.	1.13E 05	7.25E 03	2.80E 07	1.11E 07	2.06E 07	8.41E 0
2.75	3.00	0.	0.	1.06E 05	6.55E 03	1.69E 07	6.63E 06	1.22E 07	4.90E 0
3.00	3.25	0.	0.	9.97E 04	6.06E 03	1.03E 07	3.96E 06	7.30E 06	2.86E D6
3.25	3.50	0.	0.	9.36E 04	5.57E 03	6.35E 06	2.37E 06	4.43E 06	1.68E 06
3.50	3.75	0.	0.	8.80E 04	5.14E 03	3.99E 06	1.43E 06	2.75E 06	9.98E 05
3.75	4.00	0.	0.	8.29E 04	4.79E 03		8.69E 05	1.76E 06	5.97E 0
4.00	4.25	0.	0.	7.81E 04	4.42E 03		5.35E 05	1.16E 06	3.63E 05
4.25	4.50	0.	0.	7.37E 04	4.20E 03	1.15E 06	3.30E 05	7.97E 05	2.22E 0
4.50	4.75	0.	0.	6.95E 04	3.86E 03	8.19E 05	2.06E 05	5.75E 05	1.38E 05
4.75	5.00	0.	0.	6.56E 04	3.56E 03	6.13E 05	1.32E 05	4.37E 05	8.77E 04
5.00	5.25	0.	0.	6.21E 04	3.41E 03	4.82E 05	8.54E 04	3.50E 05	5.72E 04
5.25	5.50	0.	0.	5.87E 04	3.19€ 03	3.96E 05	5.77E 04	2.92E 05	3.90E 04
5.50	5.75	0.	0.	5.55E 04	2.90E 03	3.39E 05	3.96E 04	2.54E 05	2.71E 04
5.75	6.00	0.	0.	5.26E 04	2.92E 03	2.99E 05	2.95E 04	2.26E 05	2.06E 04
6.00	6.25	0.	0.	4.97E 04	2.55E 03	2.70E 05	2.16E 04	2.06E 05	1.54E 04
6.25	6.50	0.	0.	4.71E 04	2.46E 03	2.48E 05	1.74E 04	1.90E 05	1.27E 04
6.50	6.75	0.	0.	4.46E 04	2.39E 03	2.31E 05	1.48E 04	1.78E 05	1-10E 04
6.75	7.00	0.	0.	4.22E 04	2.12E 03	2.16E C5	1.22E 04	1.67E 05	9.23E 03

URBIT ALTITUDE.. 300 N MI

TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ENE	<b>V</b>	0 D	L FLUX EG	30 1	DEG	60	L FLUX DEG	90	DEG
El			E1-E2				E1-E2		£1-E2
0.	0.25	4.51E 06	3.41E 06	6.37E 10	5.35E 10	7.92E 10			
0.25	0.50	1.10E 06	8.30E 05	1.02E 10	8.56E 09		1.16E 10	1.51E 10	1.04E 1
0.50	0.75	2.67E 05	2.02E 05	1.69E 09	1.40E 09	4.71E 09	2.63E 09	4.67E 09	2.57E 0
0.75	1.00	6.48E 04	4.91E U4	2.87E 08	2.36E 08	2.08E 09	9.92E 08	2.10E 09	1.01E 0
1.00	1.25	1.58E 04	1.19E 04	5.09E 07	3.65E 07	1.09E 09	4.77E 08	1.09E 09	4.91E 0
1.25	1.50	3.84E 03	2.78E 03	1.44E 07	4.35E 06	6.12E 08	2.58E 08	5.97E 08	2.59E 0
1.50	1.75	1.06E 03	3.09E 02	1.00E 07	7.85E 05	3.54E Q8	1.46E 08	3.37E 08	1.44E 0
1.75	2.00	7.50E 02	2.19E 02	9.22E 06	6.64E 05	2.09E 08	8.35E 07	1.93E 08	8.05E 0
2.00	2.25	5.31E 02	1.55E 02	8.56E 06	5.81E 05	1.25E C8	4.85E 07	1.13E 08	4.54E 0
2.25	2.50	3.76E 02	1.10E 02	7.98E 06	5.15E 05	7.67E 07	2.87E 07	6.72E 07	2.63E 0
2.50	2.75	2.66E 02	7.76E 01	7.46E 06	4.82E 05	4.81E 07	1.69E 07	4.09E D7	1.51E 0
2.75	3.00	1.88E 02	5.49E 01	6.98E 06	4.38E 05	3.11E 07	1.02E 07	2.58E 07	8.92E O
3.00	3.25	1.33E 02	3.89E 01	6.54E 06	4.04E 05	2.09E 07	6.23E 06	1.69E 07	5.31E 0
3.25	3.50	9.42E 01	2.75E 01	6.14E 06	3.72E 05	1.47E 07	3.84E 06	1.16E 07	3.19E 0
3.50	3.75	6.67E 01	1.95E 01	5.76E 06	3.43E 05	1.08E 07	2.42E 06	8.39E 06	1.97E 0
3.75	4.00	4.72E 01	1.39E 01	5.42E 06	3.19E 05	8.40E 06	1.56E 06	6.42E 06	1.24E 0
4.00	4.25	3.33E 01	9.66E 00	5.10E 06	2.94E 05	6.85E 06	1.04E 06	5.18E 06	8.12E 0
4.25	4.50	2.37E 01	6.93E 00	4.81E 06	2.80E 05	5.81E 06	7.14E 05	4.36E 06	5.52E 0
4.50	4.75	1.68E 01	4.88E 00	4.53E 06	2.58E 05	5.10E 06	5.10E 05	3.81E 06	3.90E 0
4.75	5.00	1.19E 01	3.47E 00	4.27E 06	2.36E 05	4.58E 06	3.83E Q5	3.42E 06	2.90E 0
5.00	5.25	8.40E 00	2.45E 00	4.03E 06	2.26E 05	4.20E 06	3.00E 05	3.13E 06	2.28E 0
5.25	5.50	5.95E 00	1.73E 00	3.81E 06	2.118 05	3.90E 06	2.52E 05	2.90E 06	1.90E 0
5.50	5.75	4.21E 00	1.23E 00	3.60E 06	1.92E 05	3.65E 06	2.07E 05	2.71E 06	1.57E 0
5.75	6.00	2.99E 00	8.78E-01	3.40E 06	1.93E 05	3.44E 06	1.94E 05	2.56E 06	1.47E 0
6.00	6.25	2.11E 00	6.16E-01	3.21E 06	1.68E 05	3.25E 06	1.62E 05	2.41E 06	1.23E 0
6.25	6.50	1.49E 00	4.37E-01	3.04E 06	1.62E 05	3.09E 06	1.53E 05	2.29E 06	1.16E 0
6.50	6.75	1.06E 00	3.07E-01	2.88E 06	1.58E 05	2.93E 06	1.46E 05	2.17E 06	1.12E 0
6.75	7.00	7.50E-01	2.19E-01	2.72E 06	1.39E 05	2.79E 06	1.29E 05	2.06E 06	9.80E 0
7.00		5.31E-01	5.31E-01	2.58E 06	2.58E 06	2.66E 06	2.66E 06	1.96E 06	1.96E 0

# ORBITAL INTEGRATION FOR PROJECTED 1968 ELECTRON ENVIRONMENT

ORBIT ALTITUDE.. 450 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1.MINUTES

ENER	RGY V	ORBITA O D	L FLUX EG	ORBITA 30	DEG	60	L FLUX DEG	ORBITA 90	L FLUX DEG
Εl	E2	#E1	E1-E2	•E1	E1-E2	*E1	E1-E2	•E1	
0.	0.25	9.17E 09	7.02E U9	4.71E 11	3.94E 11		2.62E 11		
0.25	0.50	2.15E 09	1.65E 09	7.72E 10	6.42E 10			5.15E 10	
0.50	0.75	4.91E 08	3.79E 08	1.30E 10	1.07E 10	1.49E 10		1.31E 10	8.13E 0
0.75	1.00	1.13E 08	8.64E 07	2.27E 09	1.85E 09	5.49E 09	2.90E 09	4.98E 09	2.60E 0
1.00	1.25	2.61E 07	2.02E 07	4.13E Ú8	3.00E 08	2.59E 09	1.20E 09	2.38E 09	1.10E 09
1.25	1.50	5.91E 06	3.86E 06	1.13E 08	3.76E 07	1.39E 09	5.98E 08	1.28E 09	5.52E 0
1.50	1.75	2.05E 06	4.85E 05	7.53E 07	6.55E 06	7.92E 08	3.27E 08	7.25E 08	3.01E 0
1.75	2.00	1.56E 06	3.62E 05	6.87E 07	5.48E 06	4.65E 08	1.84E 08	4.24E 08	1.69E 0
2.00	2.25	1.20E 06	2.59E 05	6.33E 07	4.65E 06	2.81E 08	1.05E 08	2.54E 08	9.65E 0
2.25	2.50	9.41E 05	1.93E 05	5.86E 07	4.05E 06	1.76E 08	6.14E 07	1.58E 08	5.63E 0
2.50	2.75	7.48E 05	1.46E 05	5.46E 07	3.72E 06	1.14E 08	3.60E 07	1.01E 08	3.30E 0
2.75	3.00	6.02E 05	1.15E 05	5.09E 07	3.35E 06	7.85E 07	2.18E 07	6.84E 07	1.99E 0
3.00	3.25	4.87E 05	8.72E 04	4.75E Q7	3.05E 06	5.67E 07	1.34E 07	4.86E 07	1.21E 0
3.25	3.50	4.00E 05	7.03E 04	4.44E 07	2.80E 06	4.33E 07	8.45E 06	3.64E 07	7.58E 0
3.50	3.75	3.29E 05	5.56E 04	4.17E 07	2.56E 06	3.48E 07	5.54E 06	2.88E 07	4.91E 0
3.75	4.00	2.74E 05	4.36E U4	3.91E 07	2.36E 06	2.93E 07	3.78E 06	2.39E 07	3.30E 0
4.00	4.25	2.30E 05	3.66E 04	3.67E 07	2.17E 06	2.55E 07	2.71E 06	2.06E 07	2.32E 0
4.25	4.50	1.94E 05	2.96E 04	3.46E G7	2.05€ 06	2.28E 07	2.05E 06	1.83E 07	1.72E 0
4.50	4.75	1.64E 05	2.46E 04	3.25E 07	1.88E 06	2.08E 07	1.60E 06	1.66E 07	1.32E 0
4.75	5.00	1.39E 05	2.04E Ü4	3.06E 07	1.72E 06	1.92E 07		1.53E 07	
5.00	5.25	1.19E 05	1.70E 04	2.89E 07	1.63E 06	1.78E 07		1.42E 07	9.08E 0
5.25	5.50	1.02E 05	1.43E 04	2.73E 07	1.53E 06	1.67E 07		1.33E 07	7.99E 0
5.50	5.75	8.76E 04	1.23E 04	2.57E 07	1.39E 06	1.57E 07	8.71E 05	1.25E 07	6.89E 0
5.75	6.00	7.54E 04	1.04E 04	2.44E 07	1.38E 06	1.48E 07	8.46E 05	1.18E 07	6.67E 0
6.00	6.25	6.49E 04	8.82E 03	2.30E G7	1.21E 06	1.40E 07	7.27E 05	1.11E 07	5.72E 0
6.25	6.50	5.61E 04	7.69E 03	2.18E 07	1.16E 06	1.33E 07	6.93E 05	1.05E 07	5.43E 0
6.50	6.75	4.84E 04	6.44E 03	2.06E 07	1.13E 06	1.26E 07	6.69E 05	1.00E 07	
6.75	7.00	4.20E 04	5.60E 03	1.95E 07		1.19E 07		9.48E 06	4.64E 0
7.00		3.64E 04	3.64E 04	1.85E 07	1.85E 07	1.13E 07	1.13E 07	9.02E 06	9.02E 0

ORBIT ALTITUDE.. 600 N MI TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ENER MEV		ORBITA O D		ORBITAL 30	L FLUX DEG	ORBITAL 60 I	FLUX DEG	ORBITAL 90 (	
E1	E2	+E1	E1-E2	*E1	E1-E2	*E1	£1-E2	<b>+</b> €1	E1-E2
0.	0.25	5.55E 11	4.36E 11	1.72E 12	1.44E 12	1.03E 12	8.39E 11	8.36E 11	6.80E 11
0.25	0.50	1.19E 11	9.37E 10	2.81E 11	2.34E 11	1.89E 11	1.46E 11	1.56E 11	1.20E 11
0.50	0.75	2.51E 10	1.98E 10	4.71E 10	3.89E 10	4.31E 10	2.86E 10	3.64E 10	2.40E 10
0.75	1.00	5.32E 09	4.17E 09	8.19E 09	6.71E 09	1.45E 10	7.94E 09	1.24E 10	6.83E 09
1.00	1.25	1.15E 09	9.04E 08	1.47E 09	1.08E 09	6.53E 09	3.05E 09	5.55E 09	2.64E 09
1.25	1.50	2.49E 08	1.37E 08	3.98E 08	1.24E 08	3.49E 09	1.46E 09	2.91E 09	1.25E 09
1.50	1.75	1.12E 08	1.90E 07	2.74E 08	2.17E 07	2.02E 09	8.08E 08	1.65E 09	6.78E 08
1.75	2.00	9.28E 07	1.50E 07	2.52E 08	1.86E 07	1.22E 09	4.63E 08	9.76E Q8	3.81E 08
2.00	2.25	7.77E 07	1.14E 07	2.33E 08	1.63E 07	7.54E 08	2.69E 08	5.96E 08	2.17E 08
2.25	2.50	6.63E 07	9.02E 06	2.17E 08	1.44E 07	4.85E 08	1.60E 08	3.79E 08	1.27E 08
2.50	2.75	5.73E 07	7.47E 06	2.03E 08	1.35E 07	3.25E 08	9.56E 07	2.52E 08	7.48E 07
2.75	3.00	4.98E 07	6.28E 06	1.89E 08	1.22E 07	2.29E 08	5.89E 07	1.77E 08	4.55E 07
3.00	3.25	4.35E 07	5.17E 06	1.77E 08	1.12E 07	1.70E 08	3.70E 07	1.31E 08	2.83E 07
3.25	3.50	3.84E 07	4.49E 06	1.66E Q8	1.03E 07	1.33E 08	2.39E 07	1.03E 08	1.81E 07
3.50	3.75	3.39E 07	3.81E 06	1.55E 08	9.49E 06	1.09E 08	1.60E 07	8.50E 07	1.21E 07
3.75	4.00	3.01E 07	3.27E 06	1.46E 08	8.83E 06	9.34E 07	1.12E 07	7.28E 07	8.49E 06
4.00	4.25	2.68E 07	2.88E 06	1.37E 08	8.14E 06	8.21E 07	8.26E 06	6.43E 07	6.27E 06
4.25	4.50	2.39E 07	2.52E 06	1.29E 08	7.68E 06	7.39E 07	6.43E 06	5.81E 07	4.89E 06
4.50	4.75	2.14E 07	2.18E 06	1.21E 08	7.01E 06	6.74E 07	5.14E 06	5.32E 07	3.94E 06
4.75	5.00	1.92E 07	1.92E 06	1.14E 08	6.48E 06	6.23E 07	4.27E 06	4.92E 07	3.29E 06
5.00	5.25	1.73E 07	1.78E 06	1.08E 08	6.19E 06	5.80E 07	3.75E 06	4.59E 07	2.89E 06
5.25	5.50	1.55E 07	1.51E 06	1.02E 08	5.74E 06	5.43E 07	3.33E 06	4.30E 07	2.59E 06
5.50	5.75	1.40E 07	1.35E 06	9.59E 07	5.20E 06	5.10E 07	2.92E 06	4.05E 07	2.27E 06
5.75	6.00	1.27E 07	1.26E 06	9.07E 07	5.22E 06	4.80E 07	2.84E 06	3.82E 07	2.22E 06
6.00	6.25	1.14E 07	1.11E G6	8.54E 07	4.58E 06	4.52E 07	2.45E 06	3.60E 07	1.91E 06
6.25	6.50	1.03E 07	9.79E 05	8.09E 07	4.36E 06	4.28E 07	2.33E 06	3.41E 07	1.82E 06
6.50	6.75	9.33E 06	8.73E 05	7.65E 07	4.21E 06	4.04E 07	2.24E 06	3.22E 07	1.75E 06
6.75	7.00	8.46E 06	7.95E U5	7.23E 07	3.77E 06	3.82E 07	1.97E 06	3.05E 07	1.55E 06
7.00		7.66E 06	7.66E 06	6.85E 07	6.85E 07	3.62E 07	3.62E 07	2.89E 07	2.89E 07

# ORBITAL INTEGRATION FOR PROJECTED 1968 ELECTRON ENVIRONMENT

ORBIT ALTITUDE .. 800 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1.MINUTES

ENE(		ORBITA O D		30	L FLUX DEG	60 1	DEG	ORBITAI 90 I	DEG
Εl	E2	•E1	E1-E2						E1-E2
0.	0.25	6.09E 12	4.94E 12	7.80E 12	6.55E 12	3.87E 12	3.21E 12	3.22E 12	2.67E 12
0.25	0.50	1.15E 12	9.31E 11	1.25E 12	1.05E 12	6.59E 11	5.31E 11	5.49E 11	4.42E 11
0.50	0.75	2.17E 11	1.76E 11	2.05E 11	1.71E 11	1.28E 11	9.43E 10	1.07E 11	7.87E 10
0.75	1.00	4.13E 10	3.33E 10	3.45E 10	2.86E 10	3.41E 10	2.12E 10	2.80E 10	1.76E 10
1.00	1.25	8.02E 09	6.25E 09	5.94E 09	4.25E 09	1.30E 10	6.37E 09	1.04E 10	5.23E 09
1.25	1.50	1.77E 09	6.98Ē Ûô	1.69E 09	4.79E 08	6.58E C9	2.66E 09	5.15E 09	2.14E 09
1.50	1.75	1.08E 09	1.12E 08	1.22E 09	8.71E 07	3.928 09	1.44E 09	3.01E 09	1.13E 09
1.75	2.00	9.64E 08	9.54E 07	1.13E 09	7.38E 07	2.48E 09	8.39E 08	1.89E 09	6.42F 08
2.00	2.25	8.69E 08	8.12E 07	1.05E 09	6.78E 07	1.64E 09	4.98E 08	1.24E 09	3.74E 08
2.25	2.50	7.87E 08	6.94E 07	9.87E 08	6.11E 07	1.14E 09	3.04E 08	8.70E 08	2.25E 08
2.50	2.75	7.18E 08	6.37E 07	9.25E 08	5.83E 07	8.38E 08	1.89E 08	6.44E 08	1.39E 0
2.75	3.00	6.54E 08	5.68E 07	8.67E 08	5.32E 07	6.49E 08	1.22E 08	5.05E 08	8.90E 07
3.00	3.25	5.98E 08	5.06E 07	8.14E 08	4.98E 07	5.27E 08	8.11E 07	4.16E 08	5.95E 07
3.25	3.50	5.47E 08	4.60E 07	7.64E 08	4.59E 07	4.46E 08	5.61E 07	3.57E 08	4.15E 07
3.50	3.75	5.01E 08	4.13E Q7	7.18E 08	4.27E 07	3.90E 08	4.09E 07	3.15E 08	3.06E 07
3.75	4.00	4.60E 08	3.79E 07	6.76E Q8	4.03E 07	3.49E 08	3.14E 07	2.85E 08	2.39E 07
4.00	4.25	4.22E 08	3.40E 07	6.35E 08	3.68E 07	3.18E 08	2.50E 07	2.61E 08	1.94E 07
4.25	4.50	3.88E Q8	3.16E 07	5.98E Q8	3.54E 07	2.93E 08	2.11E 07	2.41E 08	1.66E 07
4.50	4.75	3.56E 08	2.80E 07	5.63E 08	3.26E 07	2.72E 08	1.79E 07	2.25E 08	1.43E 0
4.75	5.00	3.28E 08	2.54E 07	5.30E 08	2.98E 07	2.54E 08	1.56E 07	2.10E 08	1.26E 07
5.00	5.25	3.03E 08	2.47E 07	5.01E 08	2.91E 07	2.38E 08	1.45E 07	1.98E 08	1.18E 07
5.25	5.50	2.78E 08	2.14E 07	4.71E 08	2.68E 07	2.24E 08	1.31E 07	1.86E 08	1.07E 07
5.50	5.75	2.57E 08	1.94E U7	4.45E Q8	2.46E 07	2.11E 08	1.17E 07	1.75E 08	9.61E 06
5.75	6.00	2.37E 08	1.90E 07	4.20E 08	2.47E 07	1.99E 08	1.16E 07	1.66E 08	9.58E 06
6.00	6.25	2.18E 08	1.68E 07	3.95E 08	2.16E 07	1.87E 08	1.01E 07	1.56E 08	8.35E 06
6.25	6.50	2.02E 08	1.53E 07	3.74E 08	2.07E 07	1.77E 08	9.63E 06	1.48E 08	7.97E 0
6.50	6.75	1.86E 08	1.42E 07	3.53E 08	2.02E 07	1.68E 08	9.31E 06	1.40E 08	7.71E 0
6.75	7.00	1.72E 08	1.28E 07	3.33E 08	1.77E 07	1.58E 08	8.26E 06		6.86E 06
7.00		1.59E 08	1.59E 08	3.15E 08	3.15E 08	1.50E 08	1.50E 08	1.25E 08	1.25E 0

URBIT ALTITUDE .. 1000 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1.MINUTES

ENER MEV		ORBITA O D	L FLUX EG	ORBITA 30		ORBITA 60	L FLUX DEG	ORBITA 90	
El	E2	•E1	E1-E2	*E1		•E1		•E1	E1-E2
0.	0.25	2.74E 13	2.27E 13	2.37E 13	2.01E 13	1.10E 13	9.22E 12	9.15E 12	7.69E 1
0.25	0.50	4.73E 12	3.90E 12	3.60E 12	3.04E 12	1.75E 12	1.45E 12	1.47E 12	1.21E 1
0.50	0.75	8.22E 11	6.78E 11	5.56E 11	4.68E 11	3.07E 11	2.38E 11	2.57E 11	2.01E 1
0.75	1.00	1.45E 11	1.19E 11	8.81E 10	7.39E 10	6.87E 10	4.65E 10	5.65E 10	3.89E 1
1.00	1.25	2.59E 10	1.94E 10	1.42E 10	9.578 09	2.22E 10	1.13E 10	1.76E 10	9.21E 0
1.25	1.50	6.50E 09	2.02E 09	4.67E 09	1.13E 09	1.09E 10	4.21E 09	8.37E 09	3.30E 0
1.50	1.75	4.48E 09	3.62E 08	3.54E 09	2.18E 08	6.69E 09	2.23E 09	5.07E 09	1.68E 0
1.75	2.00	4.12E 09	3.08E 08	3.32E 09	1.85E 08	4.47E 09	1.30E 09	3.38E 09	9.70E 0
2.00	2.25	3.81E 09	2.80E 08	3.14E 09	1.74E 08	3.16E 09	7.86E 08	2.41E 09	5.79E 0
2.25	2.50	3.53E 09	2.50E 08	2.97E 09	1.60E 08	2.38E 09	4.93E 08	1.83E 09	3.60E 0
2.50	2.75	3.28E 09	2.37E 08	2.80E 09	1.55E 08	1.88E 09	3.19E 08	1.47E 09	2.32E 0
2.75	3.00	3.04E 09	2.16E 08	2.65E Q9	1.42E 08	1.56E 09	2.14E 08	1.24E 09	1.57E 0
3.00	3.25	2.83E 09	1.99E 08	2.51E 09	1.36E 08	1.35E 09	1.52E 08	1.08E 09	1.13E 0
3.25	3.50	2.63E 09	1.83E 08	2.37E 09	1.26E 08	1.20E 09	1.12E 08	9.72E 08	8.45E 0
3.50	3.75	2.45E 09	1.69E 08	2.25E 09	1.19E 08	1.09E 09	8.72E 07	8.87E 08	6.73E 0
3.75	4.00	2.28E 09	1.58E 08	2.13E 09	1.13E 08	9.99E 08	7.16E 07	8.20E 08	5.64E 0
4-00	4.25	2.12E 09	1.43E 08	2.02E 09	1.04E 08	9.28E 08	6.00E 07	7.64E 08	4.79E 0
4.25	4.50	1.98E 09	1.37E 08	1.91E 09	1.01E 08	8.68E 08	5.37E 07	7.16E 08	4.36E 0
4.50	4.75	1.84E 09	1.24E 08	1.81E 09	9.42E 07	8.14E 08	4.74E 07	6.72E 08	3.89E 0
4.75	5.00	1.72E 09	1.12E 08	1.72E 09	8.69E 07	7.67E 08	4.24E 07	6.33E 08	3.49E 0
5.00	5.25	1.60E 09	1.11E 08	1.63E 09	8.41E 07	7.24E 08	4.01E 07	5.98E Q8	3.33E 0
5.25	5.50	1.49E 09	9.86E 07	1.54E 09	7.97E 07	6.84E 08	3.71E 07	5.65E Q8	3.09E 0
5.50	5.75	1.39E 09	9.06E 07	1.47E 09	7-29E 07	6.47E 08	3.36E 07	5.34E 08	2.80E 0
5.75	6.00	1.30E 09	8.98E 07	1.39E 09	7.40E 07	6.14E 08	3.38E 07	5.06E 08	2.82E 0
6-00	6.25	1.21E 09	7.87E 07	1.32E 09	6.44E 07	5.80E 08	2.93E 07	4.78E 08	2.45E 0
6.25	6.50	1.14E 09	7.41E 07	1.25E 09	6.30E 07	5.50E 08	2.84E 07	4.54E 08	2.37E 0
6.50	6.75	1.06E 09	7.11E 07	1.19E 09	6.21E 07	5.22E 08	2.78E 07	4.30E 08	2.33E 0
6.75	7.00	9.90E 08	6.24E 07	1.13E 09	5.44E 07	4.94E 08	2.45E 07	4.07E 08	2.04E 0
7.00		9.28E 08	9.28E 08	1.07E 09	1.07E 09	4.70E 08	4.70E 08	3.86E 08	3.86E 0

## ORBITAL INTEGRATION FOR PROJECTED 1968 ELECTRON ENVIRONMENT

ORBIT ALTITUDE..1250 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1.MINUTES

ENER ME		OKBITAI O DI		ORBITA 30		ORBITA 60	L FLUX DEG	ORBITAI 90 (	
E1	E2	#E1			E1-E2		E1-E2	*E1	E1-E2
0. 0.25 0.50 0.75 1.00 1.25	0.25 0.50 0.75 1.00 1.25 1.50	9.74E 13 1.49E 13 2.32E 12 3.67E 11 5.88E 10 1.92E 10	8.25E 13 1.26E 13 1.95E 12 3.08E 11 3.96E 10 4.61E 09	5.20E 13 7.57E 12 1.11E 12 1.68E 11 2.57E 10 9.60E 09	4.45E 13 6.46E 12 9.45E 11 1.42E 11 1.61E 10 2.04E 09	2.56E 13 3.86E 12 6.27E 11 1.27E 11 3.78E 10 1.90E 10	3.24E 12 5.00E 11 8.94E 10 1.88E 10 7.01E 09	2.17E 13 3.28E 12 5.26E 11 1.02E 11 2.80E 10 1.35E 10	1.85E 13 2.75E 12 4.23E 11 7.41E 10 1.45E 10 4.97E 09
1.50 1.75 2.00 2.25 2.50 2.75	1.75 2.00 2.25 2.50 2.75 3.00	1.46E 10 1.37E 10 1.29E 10 1.22E 10 1.16E 10 1.09E 10	8.97E 08 7.49E 08 7.17E 08 6.63E 08 6.44E 08 5.92E 08	7.56E 09 7.15E 09 6.80E 09 6.46E 09 6.14E 09 5.84E 09	4.14E 08 3.53E 08 3.36E 08 3.14E 08 3.07E 08 2.83E 08	1.19E 10 8.28E 09 6.13E 09 4.81E 09 3.97E 09 3.42E 09	3.66E 09 2.16E 09 1.32E 09 8.37E 08 5.53E 08 3.81E 08	8.51E 09 6.03E 09 4.58E 09 3.70E 09 3.14E 09 2.76E 09	2.49E 09 1.45E 09 8.81E 08 5.64E 08 3.79E 08 2.67E 08
3.00 3.25 3.50 3.75 4.00	3.25 3.50 3.75 4.00 4.25	1.03E 10 9.76E 09 9.23E 09 8.74E 09 8.27E 09	5.67E 08 5.24E 08 4.95E 08 4.72E 08 4.33E 08	5.56E 09 5.28E 09 5.03E 09 4.79E 09 4.55E 09	2.74E 08 2.55E 08 2.42E 08 2.31E 08 2.16E 08	3.04E 09 2.76E 09 2.55E 09 2.37E 09 2.23E 09	2.79E 08 2.12E 08 1.72E 08 1.46E 08 1.25E 08	2.49E 09 2.29E 09 2.13E 09 2.00E 09 1.88E 09	2.03E 08 1.59E 08 1.33E 08 1.16E 08 1.02E 08
4.25 4.50 4.75 5.00 5.25	4.50 4.75 5.00 5.25 5.50	7.83E 09 7.41E 09 7.01E 09 6.65E 09 6.30E 09	4.24E 08 3.95E 08 3.62E 08 3.54E 08 3.33E 08	4.34E 09 4.13E 09 3.93E 09 3.75E 09 3.57E 09	2.10E 08 1.98E 08 1.84E 08 1.76E 08 1.71E 08	2.10E 09 1.99E 09 1.88E 09 1.79E 09 1.70E 09	1.15E 08 1.04E 08 9.42E 07 8.91E 07 8.50E 07	1.78E 09 1.68E 09 1.60E 09 1.52E 09 1.44E 09	9.50E 07 8.69E 07 7.90E 07 7.53E 07 7.19E 07
5.50 5.75 6.00 6.25 6.50 6.75 7.00	5.75 6.00 6.25 6.50 6.75 7.00	5.97E 09 5.66E 09 5.35E 09 5.08E 09 4.82E 09 4.56E 09 4.33E 09	3.06E 08 3.10E 08 2.69E 08 2.63E 08 2.60E 08 2.26E 08 4.33E 09	3.40E 09 3.24E 09 3.08E 09 2.94E 09 2.81E 09 2.67E 09 2.55E 09	1.56E 08 1.60E 08 1.39E 08 1.37E 08 1.36E 08 1.20E 08 2.55E 09	1.62E 09 1.54E 09 1.46E 09 1.39E 09 1.33E 09 1.26E 09 1.20E 09	7.72E 07 7.82E 07 6.77E 07 6.68E 07 6.62E 07 5.78E 07 1.20E 09	1.37E 09 1.30E 09 1.24E 09 1.18E 09 1.12E 09 1.07E 09 1.02E 09	6.55E 07 6.65E 07 5.76E 07 5.68E 07 5.64E 07 4.92E 07 1.02E 09

ORBIT ALTITUDE..1500 N MI TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ENER MEV		ORBITAL O DI	EG	ORBITAL 30 (	DEG	60 E	DEG		EG
E1				•E1					
0. 0.25	0.25	2.50E 13	1.51E 14 2.15E 13	7.05E 13 9.76E 12	8.40E 12	5.27E 12	4.45E 12		3.79E 12
0.50 0.75 1.00	0.75 1.00 1.25	3.57E 12 5.23E 11 7.65E 10	3.05E 12 4.47E 11 4.53E 10	1.36E 12 1.95E 11 2.86E 10	1.16E 12 1.67E 11 1.64E 10	8.16E 11 1.64E 11 5.05E 10	6.51E 11 1.14E 11 2.39E 10	6.81E 11 1.29E 11 3.59E 10	5.52E 11 9.32E 10 1.76E 10
1.25 1.50 1.75	1.50 1.75 2.00	3.12E 10 2.51E 10 2.38E 10	6.08E 09 1.26E 09 1.08E 09	1.23E 10 10.00E 09 9.51E 09	2.29E 09 4.82E 08 4.27E 08	2.66E 10 1.69E 10 1.17E 10	9.71E 09 5.17E 09 3.04E 09	1.82E 10 1.16E 10 8.30E 09	6.60E 09 3.34E 09 1.94E 09
2.00 2.25 2.50	2.25 2.50 2.75	2.28E 10 2.17E 10	1.03E 09 9.74E 08	9.09E 09 8.68E 09	4.02E 08 3.80E 08	8.68E 09 6.84E 09	1.84E 09 1.17E 09	6.36E 09 5.19E 09	1.17E 09 7.45E 08
2.75 3.00	3.00 3.25	2.07E 10 1.98E 10 1.89E 10	9.54E 08 8.83E 08 8.62E 08	8.30E 09 7.93E 09 7.59E 09	3.72E 08 3.44E 08 3.36E 08	5.68E 09 4.91E 09 4.39E 09	7.63E 08 5.20E 08 3.79E 08	4.45E 09 3.95E 09 3.60E 09	4.98E 08 3.49E 08 2.65E 08
3.25 3.50 3.75	3.50 3.75 4.00	1.80E 10 1.72E 10 1.65E 10	8.06E 08 7.71E 08 7.35E 08	7.25E 09 6.94E 09 6.64E 09	3.16E 08 3.01E 08 2.86E 08	4.01E 09 3.73E 09 3.50E 09	2.86E 08 2.30E 08 1.93E 08	3.34E 09 3.13E 09 2.95E 09	2.08E 08 1.74E 08 1.51E 08
4.00 4.25 4.50	4.25 4.50 4.75	1.57E 10 1.50E 10 1.44E 10	6.94E 08 6.79E 08 6.43E 08	6.35E 09 6.08E 09 5.81E 09	2.74E 08 2.65E 08	3.31E 09 3.14E 09 2.98E 09	1.68E 08 1.53E 08 1.39E 08	2.80E 09 2.67E 09 2.54E 09	1.35E 08 1.26E 08 1.16E 08
4.75 5.00	5.00 5.25	1.37E 10 1.31E 10	6.03E 08 5.72E 08	5.56E 09 5.32E 09	2.51E 08 2.39E 08 2.23E 08	2.85E 09 2.72E 09	1.28E 08 1.18E 08	2.42E 09 2.32E 09	1.08E 08 9.99E 07
5.25 5.50 5.75	5.50 5.75 6.00	1.25E 10 1.20E 10 1.15E 10	5.67E 08 5.16E 08 5.31E 08	5.10E 09 4.88E 09 4.67E 09	2.24E 08 2.02E 08 2.09E 08	2.60E 09 2.48E 09 2.38E 09	1.17E 08 1.05E 08 1.08E 08	2.22E 09 2.12E 09 2.03E 09	9.92E 07 8.93E 07 9.20E 07
6.00 6.25	6.25 6.50 6.75	1.09E 10 1.05E 10	4.60E 08 4.60E 08	4.46E 09 4.28E 09	1.82E 08 1.81E 08	2.27E 09 2.18E 09	9.35E 07 9.29E 07	1.94E 09 1.86E 09	7.98E 07 7.95E 07
6.50 6.75 7.00	7.00	1.00E 10 9.55E 09 9.15E 09	4.60E 08 4.04E 08 9.15E 09	4.10E 09 3.92E 09 3.76E 09	1.81E 08 1.62E 08 3.76E 09	2.08E 09 1.99E 09 1.91E 09	9.26E 07 8.24E 07 1.91E 09		7.92E 07 7.05E 07 1.63E 09

TABLE 7 (CONT)

ORBIT ALTITUDE .. 1750 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1.MINUTES

	7.46E 12 6.48E 12 9.84E 11 8.48E 11 1.36E 11 1.16E 11 2.00E 10 1.04E 10 9.61E 09 1.62E 09 7.98E 09 3.54E 08 7.63E 09 3.34E 08 7.63E 09 3.09E 08 6.99E 09 2.89E 08	*E1 E1-E2  3.16E 13 2.73E 13 4.38E 12 3.69E 12 6.89E 11 5.30E 11 1.58E 11 1.00E 11 5.81E 10 2.62E 10 3.19E 10 1.22E 10 1.97E 10 6.70E 09 1.30E 10 3.87E 09 9.14E 09 2.29E 09	•E1 E1-E2
0.25	7.46E 12 6.48E 12 9.84E 11 8.48E 11 1.36E 11 1.16E 11 2.00E 10 1.04E 10 9.61E 09 1.62E 09 7.98E 09 3.54E 08 7.63E 09 3.34E 08 7.63E 09 3.09E 08 6.99E 09 2.89E 08	4.38E 12 3.69E 12 6.89E 11 5.30E 11 1.58E 11 1.00E 11 5.81E 10 2.62E 10 3.19E 10 1.22E 10 1.97E 10 6.70E 09 1.30E 10 3.87E 09 9.14E 09 2.29E 00	3.75E 12 3.18E 5.68E 11 4.50E 1.18E 11 7.95E 3.86E 10 1.79E 2.07E 10 7.76E 1.29E 10 4.10E 8.85E 09 2.37E
0.50	9.84E 11 8.48E 11 1.36E 11 1.16E 11 2.00E 10 1.04E 10 9.61E 09 1.62E 09 7.98E 09 3.54E 08 7.63E 09 3.09E 08 6.99E 09 2.89E 08	6.89E 11 5.30E 11 1.58E 11 1.00E 11 5.81E 10 2.62E 10 3.19E 10 1.22E 10 1.97E 10 6.70E 09 1.30E 10 3.87E 09 9.14E 09 2.29E 09	5.68E 11 4.50E 1.18E 11 7.95E 3.86E 10 1.79E 2.07E 10 7.76E 1.29E 10 4.10E 8.85E 09 2.37E
0.75	1.36E 11	1.58E 11 1.00E 11 5.81E 10 2.62E 10 3.19E 10 1.22E 10 1.97E 10 6.70E 09 1.30E 10 3.87E 09 9.14E 09 2.29E 09	5.68E 11 4.50E 1.18E 11 7.95E 3.86E 10 1.79E 2.07E 10 7.76E 1.29E 10 4.10E 8.85E 09 2.37E
1.00 1.25 5.88E 10 3.02E 10 1.25 1.50 2.86E 10 4.56E 09 1.50 1.75 2.40E 10 8.87E 08 1.75 2.00 2.31E 10 8.87E 08 2.00 2.25 2.22E 10 8.21E U8 2.25 2.50 2.14E 10 7.87E 08 2.50 2.75 2.06E 10 7.25E 08 3.00 3.25 1.91E 10 7.20E 08 3.25 3.50 1.84E 10 6.88E U8 3.25 3.50 1.84E 10 6.88E U8 3.50 3.75 1.77E 10 6.56E 08 3.75 4.00 1.70E 10 6.24E 08 4.00 4.25 1.64E 10 6.23E U8 4.25 4.50 1.58E 10 5.90E 08 4.75 5.00 1.46E 10 5.59E 08 5.00 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	2.00E 10 1.04E 10 9.61E 09 1.62E 09 7.98E 09 3.54E 08 7.63E 09 3.34E 08 7.30E 09 3.09E 08 6.99E 09 2.89E 08	5.81E 10 2.62E 10 3.19E 10 1.22E 10 1.97E 10 6.70E 09 1.30E 10 3.87E 09 9.14E 09 2.29E 09	3.86E 10 1.79E 2.07E 10 7.76E 1.29E 10 4.10E 8.85E 09 2.37E
1.25	7.63E 09 1.62E 09 7.98E 09 3.54E 08 7.63E 09 3.34E 08 7.30E 09 3.09E 08 6.99E 09 2.89E 08	3.19E 10 1.22E 10 1.97E 10 6.70E 09 1.30E 10 3.87E 09 9.14E 09 2.29E 09	2.07E 10 7.76E 1.29E 10 4.10E 8.85E 09 2.37E
1.50	7.98E 09 3.54E 08 7.63E 09 3.34E 08 7.30E 09 3.09E 08 6.99E 09 2.89E 08	1.97E 10 6.70E 09 1.30E 10 3.87E 09 9.14E 09 2.29E 09	1.29E 10 4.10E 8.85E 09 2.37E
1.75	7.63E 09 3.34E 08 7.30E 09 3.09E 08 6.99E 09 2.89E 08	1.30E 10 3.87E 09 9.14E 09 2.29E 09	8.85E 09 2.37E
2.00 2.25 2.22E 10 8.21E U8 2.25 2.50 2.14E 10 7.87E 08 2.50 2.75 2.06E 10 7.85E 08 2.75 3.00 1.98E 10 7.23E 08 3.25 3.50 1.91E 10 7.20E 08 3.25 3.50 1.84E 10 6.88E U8 3.50 3.75 1.77E 10 6.56E 08 3.75 4.00 1.70E 10 6.24E 08 4.00 4.25 1.64E 10 5.90E 08 4.50 4.75 1.52E 10 5.59E 08 4.50 4.75 1.52E 10 5.59E 08 4.75 5.00 1.46E 10 5.58E 08 5.00 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	7.30E 09 3.09E 08 6.99E 09 2.89E 08	9.14E 09 2.29E 09	
2.25 2.50 2.14E 10 7.87E 08 2.50 2.75 2.06E 10 7.85E 08 2.75 3.00 1.98E 10 7.20E 08 3.00 3.25 1.91E 10 7.20E 08 3.50 3.75 1.77E 10 6.56E 08 3.50 3.75 1.77E 10 6.56E 08 3.75 4.00 1.70E 10 6.24E 08 4.00 4.25 1.64E 10 6.23E 08 4.50 4.75 1.52E 10 5.59E 08 4.50 4.75 1.52E 10 5.59E 08 4.50 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	6.99E 09 2.89E 08		6.48E 09 1.40E
2.50		6-85E 09 1-41E 09	
2.75			5.08E 09 8.72E
3.00 3.25 1.91E 10 7.20E 08 3.25 3.50 1.84E 10 6.88E 08 3.50 3.75 1.77E 10 6.56E 08 3.75 4.00 1.70E 10 6.24E 08 4.00 4.25 1.64E 10 5.90E 08 4.50 4.75 1.52E 10 5.59E 08 4.50 4.75 1.52E 10 5.59E 08 5.00 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	6.70E 09 2.83E 08	5.44E 09 8.84E 08	4.20E 09 5.61E
3.25 3.50 1.84E 10 6.88E 08 3.50 3.75 1.77E 10 6.56E 08 3.75 4.00 1.70E 10 6.24E 08 4.00 4.25 1.64E 10 6.23E 08 4.50 4.75 1.52E 10 5.59E 08 4.50 4.75 1.52E 10 5.59E 08 5.00 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	6.41E 09 2.60E 08	4.55E 09 5.75E 08	3.64E 09 3.76E
3.50 3.75 1.77E 10 6.56E 08 3.75 4.00 1.70E 10 6.24E 08 4.00 4.25 1.64E 10 6.23E 08 4.25 4.50 1.58E 10 5.90E 08 4.50 4.75 1.52E 10 5.59E 08 4.75 5.00 1.46E 10 5.58E 08 5.00 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	6.15E 09 2.55E 08	3.98E 09 3.97E 08	3.27E 09 2.70E
3.75 4.00 1.70E 10 6.24E 08 4.00 4.25 1.64E 10 6.23E 08 4.25 4.50 1.58E 10 5.90E 08 4.50 4.75 1.52E 10 5.59E 08 4.75 5.00 1.46E 10 5.58E 08 5.00 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	5.90E 09 2.42E 08	3.58E 09 2.85E 08	3.00E 09 2.03E
4.00 4.25 1.64E 10 6.23E 08 4.25 4.50 1.58E 10 5.90E 08 4.50 4.75 1.52E 10 5.59E 08 4.75 5.00 1.46E 10 5.58E 08 5.00 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	5.66E 09 2.29E 08	3.30E 09 2.16E 08	2.79E 09 1.61E
4.25 4.50 1.58E 10 5.90E 08 4.50 4.75 1.52E 10 5.59E 08 4.75 5.00 1.46E 10 5.58E 08 5.00 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	5.43E 09 2.17E 08	3.08E 09 1.73E 08	2.63E 09 1.34E
4.50 4.75 1.52E 10 5.59E 08 4.75 5.00 1.46E 10 5.58E 08 5.00 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	5.21E 09 2.13E 08	2.91E 09 1.49E 08	2.50E 09 1.20E
4.75 5.00 1.46E 10 5.58E 08 5.00 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	5.00E 09 2.02E 08	2.76E 09 1.29E 08	2.38E 09 1.06E
5.00 5.25 1.41E 10 4.97E 08 5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	4.80E 09 1.91E 08	2.63E 09 1.15E 08	2.27E 09 9.66E
5.25 5.50 1.36E 10 5.24E 08 5.50 5.75 1.31E 10 4.64E 08	4.61E 09 1.87E 08	2.52E 09 1.08E 08	2.18E 09 9.20E
5.50 5.75 1.31E 10 4.64E 08	4.42E G9 1.69E 08	2.41E 09 9.51E 07	2.08E 09 8.17E
	4.25E U9 1.74E 08	2.31E 09 9.64E 07	2.00E 09 8.32E
5.75 6.00 1.26F 10 4.03F 08	4.08E 09 1.55E 08	2.22E 09 8.49E 07	1.92E 09 7.36E
30.3 0000 1.200 10 4.330 00	3.92E 09 1.63E 08	2.13E 09 8.83E 07	1.85E 09 7.68E
6.00 6.25 1.21E 10 4.32E 08	3.76E 09 1.43E 08	2.04E 09 7.73E 07	1.77E 09 6.72E
6.25 6.50 1.17E 10 4.31E 08	3.61E 09 1.42E 08	1.97E 09 7.63E 07	1.70E 09 6.65E
6.50 6.75 1.12E 10 4.30E 08	707F A1 T04FF 00	1.89E 09 7.57E 07	1.63E 09 6.60E
6.75 7.00 1.08E 10 3.99E 08		1.81E 09 7.00E 07	1.57E 09 6.08E

ORBIT ALTITUDE.. 2000 N MI TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ENE!	V	ORBITAI O Di	EG	30	L FLUX Deg	60	DEG		
El					E1-E2			*E1	E1-E2
0.	0.25	7.37E 13	6.44E 13	3.05E 13	2.67E 13	1.77E 13	1.52E 13	1.50E 13	1.29E 1
0.25	0.50	9.25E 12	8.08E 12	3.76E 12	3.29E 12	2.50E 12	2.04E 12	2.04E 12	1.70E 1
0.50	0.75	1.17E 12	1.02E 1?	4.71E 11	4.09E 11	4.57E 11	3.15E 11	3.43E 11	2.49E 1
0.75	1.00	1.55E 11	1.30E 11	6.18E 10	5.12E 10	1.41E 11	7.55E 10	9.35E 10	5.32E 1
1.00	1.25	2.43E 10	1.20E 10	1.06E 10	5.09E 09	6.59E 10	2.88E 10	4.03E 10	1.80E 1
1.25	1.50	1.23E 10	2.06E 09	5.55E 09	9.95E 08	3.71E 10	1.49E 10	2.23E 10	8.91E 0
1.50	1.75	1.02E 10	4.52E 08	4.56E 09	2.86E 08	2.22E 10	8.44E 09	1.34E 10	4.91E 0
1.75	2.00	9.78E 09	4.52E 08	4.27E 09	2.50E 08	1.38E 10	4.87E 09	8.48E 09	2.82E 0
2.00	2.25	9.33E 09	4.10E 08	4.02E 09	2.29E 0B	8.88E 09	2.86E 09	5.67E 09	1.66E 0
2.25	2.50	8.92E 09	3.89E 08	3.79E 09	1.99E 08	6.03E 09	1.72E 09	4.01E 09	1.00E 0
2.50	2.75	8.53E 09	3.81E 08	3.59E 09	1.87E 08	4.30E 09	1.05E 09	3.01E 09	6.21E 0
2.75	3.00	8.15E 09	3.53E 08	3.41E 09	1.70E 08	3.26E 09	6.57E 08	2.38E 09	3.97E 0
3.00	3.25	7.80E 09	3.44E 08	3.24E 09	1.61E 08	2.60E 09	4.24E 08	1.99E 09	2.65E 0
3.25	3.50	7.45E 09	3.27E 08	3.08E 09	1.50E 08	2.17E 09	2.83E 08	1.72E 09	1.84E 0
3.50	3.75	7.13E 09	3.08E 08	2.93E 09	1.39E 08	1.89E 09	1.97E 08	1.54E 09	1.34E 0
3.75	4.00	6.82E 09	2.92E 08	2.79E 09	1.30E 08	1.69E Q9	1.44E 08	1.40E 09	1.03E 0
4.00	4.25	6.53E 09	2.87E 08	2.66E 09	1.26E 08	1.55E 09	1.13E 0B	1.30E 09	8.44E 0
4.25	4.50	6.24E 09	2.68E Q8	2.53E 09	1.17E 08	1.44E 09	9.03E 07	1.22E 09	6.99E 0
4.50	4.75	5.97E 09	2.54E 08	2.41E 09	1.10E 08	1.35E 09	7.59E 07	1.15E 09	6.06E 0
4.75	5.00	5.72E 09	2.49E 08	2.30E 09	1.07E 08	1.27E 09	6.77E 07	1.09E 09	5.54E 0
5.00	5.25	5.47E 09	2.26E 08	2.20E 09	9.69E 07	1.20E 09	5.82E 07	1.03E 09	4.84E 0
5.25	5.50	5.24E 09	2.28E U8	2.10E 09	9.63E 07	1.15E 09	5.56E 07	9.83E 08	4.69E 0
5.50	5.75	5.01E 09	2.04E 08	2.00E 09	8.66E 07	1.09E 09	4.87E 07	9.36E 08	4.14E 0
5.75	6.00	4.81E 09	2.11E 08	1.92E 09	8.83E 07	1.04E 09	4.88E 07	8.95E 08	4.17E 0
6.00	6.25	4.60E 09	1.88E 08	1.83E 09	7.89E 07	9.92E 08	4.31E 07	8.53E 08	3.70E 0
6.25	6.50	4.41E 09	1.83E 08	1.75E 09	7.62E 07	9.49E 08	4.14E 07	8.16E 08	3.56E Q
6.50	6.75	4.23E 09	1.81E 08	1.67E 09	7.47E 07	9.08E 08	4.04E 07	7.80E 08	3.48E 0
6.75	7.00	4.05E 09	1.69E 08	1.60E 09	6.99E 07	8.67E 08	3.77E 07	7.46E 08	3.25E 0
7.00		3.88E 09	3.88E 09	1.53E 09	1.53E 09	8.30E 08	8.30E 08	7.13E 08	7.13E 0

#### ORBITAL INTEGRATION FOR PROJECTED 1968 ELECTRON ENVIRONMENT

ORBIT ALTITUDE .. 2250 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL. 1.MINUTES

ENEF ME\		ORBITA O D		30 1	DEG	60 1	L FLUX DEG	90 (	DEG
El	E2	*E1		=			£1-E2		
0.	0.25	3.62E 13	3.23E 13	1.39E 13	1.24E 13	9.08E 12	7.69E 12	7.47E 12	6.41E 1
0.25	0.50	3.89E 12	3.47E 12	1.54E 12	1.36E 12	1.39E 12	1.06E 12	1.06E 12	8.34E 1
0.50	0.75	4.18E 11	3.75E 11	1.75E 11	1.53E 11	3.33E 11	1.94E 11	2.26E 11	1.40E 1
0.75	1.00	4.39E 10	3.26E 10	2.16E 10	1.54E 10	1.39E 11	6.47E 10	8.60E 10	4.14E 1
1.00	1.25	1.13E 10	4.81E 09	6.14E 09	2.53E 09	7.39E 10	3.20E 10	4.45E 10	1.95E 1
1.25	1.50	6.46E 09	1.22E 09	3.61E 09	8.11E 08	4.19E 10	1.73E 10	2.50E 10	1.03E 1
1.50	1.75	5.24E 09	3.42E 08	2.80E 09	3.70E 08	2.46E 10	9.87E 09	1.46E 10	5.81E 0
1.75	2.00	4.90E 09	3.35E Q8	2.43E 09	2.73E 08	1.48E 10	5.67E 09	8.82E 09	3.32E 0
2.00	2.25	4.56E 09	3.03E 08	2.16E 09	2.37E 08	9.09E 09	3.33E 09	5.51E 09	1.94E 0
2.25	2.50	4.26E 09	2.76E 08	1.92E 09	1.80E 08	5.76E 09	2.00E 09	3.56E 09	1.16E 0
2.50	2.75	3.98E 09	2.62E 08	1.74E 09	1.53E 08	3.76E 09	1.20E 09	2.40E 09	7.04E 0
2.75	3.00	3.72E 09	2.46E 08	1.59E 09	1.31E 08	2.56E 09	7.44E 08	1.69E 09	4.40E 0
3.00	3.25	3.47E 09	2.29E 08	1.46E 09	1.14E 08	1.82E 09	4.66E 08	1.25E 09	2.80E 0
3.25	3.50	3.24E 09	2.16E 08	1.34E 09	1.01E 08	1.35E 09	2.99E 08	9.73E 08	1.84E 0
3.50	3.75	3.03E 09	1.99E 08	1.24E 09	8.95E 07	1.05E 09	1.97E 08	7.89E 08	1.25E 0
3.75	4.00	2.83E 09	1.86E 08	1.15E 09	8.06E 07	8.56E 08	1.34E 08	6.64E 08	8.82E 0
4.00	4.25	2.64E 09	1.77E 08	1.07E 09	7.43E 07	7.22E 08	9.62E 07	5.76E 08	6.59E 0
4.25	4.50	2.47E 09	1.61E 08	9.96E 08	6.63E 07	6.26E 08	7.02E 07	5.10E 08	5.00E 0
4.50	4.75	2.31E 09	1.52E 08	9.29E Q8	6.14E 07	5.56E 08	5.43E 07	4.60E 08	4.04E 0
4.75	5.00	2.15E 09	1.43E 08	8.68E Q8	5.72E 07	5.01E 08	4.40E 07	4.20E 08	3.40E 0
5.00	5.25	2.01E 09	1.35E 08	8.11E 08	5.25E 07	4.57E 08	3.64E 07	3.86E 08	2.91E 0
5.25	5.50	1.88E 09	1.22E 08	7.58E 08	4.82E 07	4.21E 08	3.11E 07	3.57E 08	2.53E (
5.50	5.75	1.75E 09	1.14E 08	7.10E 08	4.41E 07	3.90E 08	2.69E 07	3.32E 08	2.23E 0
5.75	6.00	1.64E 09	1.09E 08	6.66E 08	4.23E 07	3.63E 08	2.47E 07	3.09E 08	2.08E 0
6.00	6.25	1.53E 09	1.01E 08	6.24E 08	3.88E 07	3.38E 08	2.21E 07	2.88E 08	1.88E C
6.25	6.50	1.43E 09	9.27E 07	5.85E 08	3.57E 07	3.16E 08	1.99E 07	2.70E 08	1.70E C
6.50	6.75	1.34E 09	8.83E Q7	5.49E 08	3.39E 07	2.96E 08	1.87E 07	2.53E 08	1.60E C
6.75	7.00	1.25E 09	8.40E 07	5.15E Q8	3.20E 07	2.78E 08	1.74E 07	2.37E 08	1.50E C
7.00		1.16E 09	1.16E 09	4.83E 08	4.83E 08	2.60E 08	2.60E 08	2.22E 08	2.22E C

DRBIT ALTITUDE .. 2500 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1.MINUTES

 ENE!	1	0 D		30	L FLUX DEG	60 (	D€G	90 (	ŒG
 €1	E2		E1-E2		E1-E2			*E1	
 0.25 0.50 0.75 1.00 1.75 2.00 2.25 2.50 2.75 3.00 3.75 4.00 4.25 4.50 4.75 5.00 5.25 5.50	0.25 0.50 0.75 1.00 1.25 1.50 2.25 2.00 2.25 2.50 3.25 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.25 5.00 5.50 5.50 5.75	1.62E 13 1.70E 12 1.79E 11 1.85E 10 4.98E 09 2.93E 09 2.40E 09 2.23E 09 1.79E 09 1.79E 09 1.55E 09 1.55E 09 1.17E 09 1.17E 09 1.17E 09 1.17E 09 1.17E 09 1.17E 09 1.17E 09 1.17E 09 1.17E 09 1.9E 08 8.80E 08 8.80E 08 8.80E 08	1.45E 13 1.52E 12 1.61E 11 1.35E 10 2.05E 09 5.36E 08 1.70E 08 1.44E 08 1.63E 08 1.44E 08 1.63E 08 1.07E 08 1.16E 08 1.07E 08 1.16E 07 8.59E 07 8.59E 07 6.58E 07 6.58E 07 5.58E 07 5.517E 07	7.69E 12 8.19E 11 9.58E 10 1.52E 10 6.68E 09 4.19E 09 3.05E 09 1.89E 09 1.27E 09 1.27E 09 1.27E 09 1.27E 08 7.30E 08 6.53E 08 5.89E 08 5.89E 08 5.89E 08 4.45E 08 4.75E 08 3.75E 08	6.87E 12 7.24E 11 8.06E 10 8.54E 09 2.50E 09 1.14E 09 6.99E 08 4.59E 08 3.66E 08 1.89E 08 1.46E 08 1.15E 08 1.15E 08 7.64E 07 6.43E 07 5.52E 07 4.71E 07 4.71E 07 3.72E 07 3.72E 07 2.67E 07	6.02E 12 1.10E 12 3.32E 11 1.56E 11 8.52E 10 4.81E 10 2.80E 10 1.65E 10 9.92E 09 6.10E 09 3.83E 09 1.65E 09 1.65E 09 1.14E 09 8.16E 08 6.11E 08 4.76E 08 3.85E 08 3.22E 08 2.42E 08 2.42E 08 1.94E 08	4.91E 12 7.71E 11 1.76E 11 7.11E 10 3.72E 10 1.15E 10 6.55E 09 3.82E 09 9.227E 09 1.35E 08 9.11E 08 9.12E 08 9.13E 07 4.57E 07 3.44E 07 2.67E 07 1.78E 07	4.64E 12 7.69E 11 2.09E 11 9.32E 10 5.04E 10 1.66E 10 9.87E 09 3.76E 09 2.41E 09 1.60E 09 1.09E 09 1.09E 09 7.81E 08 3.63E 08 2.58E 08 2.58E 08 2.00E 08 1.80E 08 1.63E 08	3.87E 12 5.60E 11 1.16E 11 4.28E 10 2.19E 10 1.18E 10 6.74E 09 3.85E 09 2.26E 09 1.35E 09 8.13E 08 5.02E 08 3.14E 08 1.30E 08 1.30E 08 8.76E 07 6.11E 07 4.35E 07 2.54E 07 2.54E 07 1.68E 07 1.42E 07
5.75 6.00 6.25 6.50 6.75 7.00	6.00 6.25 6.50 6.75 7.00	7.12E 08 6.63E 08 6.17E 08 5.75E 08 5.36E 08 4.99E 08	4.88E 07 4.57E 07 4.16E 07 3.93E 07 3.70E 07 4.99E 08	3.18E 08 2.94E 08 2.71E 08 2.51E 08 2.33E 08 2.15E 08	2.44E 07 2.25E 07 2.02E 07 1.86E 07 1.73E 07 2.15E 08	1.76E 08 1.61E 08 1.47E 08 1.36E 08 1.25E 08 1.16E 08	1.52E 07 1.34E 07 1.16E 07 1.05E 07 9.57E 06 1.16E 08	1.49E 08 1.37E 08 1.26E 08 1.16E 08 1.07E 08 9.90E 07	1.24E 07 1.10E 07 9.69E 06 8.79E 06 8.09E 06 9.90E 07

#### ORBITAL INTEGRATION FOR PROJECTED 1968 ELECTRON ENVIRONMENT

DRBIT ALTITUDE .. 2750 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1.MINUTES

ENEF ME\		ORBITA O D		ORBITAL FLUX 30 DEG		ORBITAL FLUX 60 DEG		ORBITAI 90 I	
E1	E2	*£1	E1-E2	+E1	E1-E2	*E1	E1-E2	*E1	E1-E2
0.	0.25	1.11E 13	9.98E 12	5.52E 12	4.93E 12	5.01E 12	3.97E 12	3.73E 12	3.03E 12
0.25	0.50	1.10E 12	9.94E 11	5.94E 11	5.13E 11	1.04E 12	6.93E 11	7.02E 11	4.84E 11
0.50	0.75	1.10E 11	9.88E 10	8.10E 10	6.14E 10	3.49E 11	1.78E 11	2.18E 11	1.14E 11
0.75	1.00	1.08E 10	7.46E 09	1.97E 10	8.79E 09	1.71E 11	7.72E 10	1.04E 11	4.68E 10
1.00	1.25	3.36E 09	1.22E 09	1.09E 10	3.91E 09	9.42E 10	4.10E 10	5.68E 10	2.46E 10
1.25	1.50	2.14E 09	3.53E Q8	6.96E 09	2.085 09	5.33E 10	2.23E 10	3.22E 10	1.33E 10
1.50	1.75	1.78E 09	1.55E 08	4.88E 09	1.42E 09	3.10E 10	1.28E 10	1.89E 10	7.67E 09
1.75	2.00	1.63E 09	1.02E 08	3.46E 09	9.02E 08	1.82E 10	7.28E 09	1.12E 10	4.40E 09
2.00	2.25	1.53E 09	1.60E 08	2.56E 09	6.66E 08	1.09E 10	4.26E 09	6.83E 09	2.60E 09
2.25	2.50	1.37E 09	1.08E 08	1.89E 09	4.40E 08	6.67E 09	2.53E 09	4.23E 09	1.56E 09
2.50	2.75	1.26E 09	9.59E 07	1.45E 09	3.12E 08	4.14E 09	1.51E 09	2.67E 09	9.40E 08
2.75	3.00	1.16E 09	9.41E 07	1.14E 09	2.25E 08	2.63E 09	9.23E 08	1.73E 09	5.81E 00
3.00	3.25	1.07E 09	8.42E 07	9.13E 08	1.65E 08	1.71E 09	5.68E 08	1.15E 09	3.62E 08
3.25	3.50	9.84E 08	7.65E 07	7.48E 08	1.23E 08	1.14E 09	3.54E 08	7.84E 08	2.29E 08
3.50	3.75	9.08E 08	7.07E 07	6.25E Q8	9.43E 07	7.85E 08	2.25E 08	5.55E Q8	1.48E 06
3.75	4.00	8.37E 08	6.55E 07	5.31E 08	7.37E 07		1.46E 08	4.07E 08	9.77E 07
4.00	4.25	7.71E 08	5.96E 07	4.57E 08	5.88E 07		9.68E 07	3.10E 08	6.62E 07
4.25	4.50	7.12E 08	5.47E 07	3.98E 08	4.76E 07	3.16E 08	6.54E 07	2.43E 08	4.58E 07
4.50	4.75	6.57E 08	5.10E 07	3.51E 08	3.97E 07	2.51E 08	4.58E 07	1.98E 08	3.29E 07
4.75	5.00	6.06E 08	4.73E 07	3.11E 08	3.35E 07	2.05E 08	3.31E 07	1.65€ 08	2.44E 07
5.00	5.25	5.59E 08	4.27E 07	2.78E 08	2.83E 07	1.72E 08	2.45E 07	1.40E 08	1.85E 07
5.25	5.50	5.16E 08	4.02E 07	2.49E U8	2.48E 07	1.48E 08	1.90E 07	1.22E 08	1.47E 07
5.50	5.75	4.76E 08	3.67E 07	2.25E 08	2.15E 07	1.29E 08	1.50E 07	1.07E 08	1.19E 07
5.75	6.00	4.39E 08	3.32E 07	2.03E Q8	1.87E 07	1.14E 08	1.22E 07	9.51E 07	9.77E 0
6.00	6.25	4.06E 08	3.20E 07	1.84E 08	1.71E 07	1.01E 08	1.04E 07	8.54E 07	8.51E 06
6.25	6.50	3.74E 08	2.86E 07	1.67E 08	1.49E 07	9.09E 07	8.75E 06	7.69E 07	7.21E 0
6-50	6.75	3.45E 08	2.62E 07	1.52E 08	1.32E 07	8.22E 07	7.51E 06	6.96E 07	6.25E 06
6.75 7.00	7.00	3.19E 08	2.41E 07	1.39E 08	1.20E 07	7.47E 07	6.67E 06	6.34E 07	5.58E Q

ORBIT ALTITUDE .. 3000 N MI

TOTAL TIME.. 24.HOURS TIME INTERVAL.. 1.MINUTES

ME	1	0 D	EG	30 1	DEG	60	L FLUX DEG	90	DEG
Εl			E1-E2		E1-E2		E1-E2		
0.	0.25	8.87E 12			4.35E 12		3.80E 12		2.70E 12
0.25	0.50	8.59E 11	7.76E 11	5.61E 11	4.66E 11	1.10E 12	7.12E 11		
0.50	0.75	8.31E 10	7.50E 10	9.51E 10			1.95E 11	2.14E 11	1.08E 1
0.75	1.00	8.13E 09	5.39E 09	3.14E 10	1.25E 10		8.71E 10	1.06E 11	4.60E 10
1.00	1.25	2.74E 09	9.18E 08	1.89E 10	6.77E 09		4.65E 10	5.97E 10	2.51E 10
1.25	1.50	1.82E 09	2.75E 08	1.21E 10	3.76E 09		2.53E 10	3.46E 10	1.39E 10
1.50	1.75	1.55E 09	1.52E 08	8.37E 09	2.68E 09	3.52E 10	1.45E 10	2.07E 10	8.24E 09
1.75	2.00	1.40E 09	1.16E 08	5.70E 09	1.69E 09	2.07E 10	8.28E 09	1.24E 10	4.80E 09
2.00	2.25	1.28E 09	1.38E 08	4.01E 09	1.18E 09	1.24E 10	4.85E 09	7.64E 09	2.88E 09
2.25	2.50	1.14E 09	1.06E 08	2.83E G9	7.81E 08	7.55E 09	2.88E 09	4.76E 09	1.75E 0
2.50	2.75	1.04E 09	9.44E 07	2.05E 09	5.37E 08	4.67E 09	1.72E 09	3.01E 09	1.07E 0
2.75	3.00	9.42E 08	8.82E 07	1.51E 09	3.71E 08	2.94E 09	1.05E 09	1.95E 09	6.64E 0
3.00	3.25	8.54E 08	7.79E 07	1.14E 09	2.61E 08	1.89E 09	6.48E 08	1.28€ 09	4.17E 0
3.25	3.50	7.76E 08	6.91E 07	8.81E 08	1.86E 08	1.24E 09	4.03E 08	8.64E 08	2.65E 0
3.50	3.75	7.07E 08	6.37E 07	6.95E 08	1.36E 08	8.40E 08	2.57E 08	5.99E 08	1.72E 0
3.75	4.00	6.43E 08	5.76E 07	5.59E 08	1.01E 08		1.65E 08	4.27E 08	1.13E 0
4-00	4.25	5.85E 08	5.22E 07	4.57E 08	7.69E-07		1.09E 08	3.14E 08	7.62E 0
4.25	4.50	5.33E 08	4.70E 07	3.8QE 08	5.92E 07		7.31E 07	2.38E 08	5.21E 0
4.50	4.75	4.86E 08	4.30E 07	3.21E 08	4.69E 07	2.36E 08		1.86E 08	3.68E 0
4.75	5.00	4.43E Q8	3.92E 07	2.74E 08	3.77E 07	1.86E 08		1.49E 08	2.67E Q
5.00	5.25	4.04E 08	3.53E 07	2.37E 08	3.06E 07	1.50E 08	2.59E 07	1.22E 08	1.98E 0
5.25	5.50	3.68E 08	3.24E 07	2.06E 08	2.57E 07	1.24E 08	1.96E 07	1.03E 08	1.53E 0
5.50	5.75	3.36E 08	2.93E 07	1.80E 08	2.14E 07	1.04E 08	1.50E 07	8.73E 07	1.19E 0
5.75	6.00	3.07E 08	2.62E 07	1.59E 08	1.80E 07	8.94E 07	1.18E 07	7.54E 07	9.52E 0
6.00	6.25	2.81E 08	2.47E 07	1.41E 08	1.58E 07	7.76E 07	9.75E 06	6.59E 07	8.01E 0
6.25	6.50	2.56E 08	2.19E 07	1.25E 08	1.35E 07		7.98E 06	5.79E 07	6.62E 0
6.50	6.75	2.34E 08	1.96E 07	1.12E 08		5.99E 07		5.12E 07	5.51E 0
6.75	7.00	2.14E 08	1.83E 07	1.00E 08		5.33E 07		4.57E 07	4.86E 0
7.00		1.96E 08	1.96E 08	8.97E 07	8.97E 07	4.75E 07	4.75E 07	4.09E 07	4.09E 0

# ORBITAL INTEGRATION FOR PROJECTED 1968 ELECTRON ENVIRONMENT

URBIT ALTITUDE .. 3500 N MI

TOTAL TIME.. 24.HOURS

TIME INTERVAL.. 1.MINUTES

ENEF ME	RGY /	ORBITA O D			DEG	60		90	DEG
E 1	E2	•E1			E1-E2		E1-E2		E1-E2
0.	0.25	7.87E 12	7.14E 12	5.09E 12	4.37E 12	5.13E 12	3.89E 12		
0.25	0.50	7.29E 11	6.57E 11	7.19E 11	5.39E 11	1.24E 12	7.85E 11	7.55E 11	4.89E 11
0.50	0.75	7-21E 10	6.45E 10	1.80E 11	1.00E 11	4.51E 11	2.26E 11	2.66E 11	1.32E 11
0.75	1.00	7.56E 09	4.40E 09	8.03E 10	3.05E 10	2.25E 11	1.01E 11	1.34E 11	5.74E 10
1.00	1.25	3.16E 09	9.52E 08	4.98E 10	1.81E 10	1.25E 11	5.38E 10	7.62E 10	3.17E 10
1.25	1.50	2.21E 09	2.42E 08	3.17E 10	1.05E 10	7.09E 10	2.92E 10	4.45E 10	1.76E 10
1.50	1.75	1.97E 09	2.75E 08	2.12E 10	7.25E 09	4.17E 10	1.70E 10	2.69E 10	1.06E 10
1.75	2.00	1.69E 09	2.18E U8	1.40E 10	4.59E 09	2.48E 10	9.73E 09	1.63E 10	6.20E 09
2.00	2.25	1.48E 09	1.87E 08	9.39E 09	3.03E 09	1.50E 10	5.78E 09	1.01E 10	3.76E 09
2.25	2.50	1.29E 09	1.58E U8	6.35E 09	1.99E 09	9.26E 09	3.47E 09	6.32E 09	2.30E 09
2.50	2.75	1.13E 09	1.39E 08	4.36E 09	1.32E 09	5.78E 09	2.11E 09	4.02E 09	1.42E 09
2.75	3.00	9.91E 08	1.21E 08	3.03E 09	8.86E 08	3.68E 09	1.30E 09	2.60E 09	8.91E 08
3.00	3.25	8.70E 08	1.06E 08	2.15E 09	6.01E 08	2.38E 09	8.13E 08	1.71E 09	5.65E 08
3.25	3.50	7.64E 08	9.23E 07	1.55E 09	4.12E 08	1.57E 09	5.13E 08	1.14E 09	3.62E 08
3.50	3.75	6.72E 08	8.18E 07	1.14E 09	2.87E 08	1.05E 09	3.30E 08	7.80E 08	2.36E 08
3.75	4.00	5.90E 08	7.14E 07	8.49E 08	2.03E 08	7.22E 08	2.15E 08	5.44E Q8	1.56E 08
4.00	4.25	5.19E 08	6.31E 07	6.47E 08	1.46E 08	5.07E 08	1.43E 08	3.88E 08	1.05E 08
4.25	4.50	4.55E 08	5.50E 07	5.01E 08	1.06E 08	3.64E 08	9.62E 07	2.83E 08	7.17E 07
4.50	4.75	4.00E 08	4.86E 07	3.95E 08	7.92E 07	2.68E 08	6.62E 07	2.11E 08	5.01E 07
4.75	5.00	3.52E 08	4.26E 07	3.16E 08	5.98E 07	2.02E 08	4.65E 07	1.61E 08	3.57E 07
5.00	5.25	3.09E 08	3.75E 07	2.56E Q8	4.59E 07	1.55E 08	3.33E 07	1.25E 08	2.59E 07
5.25	5.50	2.72E 08	3.31E 07	Z-10E 08	3.64E 07	1.22E 08	2.46E 07	9.91E 07	1.94E 07
5.50	5.75	2.39E 08	2.88E 07	1.74E 08	2.86E 07	9.72E 07	1.83E 07	7.97E 07	1.46E 07
5.75	6.00	2.10E 08	2.51E 07	1.45E 08	2.28E 07	7.88E 07	1.39E 07	6.51E 07	1.12E 07
6.00	6.25	1.85E 08	2.26E 07	1.22E 08	1.89E 07	6.49E 07	1.10E 07	5.38E 07	8.96E 06
6.25	6.50	1.62E 08	1.97E 07	1.03E 08	1.56E 07	5.39E 07	8.76E 06	4.49E 07	7.17E 06
6.50	6.75	1.42E 08	1.67E 07	8.75E 07	1.26E 07	4.51E 07	6.88E 06	3.77E 07	5.66E 06
6.75	7.00	1.26E 08	1.55E 07	7.50E 07	1.09E 07	3.82E 07	5.79E 06	3.20E 07	4.80E 06
7.00		1.10E 08	1.10E 08	6.41E 07	6.41E 07	3.24E 07	3.24E 07		2.72E 07

URBIT ALTITUDE..4000 N MI TOTAL TIME.. 48.HOURS TIME INTERVAL.. 2.MINUTES

ENE ME	٧	0 D	€G	30	L FLUX DEG	60 1	DEG	90 (	
El	E2	*E1			E1-E2			*E1	
0.	0.25	9.08E 12		5.87E 12	4.79E 12	5.62E 12			2.97E 12
0.25	0.50	8.44E 11		1.07E 12	7.35E 11	1.42E 12	8.92E 11		5.74E 11
0.50	0.75	1.07E 11	9.28E 10	3.37E 11	1.75E 11	5.27E 11	2.65E 11	3.29E 11	1.63E 11
0.75	1.00	1.44E 10		1.62E 11	6.24E 10	2.62E 11	1.16E 11	1.66E 11	7.06E 10
1.00	1.25	6.35E 09		9.97E 10	3.71E 10	1.46E 11	6.24E 10		3.94E 10
1.25	1.50	4.29E 09	3.96E 08	6.25E 10	2.15E 10	8.35E 10	3.38E 10	5.64E 10	2.19E 10
1.50	1.75	3.89E 09		4.10E 10	1.44E 10	4.97E 10	1.99E 10		1.34E 10
1.75	2.00	3.17E 09	5.13E 08	2.67E 10	8.95E 09	2.98E 10	1.15E 10	2.11E 10	7.89E 09
2.00	2.25	2.66E 09	4.05E 08	1.77E 10	5.93E 09	1.83E 10	6.92E 09	1.32E 10	4.86E 09
2.25	2.50	2.25E Q9	3.13E 08	1.18E 10	3.82E 09	1.14E 10	4.19E 09	8.37E 09	2.99E 09
2.50	2.75	1.94E 09	2.71E 08	7.95E Q9	2.51E 09	7.23E 09	2.58E 09	5.37E 09	1.87E 09
2.75	3.00	1.67E 09	2.30E 08	5.44E 09	1.67E 09	4.66E 09	1.61E 09	3.50E 09	1.18E 09
3.00	3.25	1.44E 09	1.99E 08	3.77E 09	1.12E 09	3.05E 09	1.02E 09	2.32E 09	7.59E 08
3.25	3.50	1.24E 09	1.72E 08	2.65E 09	7.57E 08	2.02E 09	6.53E 08	1.56E 09	4.91E 08
3.50	3.75	1.06E 09	1.47E 08	1.89E 09	5.20E 08	1.37E 09	4.26E 08	1.07E 09	3.24E 08
3.75	4.00	9.17E 08	1.28E 08	1.37E 09	3.62E 08	9.45E 08	2.81E 08	7.46E 08	2.16E 08
4.00	4.25	7.89E 08	1.10E 08	1.01E 09	2.55E 08	6.64E 08	1.89E 08	5.30E 08	1.47E Q8
4-25	4.50	6.79E 08	9.42E 07	7.56E 08	1.82E 08	4.75E 08	1.28E 08	3.83E 08	1.00E 08
4.50	4.75	5.85E 08	8.09E 07	5.74E 08	1.32E 08	3.47E 08	8.88E 07	2.83E 08	7.03E 07
4.75	5.00	5-04E 08	7.02E 07	4.42E 08	9.70E 07	2.58E 08	6.26E 07	2.13E 08	5.00E 07
5.00	5.25	4.34E 08	5.97E 07	3.45E 08	7.20E 07	1.96E 08	4.47E 07	1.62E 08	3.61E 07
5.25	5.50	3.74E 08	5.24E 07	2.73E 08	5.53E 07	1.51E 08	3.31E 07	1.26E 08	2.69E 07
5.50	5.75	3.22E 08	4.49E 07	2.18E 08	4.21E 07	1.18E 08	2.44E 07	9.95E 07	2.01E 07
5.75	6.00	2.77E 08	3.77E 07	1.75E 08	3.24E 07	9.37E 07	1.83E 07	7.94E 07	1.51E 07
6.00	6.25	2.39E 08	3.34E 07	1.43E 08	2.59E 07	7.54E 07	1.42E 07	6.42E 07	1.19E 07
6.25	6.50	2.06E 08	2.91E 07	1-17E 08	2.07E 07	6.12E 07	1.12E 07	5.23E 07	9.40E 06
6.50	6.75	1.77E 08	2.39E 07	9.65E 07	1.61E 07	5.00E 07	8.59E 06	4.29E 07	7.26E 06
6.75	7.00	1.53E 08	2.16E 07	8.03E 07	1.34E 07	4.14E 07	7.06E 06	3.57E 07	6.01E 06
7.00		1.31E 08	1.31E 08	6.69E 07	6.69E 07	3.43E 07	3.43E 07		2.97E 07
					010/2 01	30 73L UI		••	

TABLE 7 (CONT)

ORBIT ALTITUDE .. 4500 N MI

TOTAL TIME.. 48.HOURS

TIME INTERVAL.. 2.MINUTES

ENE!		ORBITA O D		ORBITA 30		ORBITA 60		ORBITA 90	DEG
£1	E2	•E1			E1-E2	_		*E1	E1-E2
0.	0.25	9.35E 12	8.25E 12	6.01E 12	4.50E 12	5.60E 12	4.00E 12	3.90E 12	2.82E 1
0.25	0.50	1.10E 12	9.07E 11	1.51E 12	9.64E 11	1.60E 12	9.88E 11	1.07E 12	6.63E
0.50	0.75	1.94E 11	1.53E 11	5.43E 11	2.73E 11	6.13E 11	3.07E 11	4-10E 11	2.02E 1
0.75	1.00	4.12E 10	2-13E 10	2.70E 11	1.05E 11	3.06E 11	1.34E 11	2.08E 11	8.74E 1
1.00	1.25	1.99E 10	6.94E 09	1.65E 11	6.21E 10	1.72E 11	7.23E 10	1.20E 11	4.90E 1
1.25	1.50	1.29E 10	2.92E 09	1.03E 11	3.62E 10	9.95E 10	3-94E 10	7.13E 10	2.74E 1
1.50	1.75	1.00E 10	2.21E 09	6.68E 10	2.36E 10	6.01E 10	2.35E 10	4.39E 10	1-68E 1
1.75	2.00	7.80E 09	1.65E 09	4.32E 10	1.47E 10	3.66E 10	1.37E 10	2.71E 10	9.97E (
2.00	2.25	6.15E 09	1.26E 09	2.85E 10	9.70E 09	2.29E 10	8.45E 09	1.72E 10	6.24E 0
2.25	2.50	4.88E 09	9.64E 08	1.88E 10	6.23E 09	1.44E 10	5.18E 09	1.09E 10	3.87E (
2.50	2.75	3.92E 09	7.62E 08	1.26E 10	4.08E 09	9.22E 09	3.23E 09	7.07E 09	2.44E (
2.75	3.00	3.16E 09	5.99E 08	8.50E 09	2.69E 09	5.99E 09	2.05E 09	4.63E 09	1.56E 0
3.00	3.25	2.56E 09	4.85E U8	5.80E 09	1.80E 09	3.94E 09	1.32E 09	3.07E 09	1.01E C
3.25	3.50	2.07E 09	3.84E 08	4.00E 09	1.21E 09	2.62E 09	8.50E 08	2.06E 09	6.58E (
3.50	3.75	1.69E 09	3.08E 08	2.80E 09	8.22E 08	1.77E 09	5.59E 08	1.41E 09	4.36E (
3.75	4-00	1.38E 09	2.49E 08	1.97E 09	5.65E 08	1.21E 09	3.71E 08	9.70E 08	2.92E 0
4.00	4.25	1.13E 09	2.01E 08	1.41E 09	3.92E 08	8.43E 08	2.50E 08	6.79E 08	1.98E 0
4.25	4.50	9.33E 08	1.62E 08	1.02E 09	2.74E 08	5.92E 08	1.70E 08	4.81E 08	1.35E 0
4.50	4.75	7.71E 08	1.32E 08	7.43E 08	1.95E 08	4.23E 08	1.17E 08	3.46E 08	9.40E 0
4.75	5.00	6.39E 08	1.08E 08	5.48E 08	1.39E 08	3.05E 08	8.16E 07	2.52E 08	6.59E (
5-00	5.25	5.31E Q8	8.75E 07	4.09E 08	1.00E 08	2.24E 08	5.74E 07	1.86E 08	4.67E (
5.25	5.50	4.44E 08	7.35E 07	3.09E 08	7.43E 07	1.66E 08	4.16E 07	1.39E 08	3.41E (
5.50	5.75	3.70E 08	6.02E 07	2.35E Q8	5.44E 07	1.25E 08	2.99E 07	1.05E 08	2.47E (
5.75	6.00	3.10E 08	4.89E 07	1.81E Q8	4.04E 07	9.49E 07	2.18E 07	8.05E 07	1.81E C
6.00	6.25	2.61E 08	4.15E 07	1.40E DB	3.07E 07	7.31E 07	1.63E 07	6.23E 07	1.37E (
6.25	6.50	2.19E 08	3.49E 07	1.10E 08	2.34E 07	5.67E 07	1.23E 07	4.87E 07	1.04E
6.50	6.75	1.85E 08	2.80E 07	8.64E 07	1.76E 07	4.44E 07	9.17E 06	3.83E 07	7.76E (
6.75	7.00	1.57E 08	2.44E 07	6.88E 07	1.38E 07	3.52E 07	7.14E 06	3.05E 07	6.08E (

URBIT ALTITUDE..5000 N MI

TOTAL TIME.. 48.HOURS

TIME INTERVAL.. 2.MINUTES

ENE!	1	ORBITAI O Di		30 1	DEG	60		90	DEG
Εl		*E1					E1-E2		E1-E2
0.	0.25	4.58E 12	3.29E 12	5.96E 12	3.94E 12	5.41E 12	3.62E 12		
0.25	0.50	1.28E 12	9.24E 11	2.02E 12	1.22E 12	1.79E 12	1.08E 12	1.25E 12	7.48E 1
0.50	0.75	3.59E 11	2.48E 11	8.01E 11	3.90E 11	7.09E 11	3.53E 11	4.98E 11	2.43E 1
0.75	1.00	1.11E 11	5.32E 10	4.12E 11	1.60E 11	3.57E 11	1.54E 11	2.55E 11	1.06E 1
1.00	1.25	5.75E 10	2.11E 10	2.51E 11	9.59E 10	2.03E 11	8.43E 10	1.49E 11	6.02E 1
1.25	1.50	3.64E 10	1.08E 10	1.55E 11	5.55E 10	1.18E 11	4.62E 10	8.86E 10	3.38E 1
1.50	1.75	2.57E 10	6.47E 09	1.00E 11	3.57E 10	7.21E 10	2.78E 10	5.49E 10	2.07E 1
1.75	2.00	1.92E 10	4.67E 09	6.43E 10	2.19E 10	4.43E 10	1.64E 10	3.41E 10	1.24E 1
2.00	2.25	1.45E 10	3.66E 09	4.24E 10	1.47E 10	2.79E 10	1.02E 10	2.18E 10	7.86E 0
2.25	2.50	1.09E 10	2.63E 09	2.77E 10	9.26E 09	1.77E 10	6.30E 09	1.39E 10	4.88E 0
2.50	2.75	8.24E 09	1.99E 09	1.84E 10	6.06E 09	1.14E 10	3.97E 09	9.02E 09	3.10E 0
2.75	3.00	6.25E 09	1.50E 09	1.24E 10	3.99E 09	7.44E 09	2.54E 09	5.92E 09	2.00E 0
3.00	3.25	4.75E 09	1.16E 09	8.38E 09	2.66E 09	4.90E 09	1.64E 09	3.92E 09	1.30E 0
3.25	3.50	3.60E 09	8.68E 08	5.72E 09	1.78E 09	3.26E 09	1.07E 09	2.63E 09	8.50E O
3.50	3.75	2.73E 09	6.59E 08	3.94E 09	1.21E 09	2.19E 09	7.05E 08	1.78E 09	5.64E 0
3.75	4.00	2.07E 09	5.01E 08	2.74E 09	8.23E 08	1.49E 09	4.69E 08	1.21E 09	3.77E 0
4.00	4.25	1.57E 09	3.79E 08	1.91E 09	5.67E 08	1.02E 09	3.16E 08	8.34E 08	2.55E Ø
4.25	4.50	1.19E 09	2.86E 08	1.35E 09	3.91E 08	7.06E 08	2.13E 08	5.79E 08	1.73E 0
4.50	4.75	9.03E 08	2.19E 08	9.54E 08	2.74E 08	4.92E 08	1.47E 08	4.05E 08	1.20E 0
4.75	5.00	6.84E 08	1.64E 08	6.80E 08	1.92E 08	3.46E Q8	1.01E 08	2.85E 08	8.26E 0
5.00	5.25	5.19E 08	1.24E 08	4.88E 08	1.35E 08	2.45E 08	7.00E 07	2.03E 08	5.75E Q
5.25	5.50	3.96E 08	9.65E 07	3.53E 08	9.77E 07	1.75E 08	4.97E 07	1.45E Q8	4.10E 0
5.50	5.75	2.99E 08	7.20E 07	2.55E 08	6.93E 07	1.25E 08	3.48E 07	1.04E 08	2.88E 0
5.75	6.00	2.27E 08	5.48E 07	1.86E 08	5.00E 07	9.04E 07	2.48E 07	7.55E 07	2.06E 0
6.00	6.25	1.72E 08	4.17E 07	1.36E 08	3.62E 07	6.56E 07	1.78E 07	5.49E 07	1.48E 0
6.25	6.50	1.31E 08	3.16E 07	9.94E 07	2.63E 07	4.77E 07	1.28E 07	4-00E 07	1.07E 0
6.50	6.75	9.91E 07	2.40E 07	7.31E 07	1.92E 07	3.49E 07	9.26E 06	2.93E 07	7.75E 0
6.75	7.00	7.52E 07	1.79E 07	5.39E 07	1.40E 07	2.56E 07		2.16E 07	5.62E 0
7.00		5.73E 07	5.73E 07	3.99E 07	3.99E 07	1.89E 07	1.89E 07	1.60E 07	1.60E 0

# ORBITAL INTEGRATION FOR PROJECTED 1968 ELECTRON ENVIRONMENT

ORBIT ALTITUDE .. 5500 N MI

TOTAL TIME.. 48.HOURS

TIME INTERVAL.. 2.MINUTES

ENE!	v	O D	EG	30	L FLUX DEG	60 1	DEG	90 (	
£1	E2	*E1			E1-E2				E1-E2
0.25 0.50 0.75 1.00 1.25 1.50 2.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00	0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 3.00 3.25 3.50 3.75 4.00 4.25 4.50	4.95E 12 1.74E 12 5.95E 11 2.40E 11 1.40E 11 8.61E 10 5.79E 10 4.06E 10 3.02E 10 2.11E 10 1.57E 10 1.17E 10 8.68E 09 6.45E 09 4.81E 09 3.58E 09 2.67E 09 1.98E 09	3.21E 12 1.14E 12 3.55E 11 9.94E 10 5.42E 10 2.82E 10 1.73E 10 1.04E 10 9.12E 09 5.43E 09 4.03E 09 2.99E 09 2.22E 09 1.65E 09 1.23E 09 9.12E 09 9.12E 09	7.17E 12 2.54E 12 1.06E 12 5.68E 11 3.51E 11 2.17E 11 1.40E 11 8.90E 10 5.84E 10 3.78E 10 2.50E 10 1.66E 10 1.11E 10 7.49E 09 5.08E 09 3.47E 09 2.39E 09 2.39E 09	4.63E 12 1.48E 12 4.93E 11 2.17E 11 1.34E 11 7.76E 10 5.05E 10 3.06E 10 1.29E 10 8.39E 09 5.49E 09 2.40E 09 1.61E 09 7.37E 08 5.01E 08	5.76E 12 1.97E 12 8.02E 11 4.14E 11 1.42E 11 8.75E 10 5.42E 10 3.45E 10 2.19E 10 1.42E 10 9.25E 09 6.10E 09 4.06E 09 2.73E 09 1.84E 09 1.84E 09 8.64E 08	3.79E 12 1.17E 12 3.88E 11 1.74E 11 9.83E 10 5.45E 10 3.34E 10 1.97E 10 1.26E 10 7.73E 09 4.91E 09 3.15E 09 2.04E 09 1.33E 09 8.81E 08 5.86E 08 3.94E 08 2.66E 08	4.17E 12 1.45E 12 5.98E 11 3.14E 11 1.86E 10 4.35E 10 2.79E 10 1.78E 10 1.16E 10 7.60E 09 5.03E 09 3.36E 09 2.27E 09 1.54E 09 1.05E 09 7.26E 08	2.73E 12 8.51E 11 2.83E 11 1.28E 11 7.46E 10 4.20E 10 2.62E 10 1.56E 10 1.01E 10 6.22E 09 3.97E 09 2.57E 09 1.67E 09 1.10E 09 7.27E 08 4.85E 08 3.28E 08 2.22E 08
4.50 4.75 5.00 5.25 5.50 5.75 6.00 6.25 6.50 6.75 7.00	4.75 5.00 5.25 5.50 5.75 6.00 6.25 6.50 6.75 7.00	1.48E 09 1.11E 09 8.24E 08 6.17E 08 4.59E 08 3.43E 08 2.56E 08 1.91E 08 1.43E 08 1.07E 08 8.00E 07	3.75E 08 2.81E 08 2.08E 08 1.58E 08 1.16E 08 8.67E 07 6.49E 07 4.83E 07 3.60E 07 2.70E 07 8.00E 07	1.15E 09 8.05E 08 5.67E 08 4.02E 08 2.85E 08 2.04E 08 1.46E 08 1.05E 08 7.62E 07 5.53E 07 4.03E 07	3.45E 08 2.38E 08 1.65E 08 1.17E 08 8.14E 07 5.76E 07 4.10E 07 2.93E 07 2.09E 07 1.50E 07 4.03E 07	5.98E 08 4.17E 08 2.93E 08 2.07E 08 1.47E 08 1.05E 08 7.51E 07 3.91E 07 2.84E 07 2.07E 07	1.81E 08 1.24E 08 8.57E 07 6.03E 07 4.19E 07 2.96E 07 2.10E 07 1.50E 07 7.70E 06 2.07E 07	5.04E 08 3.52E 08 1.76E 08 1.25E 08 8.94E 07 6.42E 07 4.63E 07 2.44E 07 1.78E 07	1.52E 08 1.04E 08 7.22E 07 5.10E 07 3.55E 07 2.51E 07 1.79E 07 1.28E 07 9.13E 06 6.60E 06

ORBIT ALTITUDE .. 6000 N MI

TOTAL TIME.. 48.HOURS

TIME INTERVAL.. 2.MINUTES

ENE ME		ORBITAI O Di		ORBITA 30		ORBITAL 60 I		ORBITAL 90 E	
El	E2	+E1	E1-E2	*E1	E1-E2	+E1	E1-E2	•E1	E1-E2
0.	0.25	6.12E 12	3.81E 12	8.49E 12	5.44E 12	6.15E 12	4.01E 12	4.52E 12	2.93E 12
0.25	0.50	2.32E 12	1.41E 12	3.05E 12	1.73E 12	2.13E 12	1.24E 12	1.59E 12	9.17E 11
0.50	0.75	9.04E 11	4.72E 11	1.32E 12	5.88E 11	8.90E 11	4.19E 11	6.76E 11	3.11E 11
0.75	1.00	4.32E 11	1.61E 11	7.35E 11	2.78E 11	4.71E 11	1.94E 11	3.66E 11	1.46E 11
1.00	1.25	2.71E 11	1.03E 11	4.58E 11	1.75E 11	2.77E 11	1.12E 11	2.20E 11	8.72E 10
1.25	1.50	1.68E 11	5.74E 10	2.83E 11	1.02E 11	1.65E 11	6.29E 10	1.32E 11	4.97E 10
1.50	1.75	1.11E 11	3.59E 10	1.81E 11	6.63E 10	1.02E 11	3.89E 10	8.28E 10	3.12E 10
1.75	2.00	7.48E 10	2.05E 10	1.14E 11	4.02E 10	6.30E 10	2.29E 10	5.16E 10	1.85E 10
2.00	2.25	5.43E 10	1.81E 10	7.42E 10	2.66E 10	4.01E 10	1.48E 10	3.31E 10	1.21E 10
2.25	2.50	3.62E 10	1.06E 10	4.75E 10	1.67E 10	2.53E 10	9.07E 09	2.10E 10	7.45E 09
2.50	2.75	2.55E 10	7.51E 09	3.09E 10	1.07E 10	1.63E 10	5.75E 09	1.35E 10	4.75E 09
2.75	3.00	1.80E 10	5.27E 09	2.01E 10	6.93E 09	1.05E 10	3.67E 09	8.78E 09	3.04E 09
3.00	3.25	1.27E 10	3.71E 09	1.32E 10	4.50E 09	6.85E 09	2.36E 09	5.74E 09	1.96E 09
3.25	3.50	9.04E 09	2.61E 09	8.71E 09	2.93E 09	4.49E 09	1.52E 09	3.77E 09	1.27E 09
3.50	3.75	6.43E 09	1.85E Q9	5.78E 09	1.93E 09	2.97E 09	9.97E 08	2.50E 09	8.36E 08
3.75	4.00	4.58E 09	1.32E 09	3.85E 09	1.27E 09	1.97E 09	6.54E 08	1.67E 09	5.50E 08
4.00	4.25	3.26E 09	9.36E 08	2.57E 09	8.44E 08	1.32E 09	4.33E 08	1.12E 09	3.65E 08
4.25	4.50	2.32E 09	6.64E 08	1.73E 09	5.61E 08	8.85E 08	2.87E 08	7.51E 08	2.42E 08
4.50	4.75	1.66E 09	4.76E 08	1.17E 09	3.77E 08	5.98E C8	1.92E 08	5.08E 08	1.63E 08
4.75	5.00	1.18E 09	3.36E 08	7.92E 08	2.52E 08	4.06E 08	1.29E 08	3.45E 08	1.09E 08
5.00	5.25	8.46E 08	2.40E 08	5.40E 08	1.70E 08	2.77E 08	8.70E 07	2.36E 08	7.39E 07
5.25	5.50	6.06E 08	1.72E 08	3.70E 08	1.16E 08	1.90E 08	5.92E 07	1.63E 08	5.04E 07
5.50	5.75	4.34E 08	1.23E 08	2.54E 08	7.86E 07	1.31E 08	4.03E 07	1.12E 08	3.43E 07
5.75	6.00	3.11E 08	8.75E 07	1.76E 08	5.38E 07	9.09E 07	2.76E 07	7.78E 07	2.36E 07
6.00	6.25	2.24E 08	6.29E 07	1.22E 08	3.70E 07	6.33E 07	1.91E 07	5.42E 07	1.63E 07
6.25	6.50	1.61E 08	4.53E 07	8.48E 07	2.56E 07	4.43E 07	1.32E 07	3.79E 07	1.13E 07
6.50	6.75	1.16E 08	3.22E 07	5.91E 07	1.76E 07	3.10E 07	9.13E 06	2.66E 07	7.82E 06
6.75	7.00	8.35E 07	2.33E 07	4.15E 07	1.23E 07	2.19E 07	6.41E 06	1.88E 07	5.50E 06
7.00		6.02E 07	6.02E 07	2.92E 07	2.92E 07	1.55E 07	1.55E 07	1.33E 07	1.33E 07
					~= /LL U!				

TABLE 7 (CONT)

ORBIT ALTITUDE .. 7000 N MI

TOTAL TIME.. 96.HOURS

TIME INTERVAL. 4.MINUTES

	RGY V	0 DI	_ FLUX EG	ORBITA 30		ORBITA 60		ORBITAI 90 I	
E1	E2	#E1	E1-E2	+E1	E1-E2	*E1	E1-E2	•E1	£1-E2
0.	0.25	1.00E 13	6.48E 12	1.09E 13	7.10E 12	6.70E 12	4.40E 12	5.37E 12	3.51E 1
0.25	0.50	3.55E 12	1.95E 12	3.84E 12	2.11E 12	2.30E 12	1.30E 12	1.85E 12	1.04E 1
0.50	0.75	1.60E 12	6.60E 11	1.73E 12	7.21E 11	9.99E 11	4.42E 11	8.12E 11	3.54E 1
0.75	1.00	9.40F 11	3.17E 11	1.01E 12	3.82E 11	5.58E 11	2.23E 11	4.58E 11	1.81E 1
1.00	1.25	6.23E 11	2.18E 11	6.29E 11	2.41E 11	3.35E 11	1.33E 11	2.77E 11	1.09E 1
1.25	1.50	4.06E 11	1.37E 11	3.89E 11	1.41E 11	2.02E 11	7.60E 10	1.68E 11	6.29E 1
1.50	1.75	2.69E 11	9.44E 10	2.47E 11	9.42E 10	1.26E 11	4.88E 10	1.05E 11	4.05E 1
1.75	2.00	1.74E 11	6.12E 10	1.53E 11	5.77E 10	7.72E 10	2.95E 10	6.46E 10	2.46E 1
2.00	2.25	1.13E 11	3.92E 10	9.56E 10	3.52E 10	4.77E 10	1.78E 10	4.01E 10	1.49E 1
2.25	2.50	7.4CE 10	2.60E 10	6.04E 10	2.26E 10	2.99E 10	1.13E 10	2.52E 10	9.46E 0
2.50	2.75	4.80E 10	1.70E 10	3.78E 10	1.41E 10	1.86E 10	6.99E 09	1.57E 10	5.88£ 0
2.75	3.00	3.16E 10	1.09E 10	2.37E 10	8.81E 09	1.16E 10	4.34E 09	9.83E 09	3.66E 0
3.00	3.25	2.01E 10	7.06E 09	1.49E 10	5.53E 09	7.30E 09	2.71E 09	6.17E 09	2.29E 0
3.25	3.50	1.31E 10	4.59E 09	9.39E 09	3.47E 09	4.59E C9	1.70E 09	3.88E 09	1.43E 0
3.50	3.75	8.47E 09	2.98E U9	5.92E 09	2.19E 09	2.89E 09	1.07E 09	2.45E 09	9.03E 0
3.75	4.00	5.49E 09	1.93E (/9	3.74E 09	1.37E 09	1.82E C9	6.71E 08	1.54E 09	5.68E 0
4.00	4.25	3.56E 09	1.25E ú9	2.36E 09	8.69E 08	1.15E 09	4.23E 08	9.77E 08	3.59E 0
4.25	4.50	2.31E 09	8.07E 08	1.49E 09	5.47E 08	7.28E 08	2.67E 08	6.18E 08	2.26E 0
4.50	4.75	1.51E 09	5.30E 08	9.47E 08	3.47E 08	4.62E C8	1.69E 08	3.92E 08	1.43E 0
4.75	5.00	9.76E 08	3.42E (8	6.COE 08	2.19E 08	2.93E 08	1.07E 08	2.49E 08	9.08E 0
5.00	5.25	6.34E 08	2.22E 08	3.81E 08	1.39E 08	1.86E 08	6.77E 07	1.58E 08	5.76E 0
5.25	5.50	4.12E 08	1.44E 08	2.42E 08	8.81E 07	1.18E C8	4.30E 07	1.01E 08	3.66E 0
5.50	5.75	2.68E 08	9.36E 07	1.53E 08	5.58E 07	7.51E 07	2.73E 07	6.40E 07	2.32E 0
5.75	6.00	1.74E 08	6.10E U7	9.76E 07	3.55E 07	4.78E 07	1.74E 07	4.08E 07	1.48E 0
6.00	6.25	1.13E Q8	3.95E 07	6.21E 07	2.25E 07	3.04E 07	1.10E 07	2.60E 07	9.39E 0
6.25	6.50	7.37E 07	2.58E 07	3.95E 07	1.44E 07	1.94E 07	7.05E 06	1.66E 07	6.01E 0
6.50	6.75	4.79E 07	1.67E 07	2.51E 07	9.08E 06	1.24E 07	4.45E 06	1.06E 07	3.80E 0
6.75	7.00	3.12E 07	1.09E 07	1.61E 07	5.82E 06	7.92E 06	2.86E 06	6.76E 06	2.44E 0

ORBIT ALTITUDE .. 8000 N MI

TOTAL TIME.. 96.HOURS

TIME INTERVAL.. 4.MINUTES

ENE! ME		ORBITA O D	L FLUX EG	3 <b>0</b> [	DEG	ORBITA 60 I		CRBITAI 90 i	DEG
Εl	E2	*E1	E1-E2						
0.	0.25	1.22E 13	7.85E 12	1.18E 13	7.64E 12	6.63E 12	4.35E 12	5.45E 12	3.57E 1
0.25	0.50	4.35E 12	2.29E 12	4.12E 12	2.27E 12	2.28E 12	1.29E 12	1.88E 12	1.06E 1
0.50	0.75	2.07E 12	7.78E 11	1.84E 12	7.73E 11	9.94E 11	4.35E 11	8.23E 11	3.57E 1
0.75	1.00	1.29E 12	4.50E 11	1.07E 12	4.29E 11	5.59E 11	2.31E 11	4.66E 11	1.92E 1
1.00	1.25	8.39E 11	3.07E 11	6.39E 11	2.55E 11	3.27E 11	1.34E 11	2.74E 11	1.11E 1
1.25	1.50	5.32E 11	1.78E 11	3.84E 11	1.48E 11	1.93E 11	7.55E 10	1.63E 11	6.32E 1
1.50	1.75	3.54E 11	1.34E 11	2.36E 11	9.35E 10	1.18E 11	4.73E 10	9.96E 10	3.98E 1
1.75	2.00	2.20E 11	8.18E 10	1.43E 11	5.57E 10	7.07E 10	2.79E 10	5.98E 10	2.35E 1
2.00	2.25	1.39E 11	5.02E 10	8.70E 10	3.34E 10	4.28E 10	1.66E 10	3.63E 10	1.40E 1
2 - 25	2.50	8.83E 10	3.29E 10	5.36E 10	2.07E 10	2.63E 10	1.02E 10	2.23E 10	8.66E 0
2.50	2.75	5.54E 10	2.06E 10	3.28E 10	1.26E 10	1.60E 10	6.18E 09	1.36E 10	5.24E 0
2.75	3.00	3.48E 10	1.30E 10	2.02E 10	7.78E 09	9.86E 09	3.80E 09	8.39E 09	3.23E 0
3.00	3.25	2.19E 10	8.14E 09	1.25E 10	4.77E 09	6.06E 09	2.33E 09	5.16E 09	1.98E 0
3.25	3.50	1.37E 10	5.10E 09	7.69E C9	2.93E 09	3.73E C9	1.43E 09	3.18E 09	1.21E 0
3.50	3.75	8.62E 09	3.22E 09	4.76E C9	1.81E 09	2.31E C9	8.81E 08	1.97E 09	7.51E 0
3.75	4.00	5.40E 09	2.01E 09	2.94E 09	1.12E 09	1.43E 09	5.41E 08	1.22E 09	4.62E 0
4.00	4.25	3.40E 09	1.27E 09	1.83E 09	6.96E Q8	8.86E 08	3.37E 08	7.57E 08	2.88E C
4.25	4.50	2.13E 09	7.93E 08	1.13E 09	4.29E 08	5.49E CB	2.08E 08	4.69E 08	1.78E C
4.50	4.75	1.34E 09	4.97E 08	7.03E 08	2.66E 08	3.40E 08	1.29E 08	2.91E 08	1.10E C
4.75	5.00	8.39E 08	3.12E 08	4.37E 08	1.65E 08	2.12E 08	8.00E 07	1.81E 08	6.84E 0
5.00	5.25	5.27E 08	1.97E 08	2.72E 08	1.03E 08	1.32E 08	4.97E 07	1.13E 08	4.25E C
5.25	5.50	3.31E 08	1.23E 08	1.69E 08	6.40E 37	8.20E 07	3.10E 07	7.02E 07	2.65E C
5.50	5.75	2.07E 08	7.69E 07	1.05E 08	3.97E 07	5.10E C7	1.92E 07	4.37E 07	1.64E C
5.75	6.00	1.30E 08	4.86E 07	6.57E 07	2.48E 07	3.18E 07	1.20E 07	2.73E 07	1.03E 0
6.00	6.25	8.18E 07	3.05E 07	4.10E 07	1.54E 07	1.98E 07	7.46E 06	1.70E 07	6.38E 0
6.25	6.50	5.14E 07	1.92E 07	2.56E 07	9.65E 06	1.24E 07	4.67E 06	1.06E 07	4.00E 0
6.50	6.75	3.22E 07	1.19E 07	1.59E 07	5.95E 06	7.71E 06	2.88E 06	6.61E 06	2.47E (
6.75	7.00	2.03E 07	7.60E 06	9.97E 06	3.75E 06	4.83E 06	1.82E 06	4.14E 06	1.56E (
7.00		1.27E 07	1.27E 07	6.22E G6	6.22E 06	3.01E C6	3.01E 06	2.58E 06	2.58E 0

TABLE 7 (CONT)

ORBIT ALTITUDE .. 9000 N MI

TOTAL TIME.. 96.HOURS

TIME INTERVAL.. 4. MINUTES

ENEF ME		ORBITAI O CI	L FLUX EG	ORBITA 30		60		90 1	DEG
Εl	E2	<b>*</b> E1	E1-E2	*E1	E1-E2				
0.	0.25	1.24E 13	7.91E 12	1.14E 13	7.47E 12	6.15E 12	4.05E 12	5.09E 12	3.35E 12
0.25	0.50	4.51E 12	2.41E 12	3.948 12	2.23E 12	2.10E 12	1.21E 12	1.74E 12	9.98E 11
0.50	0.75	2.10E 12	8.00E 11	1.70E 12	7.66E 11	8.91E 11	4-10E 11	7.42E 11	3.39E 11
0.75	1.00	1.30E 12	5.COE 11	9.37E 11	4.07E 11	4.81E 11	2.13E 11	4.03E 11	1.77E 11
1.00	1.25	7.98E 11	3.06E 11	5.30E 11	2.26E 11	2.68E 11	1.16E 11	2.26E 11	9.69E 10
1.25	1.50	4.92E 11	1.89E 11	3.05E 11	1.28E 11	1.53E 11	6.47E 10	1.29E 11	5.44E 10
1.50	1.75	3.03E 11	1.16E 11	1.76E 11	7.32E 10	8.79E 10	3.66E 10	7.43E 10	3.09E 10
1.75	2.00	1.87E 11	7.17E 10	1.03E 11	4.25E 10	5.13E 10	2.11E 10	4.34E 10	1.79E 10
2.00	2.25	1.16E 11	4.41E 10	6.07E 10	2.47E 10	3.01E 10	1.23E 10	2.56E 10	1.04E 10
2.25	2.50	7.16E 10	2.73E 10	3.60E 10	1.46E 10	1.79E 10	7.23E 09	1.52£ 10	6.13E 09
2.50	2.75	4.42E 10	1.67E 10	2.14E 10	8.56E 09	1.06E 10	4.24E 09	9.03E 09	3.60E 09
2.75	3.00	2.75E 10	1.05E 10	1.28E 10	5.14E 09	6.39E C9	2.55E 09	5.43E 09	2.17E 09
3.00	3.25	1.70E 10	6.46E 09	7.69E 09	3.06E 09	3.84E C9	1.52E 09	3.26E 09	1.29E 09
3.25	3.50	1.05E 10	4.00E 09	4.63E Q9	1.83E 09	2.32E 09	9.12E 08	1.97E 09	7.75E 08
3.50	3.75	6.54E 09	2.48E 09	2.80E G9	1.10E 09	1.41E C9	5.51E 08	1.20€ 09	4.68E 08
3.75	4.00	4.06E 09	1.53E 09	1.69E 09	6.64E 08	8.54E C8	3.33E 08	7.27E 08	2.83E 08
4.00	4.25	2.53E 09	9.63E 08	1.03E 09	4.05E 08	5.22E C8	2.04E 08	4.44E 08	1.74E 08
4.25	4.50	1.57E 09	5.94E 08	6.25E Q8	2.45E 08	3.18E C8	1.24E 08	2.70E 08	1.05E 08
4.50	4.75	9.74E 08	3.67E G8	3.81E C8	1.48E 08	1.94E C8	7.50E 07	1.65E 08	6.38E 07
4.75	5.00	6.07E 08	2.30E 08	2.33E 08	9.06E 07	1.19E C8	4.61E 07	1.01E 08	3.92E 07
5.00	5.25	3.77E 08	1.42E 08	1.42E 08	5.50£ 07	7.31E 07	2.81E 07	6.22E 07	2.39E 07
5.25	5.50	2.35E 08	8.90E 07	8.74E 07	3.38E 07	4.5CE C7	1.736 07	3.83E 07	1.47E 07
5.50	5.75	1.46E 08	5.52E 07	5.36E 07	2.07E 07	2.77E 07	1.06E 07	2.36E 07	9.05E 06
5.75	6.00	9.10E 07	3.44E 07	3.29E 07	1.27E 07	1.71E 07	6.54E 06	1.45E 07	5.56E 06
6.00	6.25	5.67E 07	2.13E 07	2.C3E Q7	7.76E 06	1.05E 07	4.02E 06	8.95E 06	3.42E 06
6.25	6.50	3.54E 07	1.34E 07	1.25E 07	4.81E 06	6.51E 06	2.50E 06	5.54E 06	2.12E 06
6.50	6.75	2.20E 07	8.25E 06	7.68E C6	2.93E 06	4.01E 06	1.53E 06	3.41E 06	1.30E 06
6.75	7.00	1.37E 07	5.16E 06	4.75E 06	1.81E 06	2.49E 06	9.46E 05	2.12E 06	8.04E 05
7.00		8.56E Q6	8.56E 06	2.94E C6	2.94E 06	1.54E C6	1.54E 06	1.31E 06	1.31E 06

ORBIT ALTITUDE .. 10000 N MI

TOTAL TIME.. 96.HOURS TIME INTERVAL.. 4.MINUTES

ENERGY MEV			30 1	DEG	60 1	DEG	90 [	EG
	E2 *E1		*E1		*E1	€1-E2	#E1	E1-E2
E1  0. 0. 25 0 0.50 0 0.75 1 1.00 1 1.25 1 1.50 1 1.75 2 2.00 2 2.25 2 2.50 2 2.75 3 3.00 3 3.25 3 3.50 3 3.75 4 4.00 4 4.25 4	E2 +E1	8.27E 12 2.52E 12 9.03E 11 4.70E 11 2.68E 11 1.54E 10 4.99E 10 2.84E 10 1.64E 10 9.23E 09 5.29E 09 3.04E 09 1.72E 09 9.85E 08 3.22E 08 1.84E 08 1.04E 08 1.04E 08 5.97E 07		E1-E2 7.17E 12	*E1	3.68E 12 1.09E 12 3.77E 11 1.80E 11 9.23E 10 4.87E 10	*E1 4.63E 12 1.55E 12 6.36E 11 3.20E 11 1.68E 11	E1-E2
5.25 5.50 5.75 6.00 6.25 6.50 6	.50 4.54E 07 .75 2.60E 07 .00 1.48E 07 .25 8.45E 06 .50 4.82E 06 .75 2.76E 06 .00 1.57E 06 8.97E 05	1.94E 07 1.12E 07 6.35E 06 3.64E 06 2.06E 06 1.19E 06 6.73E 05	1.83E 07 1.04E 07 5.91E 06 3.36E 06 1.91E 06 1.09E 06 6.18E 05 3.52E 05	7.87E 06 4.50E 06 2.55E 06 1.45E 06 8.18E 05 4.70E 05 2.66E 05	9.55E 06 5.45E C6 3.09E 06 1.76E 06 1.00E 06 5.72E 05 3.25E 05	4.11E 06 2.35E 06 1.33E 06 7.60E 05 4.29E 05 2.47E 05 1.40E 05 1.85E 05	8.19E 06 4.67E 06 2.65E 06 1.51E 06 8.58E 05 4.90E 05 2.79E 05	3.52E 06 2.02E 06 1.14E 06 6.52E 05 3.68E 05 2.12E 05 1.20E 05

#### ORBITAL INTEGRATION FOR PROJECTED 1968 ELECTRON ENVIRONMENT

DRBIT ALTITUDE .. 11000 N MI

TOTAL TIME.. 96.HOURS

TIME INTERVAL.. 4.MINUTES

ENE!		ORBITA O D	L FLUX EG	ORBITA 3C	_	ORBITA 6C	L FLUX DEG	CRBITA 90	
E1	E2	+E1	£1~E2	*£1			E1-E2	•E1	E1-E2
0.	0.25	1.26E 13	8.34E 12	9.68E 12	6.51E 12	4.95E 12	3.34E 12	4.13E 12	2.78E 1
0.25	0.50	4.31E 12	2.51E 12	3.17E 12	1.91E 12	1.61E 12	9.80E 11	1.34E 12	8.16E 1
0.50	0.75	1.80E 12	8.82E 11	1.26E 12	6.56E 11	6.31E 11	3.33E 11	5.27E 11	2.78E 1
0.75	1.00	9.21t 11	4.42E 11	6.C2E 11	3.07E 11	2.98E 11	1.53E 11	2.49E 11	1.28E 1
1.00	1.25	4.79E 11	2.28€ 11	2.95E 11	1.48F 11	1.44E 11	7.29E 10	1.21E 11	6.11E 1
1.25	1.50	2.51E 11	1.20E 11	1.47E 11	7.32E 10	7.13É 10	3.57E 10	6.00E 10	3.00E 1
1.50	1.75	1.32E 11	6.21E 10	7.38E 1C	3.62E 10	3.56E 10	1.76E 10	3.00t 10	1.48E 1
1.75	2.00	6.95E 10	3.26E 10	3.76E 10	1.83E 10	1.81E 1C	8.80E 09	1.53E 10	7.42E C
2.00	2.25	3.69E 10	1.72E 10	1.93E 10	9.31E 09	9.28E C9	4.48E 09	7.85E 09	3.78E C
2.25	2.50	1.97E 10	9.15E 09	1.COE 10	4.78E 09	4.80E 09	2.29E 09	4.07E 09	1.94E C
2.50	2.75	1.05E 10	4.85E û9	5.24E C9	2.47E C9	2.51E C9	1.18E 09	2.13E 09	1.00E C
2.75	3.00	5.69E 09	2.61E 09	2.77E C9	1.30E 09	1.32E C9	6.21E 08	1.12E 09	5.26E 0
3.00	3.25	3.08E 09	1.41E 09	1.47E 09	6.85E 08	7.03E C8	3.27E 08	5.97E 08	2.78E C
3.25	3.50	1.67E 09	7.58E 68	7.86E 08	3.62E 08	3.75E C8	1.73E 08	3.19E 08	1.47E (
3.50	3.75	9.17E 08	4.13E 68	4.24E 08	1.94E 08	2.C2E C8	9.26E 07	1.72E 08	7.88E (
3.75	4.00	5.04E 08	2.26E C8	2.30E Q8	1.05E 08	1.1CE C8	5.00E 07	9.35E 07	4.26E (
4.00	4.25	2.78E 08	1.24E 08	1.25E G8	5.66E 07	5.97E C7	2.70E 07	5.09E 07	2.30E (
4.25	4.50	1.53E 08	6.84E 07	6.85E 07	3.09E 07	3.27E 07	1.47E 07	2.79E 07	1.26E C
4.50	4.75	8.50E 07	3.76E 07	3.76E C7	1.68E 07	1.79E 07	8.C2E 06	1.53E 07	6.84E (
4.75	5.00	4.74E 07	2.09E 67	2.08E 07	9.26E C6	9.92E 06	4.42E 06	8.48E 06	3.77E (
5.00	5.25	2.65E 07	1.17E 07	1.15E G7	5.12E 06	5.50E C6	2.44E 06	4.70E 06	2.09E (
5.25	5.50	1.48E 07	6.48E 06	6.41E G6	2.83E 06	3.06E 06	1.35E 06	2.62E 06	1.15E (
5.50	5.75	8.34E 06	3.66E 06	3.59E 06	1.58E 06	1.71E C6	7.55E 05	1.46E 06	6.45E (
5.75	6.00	4.68E 06	2.04E 06	2.00E C6	8-80E 05	9.55E C5	4.19E 05	8.18E 05	3.59E (
6.00	6.25	2.64E 06	1.15E 06	1.12E C6	4.93E 05	5.36E C5	2.35E 05	4.59E 05	2.01E (
6.25	6.50	1-49E 06	6.44E 05	6.31E C5	2.75E 05	3.01E 05	1.31E 05	2.58E 05	1.12E (
6.50	6.75	8.41E 05	3.66E 05	3.56E Q5	1.56E 05	1.70E C5	7.42E 04	1.45E C5	6.36E (
6.75	7.00	4.75E 05	2.06E 05	2.01E G5	8.71E 04	9.56E 04	4.15E 04	8.19E 04	3.56E (

DRBIT ALTITUDE .. 12000 N MI

TOTAL TIME.. 96.HOURS TIME INTERVAL.. 4.MINUTES

ENE		ORBITA O C	L FLUX IEG	ORBITAN 1 DE			L FLUX DEG	GRBITA 90	
Εl	E2	*E1	£1-E2	+E1	E1-E2	•E1	E1-E2	•E1	E1-E2
0-	0.25	1.13E 13	7.53E 12	8.43E 12	5.76E 12	4.24E 12	2.90E 12	3.59E 12	2.45E 1
0.25	0.50	3.79E 12	2.25E 12	2.67E 12	1.66E 12	1.35E 12	8.39E 11	1-14E 12	7.10E 1
0.50	0.75	1.54E 12	7.83E 11	1.01E 12	5.57E 11	5.06E 11	2.81E 11	4.30E 11	2.38E 1
0.75	1.00	7.59E 11	3.85E 11	4.48E 11	2.46E 11	2.26E 11	1.23E 11	1.92E 11	1.05E 1
1.00	1.25	3.74E 11	1.89E 11	2.03E 11	1.09E 11	1.C2E 11	5.51E 10	8.72E 10	4.69E 1
1.25	1.50	1.85E 11	9.40E 10	9.31E 10	5.01E 10	4.72E 10	2.53E 10	4.03E 10	2.16E 1
1.50	1.75	9.08E 10	4.60E 10	4.31E 1C	2.29E 10	2.19E 10	1-16E 10	1.87E 10	9.90E 0
1.75	2.00	4.48E 10	2.27E 10	2.02E 10	1.06E 10	1.03E 10	5.42E C9	8.82E 09	4.63E C
2.00	2.25	2.22E 10	1.13E 10	9.53E C9	5.02E 09	4.90E C9	2.57E 09	4-19E 09	2.19E 0
2.25	2.50	1.09E 10	5.51E 09	4.51E 09	2.35E 09	2.33E C9	1.21E 09	1.99E 09	1.03E 0
2.50	2.75	5.39E 09	2.73E 69	2.16E 09	1.12E 09	1.12E C9	5.80E 08	9.58E 08	4.968 0
2.75	3.00	2.66E 09	1.35E U9	1.04E C9	5.38E 08	5.40E C8	2.79E 08	4.62E 08	2.39E 0
3.00	3.25	1.31E 09	6.63E 08	4.99E Q8	2.58E 08	2.61E C8	1.34E 08	2.23E 08	1.15E C
3.25	3.50	6.47E 08	3.28E 08	2.41E 08	1.24E 08	1.27E C8	6.50E 07	1.08E 08	5.56E 0
3.50	3.75	3.20E 08	1.61E 08	1.17E 08	6.00E 07	6.16E 07	3.15E 07	5.27E 07	2.69E C
3.75	4.00	1.58E 08	8.02E 07	5.70E C7	2.93E 07	3.01E C7	1.54E 07	2.57E 07	1.32E (
4.00	4.25	7.80E 07	3.95E 07	2.78E 07	1.42E 07	1.47E C7	7.50E 06	1.26E 07	6.41E C
4.25	4.50	3.85E 07	1.96E 07	1.36E G7	6.95E 06	7.20E 06	3.68E 06	6.15E 06	3.15E 0
4.50	4.75	1.90E 07	9.56E 06	6.61E C6	3.36£ 06	3.51E C6	1.78E 06	3.00E 06	1.52E C
4.75	5.00	9.40E 06	4.75E 06	3.25E G6	1.65E 06	1.73E C6	8.80E 05	1.48E 06	7.52E C
5.00	5.25	4.65E 06	2.35E 06	1.59E C6	8.10E 05	8.50E 05	4.31E 05	7.26E 05	3.69E (
5.25	5.50	2.30E 06	1.17E 06	7.84E 05	4.00E 05	4.19E 05	2.13E 05	3.58E 05	1.82E C
5.50	5.75	1.13E 06	5.74E 05	3.84E C5	1.96E 05	2.06E C5	1.05E 05	1.76E 05	8.93E (
5.75	6.00	5.59E 05	2.83E 05	1.89E 05	9.57E 04	1.01E C5	5.12E 04	8.63E 04	4.37E
6.00	6.25	2.76E 05	1.40E 05	9.29E G4	4.71E 04	4.98E 04	2.52E 04	4.25E 04	2.16E (
6.25	6.50	1.37E 05	6.93E 04	4.58E 04	2.33E 04	2.46E 04	1.25E 04	2.10E 04	1.06E
6.50	6.75	6.74E 04	3.41E G4	2.25E 04	1.14E 04	1.21E 04	6.13E 03	1.03E 04	5.23E
6.75	7.00	3.33E 04	1.68E 04	1.11E 04	5.62E 03	5.97E C3	3.02E 03	5.09E 03	2.57E C
7.00		1.65E 04	1.65E 04	5.49E 03	5.49E 03	2.95E 03	2.95E 03	2.52E 03	2.52E 0

#### ORBITAL INTEGRATION FOR PROJECTED 1968 ELECTRON ENVIRONMENT

ORBIT ALTITUDE..13000 N MI

TOTAL TIME.. 96.HOURS

TIME INTERVAL.. 4.MINUTES

ENERGY MEV		ORBITA O D		ORBITAL FLUX 30 DEG		ORBITAL FLUX 60 DEG		90 DEG	
Εl	E2	*£1	E1-E2	*£1			E1-E2		
0.	0.25	1.14E 13	7.85E 12	7.33E 12	5.10E 12	3.67E 12	2.56E 12	3.13E 12	2.18E
0.25	0.50	3.50E 12	2.21E 12	2.22E 12	1.43E 12	1.12E 12	7.20E 11	9.51E 11	6.14E
0.50	0.75	1.30E 12	7.43E 11	7.89E 11	4.69E 11	3.96E 11	2.35E 11	3.38E 11	2.01E
0.75	1.00	5.54E 11	3.18E 11	3.20E 11	1.89E 11	1.60E 11	9.48E 10	1.37E 11	8.10E
1.00	1.25	2.36E 11	1.35€ 11	1.31E 11	7.65E 10	6.55E 10	3.84E 10	5.61E 10	3.28E
1.25	1.50	1.01E 11	5.78E 10	5.41E 10	3.16E 10	2.72E 10	1.58E 10	2.33E 10	1.36E
1.50	1.75	4.32E 10	2.47E 10	2.26E 10	1.31E 10	1.13E 10	6.56E 09	9.71E 09	5.63E
1.75	2.00	1.85E 10	1.05E 10	9.49E C9	5.46E 09	4.77E 09	2.74E 09	4.09E 09	2.35E
2.00	2.25	7.94E 09	4.54E 09	4.03E G9	2.31E 09	2.03E C9	1.16E 09	1.74E 09	9.96E
2.25	2.50	3.41E 09	1.94E 09	1.72E G9	9.77E 08	8.64E C8	4.92E 08	7.4CE 08	4.21E
2.50	2.75	1.47E 09	8.36E 08	7.39E 68	4.19E 08	3.72E C8	2.11E 08	3.18E 08	1.81E
2.75	3.00	6.33E 08	3.60E U8	3.20E 08	1.81E 08	1.61E 08	9.10E 07	1.38E 08	7.78E
3.00	3.25	2.73E Q8	1.55E 08	1.39E 08	7.82t 07	7.01E 07	3.946 07	5.97E 07	3.36E
3.25	3.50	1.18E 08	6.69E 07	6.11E 07	3.41E 07	3.07E C7	1.71E 07	2.61E 07	1.46E
3.50	3.75	5.14E 07	2.91E 07	2.70E G7	1.50E 07	1.35E 07	7.55E 06	1.15€ 07	6.42E
3.75	4.00	2.23E 07	1.26E 07	1.20E 07	6.61E C6	6.00E C6	3.32E 06	5.08E 06	2.81E
4.00	4.25	9.79E 06	5.50E 06	5.36E C6	2.95E 06	2.68E C6	1.48E 06	2.26E 06	1.25E
4.25	4.50	4.29E 06	2.40E 06	2.41E 06	1.32E 06	1.20E C6	6.61E 05	1.01E C6	5.57E
4.50	4.75	1.89E 06	1.05E 06	1.09E C6	5.92E 05	5.42E C5	2.95E 05	4.55E 05	2.48E
4.75	5.00	8.35E 05	4.64E 05	4.98E 05	2.70E 05	2.47E 05	1.34E 05	2.07E C5	1.12E
5.00	5.25	3.71E 05	2.05E 05	2.29E Q5	1.23E 05	1.13E C5	6.09E 04	9.43E 04	5.09E
5.25	5.50	1.66E 05	9.15E U4	1.06E C5	5.67E 04	5.22E C4	2.80E 04	4.34E 04	2.34E
5.50	5.75	7.44E 04	4.09E 04	4.90E 04	2.62E 04	2.41E 04	1.29E 04	2.00E 04	1.07E
5.75	6.00	3.36E 04	1.83E 04	2.29E C4	1.21E 04	1.12E 04	5.97E 03	.9.28E 03	4.94E
6.00	6.25	1.52E 04	8.29E 03	1.08E C4	5.68E 03	5.26E 03	2.78E 03	4.33E 03	2.30E
6.25	6.50	6.95E 03	3.76E 03	5.08E 03	2.67E 03	2.48E C3	1.31E 03	2.04E 03	1.078
6.50	6.75	3.19E 03	1.72E 03	2.41E G3	1.26E 03	1.17E 03	6.15E 02	9.61E 02	5.058
6.75	7.00	1.47E 03	7.88E 02	1.15E G3	5.97E 02	5.57E 02	2.91E 02	4.55E 02	2.38£
7.00		6.85E 02	6.85E Q2	5.50E 02	5.50E 02	2.67E C2	2.67E 02	2.17E 02	2.176

ORBIT ALTITUDE..14000 N MI

TOTAL TIME.. 432. HOURS TIME INTERVAL.. 18. MINUTES

ENE!		ORBITAN O O		ORBITA 30	L FLUX Deg	ORBITA 60		ORBITAL 90 (	
El	E2	*E1	E1-E2	*£1	E1-E2	*E1			E1-E2
0.	0.25	9.52E 12	6.62E 12	5.91E 12	4.15E 12	2.85E 12	2.00E 12	2.42E 12	1.70E 12
0.25	0.50	2.90E 12	1.85E 12	1.76E 12	1.16E 12	8.53E 11	5.61E 11	7.25E 11	4.77E 11
0.50	0.75	1.05E 12	6.14E 11	5.99E 11	3.71E 11	2.92E 11	1.80E 11	2.48E 11	1.53E 11
0.75	1.00	4.33E 11	2.54E 11	2.28E 11	1.40E 11	1.12E 11	6.87E 10	9.56E 10	5.84E 10
1.00	1.25	1.79E 11	1.05E 11	8.79E 10	5.36E 10	4.37E 10	2.65E 10	3.72E 10	2.25E 10
1.25	1.50	7.49E 10	4.36E 10	3.44E 10	2.08E 10	1.73E 10	1.G4E 10	1.47E 10	8.85E 09
1.50	1.75	3.12E 10	1.82E 10	1.36E 10	8.16E 09	6.87E C9	4.11E 09	5.85E 09	3.50E 09
1.75	2.00	1.31E 10	7.58E 09	5.40E 09	3.23E 09	2.76E 09	1.64E 09	2.35E 09	1.40E 09
2.00	2.25	5.49E 09	3.19E 09	2.17E 09	1.29E 09	1.12E C9	6.63E 08	9.54E 08	5.65E 08
2.25	2.50	2.30E 09	1.33E 09	8.79E C8	5.20E 08	4.57E 08	2.69E 08	3-89E C8	2.29E 08
2.50	2.75	9.72E 08	5.62E 08	3.59E 08	2.12E 08	1.88E C8	1.10E 08	1.60E 08	9.39E 07
2.75	3.00	4.09E 08	2.37E 08	1.47E 08	8.66E 07	7.75E 07	4.54E 07	6.59E 07	3.86E 07
3.00	3.25	1.73E 08	9.97E 07	6.07E C7	3.56E 07	3.21E 07	1.87E 07	2.73E 07	1.60E 07
3.25	3.50	7.29E 07	4.20E 07	2.51E G7	1.47E 07	1.33E 07	7.77E 06	1.14E 07	6.61E 06
3.50	3.75	3.08E 07	1.78E 07	1.05E 07	6-11E 06	5.58E 06	3.25E 06	4.75E 06	2.77E 06
3.75	4.00	1.30E 07	7.48E U6	4.35E 06	2.53£ 06	2.33E 06	1.35E 06	1.98E 06	1.15E 06
4.00	4.25	5.52E 06	3.18E 06	1.82E 06	1.06E 06	9.79E C5	5.68E 05	8.32E 05	4.83E 05
4.25	4.50	2.34E 06	1.35E 06	7.64E 05	4.43E 05	4.11E C5	2.38E 05	3.50E 05	2.03E 05
4.50	4.75	9.89E 05	5.69E 05	3.21E 05	1.86E 05	1.73E 05	9.99E 04	1.47E 05	8.50E 04
4.75	5.00	4.19E 05	2.42E 05	1.35E Q5	7.82E 04	7.29E 04	4.22E 04	6.20E 04	3.59E 04
5.00	5.25	1.78E 05	1.02E 05	5.68E 04	3.28E 04	3.07E 04	1.77E 04	2.61E 04	1.51E 04
5.25	5.50	7.54E 04	4.34E 04	2.40E 04	1.39E 04	1.30E C4	7.50E 03	1.11E 04	6.38E 03
5.50	5.75	3.20E 04	1.84E 04	1.01E 04	5.86E 03	5.50E 03	3.17E 03	4.68E C3	2.70E 03
5.75	6.00	1.36E 04	7.82E 03	4.29E 03	2.47E 03	2.33E 03	1.34E 03	1.98E 03	1.14E 03
6.00	6.25	5.76E 03	3.32E 03	1.81E 03	1.05E 03	9.84E 02	5.68E 02	8.37E 02	4.83E 02
6.25	6.50	2.44E 03	1.40E 03	7.66E 02	4.40E 02	4.16E 02	2.39E 02	3.54E 02	2.03E 02
6.50	6.75	1.04E 03	6.00E 02	3.26E 02	1.88E 02	1.77E 02	1.02E 02	1.51E 02	8.69E 01
6.75	7.00	4.40E 02	2.53E 02	1.38E C2	7.93E 01	7.49E 01	4.31E 01	6.37E 01	3.67E 01
7.00		1.87E 02	1.87E 02	5.83E G1	5.83E 01	3.17E 01	3.17E 01	2.70E 01	2.70E 01

TABLE 7 (CONT)

ORBIT ALTITUDE..15000 N MI

TOTAL TIME.. 576.HOURS

TIME INTERVAL .. 24. MINUTES

ENERGY MEV		ORBITAL FLUX O DEG		ORBITAL FLUX 30 DEG		ORBITAL FLUX 60 DEG		CRBITAL FLUX 90 DEG	
El	E2	•£1	E1-E2	*E1	E1-E2	+E1	E1-E2	*E1	£1~E2
0.	0.25	8.64E 12	6.14E 12	4.60E 12	3.25E 12	2.26E 12	1.60E 12	1.92E 12	1.36E 1
0.25	0.50	2.50E 12	1.68E 12	1.34E 12	9.15E 11	6.58E 11	4.47E 11	5.60E 11	3.80E 1
0.50	0.75	8.23E 11	5.27E 11	4.28E 11	2.81E 11	2.11E 11	1.38E 11	1.80E 11	1.17E 1
0.75	1.00	2.95E 11	1.69E 11	1.47E 11	9.63E 10	7.33E 10	4.77E 10	6.23E 10	4.06E 1
1.00	1.25	1.06E 11	6.79E 10	5.09E 10	3.325 10	2.56E 10	1.66E 10	2.17E 10	1.41E 1
1.25	1.50	3.82E 10	2.44E 10	1.77E 10	1.15E 10	8.96E C9	5.81E 09	7.61E 09	4.93E Q
1.50	1.75	1.37E 10	8.81E 09	6.17E 09	4.01E 09	3.15E 09	2.04E 09	2.67E 09	1.73E 0
1.75	2.00	4.93E 09	3.16E 09	2.15E C9	1.40E 09	1.11E C9	7.17E 08	9.39E 08	6.08E 0
2.00	2.25	1.77E 09	1.13E 09	7.55E C8	4.89E 08	3.91E C8	2.52E 08	3.31E 08	2.14E 0
2.25	2.50	6.37E 08	4.08E 08	2.66E 08	1.72E 08	1.38E C8	8.94E Q7	1.17E 08	7.57E 0
2.50	2.75	2.29E 08	1.46E Ú8	9.39E 67	6.07E 07	4.91E 07	3.16E 07	4.16E 07	2.68E 0
2.75	3.00	8.23E 07	5.27E 07	3.32E 67	2.15E 07	1.74E 07	1.12E 07	1.48E 07	9.52E 0
3.00	3.25	2.95E 07	1.89E 07	1.18E C7	7.59E 06	6.20E C6	3.99E 06	5.25E 06	3.38E 0
3.25	3.50	1.06E 07	6.79E 06	4.18E C6	2.69E 06	2.21E C6	1.42E 06	1.87E C6	1.20E 0
3.50	3.75	3.82E 06	2.44E G6	1.49E C6	9.57E 05	7.88E C5	5.06E 05	6.67E G5	4.29E 0
3.75	4.00	1.37E 06	8.81E 05	5.31E 05	3.42E 05	2.82E C5	1.81E 05	2.38E 05	1.53E 0
4.00	4.25	4.93E 05	3.16E 05	1.89E C5	1.22E 05	1.01E C5	6.46E 04	8.50E 04	5.47E 0
4.25	4.50	1.77E 05	1.13E 05	6.73E Q4	4.32E 04	3.59E 04	2.30E 04	3.04E 04	1.95E 0
4.50	4.75	6.37E 04	4.08E 04	2.41E ¢4	1.55E 04	1.29E C4	8.27E 03	1.09E 04	6.99E 0
4.75	5.00	2.29E 04	1.46E 04	8.61E 03	5.53E 03	4.61E C3	2.96E 03	3.90E C3	2.50E 0
5.00	5.25	8.23E 03	5.27E 03	3.08E C3	1.98E 03	1.65E C3	1.06E 03	1.40E 03	8.97E 0
5 • 25	5.50	2.95E 03	1.89E U3	1.10E C3	7.08E 02	5.92E C2	3.80E 02	5.00± 02	3.21E 0
5.50	5.75	1.06E 03	6.79E 02	3.95E C2	2.53E 02	2.12E C2	1.36E 02	1.79E 02	1.15E 0
5.75	6.00	3.82E U2	2.44E 02	1.42E G2	9.09E 01	7.61E C1	4.88E 01	6.44E 01	4.12E 0
6.00	6.25	1.37E 02	8.81E 01	5.09E G1	3.27E 01	2.74E C1	1.76E 01	2.31E 01	1.48E 0
6.25	6.50	4.93E 01	3.16E U1	1.82E G1	1.17E 01	9.80E CO	6.29E 00	8.28E 00	5.31E 0
6.50	6.75	1.77E 01	1.13E U1	6.53E 00	4.18E 00	3.51E CO	2.258 00	2.97E 00	1.90E 0
6.75	7.00	6.37E 00	4.08E 00	2.35E 00	1.50E 00	1.26E CO	8.10E-01	1.C7E 00	6.84E-0
7.00		2.29E 00	2.29E 00	8.42E-C1	8.42E-01	4.53E-C1	4.53E-01	3.83E-01	3.83E-0

ORBIT ALTITUDE..16000 N MI TOTAL TIME.. 864.HOURS TIME INTERVAL..36.MINUTES

	NERGY DRBITAL FLUX MEV G DEG				CRBITAL FLUX 60 DEG		CRBITAL FLUX 90 DEG		
El	EZ	*£1	E1-E2	*£1	E1-E2	•E1	£1-E2	•E1	£1-E2
0.	0.25	7.01E 12	4.95E 12	3.02E 12	2.13E 12	1.56E 12	1.10E 12	1.34E 12	9.46E 1
0.25	0.50	2.06E 12	1.42E 12	8.91E 11	6.16E 11	4.59E 11	3.16E 11	3.95E 11	2.73E 1
0.50	0.75	6.42E 11	4.29E 11	2.76E 11	1.85E 11	1.42E 11	9.52E 10	1.23E 11	8.20E 1
0.75	1.00	2.14E 11	1.42E 11	9.06E 10	6.06E 10	4.71E 10	3.14E 10	4.05E 10	2.70E 1
1.00	1.25	7.15E 10	4.74E 10	3.00E 10	2.00E 10	1.57E 10	1.04E 10	1.35E 10	8.95E 0
1.25	1.50	2.41E 10	1.59E 10	1.COE 10	6.66E 09	5.26E 09	3.49E 09	4.50E 09	2.99E 0
1.50	1.75	8.16E 09	5.38E C9	3.36E 09	2.23E 09	1.77E C9	1.17E 09	1.52E 09	1.00E 0
1.75	2.00	2.77E 09	1.82E 09	1.13E 09	7.47E 08	6.COE C8	3.96E 08	5.12E C8	3.38E 0
2.00	2.25	9.48E 08	6.22E 08	3.83E C8	2.52E 08	2.04E C8	1.34E 08	1.74E 08	1.15E 0
2.25	2.50	3.26E 08	2.14E 08	1.31E G8	8.58E 07	7.00E C7	4.59E 07	5.96E 07	3.91E 0
2.50	2.75	1.13E 08	7.36E 07	4.47E 67	2.93£ 07	2.41E C7	1.58E 07	2.05E 07	1.34E 0
2.75	3.00	3.92E 07	2.55E 07	1.54E 07	1.01E 07	8.33E C6	5.44E 06	7.08E 06	4.63E 0
3.00	3.25	1.36E 07	8.86E 06	5.32E 06	3.48E 06	2.89E C6	1.88E 06	2.46E 06	1.60E 0
3.25	3.50	4.76E 06	3.09E 66	1.85E C6	1.20E 06	1.01E C6	6.55E 05	8.55E 05	5.56E 0
3.50	3.75	1.67E 06	1.08E 66	6.45E Q5	4.19E 05	3.53E C5	2.29E 05	2.99E 05	1.94E 0
3.75	4.00	5.89E 05	3.82E 05	2.26E Q5	1.47E 05	1.24E C5	8.04E 04	1.05E 05	6.81E 0
4.00	4.25	2.08E 05	1.34E 05	7.92E 04	5.14E 04	4.36E 04	2.82E 04	3.69E 04	2.39E 0
4.25	4.50	7.33E 04	4.73E 04	2.79E 04	1.80E 04	1.54E 04	9.92E 03	1.30E 04	8.39E 0
4.50	4.75	2.60E 04	1.68E 04	9.85E 03	6.37E 03	5.44E C3	3.52E 03	4.60E 03	2.97E 0
4.75	5.00	9.23E 03	5.95E 03	3.48E 03	2.25E 03	1.93E G3	1.24E 03	1.63E 03	1.05E 0
5.00	5.25	3.29E 03	2.12E 03	1.24E G3	7.97E 02	6.85E C2	4.42E 02	5.79E C2	3.73E 0
5.25	5.50	1.17E 03	7.52E 02	4.39E 02	2.83E 02	2.44E 02	1.57E 02	2.06E 02	1.32E 0
5.50	5.75	4.17E 02	2.68E 02	1.56E 02	1.00E 02	8.67E C1	5.58E 01	7.32E 01	4.71E 0
5.75	6.00	1.49E 02	9.56E U1	5.56E 01	3.57E 01	3.10E C1	1.99E 01	2.61E 01	1.68E 0
6.00	6.25	5.33E 01	3.42E 01	1.99E 01	1.28E 01	1.11E C1	7.12E 00	9.33E 00	6.00E 0

## TABLE 7 (CONCLUDED)

## ORBITAL INTEGRATION FOR PROJECTED 1968 ELECTRON ENVIRONMENT

ORBIT ALTITUDE .. 17000 N MI

TOTAL TIME..1152.HOURS

TIME INTERVAL..48.MINUTES

ENE!		ORBITA O O	L FLUX EG	ORBITAL 30 (	_ FLUX DEG	ORBITAL 60 L	. FLUX )EG	ORBITAL 90 L	
E 1	£ 2	*E1	£1-E2	*C1	E1-E2	<b>*</b> E1	E1-E2	*E1	E1-E2
0. 0.25 0.50 0.75 1.00 1.25 1.50 1.75 2.00 2.25 2.50 2.75 3.00 3.25 3.50 3.75 4.00 4.25 4.50 4.75 5.00 5.25	0.25 0.50 0.75 1.00 1.25 1.75 2.00 2.25 2.75 3.00 3.25 3.55 4.00 4.25 4.50 4.50 4.50 5.50 5.50 5.75	5.14E 12 1.53E 12 4.55E 11 1.40E 11 4.32E 10 1.33E 10 4.11E 09 1.27E 09 3.90E 08 1.20E 08 3.70E 07 1.14E 07 3.52E 06 1.03E 05 3.18E 06 3.34E 05 1.03E 05 3.18E 03 3.02E 03 9.28E 02 2.86E 02 2.86E 02 2.83E 01 2.72E 01	3.61F 12 1.08E 12 3.15E 11 2.69E 10 2.39E 10 9.23E 09 2.84E 09 8.75E 08 2.70E 08 8.31E 07 7.91E 06 2.43E 05 7.49E 05 2.31E 05 7.11F 04 2.20E 04 6.77E 03 2.09E 03 6.42E 02 1.38E 02 1.38E 01	1.74E 12 5.20E 11 1.54E 11 4.75E 10 1.46E 10 4.52E 09 1.39E 09 4.27E 08 1.32E 08 4.07E 07 1.25E 07 3.87E 06 1.17E 06 3.67E 05 1.13E 05 3.48E 04 1.08E 04 1.08E 04 1.08E 03 3.15E 02 9.70E 01 9.92E 00	1.22E 12 3.65E 11 1.07E 11 3.28E 10 1.01E 10 3.13E 07 9.62E 08 2.96E 08 9.14E 07 2.82E 07 8.68E 06 2.68E 06 8.25E 05 7.83E 04 2.41E 04 7.45E 03 7.08E 02 2.18E 02 6.71E 01 2.07E 01 6.38E 00	9.37E 11 2.79E 10 2.55E 10 7.88E 09 2.43E 08 7.48E 08 2.31E 08 7.11E 07 2.19E 07 6.75E 06 2.08E 06 6.41E 05 1.97E 05 6.09E 04 1.87E 04 5.79E 03 1.78E 03 5.50E 02 1.69E 02 5.22E 01 1.61E 01 4.96E 00	6.58E 11 1.97E 10 5.74E 10 1.77E 10 5.45E 09 1.68E 09 5.17E 08 1.59E 08 4.92E 07 1.51E 07 4.67E 06 1.44E 06 4.44E 05 4.21E 04 1.30E 04 4.00F 03 1.23E 03 3.81E 02 1.17E 02 3.61E 01 1.11E 01 3.43E 00	8.08E 11 2.41E 11 7.15E 10 2.20E 10 6.79E 09 2.10E 09 6.45E 08 1.99E 08 6.13E 07 1.89E 06 1.79E 06 5.53E 05 1.79E 06 5.53E 05 1.79E 04 4.99E 03 4.74E 02 4.50E 01 4.50E 01	5.67E 11 1.69E 11 4.95E 10 1.52E 10 4.70E 09 4.46E 08 1.38E 08 4.24E 07 4.03E 06 1.24E 06 3.83E 05 1.18E 05 3.63E 04 1.12E 04 3.45E 03 1.06E 03 3.28E 02 1.01E 02 3.11E 01 9.296E 00
5.75 6.00 6.25 6.50 6.75 7.00	6.00 6.25 6.50 6.75 7.00	8.37E 00 2.59E 00 7.96E-01 2.45E-01 7.56E-02 2.33E-02	5.79E 00 1.79E 00 5.51E-01 1.70E-01 5.22E-02 2.33E-02	2.84E 00 8.76E-01 2.70E-01 8.31E-02 2.56E-02 7.89E-03	1.96E 00 6.06E-01 1.87E-01 5.75E-02 1.77E-02 7.89E-03	1.53E 00 4.71E-01 1.45E-01 4.47E-02 1.38E-02 4.25E-03	1.05E 00 3.26E-01 1.00E-01 3.09F-02 9.52E-03 4.25E-03	1.32E 00 4.06E-01 1.25E-01 3.85E-02 1.19E-02 3.66E-03	9.10E-01 2.81E-01 8.66E-02 2.67E-02 8.21E-03 3.66E-03

ORBIT ALTITUDE .. 18000 N MI

TOTAL TIME .. 2304. HOURS

TIME INTERVAL..96.MINUTES

ENE!		ORBITAL FLUX O DEG		ORBITAL FLUX 30 DEG		ORBITAL FLUX 60 DEG		ORBITAL FLUX 90 DEG	
εı	E2	*E1	£1-E2	*E1	E1-E2	<b>+</b> €1	E1-E2	*E1	£1-E2
0.	0.25	7.786 11	5.46E 11	3.26E 11	2.29E 11	1.80E 11	1.26E 11	1.55E 11	1.09E
0.25	0.50	2.32E 11	1.63E 11	9.72E 10	6.84E 10	5.36E 10	3.77E 10	4.62E 10	3.25E
0.50	0.75	6.89E 10	4.77E 10	2.88E 10	2.00E 10	1.59E 10	1.10E 10	1.37E 10	9.48E
0.75	1.00	2.12E 10	1.47E 10	8.89E 09	6.14E 09	4.89E 09	3.38E 09	4.22E 09	2.92E
1.00	1.25	6.54E 09	4.53E 09	2.74E 09	1.90E 09	1.51E 09	1.04E 09	1.30E 09	9.00E
1.25	1.50	2.02E 09	1.40E 09	8.45E U8	5.85E 08	4.66E 08	3.22E 08	4.01E 08	2.78E
1.50	1.75	6.21E 08	4.30E 08	2.60E 08	1.80E 08	1.43E 08	9.92E 07	1.24E 08	8.55E
1.75	2.00	1.91E 08	1.32E 08	8.02E 07	5.55E 07	4.42E 07	3.06E 07	3.81E 07	2.64E
2.00	2.25	5.900 07	4.08E 07	2.47E U7	1.71E 07	1.36E 07	9.42E 06	1.17E 07	8.13E
2.25	2.50	1.82E 07	1.26E 07	7.62E 06	5.27E 06	4.20E 06	2.90E 06	3.62E 06	2.50E
2.50	2.75	5.61E 06	3.88E 06	2.35E 06	1.62E 06	1.29E 06	8.95E 05	1.12E 06	7.71E
2.75	3.00	1.736 06	1.20E 06	7.24E 05	5.01E 05	3.99E 05	2.76E 05	3.44E 05	2.38E
3.00	3.25	5.32E 05	3.68E 05	2.23E 05	1.54E 05	1.23E 05	8.50E 04	1.06E 05	7.33E
3.25	3.50	1.648 05	1.13E 05	6.87E 04	4.75E 04	3.78E 04	2.62E 04	3.26E 04	2.26E
3.50	3.75	5.06E 04	3.50E 04	2.12E 04	1.47E 04	1.17E 04	8.07E 03	1.01E 04	6.96E
3.75	4.00	1.56E 04	1.08E 04	6.52E 03	4.51E 03	3.59E 03	2.48E 03	3.10E 03	2.14E
4.00	4.25	4.81E 03	3.33E 03	2.01E 03	1.39E 03	1.11E 03	7.68E 02	9.56E 02	6.62E
4.25	4.50	1.48E 03	1.02E 03	6.20E 02	4.29E 02	3.42E 02	2.36E 02	2.95E 02	2.04E
4.50	4.75	4.57E 02	3.16E 02	1.91E 02	1.32E 02	1.05E 02	7.29E 01	9.08F 01	6.29E
4.75	5.00	1.41E 02	9.72E 01	5.89E 01	4.07E 01	3.24E 01	2.24E 01	2.80E 01	1.93E
5.00	5.25	4.33E 01	3.00E 01	1.81E 01	1.25E 01	10.00E 00	6.91E 00	8.62E 00	5.96E
5.25	5.50	1.34F 01	9.24E 00	5.60E 00	3.87E 00	3.08E 00	2.13E 00	2.66E 00	1.84E
5.50	5.75	4.12E 00	2.85E 00	1.73E 00	1.19E 00	9.50E-01	6.58E-01	8.19E-01	5.67E
5.75	6.00	1.27E 00	8.76E-01	5.31E-01	3.67E-01	2.92E-01	2.02E-01	2.52E-01	1.74E
6.00	6.25	3.91E-01	2.71E-01	1.64E-01	1.13E-01	9.03E-02	6.248-02	7.78E-02	5.39E
6.25	6.50	1.21E-01	8.34E-02	5.05E-02	3.49E-02	2.78E-02	1.92E-02	2.40E-02	1.66E
6.50	6.75	3.71F-02	2.57E-02	1.55E-02	1.08E-02	8.56E-03	5.93E-03	7.39E-03	5.11E
6.75	7.00	1.14F-02	7.91E-03	4.79E-03	3.31E-03	2.64E-03	1.82E-03	2.27E-03	1.578
7.00		3.53E-03	3.53E-03	1.48E-03	1.48E-03	8.14E-04	8.14E-04	7.02E-04	7.02E